

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Mechanical Inspection

X192


Asset: I.S. 192 - BRONX, 650 HOLLYWOOD AVENUE, BRONX, NY, 10465

Inspection Id	Inspection Type	Time In	Last Edited
4775	MECHANICAL	2024-04-16 09:10AM	2024-05-22 01:44PM

Asset Data

Question	Answer
Have any Systems/Major Building Components been upgraded?	Systems: Exhaust Fans (~50%); Heat Pump Domestic Water Heaters Years: 2024 Systems: Steam Condensate Return Pumping System (1 of 2); Drinking Fountains (~60%) Years: 2022 Systems: Terminal Unit Thermostatic Traps (~80%); F&T/Steam Drip Trap (~80%) Years: 2021 Systems: Boiler Feedwater System; Steam Condensate Return Pumping System (1 of 2) Years: 2020 Systems: DX Split System for Room 116 (1 of 2) Years: 2019 Systems: Fixtures - Toilets, Urinals Years: 2017 Systems: Climate Control System: Temperature Control Thermostats (~90%) Years: 2015 Systems: Water Pressure Booster - Compressor; MDF Room - Dedicated A/C Equipment (1 of 2, DX Split System) Years: 2013
Are there fuel tanks?	Yes
Total # of above ground tanks	2
Total capacity of all above ground tanks in gal.	30,000
Total # of below ground tanks	0
Total capacity of all below ground tanks in gal.	0
Total # of water main service entries to the asset	3
MERs/Fan Rooms Locations	Basement - Boiler Room Mechanical Area, MER by Stair "E"; MER 228
Are there any spaces with Missing or Defective CO Detectors?	Yes
Location(s)	Boiler Room
Are there any Painted/Obstructed Sprinkler Heads?	Yes
Location(s)	Rooms B34, 110, 114 (painted, 14)
Are there any Emergency Stop Switches with Missing Hammers?	No components

Priority Condition

Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image
Yes	Defective Emergency Stop Switch	Missing Switch	Boiler Emergency Stop Switch	Boiler Room by Fuel Oil Transfer Pump	Juan Rodriguez	Fireman	

Inspection

Question	Response
Mechanical	
AIR CONDITIONING	Inspected
Chilled Water System	Does not exist
Condenser Water Distribution: Piping, Pumps and Auxiliaries	Does not exist
Cooling Coil in Ductwork	Does not exist
Cooling Tower	Does not exist

NYC Department of Education
Building Condition Assessment Survey 2023-2024

Mechanical Inspection

X192

Question	Response
AIR CONDITIONING	
DX Split System	Inspected
Indoor Unit	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Outdoor Unit	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Dry Cooler	Does not exist
Packaged / Rooftop Unit	Does not exist
Packaged Terminal A/C	Does not exist
Refrigerant Leak Detection System	Does not exist
Refrigerant Piping	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Return Fan	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
CENTRAL ACID WASTE NEUTRALIZING TANK	
Condition	3- Fair
Deficiency	No deficiencies recorded
CLIMATE CONTROL SYSTEM	
BMS	Does not exist
Pneumatic System	Inspected
Instance	Throughout
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Building Area Covered by Operational System	81-100%
Deficiency	DEFECTIVE TERMINAL UNIT CONTROL VALVE
Deficiency Location/Instance	Rooms 310, 412, 404, 420 and other locations
Deficiency Quantity	12
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Hybrid System	Does not exist
Electric System	Does not exist
COMPACTOR	
Condition	3- Fair
Deficiency	NOT IN USE
Deficiency Location/Instance	Room B21
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	NO ACTION
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 1
Violations	No violations recorded
CONVEYING	
Dumbwaiter	Does not exist
Elevator	Inspected
Condition	2- Between Good and Fair
Are all the existing elevators operable?	Yes
Deficiency	No deficiencies recorded

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Mechanical Inspection

X192

Question	Response
CONVEYING	
Escalator	Does not exist
Non-auditorium Handicap Lift - Vertical	Does not exist
Non-auditorium Handicap Lift - Stair	Does not exist
Ash Hoist	Does not exist
Sidewalk Elevator	Does not exist
DOMESTIC WATER SYSTEM	
Domestic Cold Water System	Inspected
Gravity System	Does not exist
Pressure Booster System	Inspected
Electric Pressure Booster System	Does not exist
Hydraulic/Pneumatic Booster System	Inspected
Water Pressure Booster - Compressor	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Pressure Booster Pump	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Domestic Cold Water Tank	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Water Service	Inspected
Instance	Basement - North Crawlspace by Randall Avenue, Sprinkler/Gas/Water Meter Room B31
Instance Condition	3- Fair
Instance Quantity	3
Instance Quantity Uom	EACH
Deficiency	WATER MAIN:MISSING BACKFLOW PREVENTION DEVICE
Deficiency Location/Instance	Basement - North Crawlspace by Randall Avenue, Sprinkler/Gas/Water Meter Room B31
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	INSTALL
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Domestic Hot Water System	Inspected
Domestic Hot Water Remote Storage Tank	Does not exist
Domestic Water Heat Exchanger	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Electric Domestic Water Heater	Does not exist
Gas Fired Domestic Water Heater	Does not exist
Oil Fired Domestic Water Heater	Does not exist
Heat Pump Domestic Water Heater	Inspected
Instance	Boiler Room Mechanical Area
Instance Condition	1- Good
Instance Quantity	2
Instance Quantity Uom	EACH
Manufacturer	A.O. Smith
EquipmentId	WH-1, WH-2
Capacity/Size Quantity	5
Capacity/Size UOM	KW Input
Capacity/Size 2 Quantity	119

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Mechanical Inspection

X192

Question	Response
DOMESTIC WATER SYSTEM	
Domestic Hot Water System	
Heat Pump Domestic Water Heater	
Capacity/Size 2 UOM	Gallons
Source of Capacity/Size	Documented
Installation Year	2024
Source of Installation Year	Custodial Staff
Deficiency	No deficiencies recorded
Domestic Water Distribution Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
DRAIN/WASTE/VENT AND STORM SYSTEM	
Interior Storm Piping	
Condition	3- Fair
Deficiency	No deficiencies recorded
Sewage/Waste/Vent Piping	
Condition	3- Fair
Deficiency	SEWAGE/WASTE PIPING:DEFECTIVE/LEAKS
Deficiency Location/Instance	Boy's Toilet Room 208
Deficiency Quantity	10
Quantity Uom	L.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Sewage Ejector Pump	
Condition	3- Fair
Deficiency	No deficiencies recorded
Sump Pump	
Condition	3- Fair
Deficiency	DEFECTIVE CONTROLS
Deficiency Location/Instance	MER by Stair "E" (1 of 2)
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
DUAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)	
Does not exist	
FIXTURES	
Staff And Other	
Janitor Sink	
Condition	3- Fair
Deficiency	No deficiencies recorded
Lavatory/Sink	
Condition	3- Fair
Deficiency	No deficiencies recorded
Toilet	
Condition	1- Good
Deficiency	No deficiencies recorded
Urinal	
Condition	1- Good
Deficiency	No deficiencies recorded
Student	
Drinking Fountain	
Inspected	

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Mechanical Inspection

X192

Question	Response
FIXTURES	
Student	
Drinking Fountain	
Condition	2- Between Good and Fair
Deficiency	DEFECTIVE AUXILIARY (FAUCET, SHUT OFF VALVE,ETC.)
Deficiency Location/Instance	Corridor near Room 309
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Lavatory/Sink	
	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Locker Room Shower	
	Inspected
Instance on 1st Floor - Boys	Inaccessible
Instance on 1st Floor - Girls	Inaccessible
Sink And Fountain Combo Unit	
	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Toilet	
	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Urinal	
	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
GAS FIRED FURNACE	
	Does not exist
GAS SERVICE	
	Inspected
Gas Distribution Piping	
	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Gas Meter Room Exhaust Fan	
	Does not exist
Gas Meter Room Vent	
	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Gas Pressure Booster	
	Does not exist
CO/Gas Leak Detection	
	Does not exist
HEATING	
	Inspected
Heating Coil In Ductwork	
	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Hydronic Heating	
	Does not exist
Radiator/Convactor/Fin Tube	
	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Steam Heating	
	Inspected
F&T/Steam Drip Trap	
	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
MER Steam and Condensate Piping	
	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded

NYC Department of Education
Building Condition Assessment Survey 2023-2024

Mechanical Inspection

X192

Question	Response
HEATING	
Steam Heating	
Steam Condensate Return Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Steam Condensate Return Pumping System	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Steam Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Terminal Unit Thermostatic Trap	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Steam supplied by External Sources	Does not exist
Unit Heater/Cabinet Heater	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
HEATING PLANT	Inspected
Instance on Basement	Inspected
Is there a water meter on the boiler make-up water piping?	No
Burner Manufacturer	Preferred Utilities
Burner Model	BHE7-3A4
Burner Type	Oil
Heating Plant Oil Number	2
Boiler Auxiliaries	
Instance on Basement	Inspected
Boiler Auxiliary Piping	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Boiler Emergency Stop Switch	
Instance on Basement	Inspected
Instance Condition	4- Between Fair and Poor
Deficiency	DEFECTIVE
Deficiency Location/Instance	Boiler Room by Fuel Oil Transfer Pump (1 of 2)
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
Boiler Feedwater System	
Instance on Basement	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Boiler Feedwater Treatment(Automatic)	
Instance on Basement	Does not exist
Boiler Flue Exhaust	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Boiler Make-up Water Backflow Preventer	
Instance on Basement	Does not exist

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Mechanical Inspection

X192

Question	Response
HEATING PLANT	
Boiler Auxiliaries	
Boiler Room Steam And Condensate Piping	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Boiler Safety Valve	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Boiler System	
Instance on Basement	Inspected
Coal-fired Boiler	
Instance on Basement	Does not exist
Hot Water Boiler	
Instance on Basement	Does not exist
Modular Boiler	
Instance on Basement	Does not exist
Steam Boiler	
Instance on Basement	Inspected
Instance on Basement	Inspected
Instance	Boiler Room
Instance Condition	3- Fair
Instance Quantity	4,887
Instance Quantity Uom	MBH NET
Cast Iron Boiler?	No
Manufacturer	Kewanee Boiler Corporation
EquipmentId	60258-01
Capacity/Size Quantity	6294
Capacity/Size UOM	MBH Gross
Source of Capacity/Size	Documented
Installation Year	1972
Source of Installation Year	Documented
Deficiency	LEAKY/PLUGGED TUBES
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Boiler Room
Instance Condition	3- Fair
Instance Quantity	4,887
Instance Quantity Uom	MBH NET
Cast Iron Boiler?	No
Manufacturer	Kewanee Boiler Corporation
EquipmentId	60258-02
Capacity/Size Quantity	6294
Capacity/Size UOM	MBH Gross
Source of Capacity/Size	Documented
Installation Year	1972
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Boiler Room
Instance Condition	3- Fair

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Mechanical Inspection

X192

Question	Response
HEATING PLANT	
Boiler System	
Steam Boiler	
Instance Quantity	4,887
Instance Quantity Uom	MBH NET
Cast Iron Boiler?	No
Manufacturer	Kewanee Boiler Corporation
EquipmentId	60258-03
Capacity/Size Quantity	6294
Capacity/Size UOM	MBH Gross
Source of Capacity/Size	Documented
Installation Year	1972
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Fuel System	
Instance on Basement	Inspected
Boiler Fresh Air Louver/Damper	
Instance on Basement	Inspected
Instance Condition	2- Between Good and Fair
Type	Automatic
Deficiency	No deficiencies recorded
Burner/Burner Control Panel	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Fuel Oil Storage/Supply System	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	FUEL OIL PIPING:DEFECTIVE/LEAKS
Deficiency Location/Instance	Boiler Room (defective strainers and leaking pipes)
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Gas Trains And Vent At The Boiler	
Instance on Basement	Does not exist
Enclosed IDF Room	
Instance on Room 305 G/H	Inspected
Dedicated A/C Equipment	
Instance on Room 305 G/H	Inspected
Instance Condition	4- Between Fair and Poor
Deficiency	DEFECTIVE
Deficiency Location/Instance	Room 305 G/H
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
KITCHEN	
Instance on 1st Floor	Inspected
CO Detector	
Instance on 1st Floor	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Mechanical Inspection

X192

Question	Response
KITCHEN	
CO Detector	
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Gas System	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Grease Trap	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Hood	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Hood Exhaust Ductwork	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Hood Exhaust Fan	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Hood Fire Suppression System	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Hot Water Temperature Booster	
Instance on 1st Floor	Does not exist
Kitchen Sink	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	Missing Air Gap
Deficiency Location/Instance	Kitchen
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 4
Violations	SF94684
MDF Room	
Instance on Room 315	Inspected
Dedicated A/C Equipment	
Instance on Room 315	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
SCIENCE DEMO ROOM	
Instance on Rooms 317, 417	Inspected
Alternative Use	Yes
Acid Waste Neutralizing Tank	
Instance on Rooms 317, 417	Does not exist
CO Detector	
Instance on Rooms 317, 417	Not required

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Mechanical Inspection

X192

Question	Response
SCIENCE DEMO ROOM	
Emergency Shower	
Instance on Rooms 317, 417	Does not exist
Eye Wash	
Instance on Rooms 317, 417	Does not exist
Hood Exhaust Ductwork	
Instance on Rooms 317, 417	Does not exist
Hood Exhaust Fan	
Instance on Rooms 317, 417	Does not exist
Fixed Laboratory Hood	
Instance on Rooms 317, 417	Does not exist
Laboratory Sink	
Instance on Rooms 317, 417	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Make-up Air Unit	
Instance on Rooms 317, 417	Does not exist
SCIENCE LAB	Inspected
Instance on Rooms 210, 212, 312	Inspected
Alternative Use	Yes
Instance on Rooms 310, 410, 412	Inspected
Alternative Use	No
Acid Waste Neutralizing Tank	
Instance on Rooms 210, 212, 312	Does not exist
Instance on Rooms 310, 410, 412	Does not exist
CO Detector	
Instance on Rooms 210, 212, 312	Not required
Instance on Rooms 310, 410, 412	Not required
Emergency Shower	
Instance on Rooms 210, 212, 312	Does not exist
Instance on Rooms 310, 410, 412	Does not exist
Eye Wash	
Instance on Rooms 210, 212, 312	Does not exist
Instance on Rooms 310, 410, 412	Does not exist
Hood Exhaust Ductwork	
Instance on Rooms 210, 212, 312	Does not exist
Instance on Rooms 310, 410, 412	Does not exist
Hood Exhaust Fan	
Instance on Rooms 210, 212, 312	Does not exist
Instance on Rooms 310, 410, 412	Does not exist
Fixed Laboratory Hood	
Instance on Rooms 210, 212, 312	Does not exist
Instance on Rooms 310, 410, 412	Does not exist
Laboratory Sink	
Instance on Rooms 210, 212, 312	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Rooms 310, 410, 412	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Make-up Air Unit	
Instance on Rooms 210, 212, 312	Does not exist
Instance on Rooms 310, 410, 412	Does not exist
SCIENCE PREP ROOM	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Mechanical Inspection

X192

Question	Response
SCIENCE PREP ROOM	
Instance on Room 432	Inspected
Alternative Use	Yes
Acid Waste Neutralizing Tank	
Instance on Room 432	Does not exist
CO Detector	
Instance on Room 432	Not required
Emergency Shower	
Instance on Room 432	Does not exist
Eye Wash	
Instance on Room 432	Does not exist
Hood Exhaust Ductwork	
Instance on Room 432	Does not exist
Hood Exhaust Fan	
Instance on Room 432	Does not exist
Fixed Laboratory Hood	
Instance on Room 432	Does not exist
Laboratory Sink	
Instance on Room 432	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Make-up Air Unit	
Instance on Room 432	Does not exist
SPRINKLERS, STANDPIPE, FIRE SYSTEM	Inspected
Dry Sprinkler Alarm Valve Assembly	Does not exist
Wet Sprinkler Alarm Valve Assembly	Inspected
Condition	3- Fair
Deficiency	NOT IN USE
Deficiency Location/Instance	Sprinkler/Gas/Water Meter Room B31
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	NO ACTION
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 1
Violations	No violations recorded
Fire Booster Pump Assembly	Does not exist
Roof Tank	Does not exist
Siamese Connection	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Sprinkler Head	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE/DETERIORATED
Deficiency Location/Instance	Rooms B34, 110, 114 (painted, 14)
Deficiency Quantity	14
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
Sprinkler Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Standpipe System	Inspected
Hose Valve Assembly	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Mechanical Inspection

X192

Question	Response
SPRINKLERS, STANDPIPE, FIRE SYSTEM	
Standpipe System	
Hose Valve Assembly	
Condition	3- Fair
Deficiency	No deficiencies recorded
Piping	
Condition	3- Fair
Deficiency	No deficiencies recorded
Water Gong	
Does not exist	
SWIMMING POOL	
Does not exist	
VENTILATION	
Is the building Mechanically ventilated?	Inspected Partial
Exhaust Fan	
Condition	Inspected
Approximate Total # of Fans	2- Between Good and Fair 1-25
Deficiency	DEFECTIVE
Deficiency Location/Instance	Main roof / Exhaust Fan #17
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Heating And Ventilating Unit	
Condition	Inspected
Deficiency	3- Fair
Deficiency	DEFECTIVE CONTROLS
Deficiency Location/Instance	MER 228 / Heating And Ventilating Unit #9
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	DEFECTIVE
Deficiency Location/Instance	MER 228 / Heating And Ventilating Unit #10 (defective bearing)
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Metal Ductwork	
Condition	Inspected
Condition	3- Fair
Are there any uninsulated ductwork by design in Mechanical rooms?	Yes
Are there chain operated dampers?	No
Deficiency	DEFECTIVE REGISTER/DIFFUSER
Deficiency Location/Instance	Gymnasium
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	DAMAGED FLEXIBLE CONNECTION
Deficiency Location/Instance	MER by Stair "E" @ Heating And Ventilating Unit #2
Deficiency Quantity	1

NYC Department of Education
Building Condition Assessment Survey 2023-2024

Mechanical Inspection

X192

Question	Response
VENTILATION	
Metal Ductwork	
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Supply Fan	Does not exist
Unit Ventilator	Does not exist