## **Building Condition Assessment Survey 2023-2024**

#### Mechanical Inspection

Asset:	I.S. 206B - BRONX, 2280 AQUEDUCT AVENUE, BRONX, NY, 104	168	
Inspection Id	Inspection Type	Time In	Last Edited
569	MECHANICAL	2023-10-30 07:29AM	2023-11-22 11:52AM
set Data			
Question		Answer	

Question	Answer
Have any Systems/Major Building Components been upgraded?	Systems: Heat Pump Domestic Water Heaters
	Years: 2023
	Systems: Kitchen - Grease Trap; Students Fixtures - Toilets (~50%), Urinals (~50%)
	Years: 2016
	Systems: Electric Pressure Booster System; Water Service
	Years: 2015
	Systems: Climate Control System: Thermostats (~75%)
	Years: 2013
Are there fuel tanks?	Yes
Total # of above ground tanks	1
Total capacity of all above ground tanks in gal.	10,000
Total # of below ground tanks	0
Total capacity of all below ground tanks in gal.	0
Total # of water main service entries to the asset	3
MERs/Fan Rooms Locations	Penthouse MER
Are there any spaces with Missing or Defective CO Detectors?	No
Are there any Painted/Obstructed Sprinkler Heads?	Yes
Location(s)	Basement - Room 5, Corridor (painted, 4); Basement Corridor
	by Rooms 1, 5 and 8 (obstructed, 3)
Are there any Emergency Stop Switches with Missing Hammers?	Component: Penthouse MER Entrance
	Location: Chilled Water Distribution: Piping, Pumps and Auxiliaria

#### **Priority Condition**

Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image
Yes	Defective Boiler Safety Auxiliary	(2)	Boiler Safety Valve	Boiler Room @ Boiler #1	Michael Smith	Fireman	
Yes	Defective Emergency Stop Switch	Missing Glass	Boiler Emergency Stop Switch	Boiler Room by Air Compressor	Michael Smith	Fireman	

Response
Inspected
Inspected
Does not exist
Does not exist
Does not exist
Inspected
3- Fair
AUXILIARIES: EMERGENCY STOP SWITCH: MISSING
HAMMER
Penthouse MER Entrance

## **Building Condition Assessment Survey 2023-2024**

#### **Mechanical Inspection**

estion	Response
IR CONDITIONING	
Chilled Water System	
Chilled Water Distribution: Piping, Pumps and Auxiliaries	
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
Backflow Preventer	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Central Station Air Handler	Inspected
Instance	Penthouse MER
Instance Condition	3- Fair
Instance Quantity	3
Instance Quantity Uom	EACH
Manufacturer	McQuay
Manufacturer EquipmentId	MZ-1, MZ-2, MZ-3
Equipmentia Capacity/Size Quantity	12500
Capacity/Size UOM	CFM
Source of Capacity/Size	Inspector Estimate
Installation Year	1978
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Fan Coil Unit	Does not exist
Packaged Air Cooled Chiller	Inspected
Instance	Roof
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Trane
EquipmentId	N/A
Capacity/Size Quantity	155
Capacity/Size UOM	Tons
Source of Capacity/Size	Custodial Staff
Installation Year	2010
Source of Installation Year	Documented
Refrigerant Type	R-134A
Deficiency	No deficiencies recorded
Water Cooled Chiller	Does not exist
Condenser Water Distribution: Piping, Pumps and Auxiliaries	Does not exist
Cooling Coil in Ductwork	Does not exist
Cooling Tower	Does not exist
DX Split System	Inspected
Indoor Unit	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Outdoor Unit	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Dry Cooler	Does not exist
Packaged / Rooftop Unit	Does not exist
Packaged / Rooftop Unit Packaged Terminal A/C	Does not exist           Does not exist

## **Building Condition Assessment Survey 2023-2024**

## Mechanical Inspection

unicui Inspeciion	Λ2
uestion	Response
AIR CONDITIONING	
Refrigerant Piping	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Return Fan	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
CENTRAL ACID WASTE NEUTRALIZING TANK	Does not exist
CLIMATE CONTROL SYSTEM	Inspected
BMS	Does not exist
Pneumatic System	Inspected
Instance	Throughout
Instance Condition	3- Fair
Instance Quantity	1
	EACH
Instance Quantity Uom	
Building Area Covered by Operational System	81-100% DEFECTIVE REFRIGERATED AIR DRYER
Deficiency	
Deficiency Location/Instance Deficiency Quantity	Boiler Room
Quantity Uom	1 EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
	Does not exist
Hybrid System Electric System	Does not exist
•	Does not exist
COMPACTOR	
CONVEYING	Inspected
Dumbwaiter	Does not exist
Elevator	Inspected 2- Between Good and Fair
Condition	
Are all the existing elevators operable?	Yes
Deficiency	No deficiencies recorded
Escalator	Does not exist
Non-auditorium Handicap Lift - Vertical	Does not exist
Non-auditorium Handicap Lift - Stair	Does not exist Does not exist
Ash Hoist Sidewalk Elevator	Does not exist
OOMESTIC WATER SYSTEM	Inspected
Domestic Cold Water System	Inspected
Gravity System	Does not exist
Pressure Booster System	Inspected
Electric Pressure Booster System	Inspected
Instance	Pump Room B3A
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Liquitrol
EquipmentId	N/A
Capacity/Size Quantity	2
Capacity/Size UOM	Total # Pumps
Capacity/Size 2 Quantity	10
Capacity/Size 2 UOM	Total Pumps HP
Source of Capacity/Size	Documented 2015

## **Building Condition Assessment Survey 2023-2024**

#### **Mechanical Inspection**

ostion	Besnansa
estion	Response
OMESTIC WATER SYSTEM	
Domestic Cold Water System	
Pressure Booster System	
Electric Pressure Booster System	
Source of Installation Year	Custodial Staff
Deficiency	No deficiencies recorded
Hydraulic/Pneumatic Booster System	Does not exist
Water Service	Inspected
Instance	Water Service Room B3B; Sprinkler/Water/Gas Meter Room B2
Instance Condition	1- Good
Instance Quantity	3
Instance Quantity Uom	EACH
Deficiency	No deficiencies recorded
Domestic Hot Water System	Inspected
Domestic Hot Water Remote Storage Tank	Does not exist
Domestic Water Heat Exchanger	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Electric Domestic Water Heater	Does not exist
Gas Fired Domestic Water Heater	Does not exist
Oil Fired Domestic Water Heater	Does not exist
Heat Pump Domestic Water Heater	Inspected
Instance	Kitchen
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	A.O. Smith
EquipmentId	N/A
Capacity/Size Quantity	4
Capacity/Size UOM	KW Input
Capacity/Size 2 Quantity	50
Capacity/Size 2 UOM	Gallons
Source of Capacity/Size	Documented 2023
Installation Year Source of Installation Year	2025 Custodial Staff
	No deficiencies recorded
Deficiency	Boiler Room
Instance	1- Good
Instance Condition	
Instance Quantity	2 EACH
Instance Quantity Uom	EACH
Manufacturer	A.O. Smith
EquipmentId	N/A
Capacity/Size Quantity	5
Capacity/Size UOM Capacity/Size 2 Quantity	KW Input 119
Capacity/Size 2 Quantity Capacity/Size 2 UOM	Gallons
Source of Capacity/Size	Documented
Installation Year	2023
Source of Installation Year	Custodial Staff
Deficiency	No deficiencies recorded
Domestic Water Distribution Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
RAIN/WASTE/VENT AND STORM SYSTEM	Inspected
Interior Storm Piping	Inspected

## **Building Condition Assessment Survey 2023-2024**

## Mechanical Inspection

unicui Inspection		1200
Puestion	Response	
DRAIN/WASTE/VENT AND STORM SYSTEM		
Interior Storm Piping		
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Sewage/Waste/Vent Piping	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Sewage Ejector Pump	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Sump Pump	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
DUAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)	Does not exist	
FIXTURES	Inspected	
Staff And Other	Inspected	
Janitor Sink	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Lavatory/Sink	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Toilet	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Urinal	Does not exist	
Student	Inspected	
Drinking Fountain	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Lavatory/Sink	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Locker Room Shower	Does not exist	
Sink And Fountain Combo Unit	Does not exist	
Toilet	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Urinal	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
	Does not exist	
GAS FIRED FURNACE		
GAS SERVICE	Inspected	
Gas Distribution Piping	Inspected 3- Fair	
Condition		
Deficiency	No deficiencies recorded Does not exist	
Gas Meter Room Exhaust Fan Gas Meter Room Vent	Inspected	
	2- Between Good and Fair	
Condition		
Deficiency	No deficiencies recorded	

# Building Condition Assessment Survey 2023-2024

#### **Mechanical Inspection**

	X200
lestion	Response
IEATING	
Heating Coil In Ductwork	Does not exist
Hydronic Heating	Does not exist
Radiator/Convector/Fin Tube	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Steam Heating	Inspected
F&T/Steam Drip Trap	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
MER Steam and Condensate Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Steam Condensate Return Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Steam Condensate Return Pumping System	Does not exist
Steam Condensate Return Pumping System Steam Piping	Inspected
Condition	3- Fair
	No deficiencies recorded
Deficiency	
Terminal Unit Thermostatic Trap	Does not exist
Steam supplied by External Sources	Does not exist
Unit Heater/Cabinet Heater	Does not exist
IEATING PLANT	Inspected
Instance on Basement	Inspected
Is there a water meter on the boiler make-up water piping?	No
Burner Manufacturer Burner Model	Preferred Utilities BE 25 3M4
Burner Type	Oil
Heating Plant Oil Number	2(B10)
Boiler Auxiliaries	
Instance on Basement	Inspected
Boiler Auxiliary Piping	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Boiler Emergency Stop Switch	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency Deficiency Location/Instance	DEFECTIVE Boiler Room by Air Compressor (missing glass, 1 of 3)
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
Boiler Feedwater System	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Boiler Feedwater Treatment(Automatic)	Decement artist
Instance on Basement Boiler Flue Exhaust	Does not exist
Roller Flue Fyhaust	
Instance on Basement	Inspected

## **Building Condition Assessment Survey 2023-2024**

#### **Mechanical Inspection**

stion	Response	
CATING PLANT	Kisponse	
Boiler Auxiliaries		
Boiler Flue Exhaust		
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Boiler Make-up Water Backflow Preventer	No deficicies recorded	
Instance on Basement	Does not exist	
Boiler Room Steam And Condensate Piping	Does not exist	
Instance on Basement	Inspected	
Instance Condition	3- Fair	
	No deficiencies recorded	
	No deficiencies recorded	
Boiler Safety Valve	Y . 1	
Instance on Basement	Inspected	
Instance Condition	4- Between Fair and Poor	
Deficiency	DEFECTIVE	
Deficiency Location/Instance	Boiler Room @ Boiler #1	
Deficiency Quantity	2	
Quantity Uom Potential Action	EACH REPLACE	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 6	
Violations	No violations recorded	
	No violations recorded	
Boiler System Instance on Basement	Inspected	
Coal-fired Boiler	inspected	
	Does not exist	
Instance on Basement	Does not exist	
Hot Water Boiler		
Instance on Basement	Does not exist	
Modular Boiler		
Instance on Basement	Does not exist	
Steam Boiler		
Instance on Basement	Inspected	
Instance on Basement	Inspected	
Instance	Boiler Room	
Instance Condition	3- Fair	
Instance Quantity	2,064	
Instance Quantity Uom	MBH NET	
Cast Iron Boiler?	No	
Manufacturer	Federal Boiler Company	
EquipmentId	68621-01	
Capacity/Size Quantity	2064	
Capacity/Size UOM	MBH Net	
Source of Capacity/Size	Documented 1978	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Instance	Boiler Room	
Instance Condition	3- Fair	
Instance Quantity	2,064 MDH NET	
Instance Quantity Uom	MBH NET	
Cast Iron Boiler?	No Estand Deiler Community	
Manufacturer	Federal Boiler Company	
EquipmentId	68621-02 2064	
Capacity/Size Quantity Capacity/Size UOM	2064 MBH Net	

## **Building Condition Assessment Survey 2023-2024**

#### **Mechanical Inspection**

		A20
uestion	Response	
HEATING PLANT		
Boiler System		
Steam Boiler		
Source of Capacity/Size	Documented	
Installation Year	1978	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Fuel System		
Instance on Basement	Inspected	
Boiler Fresh Air Louver/Damper		
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Туре	Automatic	
Deficiency	No deficiencies recorded	
Burner/Burner Control Panel		
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Fuel Oil Storage/Supply System		
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Gas Trains And Vent At The Boiler		
Instance on Basement	Does not exist	
Enclosed IDF Room	Does not exist	
KITCHEN	Inspected	
Instance on 1st Floor	Inspected	
CO Detector		
Instance on 1st Floor	Not required	
Gas System		
Instance on 1st Floor	Does not exist	
Grease Trap		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Hood		
Instance on 1st Floor	Does not exist	
Hood Exhaust Ductwork		
Instance on 1st Floor	Does not exist	
Hood Exhaust Fan		
Instance on 1st Floor	Does not exist	
Hood Fire Suppression System		
Instance on 1st Floor	Does not exist	
Hot Water Temperature Booster		
Instance on 1st Floor	Does not exist	
Kitchen Sink		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	Missing Air Gap	
Deficiency Location/Instance	Kitchen	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 4	

## **Building Condition Assessment Survey 2023-2024**

#### **Mechanical Inspection**

Puestion	Response
KITCHEN	Kspolse
Kitchen Sink	
Violations	SF103319
MDF Room	Inspected
Instance on Room 219	Inspected
Dedicated A/C Equipment	Inspected
Instance on Room 219	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
SCIENCE DEMO ROOM	Does not exist
SCIENCE LAB	Inspected
Instance on Room 303	Inspected
Alternative Use	No
Acid Waste Neutralizing Tank	NO
Instance on Room 303	Does not exist
CO Detector	
Instance on Room 303	Not required
Emergency Shower	1
Instance on Room 303	Does not exist
Eye Wash	
Instance on Room 303	Does not exist
Hood Exhaust Ductwork	
Instance on Room 303	Does not exist
Hood Exhaust Fan	
Instance on Room 303	Does not exist
Fixed Laboratory Hood	
Instance on Room 303	Does not exist
Laboratory Sink	
Instance on Room 303	Inspected
Instance Condition	4- Between Fair and Poor
Deficiency	DEFECTIVE AUXILIARY (FAUCET, SHUT OFF
Deficience I continu (Instance	VALVE,ETC.)
Deficiency Location/Instance Deficiency Quantity	Room 303 (3 of 4) 3
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Make-up Air Unit	
Instance on Room 303	Does not exist
SCIENCE PREP ROOM	Inspected
Instance on Room 309	Inspected
Alternative Use	Yes
Acid Waste Neutralizing Tank	
Instance on Room 309	Does not exist
CO Detector	
Instance on Room 309	Not required
Emergency Shower	
Instance on Room 309	Does not exist
Eye Wash	
Instance on Room 309	Does not exist
Hood Exhaust Ductwork	
Instance on Room 309	Does not exist

## **Building Condition Assessment Survey 2023-2024**

#### **Mechanical Inspection**

uestion	Response
	Kesponse
SCIENCE PREP ROOM	
Hood Exhaust Fan Instance on Room 309	Does not exist
Fixed Laboratory Hood Instance on Room 309	Does not exist
Laboratory Sink	
Instance on Room 309	Inspected
Instance Condition	3- Fair
	No deficiencies recorded
Deficiency	No deficiencies recorded
Make-up Air Unit	Description in the second seco
Instance on Room 309	Does not exist
SPRINKLERS, STANDPIPE, FIRE SYSTEM	Inspected
Dry Sprinkler Alarm Valve Assembly	Does not exist
Wet Sprinkler Alarm Valve Assembly	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Fire Booster Pump Assembly	Does not exist
Roof Tank	Does not exist
Siamese Connection	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Sprinkler Head	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE/DETERIORATED
Deficiency Location/Instance	Basement - Room 5, Corridor (painted, 4); Basement Corridor by
	Rooms 1, 5 and 8 (obstructed, 3)
Deficiency Quantity	7
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
Sprinkler Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Standpipe System	Inspected
Hose Valve Assembly	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE FIRE HOSE CABINET
Deficiency Location/Instance	Stairs "A/3", "A/2", "B/1"
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Water Gong	Does not exist
-	Does not exist
SWIMMING POOL	
VENTILATION	Inspected
Is the building Mechanically ventilated?	Yes
Exhaust Fan	Inspected 3- Fair

## **Building Condition Assessment Survey 2023-2024**

#### **Mechanical Inspection**

lestion	Response	
/ENTILATION		
Exhaust Fan		
Approximate Total # of Fans	1-25	
Deficiency	No deficiencies recorded	
Heating And Ventilating Unit	Does not exist	
Metal Ductwork	Inspected	
Condition	3- Fair	
Are there any uninsulated ductwork by design in Mechanical rooms?	Yes	
Are there chain operated dampers?	No	
Deficiency	DEFECTIVE REGISTER/DIFFUSER	
Deficiency Location/Instance	Gymnasium, MDF Room 219	
Deficiency Quantity	4	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Deficiency	DAMAGED/MISSING INSULATION	
Deficiency Location/Instance	Penthouse MER	
Deficiency Quantity	100	
Quantity Uom	L.F.	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Supply Fan	Does not exist	
Unit Ventilator	Does not exist	