Building Condition Assessment Survey 2023-2024

Mechanical Inspection X415

CHRISTOPHER COLUMBUS HS - BRONX, 925 ASTOR AVENUE, BRONX, NY, 10469

| Inspection Id Inspection Type | | Time In | Last Edited |
|---|-----------------|---|---|
| 4693 MECHANICAL | | 2024-04-11 09:57AM | 2024-05-30 05:09PM |
| sset Data | | | |
| Question | Answer | | |
| Have any Systems/Major Building Components been upgraded? | Systems: | Gas Fired Domestic Water Heate | er (1 of 2) |
| | Years: | 2024 | |
| | Systems: Years: | Fixtures - Drinking Fountains (~ (except door); DX Split Systems 361F, 361G (3 of 7) 2022 | · · · · · · · · · · · · · · · · · · · |
| | Systems: | Kitchen- Grease Trap (1 of 2) | |
| | Years: | 2021 | |
| | Systems: Years: | Climate Control System - Pneum Temperature Control Thermostat System - Electric System: Termin (~50%); Domestic Hot Water Re Gas Fired Domestic Water Heate 2020 | s; Climate Control nal Unit Control Valves mote Storage Tank; |
| | Systems: | Kitchen - Hood Fire Suppression Drip Traps; Terminal Unit Therm | • |
| | Years: | 2019 | |

Systems: Kitchen - Grease Trap (1 of 2); MDF Room - Dedicated A/C Equipment: Room 114 (DX Split System); Enclosed IDF Rooms - Dedicated A/C Equipment (DX Split Systems); CO/Gas Leak Detection; DX Split Systems (2 of 7) for Camera Room 120 and Telephone Room 136 Years: 2013 Are there fuel tanks? Yes

Years:

2015

Systems: DX Split System (1 of 7) and Climate Control System -

(Automatic); Fixtures - Toilets

BMS for Health Clinic 228A; MDF Room - Dedicated A/C Equipment for MDF Room inside Health Clinic 228A (DX Split System); Boiler Feedwater Treatment

Total # of above ground tanks Total capacity of all above ground tanks in gal. 10,000 Total # of below ground tanks 0 Total capacity of all below ground tanks in gal. 0 Total # of water main service entries to the asset MERs/Fan Rooms Locations Basement - MER B63, East and West MERs; Health Clinic

228A - MER; Penthouse MER

Are there any spaces with Missing or Defective CO Detectors? No Are there any Painted/Obstructed Sprinkler Heads? Yes Location(s)

Weight Room B9 (obstructed, 5), Auditorium Stage, Room 361G (painted, 5) Are there any Emergency Stop Switches with Missing Hammers? No components

Priority Condition

Asset:

| Exist | Priority | Condition | Component | Location | Person(s) | Person(s) | Photo |
|------------|--------------------------------------|---|--------------|--------------------------------|--------------------|-----------|-------|
| Last Year? | Category | Description | Affected | Description | Notified | Title | Image |
| Yes | Defective Boiler Safety Auxiliary | Secondary Low Water Cut-offs are defective (2) | Steam Boiler | Boiler Room / Boiler #2, #4 | Leonel Guerrero | Fireman | |

Building Condition Assessment Survey 2023-2024

| Mechan | ical Inspection | | | | | | X415 |
|--------|------------------------------------|------------------------|---------------------------|---|--------------------|---------|------|
| Yes | Other | Defective | Science Lab - Eye Wash | Room 425 | Leonel Guerrero | Fireman | |
| Yes | Defective CO/Gas Leak Detection | Fault Signal At Panels | CO/Gas Leak Detection | Boiler Room, Custodian's Office 143 | Leonel Guerrero | Fireman | |

Inspection

| ection | |
|---|--------------------------|
| uestion | Response |
| [echanical | |
| AIR CONDITIONING | Inspected |
| Chilled Water System | Does not exist |
| Condenser Water Distribution: Piping, Pumps and Auxiliaries | Does not exist |
| Cooling Coil in Ductwork | Does not exist |
| Cooling Tower | Does not exist |
| DX Split System | Inspected |
| Indoor Unit | Inspected |
| Condition | 1- Good |
| Deficiency | No deficiencies recorded |
| Outdoor Unit | Inspected |
| Condition | 1- Good |
| Deficiency | No deficiencies recorded |
| Dry Cooler | Does not exist |
| Packaged / Rooftop Unit | Inspected |
| Instance | Roof - Northeast Side |
| Instance Condition | 3- Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Manufacturer | Trane |
| EquipmentId | N/A |
| Capacity/Size Quantity | 12 |
| Capacity/Size UOM | Tons |
| Source of Capacity/Size | Inspector Estimate |
| Installation Year | 1990 |
| Source of Installation Year | Inspector Estimate |
| Source of Heating | N/A |
| Refrigerant Type | R-22 |
| Deficiency | No deficiencies recorded |
| Packaged Terminal A/C | Does not exist |
| Refrigerant Leak Detection System | Does not exist |
| Refrigerant Piping | Inspected |
| Condition | 1- Good |
| Deficiency | No deficiencies recorded |
| Return Fan | Does not exist |
| CENTRAL ACID WASTE NEUTRALIZING TANK | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| CLIMATE CONTROL SYSTEM | Inspected |
| BMS | Inspected |
| Instance | Health Clinic 228A |

Building Condition Assessment Survey 2023-2024

| uestion | Response |
|--|--|
| CLIMATE CONTROL SYSTEM | |
| BMS | |
| Instance Condition | 2- Between Good and Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Building Area Covered by Operational System | 81-100% |
| Installation Year | 2015 |
| Source of Installation Year | Inspector Estimate |
| Deficiency | No deficiencies recorded |
| Pneumatic System | Inspected |
| Instance | Basement, 1st, 2nd, 3rd and 4th Floors Various Locations |
| Instance Condition | 3- Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Building Area Covered by Operational System | 41-60% |
| Deficiency | DEFECTIVE DAMPER ACTUATOR |
| Deficiency Location/Instance | MER B63 @ Gymnasium Blower |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | MAINTENANCE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Deficiency | DEFECTIVE TEMPERATURE CONTROL THERMOSTAT |
| Deficiency Location/Instance | Rooms 117, 205, 211, 445 and other locations |
| Deficiency Quantity | 45 |
| Quantity Uom | EACH |
| Potential Action | MAINTENANCE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Hybrid System | Does not exist |
| Electric System | Inspected |
| Instance | Basement, 1st, 2nd, 3rd and 4th Floors Various Locations |
| Instance Condition | 3- Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Building Area Covered by Operational System | 81-100% |
| Deficiency | No deficiencies recorded |
| COMPACTOR | Does not exist |
| CONVEYING | Inspected |
| | Does not exist |
| Dumbwaiter Elevator | Inspected |
| Condition | 1- Good |
| Are all the existing elevators operable? | Yes |
| Deficiency | No deficiencies recorded |
| | Does not exist |
| Escalator Non auditorium Handison Lift Ventical | Does not exist Does not exist |
| Non-auditorium Handicap Lift - Vertical Non-auditorium Handicap Lift - Stair | Does not exist Does not exist |
| Ash Hoist | Does not exist Does not exist |
| Asii Hoist Sidewalk Elevator | Does not exist Does not exist |
| DOMESTIC WATER SYSTEM | Inspected |
| | Inspected |
| Domestic Cold Water System Cravity System | Does not exist |
| Gravity System Pressure Posetor System | Inspected |
| Pressure Booster System | mspecieu |

Building Condition Assessment Survey 2023-2024

| Question | Response |
|------------------------------------|--|
| DOMESTIC WATER SYSTEM | <u> </u> |
| Domestic Cold Water System | |
| Pressure Booster System | |
| Electric Pressure Booster System | Inspected |
| Instance | Boiler Room - West MER |
| Instance Condition | 4- Between Fair and Poor |
| Instance Quantity | 1 |
| | EACH |
| Instance Quantity Uom | |
| Manufacturer | Canariis |
| EquipmentId | N/A |
| Capacity/Size Quantity | 1 |
| Capacity/Size UOM | Total # Pumps |
| Capacity/Size 2 Quantity | 8 T-1D-1VD |
| Capacity/Size 2 UOM | Total Pumps HP |
| Source of Capacity/Size | Inspector Estimate |
| Installation Year | 1993 |
| Source of Installation Year | Inspector Estimate |
| Deficiency | DEFECTIVE CONTROLS |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | REPAIR |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Hydraulic/Pneumatic Booster System | Does not exist |
| Water Service | Inspected |
| Instance | Basement Boys Locker Room - Room B65A |
| Instance Condition | 2- Between Good and Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Deficiency | WATER MAIN:MISSING BACKFLOW PREVENTION DEVICE |
| Deficiency Location/Instance | Basement Boys Locker Room - Room B65A |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | INSTALL |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Instance | Cafeteria - Water Meter Room B27 |
| Instance Condition | 1-Good |
| Instance Quantity | 1 |

Instance Quantity Uom

Domestic Hot Water Remote Storage Tank

Deficiency

Domestic Hot Water System

Deficiency

Deficiency

Deficiency

Domestic Water Heat Exchanger

Electric Domestic Water Heater

Gas Fired Domestic Water Heater

Condition

Condition

Condition

EACH

Inspected

Inspected

1- Good

Inspected

Inspected

Inspected

3- Fair

3- Fair

No deficiencies recorded

No deficiencies recorded

No deficiencies recorded

No deficiencies recorded

| Duestion | Response | |
|--|--------------------------|--|
| DOMESTIC WATER SYSTEM | - Coponic | |
| Domestic Hot Water System | | |
| Gas Fired Domestic Water Heater | | |
| Instance | Boiler Room | |
| Instance Condition | 3- Fair | |
| Instance Quantity | 1 | |
| <u></u> | EACH | |
| Instance Quantity Uom | | |
| Manufacturer | PVI | |
| EquipmentId | Kitchen 600 | |
| Capacity/Size Quantity | | |
| Capacity/Size UOM Capacity/Size 2 Quantity | MBH Input 400 | |
| Capacity/Size 2 UOM | Gallons | |
| Source of Capacity/Size | Documented | |
| Installation Year | 2000 | |
| Source of Installation Year | Inspector Estimate | |
| Deficiency | NOT IN USE | |
| Deficiency Location/Instance | Boiler Room | |
| Deficiency Quantity | 1 | |
| Quantity Uom | EACH | |
| Potential Action | NO ACTION | |
| Urgency of Action | PRIORITY 1 | |
| Purpose of Action | LEVEL 1 | |
| Violations | No violations recorded | |
| Instance | Boiler Room | |
| Instance Condition | 1- Good | |
| Instance Quantity | 1 | |
| <u></u> | EACH | |
| Instance Quantity Uom | Lochinvar | |
| Manufacturer | Locninvar N/A | |
| EquipmentId | N/A 500 | |
| Capacity/Size Quantity Capacity/Size UOM | | |
| Capacity/Size 2 Quantity | MBH Input 0 | |
| Capacity/Size 2 Quantity Capacity/Size 2 UOM | 0 Gallons | |
| Source of Capacity/Size | Documented | |
| Installation Year | 2020 | |
| Source of Installation Year | Custodial Staff | |
| Deficiency | No deficiencies recorded | |
| <u>-</u> | Boiler Room | |
| Instance Condition | 1- Good | |
| Instance Condition | | |
| Instance Quantity | 1 | |
| Instance Quantity Uom | EACH | |
| Manufacturer | A.O. Smith | |
| EquipmentId | N/A | |
| Capacity/Size Quantity | 275 | |
| Capacity/Size UOM | MBH Input | |
| Capacity/Size 2 Quantity | 100 | |
| Capacity/Size 2 UOM | Gallons | |
| Source of Capacity/Size | Documented | |
| Installation Year | 2024 | |
| Source of Installation Year | Custodial Staff | |
| Deficiency | No deficiencies recorded | |
| Oil Fired Domestic Water Heater | Does not exist | |
| Heat Pump Domestic Water Heater | Does not exist | |
| Domestic Water Distribution Piping | Inspected | |

| Mechanical Inspection | X415 |
|-----------------------|------|
| | |

| Question | Response |
|---|---|
| DOMESTIC WATER SYSTEM | |
| Domestic Water Distribution Piping | |
| Deficiency | No deficiencies recorded |
| DRAIN/WASTE/VENT AND STORM SYSTEM | Inspected |
| Interior Storm Piping | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Sewage/Waste/Vent Piping | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Sewage Ejector Pump | Does not exist |
| Sump Pump | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| DUAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER) | Does not exist |
| | Inspected |
| FIXTURES Staff And Others | Inspected |
| Staff And Other Janitor Sink | Inspected |
| | 3- Fair |
| Condition | |
| Deficiency | No deficiencies recorded |
| Lavatory/Sink | Inspected |
| Condition | 3- Fair |
| Deficiency | DEFECTIVE AUXILIARY (FAUCET, SHUT OFF |
| | VALVE,ETC.) |
| Deficiency Location/Instance | Staff Toilet Room 344 |
| Deficiency Quantity | 1 Fredu |
| Quantity Uom | EACH |
| Potential Action | MAINTENANCE |
| Urgency of Action | PRIORITY 3 LEVEL 2 |
| Purpose of Action Violations | No violations recorded |
| | |
| Toilet | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| U <u>r</u> inal | Inspected |
| Condition | 3- Fair |
| Deficiency | CRACKED/PHYSICAL DAMAGE |
| Deficiency Location/Instance | Staff Toilet Room 344 |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Student | Inspected |
| Drinking Fountain | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | CRACKED/PHYSICAL DAMAGE |
| Deficiency Location/Instance | 1st Floor Gymnasium, 4th Floor North/South Gymnasiums |
| Deficiency Quantity | 3 |
| Quantity Uom | EACH |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |

Building Condition Assessment Survey 2023-2024

| Duestion | Response | |
|--|---------------------------------------|--|
| FIXTURES | | |
| Student | | |
| Drinking Fountain | | |
| Deficiency | DEFECTIVE AUXILIARY (FAUCET, SHUT OFF | |
| | VALVE,ETC.) | |
| Deficiency Location/Instance | Corridor near room 223 | |
| Deficiency Quantity | 1 | |
| Quantity Uom | EACH | |
| Potential Action | MAINTENANCE | |
| Urgency of Action | PRIORITY 3 | |
| Purpose of Action | LEVEL 2 | |
| Violations | No violations recorded | |
| Lavatory/Sink | Inspected | |
| Condition | 3- Fair | |
| Deficiency | CLOGGED/LEAKING | |
| Deficiency Location/Instance | 3rd Floor Boys Locker room | |
| Deficiency Quantity | 1 | |
| Quantity Uom | EACH | |
| Potential Action | MAINTENANCE | |
| Urgency of Action | PRIORITY 3 | |
| Purpose of Action | LEVEL 2 | |
| Violations | No violations recorded | |
| Locker Room Shower | Inspected | |
| Instance on Inside Locker Room 330 - Girls | Inaccessible | |
| Instance on Inside Locker Room 332 - Boys | Inaccessible | |
| Instance on Inside Locker Room B65 - Boys | Inaccessible | |
| Sink And Fountain Combo Unit | Does not exist | |
| Toilet | Inspected | |
| Condition | 2- Between Good and Fair | |
| Deficiency | No deficiencies recorded | |
| Urinal | Inspected | |
| Condition | 3- Fair | |
| Deficiency | CRACKED/PHYSICAL DAMAGE | |
| Deficiency Deficiency Location/Instance | 3rd Floor Boys Locker room | |
| Deficiency Quantity | 2 | |
| Quantity Uom | EACH | |
| Potential Action | REPLACE | |
| Urgency of Action | PRIORITY 3 | |
| Purpose of Action | LEVEL 2 | |
| Violations | No violations recorded | |
| | Does not exist | |
| GAS FIRED FURNACE | | |
| GAS SERVICE | Inspected | |
| Gas Distribution Piping | Inspected | |
| Condition | 3- Fair | |
| Deficiency | No deficiencies recorded | |
| Gas Meter Room Exhaust Fan | Inspected | |
| Condition | 3- Fair | |
| Deficiency | No deficiencies recorded | |
| Gas Meter Room Vent | Inspected | |
| Condition | 3- Fair | |
| Deficiency | No deficiencies recorded | |
| Gas Pressure Booster | Does not exist | |
| CO/Gas Leak Detection | Inspected | |
| Instance | Gas Meter Room, Boiler Room | |
| Instance Condition | 3- Fair | |

Building Condition Assessment Survey 2023-2024

| estion | Response |
|---|---|
| GAS SERVICE | |
| CO/Gas Leak Detection | |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Installation Year | 2013 |
| Source of Installation Year | Documented |
| Deficiency | DEFECTIVE CONTROL PANEL |
| Deficiency Location/Instance | Custodian's Office 143, Boiler Room (Fault Signal At Panel) |
| Deficiency Quantity | 2 |
| Quantity Uom | EACH |
| Potential Action | REPAIR |
| Urgency of Action | PRIORITY 5 |
| Purpose of Action | LEVEL 6 |
| Violations | No violations recorded |
| HEATING | Inspected |
| Heating Coil In Ductwork | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| | Inspected |
| Hydronic Heating Hydronic Hot Water Distribution: Piping, Pumps and Auxiliaries | Inspected |
| Condition | 3- Fair |
| | - |
| Deficiency | No deficiencies recorded |
| Backflow Preventer | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Hot Water Heat Exchanger | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Radiator/Convector/Fin Tube | Inspected |
| Condition | 3- Fair |
| Deficiency | AUXILIARY (VALVE, VENT): DEFECTIVE |
| Deficiency Location/Instance | 3rd Floor Boys Locker room; Corridor near Room 317, 455, 467, |
| , | 483 and other locations |
| Deficiency Quantity | 20 |
| Quantity Uom | EACH |
| Potential Action | MAINTENANCE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Steam Heating | Inspected |
| F&T/Steam Drip Trap | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| · | |
| MER Steam and Condensate Piping | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Steam Condensate Return Piping | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Steam Condensate Return Pumping System | Inspected |
| Condition | 3- Fair |
| Deficiency | DEFECTIVE PUMP |
| Deficiency Location/Instance | MER B63 |
| Controller Document Industries | |
| Deficiency Quantity | 2 |

| Mechanical Inspection | X415 |
|-----------------------|------|
| | |

| Question | Response |
|--|---|
| HEATING | |
| Steam Heating | |
| Steam Condensate Return Pumping System | |
| Potential Action | MAINTENANCE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Steam Piping | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Terminal Unit Thermostatic Trap | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Steam supplied by External Sources | Does not exist |
| Unit Heater/Cabinet Heater | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| HEATING PLANT | Inspected |
| Instance on Basement | Inspected |
| Is there a water meter on the boiler make-up water piping? | No |
| Burner Manufacturer | Johnson Burner |
| Burner Model | FD68CA-LM |
| Burner Type | Dual Fuel (Gas/Oil) |
| Heating Plant Oil Number Boiler Auxiliaries | 2 |
| Instance on Basement | Inspected |
| Boiler Auxiliary Piping | inspected |
| Instance on Basement | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Boiler Emergency Stop Switch | 110 deficiences recorded |
| Instance on Basement | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Boiler Feedwater System | ivo deficiencies recorded |
| Instance on Basement | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | FEEDWATER TANK:DAMAGED/MISSING INSULATION |
| Deficiency Location/Instance | Boiler Room |
| Deficiency Quantity | 50 |
| Quantity Uom | S.F. |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Boiler Feedwater Treatment(Automatic) | |
| Instance on Basement | Inspected |
| Instance Condition | 1- Good |
| Deficiency | No deficiencies recorded |
| Boiler Flue Exhaust | |
| Instance on Basement | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Boiler Make-up Water Backflow Preventer | |
| Instance on Basement | Does not exist |
| | |

| unical Inspection | | X41 |
|---|--------------------------------|-----|
| estion | Response | |
| HEATING PLANT | | |
| Boiler Auxiliaries | | |
| Boiler Make-up Water Backflow Preventer | | |
| Boiler Room Steam And Condensate Piping | | |
| Instance on Basement | Inspected | |
| Instance Condition | 3- Fair | |
| Deficiency | No deficiencies recorded | |
| Boiler Safety Valve | | |
| Instance on Basement | Inspected | |
| Instance Condition | 3- Fair | |
| Deficiency | No deficiencies recorded | |
| Boiler System | | |
| Instance on Basement | Inspected | |
| Coal-fired Boiler | | |
| Instance on Basement | Does not exist | |
| Hot Water Boiler | | |
| Instance on Basement | Does not exist | |
| Modular Boiler | | |
| Instance on Basement | Does not exist | |
| Steam Boiler | | |
| Instance on Basement | Inspected | |
| Instance on Basement | Inspected | |
| Instance | Boiler Room | |
| Instance Condition | 3- Fair | |
| | | |
| Instance Quantity | 5,217 MBH NET | |
| Instance Quantity Uom | | |
| Cast Iron Boiler? | No Titusville Iron Works Co | |
| Manufacturer | 1980-1 | |
| EquipmentId Capacity/Size Quantity | 60 | |
| Capacity/Size UOM | Burner GPH | |
| Source of Capacity/Size | Documented | |
| Installation Year | 1939 | |
| Source of Installation Year | Documented | |
| Deficiency | LEAKY/PLUGGED TUBES | |
| Deficiency Quantity | 1 | |
| Quantity Uom | EACH | |
| Potential Action | REPLACE | |
| Urgency of Action | PRIORITY 3 | |
| Purpose of Action | LEVEL 2 | |
| Violations | No violations recorded | |
| Instance | Boiler Room | |
| Instance Condition | 3- Fair | |
| Instance Quantity | 5,217 | |
| Instance Quantity Uom | MBH NET | |
| Cast Iron Boiler? | No | |
| Manufacturer | Titusville Iron Works Co | |
| EquipmentId | 1980-2 | |
| Capacity/Size Quantity | 60 | |
| Capacity/Size UOM | Burner GPH | |
| Source of Capacity/Size | Documented | |
| Installation Year | 1939 | |
| Source of Installation Year | Documented | |
| Deficiency | LEAKY/PLUGGED TUBES | |
| Deficiency Quantity | 2 | |

| Mechanical Inspection | X415 |
|-----------------------|------|
| | |

| On | Response |
|---------------------------------|--|
| TING PLANT | |
| ler System | |
| team Boiler | |
| Quantity Uom | EACH |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Deficiency | DEFECTIVE SAFETY AUXILIARY: LOW-WATER CUT-OFF, WATER COLUMN ASSEMBLY |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | MAINTENANCE |
| Urgency of Action | PRIORITY 5 |
| Purpose of Action | LEVEL 6 |
| Violations | No violations recorded |
| Instance | Boiler Room |
| Instance Condition | 3- Fair |
| Instance Quantity | 5,217 |
| | MBH NET |
| Instance Quantity Uom | |
| Cast Iron Boiler? | No |
| Manufacturer | Titusville Iron Works Co |
| EquipmentId | 1980-3 |
| Capacity/Size Quantity | 60 |
| Capacity/Size UOM | Burner GPH |
| Source of Capacity/Size | Documented |
| Installation Year | 1939 |
| Source of Installation Year | Documented |
| Deficiency | No deficiencies recorded |
| Instance | Boiler Room |
| Instance Condition | 3- Fair |
| Instance Quantity | 5,217 |
| Instance Quantity Uom | MBH NET |
| Cast Iron Boiler? | No |
| Manufacturer | Titusville Iron Works Co |
| EquipmentId | 1980-4 |
| Capacity/Size Quantity | 60 |
| Capacity/Size UOM | Burner GPH |
| Source of Capacity/Size | Documented |
| Installation Year | 1939 |
| Source of Installation Year | Documented |
| Deficiency | DEFECTIVE SAFETY AUXILIARY: LOW-WATER CUT-OFF, WATER COLUMN ASSEMBLY |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | MAINTENANCE |
| Urgency of Action | PRIORITY 5 |
| Purpose of Action | LEVEL 6 |
| Violations | No violations recorded |
| Instance | Boiler Room |
| Instance Condition | 3- Fair |
| Instance Quantity | 5,217 |
| Instance Quantity Uom | MBH NET |
| Cast Iron Boiler? | No |
| Cast Iron Boiler? Manufacturer | Titusville Iron Works Co |
| EquipmentId | 1980-5 |

| Ouestion Response | Mechanicai Inspectio | |
|-------------------|----------------------|--|
| enstrem enstreme | Question | |

| iunicui Inspection | | АТІЗ |
|--|--------------------------------|------|
| Question | Response | |
| HEATING PLANT | | |
| Boiler System | | |
| Steam Boiler | | |
| Capacity/Size Quantity | 60 | |
| Capacity/Size UOM | Burner GPH | |
| Source of Capacity/Size | Documented | |
| Installation Year | 1939 | |
| Source of Installation Year | Documented | |
| Deficiency | No deficiencies recorded | |
| Fuel System | | |
| Instance on Basement | Inspected | |
| Boiler Fresh Air Louver/Damper | | |
| Instance on Basement | Inspected | |
| Instance Condition | 4- Between Fair and Poor | |
| Туре | Automatic | |
| Deficiency | DEFECTIVE ACTUATOR | |
| Deficiency Location/Instance | Boiler Room | |
| Deficiency Quantity | 5 | |
| Quantity Uom | EACH | |
| Potential Action | MAINTENANCE | |
| Urgency of Action | PRIORITY 3 | |
| Purpose of Action | LEVEL 2 | |
| Violations | No violations recorded | |
| Burner/Burner Control Panel | The Monantain recorded | |
| Instance on Basement | Inspected | |
| Instance Condition | 3- Fair | |
| Deficiency | No deficiencies recorded | |
| | No deficiencies recorded | |
| Fuel Oil Storage/Supply System | | |
| Instance on Basement | Inspected | |
| Instance Condition | 3- Fair | |
| Deficiency | FUEL OIL LEVEL GAUGE:DEFECTIVE | |
| Deficiency Location/Instance | Boiler Room - West MER | |
| Deficiency Quantity | 1 | |
| Quantity Uom | EACH | |
| Potential Action | MAINTENANCE | |
| Urgency of Action | PRIORITY 3 | |
| Purpose of Action | LEVEL 2 | |
| Violations | No violations recorded | |
| Gas Trains And Vent At The Boiler | | |
| Instance on Basement | Inspected | |
| Instance Condition | 3- Fair | |
| Deficiency | No deficiencies recorded | |
| Enclosed IDF Room | Inspected | |
| Instance on Rooms 183, 214, 314, 414, 438, 483 | Inspected | |
| Dedicated A/C Equipment | 1 | |
| Instance on Rooms 183, 214, 314, 414, 438, 483 | Inspected | |
| Instance Condition | 2- Between Good and Fair | |
| Deficiency | No deficiencies recorded | |
| | | |
| KITCHEN | Inspected | |
| Instance on Basement | Inspected | |
| CO Detector | | |
| Instance on Basement | Inspected | |
| Instance Condition | 1- Good | |
| Deficiency | No deficiencies recorded | |
| Gas System | | |

| Mechanical Inspection | X415 |
|-----------------------|------|
|-----------------------|------|

| nestion | Response | |
|--|--------------------------|---|
| KITCHEN | | |
| Gas System | | |
| Instance on Basement | Inspected | |
| Instance Condition | 3- Fair | |
| Deficiency | No deficiencies recorded | |
| Grease Trap | | |
| Instance on Basement | Inspected | |
| Instance Condition | 1- Good | |
| Deficiency | No deficiencies recorded | |
| Hood | | |
| Instance on Basement | Inspected | |
| Instance Condition | 3- Fair | - |
| Deficiency | No deficiencies recorded | |
| Hood Exhaust Ductwork | | |
| Instance on Basement | Inspected | |
| Instance Condition | 3- Fair | |
| Deficiency | No deficiencies recorded | |
| Hood Exhaust Fan | | |
| Instance on Basement | Inspected | |
| Instance Condition | 3- Fair | |
| Deficiency | No deficiencies recorded | |
| Hood Fire Suppression System | | |
| Instance on Basement | Inspected | |
| Instance Condition | 1- Good | |
| Deficiency | No deficiencies recorded | |
| Hot Water Temperature Booster | 1.0 delicities 1001.ded | |
| Instance on Basement | Does not exist | |
| Kitchen Sink | | |
| Instance on Basement | Inspected | |
| Instance Condition | 3- Fair | |
| Deficiency | Missing Air Gap | |
| Deficiency Location/Instance | Kitchen | |
| Deficiency Quantity | 2 | |
| Quantity Uom | EACH | |
| Potential Action | MAINTENANCE | |
| Urgency of Action | PRIORITY 3 | |
| Purpose of Action | LEVEL 2 | |
| Violations | No violations recorded | |
| IDF Room | Inspected | |
| Instance on Closet inside Health Clinic 228A | Inspected | |
| Instance on Room 114 | Inspected | |
| Dedicated A/C Equipment | 1 | |
| Instance on Closet inside Health Clinic 228A | Inspected | |
| Instance Condition | 2- Between Good and Fair | |
| Deficiency | No deficiencies recorded | |
| Instance on Room 114 | Inspected | |
| Instance Condition | 2- Between Good and Fair | |
| Deficiency | No deficiencies recorded | |
| | | |
| CIENCE DEMO ROOM | Inspected | |
| Instance on Room 105 | Inspected | |
| Alternative Use | No | |
| Instance on Room 115 | Inspected | |
| Alternative Use | Yes | |
| Instance on Rooms 302, 313, 352 | Inspected | |

Building Condition Assessment Survey 2023-2024

| | Response | |
|---------------------------------|--------------------------|--|
| uestion | Response | |
| SCIENCE DEMO ROOM | | |
| Alternative Use | Yes | |
| Acid Waste Neutralizing Tank | D | |
| Instance on Room 105 | Does not exist | |
| Instance on Room 115 | Does not exist | |
| Instance on Rooms 302, 313, 352 | Does not exist | |
| CO Detector | | |
| Instance on Room 105 | Inspected | |
| Instance Condition | 3- Fair | |
| Deficiency | No deficiencies recorded | |
| Instance on Room 115 | Not required | |
| Instance on Rooms 302, 313, 352 | Not required | |
| Emergency Shower | | |
| Instance on Room 105 | Does not exist | |
| Instance on Room 115 | Does not exist | |
| Instance on Rooms 302, 313, 352 | Does not exist | |
| Eye Wash | | |
| Instance on Room 105 | Inspected | |
| Instance Condition | 3- Fair | |
| Deficiency | No deficiencies recorded | |
| Instance on Room 115 | Inspected | |
| Instance Condition | 3- Fair | |
| Deficiency | No deficiencies recorded | |
| Instance on Rooms 302, 313, 352 | Does not exist | |
| Hood Exhaust Ductwork | | |
| Instance on Room 105 | Does not exist | |
| Instance on Room 115 | Does not exist | |
| Instance on Rooms 302, 313, 352 | Does not exist | |
| Hood Exhaust Fan | | |
| Instance on Room 105 | Does not exist | |
| Instance on Room 115 | Does not exist | |
| Instance on Rooms 302, 313, 352 | Does not exist | |
| Fixed Laboratory Hood | | |
| Instance on Room 105 | Does not exist | |
| Instance on Room 115 | Does not exist | |
| Instance on Rooms 302, 313, 352 | Does not exist | |
| Laboratory Sink | | |
| Instance on Room 105 | Inspected | |
| Instance Condition | 3- Fair | |
| Deficiency | No deficiencies recorded | |
| Instance on Room 115 | Inspected | |
| Instance Condition | 3- Fair | |
| Deficiency | No deficiencies recorded | |
| Instance on Rooms 302, 313, 352 | Inspected | |
| Instance Condition | 3- Fair | |

Does not exist

Does not exist

Does not exist

Inspected

Inspected

Inspected

No

Make-up Air Unit

SCIENCE LAB

Instance on Room 105

Instance on Room 115

Instance on Rooms 109
Alternative Use

Instance on Rooms 205, 304

Instance on Rooms 302, 313, 352

Building Condition Assessment Survey 2023-2024

| anical Inspe | | n | X |
|--------------|--------------------------------|--------------------------|---|
| uestion | | Response | |
| SCIENCE LAB | | | |
| | ative Use | No | |
| | ce on Room 425 | Inspected | |
| | ative Use | No | |
| | ce on Rooms 117, 211, 402, 423 | Inspected | |
| | ative Use | No | |
| | ce on Rooms 408, 427 | Inspected | |
| Altern | ative Use | No | |
| · · | utralizing Tank | | |
| | ce on Rooms 109 | Does not exist | |
| | ce on Rooms 205, 304 | Does not exist | |
| - | ce on Room 425 | Does not exist | |
| - | ce on Rooms 117, 211, 402, 423 | Does not exist | |
| Instan | ce on Rooms 408, 427 | Does not exist | |
| CO Detector | | | |
| | ce on Rooms 109 | Inspected | |
| | ce Condition | 1- Good | |
| Defici | | No deficiencies recorded | |
| | ce on Rooms 205, 304 | Inspected | |
| | ce Condition | 3- Fair | |
| Defici | | No deficiencies recorded | |
| | ce on Room 425 | Inspected | |
| | ce Condition | 3- Fair | |
| Defici | ency | No deficiencies recorded | |
| | ce on Rooms 117, 211, 402, 423 | Inspected | |
| | ce Condition | 3- Fair | |
| Defici | | No deficiencies recorded | |
| | ce on Rooms 408, 427 | Inspected | |
| | ce Condition | 3- Fair | |
| Defici | | No deficiencies recorded | |
| Emergency Sh | | | |
| - | ce on Rooms 109 | Inspected | |
| - | ce Condition | 3- Fair | |
| Defici | - | No deficiencies recorded | |
| | ce on Rooms 205, 304 | Inspected | |
| | ce Condition | 3- Fair | |
| Defici | · · | No deficiencies recorded | |
| - | ce on Room 425 | Does not exist | |
| | ce on Rooms 117, 211, 402, 423 | Does not exist | |
| | ce on Rooms 408, 427 | Inspected | |
| | ce Condition | 3- Fair | |
| Defici | ency | No deficiencies recorded | |
| Eye Wash | | <u> </u> | |
| | ce on Rooms 109 | Inspected | |
| | ce Condition | 3- Fair | |
| Defici | | No deficiencies recorded | |
| | ce on Rooms 205, 304 | Inspected | |
| | ce Condition | 3- Fair | |

Deficiency

Instance on Room 425

Deficiency Location/Instance

Instance Condition

No deficiencies recorded

4- Between Fair and Poor

Inspected

DEFECTIVE

Room 425

| Question | Response | |
|---|--------------------------|--|
| SCIENCE LAB | | |
| Eye Wash | | |
| Deficiency Quantity | 1 | |
| Quantity Uom | EACH | |
| Potential Action | MAINTENANCE | |
| Urgency of Action | PRIORITY 5 | |
| Purpose of Action | LEVEL 6 | |
| Violations | No violations recorded | |
| Instance on Rooms 117, 211, 402, 423 | Inspected | |
| Instance Condition | 3- Fair | |
| Deficiency | No deficiencies recorded | |
| Instance on Rooms 408, 427 | Inspected | |
| Instance Condition | 3- Fair | |
| Deficiency | No deficiencies recorded | |
| Hood Exhaust Ductwork | | |
| Instance on Rooms 109 | Inspected | |
| Instance Condition | 3- Fair | |
| Deficiency | No deficiencies recorded | |
| Instance on Rooms 205, 304 | Inspected | |
| Instance Condition | 3- Fair | |
| Deficiency | No deficiencies recorded | |
| Instance on Room 425 | Does not exist | |
| Instance on Rooms 117, 211, 402, 423 | Does not exist | |
| Instance on Rooms 408, 427 | Inspected | |
| Instance Condition | 3- Fair | |
| Deficiency | No deficiencies recorded | |
| Hood Exhaust Fan | | |
| Instance on Rooms 109 | Inspected | |
| Instance Condition | 4- Between Fair and Poor | |
| Deficiency | DEFECTIVE | |
| Deficiency Location/Instance | Roof | |
| Deficiency Quantity | 1 | |
| Quantity Uom | EACH | |
| Potential Action | MAINTENANCE | |
| Urgency of Action | PRIORITY 3 | |
| Purpose of Action | LEVEL 2 | |
| Violations | No violations recorded | |
| Instance on Rooms 205, 304 | Inspected | |
| Instance Condition | 3- Fair | |
| Deficiency | No deficiencies recorded | |
| Instance on Room 425 | Does not exist | |
| Instance on Rooms 117, 211, 402, 423 | Does not exist | |
| Instance on Rooms 408, 427 | Inspected | |
| Instance Condition | 3- Fair | |
| Deficiency | No deficiencies recorded | |
| Fixed Laboratory Hood | | |
| Instance on Rooms 109 | Inspected | |
| Instance Condition | 3- Fair | |
| Deficiency | No deficiencies recorded | |
| | Inspected | |
| Instance on Rooms 205, 304 | F | |
| Instance on Rooms 205, 304 Instance Condition | 3- Fair | |
| | | |
| Instance Condition | 3- Fair | |

| Mechanical Inspection | X415 |
|-----------------------|----------|
| Question | Response |

| Question | Response |
|--|---------------------------------------|
| SCIENCE LAB | |
| Fixed Laboratory Hood | |
| Instance on Rooms 408, 427 | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Laboratory Sink | |
| Instance on Rooms 109 | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Instance on Rooms 205, 304 | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | DEFECTIVE AUXILIARY (FAUCET, SHUT OFF |
| | VALVE,ETC.) |
| Deficiency Location/Instance | Room 304 |
| Deficiency Quantity | 4 |
| Quantity Uom Potential Action | EACH |
| Urgency of Action | MAINTENANCE PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Instance on Room 425 | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Instance on Rooms 117, 211, 402, 423 | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Instance on Rooms 408, 427 | |
| | Inspected 3- Fair |
| Instance Condition Deficiency | No deficiencies recorded |
| Make-up Air Unit | No deficiencies recorded |
| Instance on Rooms 109 | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Instance on Rooms 205, 304 | Does not exist |
| Instance on Room 425 | Does not exist |
| Instance on Rooms 117, 211, 402, 423 | Does not exist |
| Instance on Rooms 408, 427 | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| • | Inspected |
| SCIENCE PREP ROOM | |
| Instance on Room 109A Alternative Use | Inspected |
| | No |
| Instance on Room 404 | Inspected |
| Alternative Use | Yes |
| Instance on Room 429 | Inspected |
| Alternative Use | No |
| Instance on Room 205A, 306 | Inspected |
| Alternative Use | No |
| Acid Waste Neutralizing Tank | D |
| Instance on Room 109A | Does not exist |
| Instance on Room 404 | Does not exist |
| Instance on Room 429 | Does not exist |
| Instance on Room 205A, 306 | Does not exist |
| CO Detector | |

| Question | Response | |
|---|--------------------------|--|
| SCIENCE PREP ROOM | | |
| CO Detector | | |
| Instance on Room 109A | Inspected | |
| Instance Condition | 1- Good | |
| Deficiency | No deficiencies recorded | |
| Instance on Room 404 | Not required | |
| Instance on Room 429 | Inspected | |
| Instance Condition | 3- Fair | |
| Deficiency | No deficiencies recorded | |
| Instance on Room 205A, 306 | Inspected | |
| Instance Condition | 1- Good | |
| Deficiency | No deficiencies recorded | |
| Emergency Shower | | |
| Instance on Room 109A | Inspected | |
| Instance Condition | 3- Fair | |
| Deficiency | No deficiencies recorded | |
| Instance on Room 404 | Inspected | |
| Instance Condition | 3- Fair | |
| Deficiency | No deficiencies recorded | |
| Instance on Room 429 | Inspected | |
| Instance Condition | 3- Fair | |
| Deficiency | No deficiencies recorded | |
| Instance on Room 205A, 306 | Inspected | |
| Instance Condition | 3- Fair | |
| Deficiency | No deficiencies recorded | |
| Eye Wash | no deficiences recorded | |
| Instance on Room 109A | Inspected | |
| Instance Condition | 3- Fair | |
| Deficiency | No deficiencies recorded | |
| Instance on Room 404 | Inspected | |
| Instance Condition | 3- Fair | |
| Deficiency | No deficiencies recorded | |
| Instance on Room 429 | Inspected | |
| Instance Condition | 3- Fair | |
| Deficiency | No deficiencies recorded | |
| Instance on Room 205A, 306 | Inspected | |
| Instance Condition | 3- Fair | |
| Deficiency | No deficiencies recorded | |
| Hood Exhaust Ductwork | No deficiencies recorded | |
| Instance on Room 109A | Does not exist | |
| Instance on Room 404 | Inspected | |
| Instance Condition | 3- Fair | |
| Deficiency | No deficiencies recorded | |
| Instance on Room 429 | Inspected | |
| Instance Condition | 3- Fair | |
| | No deficiencies recorded | |
| Deficiency | | |
| Instance on Room 205A, 306 | Inspected | |
| Instance Condition | 3- Fair | |
| Deficiency | No deficiencies recorded | |
| Hood Exhaust Fan | Door noti-t | |
| Instance on Room 109A | Does not exist | |
| Instance on Room 404 Instance Condition | Inspected 3- Fair | |

| uestion | Response | |
|------------------------------------|--------------------------|--|
| SCIENCE PREP ROOM | • | |
| Hood Exhaust Fan | | |
| Deficiency | No deficiencies recorded | |
| Instance on Room 429 | Inspected | |
| Instance Condition | 3- Fair | |
| Deficiency | No deficiencies recorded | |
| Instance on Room 205A, 306 | Inspected | |
| Instance Condition | 3- Fair | |
| Deficiency | No deficiencies recorded | |
| Fixed Laboratory Hood | | |
| Instance on Room 109A | Does not exist | |
| Instance on Room 404 | Inspected | |
| Instance Condition | 3- Fair | |
| Deficiency | No deficiencies recorded | |
| Instance on Room 429 | Inspected | |
| Instance Condition | 3- Fair | |
| Deficiency | No deficiencies recorded | |
| Instance on Room 205A, 306 | Inspected | |
| Instance Condition | 3- Fair | |
| Deficiency | No deficiencies recorded | |
| Laboratory Sink | | |
| Instance on Room 109A | Inspected | |
| Instance Condition | 3- Fair | |
| Deficiency | No deficiencies recorded | |
| Instance on Room 404 | Inspected | |
| Instance Condition | 3- Fair | |
| Deficiency | No deficiencies recorded | |
| Instance on Room 429 | Inspected | |
| Instance Condition | 3- Fair | |
| Deficiency | No deficiencies recorded | |
| Instance on Room 205A, 306 | Inspected | |
| Instance Condition | 3- Fair | |
| Deficiency | No deficiencies recorded | |
| Make-up Air Unit | | |
| Instance on Room 109A | Does not exist | |
| Instance on Room 404 | Inspected | |
| Instance Condition | 3- Fair | |
| Deficiency | No deficiencies recorded | |
| Instance on Room 429 | Inspected | |
| Instance Condition | 3- Fair | |
| Deficiency | DEFECTIVE | |
| Deficiency Location/Instance | Room 429 | |
| Deficiency Quantity | 1 | |
| Quantity Uom | EACH | |
| Potential Action | MAINTENANCE | |
| Urgency of Action | PRIORITY 3 | |
| Purpose of Action | LEVEL 2 | |
| Violations | No violations recorded | |
| Instance on Room 205A, 306 | Does not exist | |
| SPRINKLERS, STANDPIPE, FIRE SYSTEM | Inspected | |
| Dry Sprinkler Alarm Valve Assembly | Inspected | |
| Condition | 3- Fair | |
| Deficiency | No deficiencies recorded | |

Building Condition Assessment Survey 2023-2024

| estion | Response |
|---|---|
| PRINKLERS, STANDPIPE, FIRE SYSTEM | |
| Fire Booster Pump Assembly | Does not exist |
| Roof Tank | Does not exist |
| Siamese Connection | Does not exist |
| Sprinkler Head | Inspected |
| Condition | 3- Fair |
| Deficiency | DEFECTIVE/DETERIORATED |
| Deficiency Location/Instance | Weight Room B9 (obstructed, 5), Auditorium Stage, Room 361G |
| · | (painted, 5) |
| Deficiency Quantity | 10 |
| Quantity Uom | EACH |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 5 |
| Purpose of Action | LEVEL 6 |
| Violations | No violations recorded |
| Sprinkler Piping | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Standpipe System | Does not exist |
| Water Gong | Does not exist |
| WIMMING POOL | Does not exist |
| | |
| /ENTILATION | Inspected |
| Is the building Mechanically ventilated? | Partial |
| Exhaust Fan | Inspected |
| Condition | 3- Fair |
| Approximate Total # of Fans | 1-25 |
| Deficiency | DEFECTIVE |
| Deficiency Location/Instance | Roof - Northeast Side (EF for Room B53), Penthouse MER / House Exhaust Fan |
| Deficiency Quantity | 2 |
| Quantity Uom | EACH |
| Potential Action | MAINTENANCE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Heating And Ventilating Unit | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Metal Ductwork | Inspected |
| Condition | 3- Fair |
| Are there any uninsulated ductwork by design in Mechanical rooms? | Yes |
| Are there chain operated dampers? | Yes |
| Deficiency | DEFECTIVE DUCTWORK |
| Deficiency Location/Instance | Courtyard by Room B52 |
| Deficiency Location instance Deficiency Quantity | 10 |
| Quantity Uom | L.F. |
| Potential Action | MAINTENANCE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Purpose of Action Violations | No violations recorded |
| | |
| Supply Fan | Inspected |
| Condition | 3- Fair |
| Approximate Total # of Fans | 6-10 |
| Deficiency | No deficiencies recorded |
| Unit Ventilator | Inspected |

Building Condition Assessment Survey 2023-2024

| Question | Response |
|------------------------------|---|
| VENTILATION | |
| Unit Ventilator | |
| Deficiency | DEFECTIVE |
| Deficiency Location/Instance | Rooms 105, 145, 147 and other locations |
| Deficiency Quantity | 38 |
| Quantity Uom | EACH |
| Potential Action | REPAIR |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |