NYC Department of Education

Building Condition Assessment Survey 2023-2024

Asset:	COLUMBUS	HS AF - BRONX, 925 ASTO	R AVENUE, BRO	ONX, NY, 10469				
Inspection Id	Inspection Type		-		Time	In	Last Edited	
4727	ELECTRICAL				2024-	-04-11 08:25AM	I 2024-05-17 11:34A	
et Data								
Ouestion				Answer				
Have any Systems/Major Building Components been upgraded?				Systems:	All Electrical	Systems and Co	mponents	
The control of the state of the				Years:	2000		•	
Type of Service				Below Gro	ound			
Does Interactive Whiteboard (IWB) Exist?				No				
Water Penetration In Electrical Room?				No				
DEDICATEI	D INTERCOMS	S IN FIRE RESCUE AREAS						
Question					Response			
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, ar			and/or Holding Room	ms in N	lo			
your building								
ority Condit	ion							
	ority	Condition	Component	Location	Person(s)	Person(s)	Photo	
st Year? Cat	egory	Description	Affected	Description	Notified	Title	Image	
No condition re	ecorded							
spection								
•				D				
Question				Response				
Electrical								
ATHLETIC FIELD				Inspected				
Exterior Lighting			Inspected					
Condition			4- Between Fair and Poor					
Deficiency			LIGHTING FIXTURE NOT OPERATIONAL					
Deficiency Quantity			10					
Quantity Uom				EACH				
Potential Action				REPAIR				
Urgency of Action				PRIORITY	Y 3			
Purpose of Action				LEVEL 2				
Violations					ons recorded			
Local Sound System				Inspected				
Condition				5- Poor				
Installation Year			2000					
Source of Installation Year			Documented AND LEVED NOT OBERATIONAL					
Deficiency Deficiency Quantity			AMPLIFIER NOT OPERATIONAL					
				1 EACH				
Quantity Uom Potential Action				EACH DEDLACE	E SYSTEM			
Urgency of Action				PRIORITY				
Purpose of Action				LEVEL 2	1 2			
	Violations				ons recorded			
				Inspected	ons recorded			
Scoreboard Instance					ern Side of the	Athletic Field		
Instance Condition				5- Poor	Side of the /	Innerio i iciu		
Instance Quantity				1				
				EACH				
Instance Quantity Uom			NOT OPERATIONAL					
Deficiency Deficiency Quantity					KAHONAL			
		щ		1 EACH				
Quantity Uom				EACH DEDLACE	7			
Potential Action			REPLACE					
	Urgency of Action			PRIORITY 3				
	Purpose of Action Violations			LEVEL 2	ons recorded			

NYC Department of Education

Building Condition Assessment Survey 2023-2024

Electrical Inspection X416

Question	Response
CAFETERIA	Does not exist
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Does not exist
COMPUTER LAB	Does not exist
GYMNASIUM	Does not exist
KITCHEN	Does not exist
LIBRARY	Does not exist
LOCKER ROOM	Does not exist
MULTIPURPOSE ROOM	Does not exist
SCIENCE DEMO ROOM	Does not exist
SCIENCE LAB	Does not exist
SCIENCE PREP ROOM	Does not exist
SWIMMING POOL	Does not exist
TOILET ROOM - STAFF	Does not exist
TOILET ROOM - STUDENT	Does not exist
AUXILIARY SIGNAL/BELL SYSTEM	Does not exist
EMERGENCY DC STANDBY BATTERY POWER	Does not exist
EMERGENCY GENERATOR SET	Does not exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Does not exist
EMERGENCY LIGHTING	Does not exist
EXIT LIGHT	Does not exist
EXIT/EMERGENCY LIGHT	Does not exist
FIRE ALARM SYSTEM	Does not exist
GROUNDING SYSTEM	Does not exist
INTERCOM SYSTEM	Does not exist
LAN	Does not exist
LIGHTNING PROTECTION	Does not exist
MOTOR CONTROLLER	Does not exist
PANEL BOARD	Does not exist
PUBLIC ADDRESS SYSTEM	Does not exist
SECURITY	Does not exist
SERVICE SWITCH	Does not exist
SWITCHBOARD	Does not exist
TELEPHONE SYSTEM	Does not exist
TRANSFORMER	Does not exist