

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X471

Asset: SOUTH BRONX HS AF - BRONX, 701 ST ANNS AVENUE, BRONX, NY, 10455

Inspection Id	Inspection Type	Time In	Last Edited
1354	ELECTRICAL	2023-11-30 12:42PM	2023-12-18 03:54PM

Asset Data

Question	Answer
Have any Systems/Major Building Components been upgraded?	Systems: Athletic Field Scoreboard, Exterior Lighting, Local Sound System, Partial Security Lighting, Exit Lights, Motor Starters, Variable Frequency Drive Years: 2020 Systems: All Other Electrical Systems and Components Years: 2005
Type of Service	Below Ground
Does Interactive Whiteboard (IWB) Exist?	No
Water Penetration In Electrical Room?	No

DEDICATED INTERCOMS IN FIRE RESCUE AREAS

Question	Response
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building?	No

Priority Condition

Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image
No		No condition recorded					

Inspection

Question	Response
Electrical	
ATHLETIC FIELD	Inspected
Exterior Lighting	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Local Sound System	Inspected
Condition	2- Between Good and Fair
Installation Year	2020
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Scoreboard	Inspected
Instance	Athletic Field South
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Deficiency	No deficiencies recorded
AUDITORIUM	Does not exist
CAFETERIA	Does not exist
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected
Lighting	Inspected
Does a Chandelier Exist?	No
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not exist
Surface Mounted	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not exist
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Inspected
Pendant Mounted	Does not exist

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X471

Question	Response
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	
Lighting	
Lighting Fixture - Incandescent	
Surface Mounted	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not exist
Lighting Fixture - LED	Does not exist
COMPUTER LAB	Does not exist
GYMNASIUM	Does not exist
KITCHEN	Does not exist
LIBRARY	Does not exist
LOCKER ROOM	Does not exist
MULTIPURPOSE ROOM	Does not exist
SCIENCE DEMO ROOM	Does not exist
SCIENCE LAB	Does not exist
SCIENCE PREP ROOM	Does not exist
SWIMMING POOL	Does not exist
TOILET ROOM - STAFF	Does not exist
TOILET ROOM - STUDENT	Does not exist
AUXILIARY SIGNAL/BELL SYSTEM	Does not exist
EMERGENCY DC STANDBY BATTERY POWER	Does not exist
EMERGENCY GENERATOR SET	Does not exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Does not exist
EMERGENCY LIGHTING	Does not exist
EXIT LIGHT	Inspected
Battery Pack	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Non Battery Pack	Does not exist
EXIT/EMERGENCY LIGHT	Does not exist
FIRE ALARM SYSTEM	Does not exist
GROUNDING SYSTEM	Does not exist
INTERCOM SYSTEM	Does not exist
LAN	Does not exist
LIGHTNING PROTECTION	Does not exist
MOTOR CONTROLLER	Inspected
MOTOR CONTROL CENTER	Does not exist
MOTOR STARTER/CONTACTOR	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Variable Frequency Drive	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
PANEL BOARD	Does not exist
PUBLIC ADDRESS SYSTEM	Does not exist
SECURITY	Inspected
IPDVS/CCTV System	Does not exist
Intrusion Alarm System	Inspected
Central Control Panel	Inspected
Instance	Field House

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X471

Question	Response
SECURITY	
Intrusion Alarm System	
Central Control Panel	
Instance Condition	5- Poor
Instance Quantity	1
Instance Quantity Uom	EACH
Model	N/A
Installation Year	2005
Source of Installation Year	Documented
Deficiency	PANEL NOT OPERATIONAL
Deficiency Quantity	1,000
Quantity Uom	S.F.
Potential Action	REPLACE SYSTEM
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 3
Violations	No violations recorded
Infrared Sensor	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Panic Switch	Does not exist
Remote Annunciator	Does not exist
Siren/Strobe	Does not exist
Lighting - Security	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
SERVICE SWITCH	Inspected
Instance	Field House
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Square D
EquipmentId	N/A
Capacity/Size Quantity	400
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2005
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
SWITCHBOARD	Inspected
Number of Spares	0
Fused Disconnect Switch Type	Does not exist
Fused Knife Switch Type	Does not exist
Molded Case Circuit Breaker Type	Inspected
Instance	Field House
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	N/A
EquipmentId	Athletic Field Power Panel
Capacity/Size Quantity	400
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	1
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Nameplate
Installation Year	2005

NYC Department of Education
Building Condition Assessment Survey 2023-2024

Electrical Inspection

X471

Question	Response
SWITCHBOARD	
Molded Case Circuit Breaker Type	
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
TELEPHONE SYSTEM	Does not exist
TRANSFORMER	Does not exist