Building Condition Assessment Survey 2023-2024

Asset:	3K CENTER	R @ 2659 WEBSTER AVENUE	- BRONX, 2659	WEBSTER AV	ENUE, BRO	NX, NY, 1045	8
Inspection Id	Inspection Typ	pe			Time	In	Last Edited
4211	MECHANICA	L			2024	-03-25 07:16Al	M 2024-05-03 02:44PM
set Data							
Question				Answer			
Have any Syste	ems/Major Build	ing Components been upgraded?		No System	n Upgraded		
Are there fuel	tanks?			No			
Total # of water	er main service er	ntries to the asset		2			
MERs/Fan Ro	oms Locations			None			
		ing or Defective CO Detectors?		No			
		ed Sprinkler Heads?		No			
		Switches with Missing Hammers?		No compo	onents		
iority Condit	tion						
	iority	Condition	Component	Location	Person(s)	Person(s)	Photo
	tegory	Description	Affected	Description	Notified	Title	Image
No condition re	ecorded						
nspection							
Question				Response	;		
Mechanical							
AIR COND	ITIONING			Inspected			
	ater System			Does not			
		ition: Piping, Pumps and Auxiliarie	es	Does not			
	oil in Ductwork	r s r s r s r s r s r s r s r s r s r s		Does not	exist		
Cooling To				Does not	exist		
DX Split S	System			Inspected			
Indoor U	U nit			Inspected			
Conditi	ion			1- Good			
$\overline{\mathrm{D}}$	Deficiency			No defici	encies recorded		
Outdoor	r Unit			Inspected			
Conditi	ion			1- Good			
$\overline{\mathrm{D}}$	Deficiency			No defici	encies recorded		
Dry Coole	er			Does not	exist		
Packaged	/ Rooftop Unit			Inspected			
<u>Ir</u>	nstance			Roof			
<u>Ir</u>	nstance Condition	1		1- Good			
Ir —	nstance Quantity			2			
Ir	nstance Quantity	Uom		EACH			
N	Manufacturer 1 4 1			Ruppair			
	EquipmentId	_		DOAS-1,	DOAS-2		
	Capacity/Size Qua			13			
	Capacity/Size UO			Tons	. 1		
_	Source of Capacity	y/Size		Documen 2023	ted		
	nstallation Year Source of Installat	ion Vear		Documen	ted		
	Source of Heating			N/A	.cu		
	Refrigerant Type			R-410A			
-	Deficiency			No defici	encies recorded		
	Terminal A/C			Does not			
	nt Leak Detectio	n System		Does not			
Refrigerar		•		Inspected			
Condition	1 0			1- Good			
$\overline{\mathbb{D}}$	Deficiency			No defici	encies recorded		
Return Fa				Does not	exist		
		NEUTRALIZING TANK		Does not	exist		

Building Condition Assessment Survey 2023-2024

Mechanical Inspection	X491
-----------------------	------

uestion	Response	
CLIMATE CONTROL SYSTEM	Inspected	
BMS	Inspected	
Instance	Throughout	
Instance Condition	1- Good	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Building Area Covered by Operational System	81-100%	
Installation Year	2023	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Pneumatic System	Does not exist	
Hybrid System	Does not exist	
Electric System	Does not exist	
COMPACTOR	Does not exist	
CONVEYING	Inspected	
Dumbwaiter	Does not exist	
Elevator	Inspected	
Condition	1- Good	
Are all the existing elevators operable?	No	
Deficiency	No deficiencies recorded	
Escalator	Does not exist	
Non-auditorium Handicap Lift - Vertical	Does not exist	
Non-auditorium Handicap Lift - Stair	Does not exist	
Ash Hoist	Does not exist	
Sidewalk Elevator	Does not exist	
DOMESTIC WATER SYSTEM	Inspected	
Domestic Cold Water System	Inspected	
Gravity System	Does not exist	
Pressure Booster System	Does not exist	
Water Service	Inspected	
Instance	Basement - Water Meter Room	
Instance Condition	1- Good	
Instance Quantity	2	
Instance Quantity Uom	EACH	
Deficiency	No deficiencies recorded	
Domestic Hot Water System	Inspected	
Domestic Hot Water Remote Storage Tank	Does not exist	
Domestic Water Heat Exchanger	Does not exist	
Electric Domestic Water Heater	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Gas Fired Domestic Water Heater	Does not exist	
Oil Fired Domestic Water Heater	Does not exist	
Heat Pump Domestic Water Heater	Does not exist	
Domestic Water Distribution Piping	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
DRAIN/WASTE/VENT AND STORM SYSTEM	Inspected	
Interior Storm Piping	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Sewage/Waste/Vent Piping	Inspected 1- Good	
Condition	1- 0000	

Building Condition Assessment Survey 2023-2024

Mechanical Inspection X491

unicui inspection		A491
Question	Response	
DRAIN/WASTE/VENT AND STORM SYSTEM		
Sewage Ejector Pump	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Sump Pump	Does not exist	
DUAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)	Does not exist	
FIXTURES	Inspected	
Staff And Other	Inspected	
Janitor Sink	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Lavatory/Sink	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Toilet	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Urinal	Does not exist	
Student Division Franction	Inspected Inspected	
Drinking Fountain Condition		
	1- Good	
Deficiency	No deficiencies recorded	
Lavatory/Sink	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Locker Room Shower	Does not exist	
Sink And Fountain Combo Unit	Does not exist	
Toilet	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Urinal	Does not exist	
GAS FIRED FURNACE	Does not exist	
GAS SERVICE	Does not exist	
HEATING	Inspected	
Heating Coil In Ductwork	Does not exist	
Hydronic Heating	Does not exist	
Radiator/Convector/Fin Tube	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Steam Heating	Does not exist	
Steam supplied by External Sources	Does not exist	
Unit Heater/Cabinet Heater	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
HEATING PLANT	Does not exist	
Enclosed IDF Room	Does not exist	
KITCHEN	Inspected	
Instance on 1st Floor	Inspected	
CO Detector	Inspected	
Instance on 1st Floor	Not required	
	riot required	
Gas System Instance on 1st Floor	Does not exist	
Instance on 1st Floor Grease Trap	Does not exist	

Building Condition Assessment Survey 2023-2024

Mechanical Inspection	X491
-----------------------	------

4		
uestion	Response	
KITCHEN		
Grease Trap		
Instance on 1st Floor	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
Hood		
Instance on 1st Floor	Does not exist	
Hood Exhaust Ductwork		
Instance on 1st Floor	Does not exist	
Hood Exhaust Fan		
Instance on 1st Floor	Does not exist	
Hood Fire Suppression System		
Instance on 1st Floor	Does not exist	
Hot Water Temperature Booster		
Instance on 1st Floor	Does not exist	
Kitchen Sink		
Instance on 1st Floor	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
MDF Room	Inspected	
Instance on Room 119	Inspected	
Dedicated A/C Equipment		
Instance on Room 119	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
SCIENCE DEMO ROOM	Does not exist	
SCIENCE LAB	Does not exist	
	Does not exist	
SCIENCE PREP ROOM		
SPRINKLERS, STANDPIPE, FIRE SYSTEM	Inspected	
Dry Sprinkler Alarm Valve Assembly	Does not exist	
Wet Sprinkler Alarm Valve Assembly	Does not exist Does not exist	
Fire Booster Pump Assembly	Does not exist Does not exist	
Roof Tank Siamese Connection	Inspected	
Condition Condition	3- Fair	
Deficiency	No deficiencies recorded	
	Does not exist	
Sprinkler Head	Does not exist Does not exist	
Sprinkler Piping Standpipe System	Inspected	
Hose Valve Assembly	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
	Inspected	
Piping		
Condition	1- Good	
Deficiency	No deficiencies recorded	
Water Gong	Does not exist	
SWIMMING POOL	Does not exist	
VENTILATION	Inspected	
Is the building Mechanically ventilated?	Yes	
Exhaust Fan	Inspected	
Condition	1- Good	
Approximate Total # of Fans	1-25	
Deficiency	No deficiencies recorded	

Building Condition Assessment Survey 2023-2024

Mechanical Inspection X491

uestion	Response		
VENTILATION			
Metal Ductwork	Inspected		
Condition	1- Good		
Are there any uninsulated ductwork by design in Mechanical rooms?	No		
Are there chain operated dampers?	No		
Deficiency	No deficiencies recorded		
Supply Fan	Does not exist		
Unit Ventilator	Does not exist		