

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X876

Asset: BRONX LEADERSHIP ACADEMY - BRONX, 1710 WEBSTER AVENUE, BRONX, NY, 10457

Inspection Id	Inspection Type	Time In	Last Edited
816	ELECTRICAL	2023-11-08 09:38AM	2024-04-01 11:16AM

Asset Data

Question	Answer
Have any Systems/Major Building Components been upgraded?	Systems: Retrofitted LED Lighting, Computer Lab Room 212 (Raceway With Receptacles) Years: 2022 Systems: Molded Case Circuit Breaker Panel Board Years: 2020, 2013, 2008 Systems: Exit Light (Battery Pack), Partial Emergency Lighting (Battery Pack) Years: 2018 Systems: Gymnasium (LED Lighting) Years: 2017 Systems: LAN Years: 2015 Systems: Public Address System (Clocks, Speakers) Years: 2014 Systems: IPDVS/CCTV System Years: 2010 Systems: Telephone System, Intercom System Years: 2009 Systems: Security Lighting Years: 2008 Systems: All Other Electrical Systems and Components Years: 1997
Type of Service	Below Ground
Does Interactive Whiteboard (IWB) Exist?	Yes
Water Penetration In Electrical Room?	No

DEDICATED INTERCOMS IN FIRE RESCUE AREAS

Question	Response
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building?	No

Priority Condition

Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image
		No condition recorded					

Inspection

Question	Response
Electrical	
ATHLETIC FIELD	Does not exist
AUDITORIUM	Does not exist
CAFETERIA	Inspected
Instance on 1st Floor	Inspected
Lighting	
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Does not exist
Lighting Fixture - HID	
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not exist
Lighting Fixture - LED	
Instance on 1st Floor	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X876

Question	Response
CAFETERIA	
Lighting	
Lighting Fixture - LED	
Pendant Mounted	
Instance on 1st Floor	Does not exist
Surface Mounted	
Instance on 1st Floor	Does not exist
Recessed Mounted	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Local Sound System	
Instance on 1st Floor	Inspected
Instance Condition	5- Poor
Installation Year	1997
Source of Installation Year	Documented
Deficiency	AMPLIFIER NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE SYSTEM
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
Projection System	
Instance on 1st Floor	Does not exist
Theater Lighting System	
Instance on 1st Floor	Does not exist
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	
Lighting	
Does a Chandelier Exist?	No
Lighting Fixture - Fluorescent	Does not exist
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Inspected
Pendant Mounted	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
COMPUTER LAB	
Instance on Room 212	Inspected
Power Panel?	No
Lighting	
Instance on Room 212	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 212	Does not exist
Lighting Fixture - HID	
Instance on Room 212	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 212	Does not exist

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X876

Question	Response
COMPUTER LAB	
Lighting	
Lighting Fixture - LED	
Instance on Room 212	Inspected
Pendant Mounted	
Instance on Room 212	Does not exist
Surface Mounted	
Instance on Room 212	Does not exist
Recessed Mounted	
Instance on Room 212	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Raceway With Receptacles	
Instance on Room 212	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
GYMNASIUM	
Instance on 1st Floor	Inspected
Lighting	
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Does not exist
Lighting Fixture - HID	
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not exist
Lighting Fixture - LED	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not exist
Surface Mounted	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on 1st Floor	Does not exist
Local Sound System	
Instance on 1st Floor	Inspected
Instance Condition	5- Poor
Installation Year	1997
Source of Installation Year	Documented
Deficiency	AMPLIFIER NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE SYSTEM
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
Projection System	
Instance on 1st Floor	Does not exist
Scoreboard	
Instance on 1st Floor	Inspected
Instance Condition	5- Poor
Deficiency	NOT OPERATIONAL

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X876

Question	Response
GYMNASIUM	
Scoreboard	
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Theater Lighting System	
Instance on 1st Floor	Does not exist
KITCHEN	Inspected
Instance on 1st Floor	Inspected
Lighting	
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Does not exist
Lighting Fixture - HID	
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not exist
Lighting Fixture - LED	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not exist
Surface Mounted	
Instance on 1st Floor	Does not exist
Recessed Mounted	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
LIBRARY	Does not exist
LOCKER ROOM	
Instance on 1st Floor - Boys, 1st Floor - Girls	Inspected
Alternative Use	No
Lighting	
Instance on 1st Floor - Boys, 1st Floor - Girls	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor - Boys, 1st Floor - Girls	Does not exist
Lighting Fixture - HID	
Instance on 1st Floor - Boys, 1st Floor - Girls	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor - Boys, 1st Floor - Girls	Does not exist
Lighting Fixture - LED	
Instance on 1st Floor - Boys, 1st Floor - Girls	Inspected
Pendant Mounted	
Instance on 1st Floor - Boys, 1st Floor - Girls	Does not exist
Surface Mounted	
Instance on 1st Floor - Boys, 1st Floor - Girls	Does not exist
Recessed Mounted	
Instance on 1st Floor - Boys, 1st Floor - Girls	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
MULTIPURPOSE ROOM	Does not exist

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X876

Question	Response
SCIENCE DEMO ROOM	Inspected
Instance on Rooms 223, 224	Inspected
Power Panel?	No
Alternative Use	No
Lighting	
Instance on Rooms 223, 224	Inspected
Lighting Fixture - Fluorescent	
Instance on Rooms 223, 224	Does not exist
Lighting Fixture - HID	
Instance on Rooms 223, 224	Does not exist
Lighting Fixture - Incandescent	
Instance on Rooms 223, 224	Does not exist
Lighting Fixture - LED	
Instance on Rooms 223, 224	Inspected
Pendant Mounted	
Instance on Rooms 223, 224	Does not exist
Surface Mounted	
Instance on Rooms 223, 224	Does not exist
Recessed Mounted	
Instance on Rooms 223, 224	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Emergency Gas Shut-Off Valve	
Instance on Rooms 223, 224	Does not exist
Emergency Shut-Off Power	
Instance on Rooms 223, 224	Does not exist
Power Supply	
Instance on Rooms 223, 224	Inspected
Instructor Unit	
Instance on Rooms 223, 224	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Meter Demonstration Unit	
Instance on Rooms 223, 224	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Projection System	
Instance on Rooms 223, 224	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
SCIENCE LAB	Inspected
Instance on Rooms 222, 225	Inspected
Power Panel?	No
Alternative Use	No
Lighting	
Instance on Rooms 222, 225	Inspected
Lighting Fixture - Fluorescent	
Instance on Rooms 222, 225	Does not exist
Lighting Fixture - HID	
Instance on Rooms 222, 225	Does not exist
Lighting Fixture - Incandescent	
Instance on Rooms 222, 225	Does not exist
Lighting Fixture - LED	
Instance on Rooms 222, 225	Inspected

NYC Department of Education
Building Condition Assessment Survey 2023-2024

Electrical Inspection

X876

Question	Response
SCIENCE LAB	
Lighting	
Lighting Fixture - LED	
Pendant Mounted	
Instance on Rooms 222, 225	Does not exist
Surface Mounted	
Instance on Rooms 222, 225	Does not exist
Recessed Mounted	
Instance on Rooms 222, 225	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Emergency Gas Shut-Off Valve	
Instance on Rooms 222, 225	Does not exist
Emergency Shut-Off Power	
Instance on Rooms 222, 225	Does not exist
Power Supply	
Instance on Rooms 222, 225	Inspected
Instructor Unit	
Instance on Rooms 222, 225	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Meter Demonstration Unit	
Instance on Rooms 222, 225	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Student Unit	
Instance on Rooms 222, 225	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Projection System	
Instance on Rooms 222, 225	Does not exist
SCIENCE PREP ROOM	
Instance on Room 227	Inspected
Power Panel?	No
Alternative Use	No
Lighting	
Instance on Room 227	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 227	Does not exist
Lighting Fixture - HID	
Instance on Room 227	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 227	Does not exist
Lighting Fixture - LED	
Instance on Room 227	Inspected
Pendant Mounted	
Instance on Room 227	Does not exist
Surface Mounted	
Instance on Room 227	Does not exist
Recessed Mounted	
Instance on Room 227	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Emergency Gas Shut-Off Valve	

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X876

Question	Response
SCIENCE PREP ROOM	
Emergency Gas Shut-Off Valve Instance on Room 227	Does not exist
Emergency Shut-Off Power Instance on Room 227	Does not exist
Power Supply Instance on Room 227	Does not exist
SWIMMING POOL	Does not exist
TOILET ROOM - STAFF	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Does not exist
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Inspected
Pendant Mounted	Does not exist
Surface Mounted	Does not exist
Recessed Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Does not exist
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Inspected
Pendant Mounted	Does not exist
Surface Mounted	Does not exist
Recessed Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
EMERGENCY DC STANDBY BATTERY POWER	Does not exist
EMERGENCY GENERATOR SET	Inspected
Automatic Transfer Switch (ATS)	Inspected
Instance	Electric Room 101C
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Cummins Onan
EquipmentId	Fire Alarm ATS Switch
Capacity/Size Quantity	40
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1997
Source of Installation Year	Documented
Deficiency	PILOT LIGHT NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X876

Question	Response
EMERGENCY GENERATOR SET	
Automatic Transfer Switch (ATS)	
Instance	Electric Room 101C
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Cummins Onan
EquipmentId	Transfer Switch
Capacity/Size Quantity	150
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1997
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Battery Charger	Inspected
Instance	Electric Room 101C
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Cummins Onan
EquipmentId	Battery Charger
Capacity/Size Quantity	10
Capacity/Size UOM	AmpsDC
Capacity/Size 2 Quantity	12
Capacity/Size 2 UOM	VDC
Source of Capacity/Size	Nameplate
Installation Year	1997
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Emergency Distribution Board	Inspected
Number of Spares	14
Fused Disconnect Switch Type	Does not exist
Molded Case Circuit Breaker Type	Inspected
Instance	Electric Room 101C
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	General Electric
EquipmentId	Emergency
Capacity/Size Quantity	225
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	1
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Nameplate
Installation Year	1997
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Diesel	Does not exist
Natural Gas	Inspected
Instance	Roof - Emergency Generator Enclosure
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Cummins Onan
EquipmentId	Emergency Generator
Capacity/Size Quantity	75

NYC Department of Education
Building Condition Assessment Survey 2023-2024

Electrical Inspection

X876

Question	Response
EMERGENCY GENERATOR SET	
Natural Gas	
Capacity/Size UOM	kVA
Capacity/Size 2 Quantity	60
Capacity/Size 2 UOM	kW
Capacity/Size 3 Quantity	208
Capacity/Size 3 UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1997
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
EMERGENCY LIGHT/EXIT LIGHT PANEL	
Does not exist	
EMERGENCY LIGHTING	
Inspected	
Battery Pack	
Inspected	
Condition	3- Fair
Deficiency	FIXTURE NOT OPERATIONAL
Deficiency Location/Instance	Gymnasium
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 4
Violations	35671856M
Non Battery Pack	
Inspected	
Condition	3- Fair
Deficiency	No deficiencies recorded
EXIT LIGHT	
Inspected	
Battery Pack	
Inspected	
Condition	1- Good
Deficiency	No deficiencies recorded
Non Battery Pack	
Does not exist	
EXIT/EMERGENCY LIGHT	
Does not exist	
FIRE ALARM SYSTEM	
Inspected	
Bell/Horn	
Inspected	
Condition	3- Fair
Deficiency	No deficiencies recorded
Strobe	
Inspected	
Condition	3- Fair
Deficiency	No deficiencies recorded
Manual Pull Station	
Inspected	
Condition	3- Fair
Deficiency	No deficiencies recorded
Fan Shutdown Control	
Inspected	
Condition	3- Fair
Deficiency	No deficiencies recorded
Duct Smoke Detector	
Inspected	
Condition	3- Fair
Deficiency	No deficiencies recorded
Area Smoke Detector	
Inspected	
Condition	3- Fair
Deficiency	No deficiencies recorded
CO Detector	
Does not exist	
Heat Detector	
Does not exist	
Elevator Recall	
Inspected	
Condition	3- Fair

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X876

Question	Response
FIRE ALARM SYSTEM	
Elevator Recall	
Deficiency	No deficiencies recorded
Magnetic Door Holder/Contactor	Does not exist
Fused Cutout Panel	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Fire Alarm Digital Communicator	Does not exist
Main Panel	Inspected
Bell At Panel	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Electronic)	Inspected
Instance	Main Entrance Lobby
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Simplex
Model	4100
EquipmentId	Fire Alarm Control Panel
Installation Year	1997
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Standard)	Does not exist
Sub-Panel	Does not exist
Remote Annunciator	Inspected
Display Monitor	Inspected
Condition	5- Poor
Deficiency	MONITOR NOT OPERATIONAL
Deficiency Location/Instance	Custodian's Office
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded
Panel	Does not exist
Printer	Inspected
Condition	5- Poor
Deficiency	PRINTER NOT OPERATIONAL
Deficiency Location/Instance	Custodian's Office
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded
Punch Register	Does not exist
Sprinkler Flow/Air Pressure Switch	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Tamper Flow Switch/Chain	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
GROUNDING SYSTEM	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X876

Question	Response
GROUNDING SYSTEM	
Condition	3- Fair
Deficiency	No deficiencies recorded
INTERCOM SYSTEM	
	Inspected
Elevator	
Condition	Inspected
Deficiency	3- Fair
Deficiency	No deficiencies recorded
Holding Area	Does not exist
LAN	
	Inspected
Local Distribution Frame (I/LDF)	
	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	
	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	
	Does not exist
MOTOR CONTROLLER	
	Inspected
MOTOR CONTROL CENTER	
	Does not exist
MOTOR STARTER/CONTACTOR	
	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Variable Frequency Drive	Does not exist
PANEL BOARD	
	Inspected
Fused Disconnect Switch Type	Does not exist
Fused Knife Switch Type	Does not exist
Fused Toggle Switch Type	Does not exist
Molded Case Circuit Breaker Type	
	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
PUBLIC ADDRESS SYSTEM	
	Inspected
Instance	Room 126
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Rauland Telecenter System 21
Installation Year	1997
Source of Installation Year	Documented
Deficiency	CLOCK NOT OPERATIONAL
Deficiency Location/Instance	Throughout the Building
Deficiency Quantity	20
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
SECURITY	
	Inspected
IPDVS/CCTV System	
	Inspected
Condition	4- Between Fair and Poor
Installation Year	2010
Source of Installation Year	Documented
Deficiency	CAMERA NOT OPERATIONAL
Deficiency Location/Instance	Exterior and Interior of Building
Deficiency Quantity	6
Quantity Uom	EACH
Potential Action	REPLACE

NYC Department of Education
Building Condition Assessment Survey 2023-2024

Electrical Inspection

X876

Question	Response
SECURITY	
IPDVS/CCTV System	
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 3
Violations	No violations recorded
Intrusion Alarm System	
	Inspected
Central Control Panel	
	Inspected
Instance	MDF Room 121
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista - 50P
Installation Year	1997
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	MDF Room 121
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 3
Violations	No violations recorded
Infrared Sensor	
	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Panic Switch	
	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Remote Annunciator	
	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Siren/Strobe	
	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting - Security	
	Inspected
Condition	4- Between Fair and Poor
Deficiency	TIME CLOCK NOT OPERATIONAL
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 3
Violations	No violations recorded
Deficiency	LIGHTING FIXTURE NOT OPERATIONAL
Deficiency Location/Instance	Main Entrance, 173rd Street Side, Roof
Deficiency Quantity	8
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 3
Violations	No violations recorded
SERVICE SWITCH	
	Inspected
Instance	Electric Room 101C
Instance Condition	3- Fair

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X876

Question	Response
SERVICE SWITCH	
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	General Electric
EquipmentId	N/A
Capacity/Size Quantity	2000
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1997
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
SWITCHBOARD	
	Inspected
Number of Spares	1
Fused Disconnect Switch Type	Does not exist
Fused Knife Switch Type	Does not exist
Molded Case Circuit Breaker Type	Inspected
Instance	Electric Room 101C
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	General Electric
EquipmentId	N/A
Capacity/Size Quantity	2000
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	1
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Nameplate
Installation Year	1997
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
TELEPHONE SYSTEM	
	Inspected
PBX/Intercom	
Condition	3- Fair
Deficiency	No deficiencies recorded
Standard	
Condition	3- Fair
Deficiency	No deficiencies recorded
TRANSFORMER	
	Does not exist