### **Building Condition Assessment Survey 2023-2024**

Asset:	P.S. 90 MINISC	CHOOL - BRONX, 1116	SHERIDAN AVENU	U <b>E, BRONX, NY</b>	, 10456		
Inspection Id	Inspection Type				Time	In	Last Edited
3192	MECHANICAL				2024-	·02-13 08:57AN	M 2024-03-17 11:43AN
sset Data							
Ouestion				Answer			
	me/Major Building	Components been upgraded	?	Systems:	Student's Fixt	ures: Toilets (~5	50%)
Have any Syste	ms/Major Bunding	Components occir apgraded		Years:	2021	ares. Tonets (	7070)
				Systems:	Water Service		
				Years:	2014	,	
Are there fuel t	onles?				2014		
		1		No			
	r main service entri	es to the asset		1	MED		
MERs/Fan Roc		or Defective CO Detectors?		1st Floor 1 No	MEK		
	Painted/Obstructed S			No			
		itches with Missing Hammer	rs?	No compo	nents		
riority Condit		itenes with winsing Hammer		rvo compe	hents		
Exist Prior		Condition	Component	Location	Person(s)	Person(s)	Photo
	egory	Description	Affected	Description	Notified	Title	Image
No condition re		-		-			
Inspection							
Question				Response	<u> </u>		
Mechanical				Response	<u>′</u>		
AIR CONDI	TIONING			Inspected			
-	nter System			Does not			
-		n: Piping, Pumps and Auxi	liariae	Does not			
-	oil in Ductwork	n. 1 iping, 1 umps anu Auxi	naries	Does not			
Cooling To				Does not			
DX Split S				Inspected			
Indoor U	•			Inspected			
Condition				-	en Good and Fai	r	
	eficiency			No deficie	encies recorded		
Outdoor				Inspected			
Condition				-	en Good and Fai	r	
	eficiency				encies recorded	1	
				Does not			
Dry Cooler Packaged	Rooftop Unit			Does not			
	Ferminal A/C			Does not			
	t Leak Detection S	System		Does not			
Refrigeran		узст		Inspected			
Condition					en Good and Fai	r	
_	eficiency			No deficie	encies recorded		
Return Fai				Does not			
		UTRALIZING TANK		Does not			
	CONTROL SYSTE			Inspected			
BMS	J. TROLISISIE	****		Does not			
Pneumatic	System			Does not			
Hybrid Sys				Does not	exist		
Electric Sy				Inspected			
	stance			Througho	ut		
In	stance Condition			3- Fair			
	stance Quantity			1			
In							
_		m		EACH			
In	stance Quantity Uo	m ed by Operational System		EACH 81-100%			

### **Building Condition Assessment Survey 2023-2024**

Question	Response			
COMPACTOR	Does not exist			
CONVEYING	Does not exist			
DOMESTIC WATER SYSTEM	Inspected			
Domestic Cold Water System	Inspected			
Gravity System	Does not exist			
Pressure Booster System	Does not exist			
Water Service	Inspected			
Instance	Room M172			
Instance Condition	1- Good			
Instance Quantity	1			
Instance Quantity Uom	EACH			
Deficiency	No deficiencies recorded			
Domestic Hot Water System	Inspected			
Domestic Hot Water Remote Storage Tank	Does not exist			
Domestic Water Heat Exchanger	Does not exist			
Electric Domestic Water Heater	Inspected			
Condition	3- Fair			
Deficiency	No deficiencies recorded			
Gas Fired Domestic Water Heater	Does not exist			
Oil Fired Domestic Water Heater	Does not exist			
Heat Pump Domestic Water Heater	Does not exist			
Domestic Water Distribution Piping	Inspected			
Condition	3- Fair			
Deficiency	No deficiencies recorded			
DRAIN/WASTE/VENT AND STORM SYSTEM	Inspected			
Interior Storm Piping	Does not exist			
Sewage/Waste/Vent Piping	Inspected			
Condition	3- Fair			
Deficiency	No deficiencies recorded			
Sewage Ejector Pump	Does not exist			
Sump Pump	Does not exist			
DUAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)	Does not exist			
FIXTURES	Inspected			
Staff And Other	Inspected			
Janitor Sink	Does not exist			
Lavatory/Sink	Inspected			
Condition	3- Fair			
Deficiency	No deficiencies recorded			
Toilet	Inspected			
Condition	3- Fair			
Deficiency	No deficiencies recorded			
Urinal	Does not exist			
Student	Inspected			
Drinking Fountain	Inspected			
Condition	3- Fair			
Deficiency	No deficiencies recorded			
Lavatory/Sink	Inspected			
Condition	3- Fair			
Deficiency	DEFECTIVE AUXILIARY (FAUCET, SHUT OFF			
	VALVE,ETC.)			
Deficiency Location/Instance	Girl's Toilet Room			
Deficiency Quantity	2			
Quantity Uom	EACH			

### **Building Condition Assessment Survey 2023-2024**

Mechanical Inspection	X890
-----------------------	------

uestion	Response	
FIXTURES		
Student		
Lavatory/Sink		
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Deficiency	CRACKED/PHYSICAL DAMAGE	
Deficiency Location/Instance	Boy's Toilet Room	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Locker Room Shower	Does not exist	
Sink And Fountain Combo Unit	Does not exist	
Toilet	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Urinal	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
GAS FIRED FURNACE	Inspected	
	3- Fair	
Condition		
Deficiency	No deficiencies recorded	
GAS SERVICE	Inspected	
Gas Distribution Piping	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Gas Meter Room Exhaust Fan	Does not exist	
Gas Meter Room Vent	Does not exist	
Gas Pressure Booster	Does not exist	
CO/Gas Leak Detection	Does not exist	
HEATING	Inspected	
Heating Coil In Ductwork	Does not exist	
Hydronic Heating	Does not exist	
Radiator/Convector/Fin Tube	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Steam Heating	Does not exist	
Steam supplied by External Sources	Does not exist	
Unit Heater/Cabinet Heater	Does not exist	
HEATING PLANT	Does not exist	
Enclosed IDF Room	Does not exist	
KITCHEN	Does not exist	
MDF Room	Does not exist	
	Does not exist	
SCIENCE DEMO ROOM		
SCIENCE LAB	Does not exist	
SCIENCE PREP ROOM	Does not exist	
SPRINKLERS, STANDPIPE, FIRE SYSTEM	Does not exist	
SWIMMING POOL	Does not exist	
VENTILATION	Inspected	
Is the building Mechanically ventilated?	Yes	

### **Building Condition Assessment Survey 2023-2024**

## Mechanical Inspection X890

uestion	Response		
VENTILATION			
Exhaust Fan	Inspected		
Condition	3- Fair		
Approximate Total # of Fans	1-25		
Deficiency	No deficiencies recorded		
Heating And Ventilating Unit	Does not exist		
Metal Ductwork	Inspected		
Condition	2- Between Good and Fair		
Are there any uninsulated ductwork by design in Mechanical rooms?	Yes		
Are there chain operated dampers?	No		
Deficiency	No deficiencies recorded		
Supply Fan	Does not exist		
Unit Ventilator	Does not exist		