Building Condition Assessment Survey 2023-2024

Mechanical Inspection

Asset: HS OF AMERICAN STUDIES - BRONX, 2925 GOULDEN AVENUE, BRONX, NY, 10468 Inspection Id Inspection Type Time In						Last Edited	
Inspectio	5073 MECHANIC					05-02 09:13AM	
		AL			2024-	03-02 09:13AM	2024-03-21 01:34PM
Isset Data Ouestion				Answer			
<u> </u>					Drinking Four	atains (2 of 4)	
Have an	y Systems/Major Bui	lding Components been upgraded?		Systems: Years:	-	itallis (2 01 4)	
					2023 MDF Room - Dedicated A/C Equipment (2 of 2, DX Split Systems)		
				Systems:			
				Years:	2016)	
				Systems:		estic Water Heate	er
				Years:	2015		
Are ther	e fuel tanks?			No			
Total # c	of water main service	entries to the asset		2			
	an Rooms Locations			None			
		ssing or Defective CO Detectors?		No			
		cted Sprinkler Heads?		No			
		p Switches with Missing Hammers?	2	No compo	onents		
riority C		<u> </u>		1			
Exist	Priority	Condition	Component	Location	Person(s)	Person(s)	Photo
Last Year?	Category	Description	Affected	Description	Notified	Title	Image
No cond	ition recorded			_			-
Inspection	и						
Questio				Dosponso			
Mechan				Response	;		
				Inspected			
	CONDITIONING			Does not exist			
Chilled Water System Condenser Water Distribution: Piping, Pumps and Auxiliaries			mios	Does not exist			
	ling Coil in Ductwor			Does not exist			
Cooling Tower				Does not	exist		
	Split System			Inspected			
In	door Unit			Inspected			
Ċ	Condition			2- Betwee	en Good and Fai	r	
	Deficiency			No defici	encies recorded		
Ou	ıtdoor Unit			Inspected			
(Condition			3- Fair			
	Deficiency			UP TO 5 TONS:DEFECTIVE			
	Deficiency Location/Instance			Building	Exterior		
	Deficiency Qu			1			
	Quantity Uom			EACH			
	Potential Actio			REPAIR			
	Urgency of Ac			PRIORIT			
	Purpose of Ac	tion		LEVEL 2			
	Violations				ions recorded		
	Cooler			Does not			
Packaged / Rooftop Unit Packaged Terminal A/C			Inspected				
	ndition			3- Fair			
	Deficiency				encies recorded		
Dof	igerant Leak Detect	ion System		Does not			
	igerant Leak Detect	юп зумені		Inspected			
	ndition			3- Fair			
	Deficiency				ED/MISSING I	NSULATION	
	Deficiency Lo						
	Deficiency Lo	cation/instance		Building	Exterior		

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

23
Response
L.F.
MAINTENANCE
PRIORITY 3
LEVEL 2
No violations recorded
Does not exist
Does not exist
Inspected
Inspected
Throughout
3- Fair
1
EACH
81-100%
2000
Documented
BEYOND USEFUL LIFE
Throughout
1
EACH
REPLACE
PRIORITY 1
LEVEL 2
No violations recorded
Does not exist Does not exist
Does not exist
Does not exist
Does not exist
Inspected
Inspected
Does not exist
Does not exist
Inspected
Water/Sprinkler/Gas Meter Room 123
3- Fair
2
EACH
No deficiencies recorded
Inspected
Does not exist
Does not exist
Inspected
2- Between Good and Fair
2- Between Good and Fair No deficiencies recorded
No deficiencies recorded
No deficiencies recorded Does not exist
No deficiencies recorded Does not exist Does not exist
No deficiencies recorded Does not exist Does not exist Does not exist

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

and an anspection		11,00
Juestion	Response	
DRAIN/WASTE/VENT AND STORM SYSTEM		
Interior Storm Piping	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Sewage/Waste/Vent Piping	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Sewage Ejector Pump	Does not exist	
Sump Pump	Does not exist	
DUAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)	Does not exist	
FIXTURES	Inspected	
Staff And Other	Inspected	
Janitor Sink	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Lavatory/Sink	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Toilet	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Urinal	Does not exist	
Student	Inspected	
Drinking Fountain	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
	Inspected	
Lavatory/Sink Condition	3- Fair	
Deficiency	No deficiencies recorded	
Locker Room Shower	Does not exist	
Sink And Fountain Combo Unit	Does not exist	
Toilet	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Urinal	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
GAS FIRED FURNACE	Does not exist	
GAS SERVICE	Inspected	
Gas Distribution Piping	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Gas Meter Room Exhaust Fan	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Gas Meter Room Vent	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Gas Pressure Booster	Does not exist	
CO/Gas Leak Detection	Inspected	
Instance	Water/Sprinkler/Gas Meter Room 123	

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

	11)
Response	
EACH	
2000	
Documented	
BEYOND USEFUL LIFE	
Water/Sprinkler/Gas Meter Room 123	
1	
-	
Does not exist	
Inspected	
Inspected	
Inspected	
2- Between Good and Fair	
No deficiencies recorded	
Does not exist	
Inspected	
Inspected	
Inspected	
3- Fair	
No deficiencies recorded	
Inspected	
1- Good	
No deficiencies recorded	
Inspected	
Inspected	
	EACH 2000 Documented BEYOND USEFUL LIFE Water/Sprinkler/Gas Meter Room 123 1 EACH REPLACE PRIORITY 1 LEVEL 2 No violations recorded Inspected Does not exist Does not exist No deficiencies recorded Does not exist Inspected Inspected Inspected Inspected No deficiencies recorded No Inspected

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

<i>unical Inspection</i>		X90:
uestion	Response	
SCIENCE LAB		
Hood Exhaust Fan		
Instance on Room 120	Does not exist	
Fixed Laboratory Hood		
Instance on Room 120	Does not exist	
Laboratory Sink		
Instance on Room 120	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Make-up Air Unit		
Instance on Room 120	Does not exist	
SCIENCE PREP ROOM	Inspected	
Instance on Room 118	Inspected	
Alternative Use	No	
	INO	
Acid Waste Neutralizing Tank Instance on Room 118	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
	No deficiencies recorded	
CO Detector Instance on Room 118	Insurants d	
	Inspected 1- Good	
Instance Condition		
Deficiency	No deficiencies recorded	
Emergency Shower		
Instance on Room 118	Does not exist	
Eye Wash		
Instance on Room 118	Inspected 3- Fair	
Instance Condition		
Deficiency	No deficiencies recorded	
Hood Exhaust Ductwork		
Instance on Room 118	Does not exist	
Hood Exhaust Fan		
Instance on Room 118	Does not exist	
Fixed Laboratory Hood		
Instance on Room 118	Does not exist	
Laboratory Sink	Y . 1	
Instance on Room 118	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Make-up_Air Unit		
Instance on Room 118	Does not exist	
SPRINKLERS, STANDPIPE, FIRE SYSTEM	Inspected	
Dry Sprinkler Alarm Valve Assembly	Does not exist	
Wet Sprinkler Alarm Valve Assembly	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Fire Booster Pump Assembly	Does not exist	
Roof Tank	Does not exist	
Siamese Connection	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Sprinkler Head	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Sprinkler Piping	Inspected	

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

1			
uestion	Response		
SPRINKLERS, STANDPIPE, FIRE SYSTEM			
Sprinkler Piping			
Condition	2- Between Good and Fair		
Deficiency	No deficiencies recorded		
Standpipe System	Does not exist		
Water Gong	Does not exist		
SWIMMING POOL	Does not exist		
VENTILATION	Inspected		
Is the building Mechanically ventilated?	Yes		
Exhaust Fan	Inspected		
Condition	3- Fair		
Approximate Total # of Fans	1-25		
Deficiency	No deficiencies recorded		
Heating And Ventilating Unit	Does not exist		
Metal Ductwork	Inspected		
Condition	3- Fair		
Are there any uninsulated ductwork by design in Mechanical rooms?	No		
Are there chain operated dampers?	No		
Deficiency	No deficiencies recorded		
Supply Fan	Does not exist		
Unit Ventilator	Does not exist		