NYC Department of Education

Building Condition Assessment Survey 2023-2024

Electrical Inspection			
Asset:	P.S. 71 TRANSPORTABLE - BRONX, 3040 ROBERTS AVENUE, BRONX, NY, 10461		
Inspection Id	Inspection Type	Time In	Last Edited
987	ELECTRICAL	2023-11-15 08:52AM	2023-11-15 11:57AM

987 ELECTRICAL	2023-11-15 08:52AM 2023-11-15 11:57AM
Asset Data	
Question	Answer
Have any Systems/Major Building Components been upgraded?	Systems: Exit/Emergency Lights
	Years: 2018
	Systems: Service Switch, Switchboard, Grounding System
	Years: 2008
	Systems: LAN
	Years: 2007
	Systems: Telephone System
	Years: 2004
	Systems: All Other Electrical Systems and Components
	Years: 1998
Type of Service	Below Ground
Does Interactive Whiteboard (IWB) Exist?	No
Water Penetration In Electrical Room?	No
DEDICATED INTERCOMS IN FIRE RESCUE AREAS	
Question	Response

Question	Response
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in	No
your huilding?	

Priority Condition

Ex	ist	Priority	Condition	Component	Location	Person(s)	Person(s)	Photo
La	st Year?	Category	Description	Affected	Description	Notified	Title	Image
No condition recorded								

Inspection

pection	
Question	Response
Electrical	
ATHLETIC FIELD	Does not exist
AUDITORIUM	Does not exist
CAFETERIA	Does not exist
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inaccessible
COMPUTER LAB	Does not exist
GYMNASIUM	Does not exist
KITCHEN	Does not exist
LIBRARY	Does not exist
LOCKER ROOM	Does not exist
MULTIPURPOSE ROOM	Does not exist
SCIENCE DEMO ROOM	Does not exist
SCIENCE LAB	Does not exist
SCIENCE PREP ROOM	Does not exist
SWIMMING POOL	Does not exist
TOILET ROOM - STAFF	Inaccessible
TOILET ROOM - STUDENT	Inaccessible
AUXILIARY SIGNAL/BELL SYSTEM	Does not exist
EMERGENCY DC STANDBY BATTERY POWER	Does not exist
EMERGENCY GENERATOR SET	Does not exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Does not exist
EMERGENCY LIGHTING	Does not exist
EXIT LIGHT	Does not exist
EXIT/EMERGENCY LIGHT	Inaccessible

NYC Department of Education

Building Condition Assessment Survey 2023-2024

Electrical Inspection X948

1	
Question	Response
FIRE ALARM SYSTEM	Inaccessible
GROUNDING SYSTEM	Inaccessible
INTERCOM SYSTEM	Does not exist
LAN	Inaccessible
LIGHTNING PROTECTION	Does not exist
MOTOR CONTROLLER	Inaccessible
PANEL BOARD	Inaccessible
PUBLIC ADDRESS SYSTEM	Inaccessible
SECURITY	Inspected
IPDVS/CCTV System	Inaccessible
Intrusion Alarm System	Inaccessible
Lighting - Security	Inspected
Condition	4- Between Fair and Poor
Deficiency	LIGHTING FIXTURE NOT OPERATIONAL
Deficiency Location/Instance	Building Perimeters
Deficiency Quantity	7
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 3
Violations	No violations recorded
SERVICE SWITCH	Inaccessible
SWITCHBOARD	Inaccessible
TELEPHONE SYSTEM	Inaccessible
TRANSFORMER	Does not exist