NYC Department of Education

Building Condition Assessment Survey 2023-2024

ectrical I	nspection						X95	
Asset:	P.S.15 ANN	NEX (PLAY YARD) - BRONX, 2	195 ANDREWS	S AVENUE, BRO	NX, NY, 104	53		
Inspection	ı Id Inspection Ty	ype			Time	In	Last Edited	
	393 ELECTRICA	L			2023-	-10-24 08:23Al	M 2023-10-24 04:38PM	
set Data								
Question				Answer				
Have any Systems/Major Building Components been upgraded?				Systems:	Security Ligh	ting		
				Years:	1995			
Type of Service				Below Gro	ound			
Does Interactive Whiteboard (IWB) Exist? Water Penetration In Electrical Room?				No No				
		MS IN FIRE RESCUE AREAS		110				
Question				F	Response			
	Are there any Life Rescue Assistance Areas, Fire Rescue Areas, a			and/or Holding Rooms in No				
your bui								
iority Co	ndition							
Exist	Priority	Condition	Component	Location	Person(s)	Person(s)	Photo	
ast Year?	Category	Description	Affected	Description	Notified	Title	Image	
	ion recorded							
nspection	!							
Question			Response					
Electrical	l							
ATHLETIC FIELD				Does not e	exist			
AUDITORIUM			Does not exist					
CAFETERIA			Does not exist					
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE			Does not exist					
COMPUTER LAB			Does not exist					
GYMNASIUM			Does not exist					
KITCHEN			Does not exist					
LIBRARY			Does not exist					
LOCKER ROOM			Does not exist					
MULTIPURPOSE ROOM			Does not exist					
SCIENCE DEMO ROOM			Does not exist					
SCIENCE LAB			Does not exist					
SCIENCE PREP ROOM			Does not exist					
SWIMN	SWIMMING POOL			Does not exist				
TOILET ROOM - STAFF			Does not exist					
TOILET ROOM - STUDENT			Does not exist					
AUXILIARY SIGNAL/BELL SYSTEM			Does not exist					
EMERO	EMERGENCY DC STANDBY BATTERY POWER			Does not e	exist			
EMERO	EMERGENCY GENERATOR SET			Does not e	exist			
	EMERGENCY LIGHT/EXIT LIGHT PANEL			Does not exist				
	EMERGENCY LIGHTING			Does not exist				
EXIT LIGHT				Does not e	exist			
EXIT/EMERGENCY LIGHT				Does not e	exist			
FIRE ALARM SYSTEM				Does not e	exist			
GROUNDING SYSTEM				Does not e	exist			
INTERCOM SYSTEM			Does not exist					
LAN				Does not e				
	LIGHTNING PROTECTION			Does not exist				
MOTOR CONTROLLER				Does not e				
MOTO	PANEL BOARD							

NYC Department of Education

Building Condition Assessment Survey 2023-2024

Electrical Inspection X951

uestion	Response			
PUBLIC ADDRESS SYSTEM	Does not exist			
SECURITY	Inspected			
IPDVS/CCTV System	Does not exist			
Intrusion Alarm System	Does not exist			
Lighting - Security	Inspected			
Condition	5- Poor			
Deficiency	LIGHTING FIXTURE NOT OPERATIONAL			
Deficiency Location/Instance	Perimeters			
Deficiency Quantity	5			
Quantity Uom	EACH			
Potential Action	REPLACE			
Urgency of Action	PRIORITY 3			
Purpose of Action	LEVEL 3			
Violations	No violations recorded			
SERVICE SWITCH	Does not exist			
SWITCHBOARD	Does not exist			
TELEPHONE SYSTEM	Does not exist			
TRANSFORMER	Does not exist			