Asset:	J.H.S. 25 - MAN	HATTAN, 145 STANTON	STREET, MANI	IATTAN, NY, 10	0002		
Inspection I	d Inspection Type				Time 1	[n	Last Edited
23	09 ELECTRICAL				2024-0	01-10 09:44AM	I 2024-05-24 12:15PM
sset Data							
Question				Answer			
Have any Sy	stems/Major Building C	Components been upgraded?		Systems:	LAN, IPDVS/	CCTV System	
				Years:	2023		
				Systems:	(Non Battery I Rooms, 4th Flo (Except Siren)	Pack), Interior L oor Library), Int	ost Emergency Lighting eighting (Except Science trusion Alarm System
				Years:	2019		
				Systems:			reaker Panel Board
				Years:	2018, 2015, 20		
				Systems:	Partial Lightin	g - Security	
				Years:	2018		
				Systems:	Telephone Sys	tem	
				Years:	2015		
				Systems:		3rd Floor Scien	ce Rooms
				Years:	2014	- Ct	
				Systems:	Public Address	s System	
				Years:	2013	D D	ii-1 E 4 Di
				Systems:	Switch Type P		tial Fused Disconnect
				Years:	2009	aner Boara	
				Systems:	Fire Alarm Sys System)	stem, Auditoriui	m (Theater Lighting
				Years:	2008		
				Systems:	4th Floor Libra	ary (Fluorescent	Lighting)
				Years:	2005		
				Systems:		ght/Exit Light P	anel
				Years:	2002		
Type of Serv				Below Gro	ound		
	etive Whiteboard (IWB) ration In Electrical Roor			Yes No			
		N FIRE RESCUE AREAS		INO			
Question	ED INTERCOMS II	Y FIRE RESCUE AREAS		R	desponse		
		nce Areas, Fire Rescue Areas, a	and/or Holding Roor		[o		
riority Cond	dition						
Exist P	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image
No condition	n recorded						
nspection							
Question				Response			
Electrical							
ATHLET	IC FIELD			Does not e	xist		
AUDITO	RIUM			Inspected			
	Instance on 3rd Floor			Inspected			
House L							
	Instance on 3rd Floor			Inspected			
	Does a Chandelier Exis			No			
Lighti	ng Fixture - Fluorescer	nt					
	Instance on 3rd Floor			Inspected			
Penc	dant Mounted			τ . •			
	Instance on 3rd Floor			Inspected			

Duestion	Response	
AUDITORIUM		
House Lighting		
Lighting Fixture - Fluorescent		
Pendant Mounted		
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on 3rd Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on 3rd Floor	Does not exist	
Lighting Fixture - HID		
Instance on 3rd Floor	Does not exist	
Lighting Fixture - Incandescent		
Instance on 3rd Floor	Does not exist	
Lighting Fixture - LED		
Instance on 3rd Floor	Inspected	
Pendant Mounted		
Instance on 3rd Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on 3rd Floor	Does not exist	
Recessed Mounted		
Instance on 3rd Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Local Sound System		
Instance on 3rd Floor	Inspected	
Instance Condition	5- Poor	

Instance on 3rd Floor	Inspected	
Pendant Mounted		
Instance on 3rd Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on 3rd Floor	Does not exist	
Recessed Mounted		
Instance on 3rd Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
ocal Sound System		
Instance on 3rd Floor	Inspected	
Instance Condition	5- Poor	
Installation Year	1977	
Source of Installation Year	Documented	
Deficiency	AMPLIFIER NOT OPERATIONAL	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE SYSTEM	
Urgency of Action	PRIORITY 2	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
ojection System		
Instance on 3rd Floor	Inspected	
Instance Condition	3- Fair	
Is the projector on a cart or installed on the ceiling?	Ceiling	
Deficiency	No deficiencies recorded	
neater Lighting System		
Instance on 3rd Floor	Inspected	
Dimming System		
Instance on 3rd Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Theater Lighting		
Instance on 3rd Floor	Inspected	
Instance Condition	3- Fair	
ers Version 2.0 (P)	Page 2 of 16	Print Date: 8/8/20

Building Condition Assessment Survey 2023-2024

ricui Inspection		MIUZS
Question	Response	
AUDITORIUM		
Theater Lighting System		
Theater Lighting		
Deficiency	No deficiencies recorded	
CAFETERIA	Inspected	
Instance on 1st Floor	Inspected	
Lighting		
Instance on 1st Floor	Inspected	
Lighting Fixture - Fluorescent	1	
Instance on 1st Floor	Inspected	
Pendant Mounted		
Instance on 1st Floor	Does not exist	
Surface Mounted	2000 1000 0000	
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	No deficiences recorded	
Instance on 1st Floor	Ingrested	
Instance Condition	Inspected 2- Between Good and Fair	
	No deficiencies recorded	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID		
Instance on 1st Floor	Does not exist	
Lighting Fixture - Incandescent		
Instance on 1st Floor	Does not exist	
Lighting Fixture - LED		
Instance on 1st Floor	Does not exist	
Local Sound System		
Instance on 1st Floor	Inspected	
Instance Condition	5- Poor	
Installation Year	1977	
Source of Installation Year	Documented	
Deficiency Deficiency Countity	AMPLIFIER NOT OPERATIONAL	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE SYSTEM	
Urgency of Action	PRIORITY 2	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Projection System		
Instance on 1st Floor	Does not exist	
Theater Lighting System		
Instance on 1st Floor	Does not exist	
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected	
Lighting	Inspected	
Does a Chandelier Exist?	No	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Inspected	
Condition	2- Between Good and Fair	

Question	Response	
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Короля	
Lighting		
Lighting Fixture - Fluorescent		
Recessed Mounted		
Deficiency	No deficiencies recorded	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Does not exist	
COMPUTER LAB	Inspected	
Instance on Room 445	Inspected	
Power Panel?	No	
Lighting		
Instance on Room 445	Inspected	
Lighting Fixture - Fluorescent		
Instance on Room 445	Inspected	
Pendant Mounted		
Instance on Room 445	Does not exist	
Surface Mounted		
Instance on Room 445	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on Room 445	Does not exist	
Lighting Fixture - HID		
Instance on Room 445	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 445	Does not exist	
Lighting Fixture - LED		
Instance on Room 445	Does not exist	
Raceway With Receptacles		
Instance on Room 445	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	

Building Condition Assessment Survey 2023-2024

uestion	Response	
	Response	
GYMNASIUM		
Local Sound System Instance on 1st Floor	Inspected	
Instance Condition	5- Poor	
Installation Year	1977	
Source of Installation Year	Documented	
Deficiency	AMPLIFIER NOT OPERATIONAL	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE SYSTEM	
Urgency of Action	PRIORITY 2	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Projection System		
Instance on 1st Floor	Does not exist	
Scoreboard		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Theater Lighting System		
Instance on 1st Floor	Does not exist	
KITCHEN	Inspected	
Instance on 1st Floor	Inspected	
Lighting	•	
Instance on 1st Floor	Inspected	
Lighting Fixture - Fluorescent	•	
Instance on 1st Floor	Inspected	
Pendant Mounted	•	
Instance on 1st Floor	Does not exist	
Surface Mounted		
Instance on 1st Floor	Does not exist	
Recessed Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID	110 00110110101010101	
Instance on 1st Floor	Does not exist	
Lighting Fixture - Incandescent	DOCS HOT CAIST	
Instance on 1st Floor	Does not exist	
Lighting Fixture - LED	DOCS HOT CAISE	
Instance on 1st Floor	Does not exist	
LIBRARY	Inspected	
Instance on 4th Floor	Inspected	
Instance on Room 265	Inspected	
Lighting		
Instance on 4th Floor	Inspected	
Instance on Room 265	Inspected	
Lighting Fixture - Fluorescent		
Instance on 4th Floor	Inspected	
Instance on Room 265	Inspected	
Pendant Mounted		
Instance on 4th Floor	Does not exist	
Instance on Room 265	Does not exist	

Electrical Inspection	M025
Question	Response

Question	Response	
LIBRARY		
Lighting		
Lighting Fixture - Fluorescent		
Surface Mounted		
Instance on 4th Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Room 265	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on 4th Floor	Does not exist	
Instance on Room 265	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID		
Instance on 4th Floor	Does not exist	
Instance on Room 265	Does not exist	
Lighting Fixture - Incandescent		
Instance on 4th Floor	Does not exist	
Instance on Room 265	Does not exist	
Lighting Fixture - LED		
Instance on 4th Floor	Does not exist	
Instance on Room 265	Does not exist	
Raceway With Receptacles		
Instance on 4th Floor	Does not exist	
Instance on Room 265	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Projection System		
Instance on 4th Floor	Does not exist	
Instance on Room 265	Does not exist	
LOCKER ROOM	Inspected	
Instance on 1st Floor - Boys, 1st Floor - Girls	Inspected	
Alternative Use	No	
Lighting		
Instance on 1st Floor - Boys, 1st Floor - Girls	Inspected	
Lighting Fixture - Fluorescent		
Instance on 1st Floor - Boys, 1st Floor - Girls	Inspected	
Pendant Mounted		
Instance on 1st Floor - Boys, 1st Floor - Girls	Does not exist	
Surface Mounted		
Instance on 1st Floor - Boys, 1st Floor - Girls	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on 1st Floor - Boys, 1st Floor - Girls	Does not exist	
Lighting Fixture - HID		
Instance on 1st Floor - Boys, 1st Floor - Girls	Does not exist	
Lighting Fixture - Incandescent		
Instance on 1st Floor - Boys, 1st Floor - Girls	Does not exist	
Lighting Fixture - LED		
Instance on 1st Floor - Boys, 1st Floor - Girls	Does not exist	

trical Inspection		M025
Question	Response	
MULTIPURPOSE ROOM	Does not exist	
SCIENCE DEMO ROOM	Does not exist	
SCIENCE LAB	Inspected	
Instance on Rooms 403, 405	Inspected	
Power Panel?	Yes	
Alternative Use	No	
Instance on Rooms 203 A/B, 305 A/B	Inspected	
Power Panel?	Yes	
Alternative Use	No	
Instance on Room 469	Inspected	
Power Panel?	Yes	
Alternative Use	No	
Instance on Room 205	Inspected	
Power Panel?	Yes	
Alternative Use	No	
Lighting		
Instance on Rooms 403, 405	Inspected	
Instance on Rooms 203 A/B, 305 A/B	Inspected	
Instance on Room 469	Inspected	
Instance on Room 205	Inspected	
Lighting Fixture - Fluorescent		
Instance on Rooms 403, 405	Inspected	
Instance on Rooms 203 A/B, 305 A/B	Inspected	
Instance on Room 469	Inspected	
Instance on Room 205	Inspected	
Pendant Mounted		
Instance on Rooms 403, 405	Does not exist	
Instance on Rooms 203 A/B, 305 A/B	Does not exist	
Instance on Room 469	Does not exist	
Instance on Room 205	Does not exist	
Surface Mounted		
Instance on Rooms 403, 405	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Rooms 203 A/B, 305 A/B	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Instance on Room 469	Inspected	

ighting		
Instance on Rooms 403, 405	Inspected	
Instance on Rooms 203 A/B, 305 A/B	Inspected	
Instance on Room 469	Inspected	
Instance on Room 205	Inspected	
Lighting Fixture - Fluorescent		
Instance on Rooms 403, 405	Inspected	
Instance on Rooms 203 A/B, 305 A/B	Inspected	
Instance on Room 469	Inspected	
Instance on Room 205	Inspected	
Pendant Mounted		
Instance on Rooms 403, 405	Does not exist	
Instance on Rooms 203 A/B, 305 A/B	Does not exist	
Instance on Room 469	Does not exist	
Instance on Room 205	Does not exist	
Surface Mounted		
Instance on Rooms 403, 405	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Rooms 203 A/B, 305 A/B	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Instance on Room 469	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Room 205	Does not exist	
Recessed Mounted		
Instance on Rooms 403, 405	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Rooms 203 A/B, 305 A/B	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Instance on Room 469	Does not exist	
Instance on Room 205	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID		
tners Version 2.0 (P)	Page 7 of 16	Print Date: 8/8/2
nois reision 2.0 (1)	1 age / 01 10	11III Date. 0/0/2

Building Condition Assessment Survey 2023-2024

uestion	Response	
SCIENCE LAB	Response	
Lighting Lighting Fixture - HID		
Instance on Rooms 403, 405	Does not exist	
Instance on Rooms 203 A/B, 305 A/B	Does not exist	
Instance on Room 469	Does not exist	
Instance on Room 205	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Instance on Rooms 403, 405	Does not exist	
Instance on Rooms 203 A/B, 305 A/B	Does not exist	
Instance on Room 469	Does not exist	
Instance on Room 205	Does not exist	
Lighting Fixture - LED	Does not exist	
Instance on Rooms 403, 405	Does not exist	
Instance on Rooms 203 A/B, 305 A/B	Does not exist	
Instance on Room 469	Does not exist	
Instance on Room 205	Does not exist	
Emergency Gas Shut-Off Valve	Does not exist	
Instance on Rooms 403, 405	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Rooms 203 A/B, 305 A/B	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Instance on Room 469	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Room 205	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Emergency Shut-Off Power	140 deficiences recorded	
Instance on Rooms 403, 405	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Rooms 203 A/B, 305 A/B	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Instance on Room 469	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Room 205	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Power Supply	130 deficiencies recorded	
Instance on Rooms 403, 405	Inspected	
Instance on Rooms 203 A/B, 305 A/B	Inspected	
Instance on Room 469	Inspected	
Instance on Room 469 Instance on Room 205	Does not exist	
Instructor Unit	Does not exist	

 $\frac{Instance\ Condition}{Deficiency}$

Instance on Rooms 203 A/B, 305 A/B

3- Fair

Inspected

No deficiencies recorded

Building Condition Assessment Survey 2023-2024

uestion		Response	
SCIENC	FIAR	сеоронос	
Power			
	ictor Unit		
mstr	Instance Condition	2- Between Good and Fair	
	Deficiency	No deficiencies recorded	
	Instance on Room 469	Inspected	
	Instance Condition	3- Fair	
	Deficiency	No deficiencies recorded	
Meter	Demonstration Unit		
Meter	Instance on Rooms 403, 405	Does not exist	
	Instance on Rooms 203 A/B, 305 A/B	Does not exist	
	Instance on Room 469	Does not exist	
Stude	nt Unit		
	Instance on Rooms 403, 405	Does not exist	
	Instance on Rooms 203 A/B, 305 A/B	Does not exist	
	Instance on Room 469	Does not exist	
Project	ion System		
,	Instance on Rooms 403, 405	Inspected	
	Instance Condition	3- Fair	
	Deficiency	No deficiencies recorded	
	Instance on Rooms 203 A/B, 305 A/B	Inspected	
	Instance Condition	2- Between Good and Fair	
	Deficiency	No deficiencies recorded	
	Instance on Room 469	Inspected	
	Instance Condition	3- Fair	
	Deficiency	No deficiencies recorded	
	Instance on Room 205	Inspected	
	Instance Condition	2- Between Good and Fair	
	Deficiency	No deficiencies recorded	
SCIENC	E PREP ROOM	Inspected	
	Instance on Room 467	Inspected	
	Power Panel?	No	
	Alternative Use	No	
	Instance on Room 303	Inspected	
	Power Panel?	No	
	Alternative Use	No	
Lightin	g		
3	Instance on Room 467	Inspected	
	Instance on Room 303	Inspected	
Light	ing Fixture - Fluorescent		
-	Instance on Room 303	Inspected	
	Instance on Room 467	Inspected	
Pen	dant Mounted		
	Instance on Room 303	Does not exist	
	Instance on Room 467	Does not exist	

Inspected

Inspected 3- Fair

2- Between Good and Fair

No deficiencies recorded

No deficiencies recorded

Instance on Room 303

Instance on Room 467

Instance Condition
Deficiency

Recessed Mounted

Instance Condition
Deficiency

Electrical Inspection	M025
Question	Response

Question	Response
SCIENCE PREP ROOM	
Lighting	
Lighting Fixture - Fluorescent	
Recessed Mounted	
Instance on Room 303	Does not exist
Instance on Room 467	Does not exist
Lighting Fixture - HID	
Instance on Room 303	Does not exist
Instance on Room 467	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 303	Does not exist
Instance on Room 467	Does not exist
Lighting Fixture - LED	
Instance on Room 303	Does not exist
Instance on Room 467	Does not exist
Emergency Gas Shut-Off Valve	
Instance on Room 467	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 303	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Emergency Shut-Off Power	
Instance on Room 467	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 303	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Power Supply	To delicione is recorded
Instance on Room 467	Inspected
Instance on Room 303	Does not exist
Instructor Unit	Does not exist
Instance on Room 467	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
SWIMMING POOL	Does not exist
TOILET ROOM - STAFF	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not exist
Surface Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not exist
Daythaug Vaurian 2.0 (D)	0 of 16 Print Data: 9/9/2024

Building Condition Assessment Survey 2023-2024

псан Інѕресион	M02
euestion	Response
TOILET ROOM - STUDENT	
Lighting	
Lighting Fixture - Fluorescent	
Surface Mounted	Does not exist
Recessed Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
EMERGENCY DC STANDBY BATTERY POWER	Does not exist
EMERGENCY GENERATOR SET	Does not exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected
Condition	3- Fair
Deficiency	LESS THAN 20% SPARE CIRCUIT BREAKERS
Deficiency Location/Instance Deficiency Quantity	Electrical Room C15
	1 FACH
Quantity Uom	EACH
Potential Action	INSTALL NEW PANEL BOARD
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded
EMERGENCY LIGHTING	Inspected
Battery Pack	Inspected
Condition	3- Fair
Deficiency	BATTERY NOT OPERATIONAL
Deficiency Location/Instance	Exit 7 Vestibule, Boiler Room
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE BATTERY
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded
Non Battery Pack	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
EXIT LIGHT	Inspected
Battery Pack	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Non Battery Pack	Does not exist
EXIT/EMERGENCY LIGHT	Does not exist
FIRE ALARM SYSTEM	Inspected
	Inspected
Bell/Horn Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Strobe	Inspected 2- Between Good and Fair
Condition	
Deficiency	No deficiencies recorded
Manual Pull Station	Inspected

Building Condition Assessment Survey 2023-2024

etti Inspection	TVIO.
estion	Response
IRE ALARM SYSTEM	
Manual Pull Station	
Deficiency	No deficiencies recorded
Fan Shutdown Control	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Duct Smoke Detector	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Area Smoke Detector	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
CO Detector	Does not exist
Heat Detector	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Elevator Recall	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Magnetic Door Holder/Contactor	Does not exist
Fused Cutout Panel	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Fire Alarm Digital Communicator	Does not exist
Main Panel	Inspected
Bell At Panel	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Electronic)	Inspected
Instance	1st Floor - Room Adjacent to Elevator Lobby
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Siemens
Model	MXL - IQ
EquipmentId	Fire Alarm Control Panel
Installation Year	2008
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Standard)	Does not exist
Sub-Panel	Does not exist
Remote Annunciator	Inspected
Display Monitor	Does not exist
Panel	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Printer	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Punch Register	Does not exist
Sprinkler Flow/Air Pressure Switch	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded

Building Condition Assessment Survey 2023-2024

ricui Inspection	14102.
Question	Response
FIRE ALARM SYSTEM	
Tamper Flow Switch/Chain	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
GROUNDING SYSTEM	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
INTERCOM SYSTEM	Inspected
Elevator	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Holding Area	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
LAN	Inspected
Local Distribution Frame (I/LDF)	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	Inspected
Condition (MBT)	1- Good
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	Does not exist
MOTOR CONTROLLER	Inspected
	Does not exist
MOTOR CONTROL CENTER MOTOR STARTER/CONTACTOR	Inspected
Condition	3- Fair
Deficiency	MOTOR STARTER NOT OPERATIONAL
Deficiency Location/Instance	Kitchen, Mechanical Room Cl
Deficiency Quantity	5
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Variable Frequency Drive	Does not exist
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Boiler Room, Mechanical Room C1
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Fused Knife Switch Type	Does not exist
Fused Toggle Switch Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room C15
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1

Building Condition Assessment Survey 2023-2024

ieui Inspection	1710.
uestion	Response
PANEL BOARD	
Fused Toggle Switch Type	
Purpose of Action	LEVEL 2
Violations	No violations recorded
Molded Case Circuit Breaker Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Throughout the Building
Deficiency Quantity	28
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
PUBLIC ADDRESS SYSTEM	Inspected
Instance	Room 263
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Bogen HTA250A
Installation Year	2013
Source of Installation Year	Documented
Deficiency	CLOCK NOT OPERATIONAL
Deficiency Location/Instance	Throughout the Building
Deficiency Quantity	30
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
SECURITY	Inspected
IPDVS/CCTV System	Inspected
Condition	2- Between Good and Fair
Installation Year	2023
Source of Installation Year	Documented
Deficiency	SYSTEM DEFECTIVE
Deficiency Location/Instance	Throughout the Building
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR SYSTEM
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 3
Violations	No violations recorded
Intrusion Alarm System	Inspected
Central Control Panel	Inspected
Instance	Custodian's Office
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista 128BPT
Installation Year	2019
Source of Installation Year	Documented
	No deficiencies recorded
Deficiency Infrared Sensor	No deficiencies recorded Inspected

Building Condition Assessment Survey 2023-2024

*		
uestion	Response	
SECURITY		
Intrusion Alarm System		
Infrared Sensor		
Deficiency	No deficiencies recorded	
Panic Switch	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Remote Annunciator	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Siren/Strobe	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Lighting - Security	Inaccessible	
SERVICE SWITCH	Inspected	
	Electrical Room C15	
Instance	3- Fair	
Instance Condition		
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Federal Pacific Electric	
EquipmentId	Main Disconnect	
Capacity/Size Quantity	4000	
Capacity/Size UOM	Amps	
Source of Capacity/Size	Nameplate	
Installation Year	1977	
Source of Installation Year	Documented	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	Electrical Room C15	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
SWITCHBOARD	Inspected	
Number of Spares	0	
Fused Disconnect Switch Type	Inspected	
Instance	Electrical Room C15	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Federal Pacific Electric	
	N/A	
EquipmentId		
Capacity/Size Quantity	4000	
Capacity/Size UOM	Amps Total	
Capacity/Size 2 Quantity	4	
Capacity/Size 2 UOM	Section(s)	
Source of Capacity/Size	Service Switch Size	
Installation Year	1977	
Source of Installation Year	Documented	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	Electrical Room C15	
Deficiency Quantity	1	
Quantity Uom	EACH	
Quantity Com	Enteri	

Building Condition Assessment Survey 2023-2024

Question	Response	
SWITCHBOARD		
Fused Disconnect Switch Type		
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Fused Knife Switch Type	Does not exist	
Molded Case Circuit Breaker Type	Does not exist	
TELEPHONE SYSTEM	Inspected	
PBX/Intercom	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Standard	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
TRANSFORMER	Does not exist	