# **Building Condition Assessment Survey 2023-2024**

Asset:	P.S. 126 - MANH	ATTAN, 80 CATHERI	NE STREET, MAN	HATTAN, NY,	10038	
Inspection Id I	Inspection Type				Time In	Last Edited
1416 I	ELECTRICAL				2023-12-04 08:43AM	2023-12-22 02:22PM
set Data						
Question				Answer		
Have any System	s/Major Building Co	omponents been upgraded?		Systems:	Scoreboard (Gymnasium)	
				Years:	2020	
				Systems: Years:	Projection System (Gymnasium 2019	, Multipurpose Room)
				Systems:	Fire Alarm System (Sprinkler F Switch)	ow/Air Pressure
				Years:	2016	
				Systems:	Public Address System (Amplif Local Sound System	ier, Speakers, Tuner),
				Years:	2015	
				Systems:	Interior Fluorescent Lighting, G Lighting)	ymnasium (LED
				Years:	2013	1)
				Systems:	Emergency Lighting (Battery Pa 2012	ick)
				Years:	Partial Molded Case Circuit Bre	alzar Danal Daard
				Systems: Years:	2011, 2009, 1995	akoi i alici duafu
				Systems:		
				Years:	2011	
				Systems:		
				Years:	2010, 1995	
				Systems:	LAN	
				Years:	2010	
				Systems:	Science Lab Room 417	
				Years:	2009	
				Systems:	Telephone System	
				Years:	2008	
				Systems:	•	
				Years:	2007	
				Systems:	Emergency Light/Exit Light Par	nel
				Years:	1995	
Type of Service	W1: 1 1 (WWD) I	3 : 49		Below Gr	ound	
	Whiteboard (IWB) I In Electrical Room			Yes No		
		FIRE RESCUE AREA	S	INO		
Question	IIII III III	TIKE RESCOETIKE!		]	Response	
	ife Rescue Assistan	ce Areas, Fire Rescue Area	s, and/or Holding Roor		No	
iority Conditio	n					
xist Priori ast Year? Categ		Condition Description	Component Affected	Location Description		Photo mage
No condition reco	orded					
spection						
Question				Response	2	
Electrical						
ATHLETIC F	IELD			Does not	exist	
AUDITORIUM	м			Does not	exist	
CAFETERIA				Inspected		
	ance on 1st Floor			Inspected		
11151						

### **Building Condition Assessment Survey 2023-2024**

neut Inspection		17112(
Question	Response	
CAFETERIA		
Lighting		
Instance on 1st Floor	Inspected	
Lighting Fixture - Fluorescent		
Instance on 1st Floor	Inspected	
Pendant Mounted		
Instance on 1st Floor	Does not exist	
Surface Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID		
Instance on 1st Floor	Does not exist	
Lighting Fixture - Incandescent	2000 100 0.1100	
Instance on 1st Floor	Does not exist	
Lighting Fixture - LED	Does not exist	
Instance on 1st Floor	Does not exist	
Local Sound System	Does not exist	
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Installation Year	2015	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Projection System	Two deficiences recorded	
Instance on 1st Floor	Does not exist	
Theater Lighting System	Does not exist	
Instance on 1st Floor	Does not exist	
	Inspected	
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected	
Lighting Does a Chandelier Exist?	No	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Inspected	
Condition Condition	2- Between Good and Fair	
	No deficiencies recorded	
Deficiency		
Recessed Mounted	Does not exist	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Does not exist	
COMPUTER LAB	Inspected	
Instance on Room 423	Inspected	
Power Panel?	Yes	
Lighting		
Instance on Room 423	Inspected	
Lighting Fixture - Fluorescent		
Instance on Room 423	Inspected	
Pendant Mounted	*	

#### **Building Condition Assessment Survey 2023-2024**

Question	Response	
COMPUTER LAB		
Lighting		
Lighting Fixture - Fluorescent		
Pendant Mounted		
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on Room 423	Does not exist	
Recessed Mounted		
Instance on Room 423	Does not exist	
Lighting Fixture - HID		
Instance on Room 423	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 423	Does not exist	
Lighting Fixture - LED		
Instance on Room 423	Does not exist	
Raceway With Receptacles		
Instance on Room 423	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
GYMNASIUM	Inspected	
Instance on 2nd Floor	Inspected	
Lighting		
Instance on 2nd Floor	Inspected	
Lighting Fixture - Fluorescent		
Instance on 2nd Floor	Inspected	
Pendant Mounted		
Instance on 2nd Floor	Does not exist	
Surface Mounted		
Instance on 2nd Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on 2nd Floor	Does not exist	
Lighting Fixture - HID		
Instance on 2nd Floor	Does not exist	
Lighting Fixture - Incandescent		
Instance on 2nd Floor	Inspected	
Pendant Mounted		
Instance on 2nd Floor	Does not exist	
Surface Mounted		
Instance on 2nd Floor	Does not exist	
Recessed Mounted		
Instance on 2nd Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE	
Deficiency Quantity	14	
Quantity Uom	EACH	
	DEDLACE LIDERADE	

REPLACE-UPGRADE

No violations recorded

PRIORITY 1

LEVEL 2

Inspected

Potential Action

Urgency of Action

Purpose of Action

Instance on 2nd Floor

Violations

**Lighting Fixture - LED** 

### **Building Condition Assessment Survey 2023-2024**

trical Inspection	N
Question	Response
GYMNASIUM	
Lighting	
Lighting Fixture - LED	
Pendant Mounted	
Instance on 2nd Floor	Does not exist
Surface Mounted	
Instance on 2nd Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on 2nd Floor	Does not exist
Local Sound System	
Instance on 2nd Floor	Inspected
Instance Condition	2- Between Good and Fair
Installation Year	2015
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Projection System	
Instance on 2nd Floor	Inspected
Instance Condition	1- Good
Is the projector on a cart or installed on the ceiling?	Ceiling
Deficiency	No deficiencies recorded
Scoreboard	
Instance on 2nd Floor	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Theater Lighting System	
Instance on 2nd Floor	Inspected
Dimming System	
Instance on 2nd Floor	Does not exist
Theater Lighting	
Instance on 2nd Floor	Inspected
Instance Condition	5- Poor
Deficiency	LIGHTING FIXTURE NOT OPERATIONAL
Deficiency Quantity	36
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded

Instance on 2nd Floor	Does not exist	
Theater Lighting		
Instance on 2nd Floor	Inspected	
Instance Condition	5- Poor	
Deficiency	LIGHTING FIXTURE NOT OPERA	ATIONAL
Deficiency Quantity	36	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
TCHEN	Inspected	
Instance on 1st Floor	Inspected	
Lighting		
Instance on 1st Floor	Inspected	
<b>Lighting Fixture - Fluorescent</b>		
Instance on 1st Floor	Inspected	
Pendant Mounted		
Instance on 1st Floor	Does not exist	
Surface Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on 1st Floor	Does not exist	
tners Version 2.0 (P)	Page 4 of 13	Print Date: 8/8/202

### **Building Condition Assessment Survey 2023-2024**

Electrical Inspection	M126
Question	Response

Question	Response
KITCHEN	
Lighting	
Lighting Fixture - HID	
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not exist
Lighting Fixture - LED	
Instance on 1st Floor	Does not exist
LIBRARY	Inspected
Instance on Room 233/237	Inspected
Lighting	nspected .
Instance on Room 233/237	Inspected
Lighting Fixture - Fluorescent	1
Instance on Room 233/237	Inspected
Pendant Mounted	1
Instance on Room 233/237	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Surface Mounted	To delicible feedada
Instance on Room 233/237	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Recessed Mounted	No deficiencies recorded
Instance on Room 233/237	Does not exist
Lighting Fixture - HID	Does not exist
Instance on Room 233/237	Does not exist
	Does not exist
Lighting Fixture - Incandescent Instance on Room 233/237	Does not exist
Lighting Fixture - LED	Does not exist
Instance on Room 233/237	Does not exist
Raceway With Receptacles	Does not exist
Instance on Room 233/237	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Projection System	To delicities recorded
Instance on Room 233/237	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
LOCKER ROOM	Does not exist
MULTIPURPOSE ROOM	Inspected
Instance on 1st Floor	Inspected
Lighting	Y , 1
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	Yususakad
Instance on 1st Floor	Inspected
Pendant Mounted	Description of the second seco
Instance on 1st Floor	Does not exist
Surface Mounted	Yumandad
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on 1st Floor	Does not exist

### **Building Condition Assessment Survey 2023-2024**

Question	Response	
MULTIPURPOSE ROOM		
Lighting		
Lighting Fixture - HID		
Instance on 1st Floor	Does not exist	
Lighting Fixture - Incandescent		
Instance on 1st Floor	Does not exist	
Lighting Fixture - LED		
Instance on 1st Floor	Does not exist	
Local Sound System		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Installation Year	2015	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Projection System		
Instance on 1st Floor	Inspected	
Instance Condition	1- Good	
Is the projector on a cart or installed on the ceiling?	Ceiling	
Deficiency	No deficiencies recorded	
Theater Lighting System		
Instance on 1st Floor	Does not exist	
SCIENCE DEMO ROOM	Does not exist	
SCIENCE LAB	Inspected	
Instance on Room 417	Inspected	
Power Panel?	Yes	
Alternative Use	No	
Lighting_		
Instance on Room 417	Inspected	
Lighting Fixture - Fluorescent		
Instance on Room 417	Inspected	
Pendant Mounted		
Instance on Room 417	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on Room 417	Does not exist	
Recessed Mounted		
Instance on Room 417	Does not exist	
Lighting Fixture - HID		
Instance on Room 417	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 417	Inspected	
Pendant Mounted		
Instance on Room 417	Does not exist	
Surface Mounted		
Instance on Room 417	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on Room 417	Does not exist	
Lighting Fixture - LED		
Instance on Room 417	Does not exist	
Emergency Gas Shut-Off Valve		
Instance on Room 417	Inspected	

### **Building Condition Assessment Survey 2023-2024**

aricai Inspection		W1120
Question	Response	
SCIENCE LAB		
Emergency Gas Shut-Off Valve		
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Emergency Shut-Off Power		
Instance on Room 417	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Power Supply		
Instance on Room 417	Inspected	
Instructor Unit		
Instance on Room 417	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Meter Demonstration Unit		
Instance on Room 417	Does not exist	
Student Unit		
Instance on Room 417	Does not exist	
Projection System		
Instance on Room 417	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
SCIENCE PREP ROOM	Does not exist	
SWIMMING POOL	Does not exist	
TOILET ROOM - STAFF	Inspected	
Lighting	Inspected	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Does not exist	
Surface Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Does not exist	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - Incandescent  Lighting Fixture - LED	Does not exist	
TOILET ROOM - STUDENT	Inspected	
	Inspected	
Lighting Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Does not exist	
Surface Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Does not exist	
	Does not exist  Does not exist	
Lighting Fixture - HID	Does not exist  Does not exist	
Lighting Fixture - Incandescent	Does not exist  Does not exist	
Lighting Fixture - LED		
AUXILIARY SIGNAL/BELL SYSTEM	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
EMERGENCY DC STANDBY BATTERY POWER	Does not exist	
EMERGENCY GENERATOR SET	Does not exist	
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected	
Condition	3- Fair	

### **Building Condition Assessment Survey 2023-2024**

IVII
Response
No deficiencies recorded
Inspected
Inspected
3- Fair
No deficiencies recorded
Inspected
3- Fair
No deficiencies recorded
Inspected
Does not exist
Inspected
3- Fair
FIXTURE LAMP NOT OPERATIONAL
Basement Corridor
1 Factor
EACH
MAINTENANCE
PRIORITY 5
LEVEL 2
No violations recorded
Does not exist
Inspected
Inspected
3- Fair
No deficiencies recorded
Does not exist
Inspected
3- Fair
No deficiencies recorded
Does not exist
Inspected
3- Fair
No deficiencies recorded
Does not exist
Inspected
Inspected
3- Fair
No deficiencies recorded
Does not exist
Inspected
Basement Corridor
3- Fair
1 EACH
EACH
Edwards
Fire Alarm Control Panel
1965
Documented

### **Building Condition Assessment Survey 2023-2024**

_		
uestion	Response	
FIRE ALARM SYSTEM		
Main Panel		
Fire Alarm Control Panel (Standard)		
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	Basement Corridor	
Deficiency Quantity	88,000	
Quantity Uom	S.F.	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Sub-Panel	Inspected	
Bell At Panel	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Electronic)	Does not exist	
Fire Alarm Control Panel (Standard)	Inspected	
Instance	Basement Corridor	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Edwards	
EquipmentId	N/A	
Installation Year	1965	
Source of Installation Year	Documented	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	Basement Corridor	
Deficiency Quantity	88,000	
Quantity Uom	S.F.	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Remote Annunciator	Does not exist	
Sprinkler Flow/Air Pressure Switch	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Tamper Flow Switch/Chain	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
GROUNDING SYSTEM	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
NTERCOM SYSTEM	Does not exist	
LAN	Inspected	
	Inspected	
Local Distribution Frame (I/LDF)  Condition	3- Fair	
Deficiency  M. F. G. (MDF)	No deficiencies recorded	
Main Equipment Rack (MDF)	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
LIGHTNING PROTECTION	Does not exist	
MOTOR CONTROLLER	Inspected	

### **Building Condition Assessment Survey 2023-2024**

uestion	Response
MOTOR CONTROLLER	
MOTOR STARTER/CONTACTOR	Inspected
Condition	3- Fair
Deficiency	MOTOR STARTER NOT OPERATIONAL
Deficiency Location/Instance	Basement Corridor by Room C1 (Toilet Exh TE-18, House Exh Fan 3-H)
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Variable Frequency Drive	Does not exist
ANEL BOARD	Inspected
Fused Disconnect Switch Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Basement Corridor by Room C2, Mechanical Room 310
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Fused Knife Switch Type	Does not exist
Fused Toggle Switch Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room C4
Deficiency Quantity	1
Quantity Uom	EACH  PEN AGE UNON A DE
Potential Action	REPLACE-UPGRADE
Urgency of Action Purpose of Action	PRIORITY 1 LEVEL 2
Violations	
	No violations recorded
Molded Case Circuit Breaker Type Condition	Inspected 3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance Deficiency Quantity	Throughout the Building 12
Quantity Uom	EACH
Potential Action	EACH REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	NO SPARE
Deficiency Location/Instance	NO SPARE By Rooms (315, 415, 441)
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE PANEL BOARD
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	PANEL BOARD DOOR LOCK IS MISSING
Deficiency Location/Instance	Electrical Room C4
Deficiency Quantity	1

#### **Building Condition Assessment Survey 2023-2024**

Duestion	Response
PANEL BOARD	1
Molded Case Circuit Breaker Type	
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
PUBLIC ADDRESS SYSTEM	Inspected
Instance	General Office - Room 139
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	N/A
Installation Year	1980
Source of Installation Year	Inspector Estimate
Deficiency	CLOCK NOT OPERATIONAL
Deficiency Location/Instance	Multipurpose Room, By Rooms (215, 239, 341, 415, 437)
Deficiency Quantity	9
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	MASTER CLOCK NOT OPERATIONAL
Deficiency Location/Instance	General Office - Room 139
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	General Office - Room 139
Deficiency Quantity	88,000
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY I
Purpose of Action	LEVEL 2
Violations	No violations recorded
SECURITY	Inspected
IPDVS/CCTV System	Does not exist
Intrusion Alarm System	Inspected
Central Control Panel	Inspected
Instance	Custodian's Office - Room 133

### **Building Condition Assessment Survey 2023-2024**

Question	Response
SECURITY	•
Intrusion Alarm System	
Central Control Panel	
Violations	No violations recorded
Infrared Sensor	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Panic Switch	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Remote Annunciator	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Siren/Strobe	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting - Security	Inaccessible
SERVICE SWITCH	Inspected
Instance	Electrical Room C4
Instance Condition	3- Fair
Instance Quantity	1 EACH
Instance Quantity Uom	
Manufacturer	Metropolitan N/A
EquipmentId Capacity/Size Quantity	1600
Capacity/Size Quantity  Capacity/Size UOM	Amps
Source of Capacity/Size	Fuse Size
Installation Year	1965
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance Deficiency Quantity	Electrical Room C4
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
SWITCHBOARD	Inspected
Number of Spares	0
Fused Disconnect Switch Type	Inspected
Instance	Electrical Room C4
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Metropolitan Electric
EquipmentId	N/A
Capacity/Size Quantity	1600
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	3 Section(s)
Capacity/Size 2 UOM Source of Capacity/Size	Section(s) Service Switch Fuse Size
Source of Capacity/Size  Installation Year	Service Switch Fuse Size 1965
Installation Year Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room C4
,	

### **Building Condition Assessment Survey 2023-2024**

uestion	Response	
SWITCHBOARD		
Fused Disconnect Switch Type		
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Fused Knife Switch Type	Does not exist	
Molded Case Circuit Breaker Type	Does not exist	
TELEPHONE SYSTEM	Inspected	
PBX/Intercom	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Standard	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
TRANSFORMER	Does not exist	