Building Condition Assessment Survey 2023-2024

Inspection	1 Id Inspection Type				Time	In	Last Edited
	2478 ELECTRICAL				2024-	-01-17 09:00Al	M 2024-02-13 07:35A
sset Data							
Question				Answer			
Have any	Systems/Major Building	Components been upgrade	d?	Systems:	Service Switc	eh	
				Years:	2023, 2009		
				Systems:		Public Address	System (Clocks)
				Years:	2023		
				Systems:	Lighting (Bat	Partial LED Lig tery Pack), LAN	ghting), Most Emergency N
				Years:	2022 Talanhana Sw	retom	
				Systems: Years:	Telephone Sy 2019	Stem	
				Systems:		ite	
				Years:	2018, 1995	113	
				Systems:		Case Circuit B	reaker Panel Board
				Years:	2017, 2014, 2		
				Systems:		Room 317 (Exce	ept Lighting)
				Years:	2017	`	
				Systems:		ing (Except Audighting (Non Ba	ditorium, Library), Most attery Pack)
				Years: Systems:	2015		,
				Years:	2014		
				Systems:		TV System, Publ	lic Address System
				Years:	2011		
				Systems:	Switchboard		
				Years:	2009		
				Systems:	Library		
				Years:	2007		
				Systems:	Intrusion Alai	rm System	
				Years:	2005		
				Systems:		ight/Exit Light	Panel
				Years:	1995		
Type of S) F : 49		Below G	round		
	ractive Whiteboard (IWB netration In Electrical Roo	·		Yes No			
		IN FIRE RESCUE ARI	FAS	INO			
Question	TED IVIERCOMS	IN FIRE RESCUE ARI	LAS		Response		
	·	ance Areas, Fire Rescue Ar	eas, and/or Holding Roo		No		
Priority Co							
Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image
No	Fire Alarm System - Defective	N/A	Fire Alarm System - Main Panel	Boiler Room	Hogart Grant	Fireman	No Photo Taken
Inspection	!						
Question				Response	e		
Electrica	l						
ATHLI	ETIC FIELD			Does not	exist		
AUDIT	ORIUM			Inspected	I		
	Instance on 1st Floor			Inspected	. —		

Building Condition Assessment Survey 2023-2024

em inspection		
estion	Response	
UDITORIUM		
House Lighting		
Instance on 1st Floor	Inspected	
Does a Chandelier Exist?	No	
Lighting Fixture - Fluorescent		
Instance on 1st Floor	Inspected	
Pendant Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on 1st Floor	Does not exist	
Lighting Fixture - HID		
Instance on 1st Floor	Does not exist	
Lighting Fixture - Incandescent		
Instance on 1st Floor	Does not exist	
Lighting Fixture - LED		
Instance on 1st Floor	Inspected	
Pendant Mounted	*	
Instance on 1st Floor	Does not exist	
Surface Mounted		
Instance on 1st Floor	Does not exist	
Recessed Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Local Sound System		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Installation Year	2014	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Projection System		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Is the projector on a cart or installed on the ceiling?	Ceiling	
Deficiency	No deficiencies recorded	
Theater Lighting System		
Instance on 1st Floor	Inspected	
Dimming System		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Theater Lighting		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
AFETERIA	Inspected	
Instance on Basement - Staff	Inspected	
Instance on Basement - Students	Inspected	

Question	Response	
	Response	
CAFETERIA		
Lighting Instance on Basement - Staff	Inomostod	
Instance on Basement - Staff Instance on Basement - Students	Inspected	
	Inspected	
Lighting Fixture - Fluorescent Instance on Basement - Students	Lucanactad	
	Inspected	
Instance on Basement - Staff	Inspected	
Pendant Mounted	D	
Instance on Basement - Students	Does not exist	
Instance on Basement - Staff	Does not exist	
Surface Mounted		
Instance on Basement - Students	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Instance on Basement - Staff	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on Basement - Students	Does not exist	
Instance on Basement - Staff	Does not exist	
Lighting Fixture - HID		
Instance on Basement - Students	Does not exist	
Instance on Basement - Staff	Does not exist	
Lighting Fixture - Incandescent		
Instance on Basement - Students	Does not exist	
Instance on Basement - Staff	Does not exist	
Lighting Fixture - LED		
Instance on Basement - Students	Inspected	
Instance on Basement - Staff	Does not exist	
Pendant Mounted		
Instance on Basement - Students	Does not exist	
Surface Mounted		
Instance on Basement - Students	Does not exist	
Recessed Mounted		
Instance on Basement - Students	Inspected	

Does not exist Inspected Does not exist Does not exist Does not exist	
Does not exist Inspected Does not exist Does not exist	
Does not exist Does not exist Does not exist Does not exist Inspected Does not exist Does not exist	
Does not exist Does not exist Inspected Does not exist Does not exist	
Does not exist Does not exist Inspected Does not exist Does not exist	
Does not exist Does not exist Inspected Does not exist Does not exist	
Does not exist Inspected Does not exist Does not exist	
Does not exist Inspected Does not exist Does not exist	
Inspected Does not exist Does not exist	
Does not exist Does not exist	
Does not exist Does not exist	
Does not exist	
Does not exist	
Does not exist	
Inspected	
2- Between Good and Fair	
No deficiencies recorded	
Does not exist	
Inspected	
5- Poor	-
1955	-
Documented	
AMPLIFIER NOT OPERATIONAL	
1	
EACH	
No violations recorded	
Does not exist	
3 of 15 Print Date: 9	8/8/202.
	Inspected 2- Between Good and Fair No deficiencies recorded Does not exist Inspected 5- Poor 1955 Documented AMPLIFIER NOT OPERATIONAL 1

Building Condition Assessment Survey 2023-2024

ctrical Inspection		M167
Question	Response	
CAFETERIA		
Theater Lighting System		
Instance on Basement - Staff	Does not exist	
Instance on Basement - Students	Does not exist	
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected	
Lighting	Inspected	
Does a Chandelier Exist?	No	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Does not exist	
COMPUTER LAB	Inspected	
Instance on Rooms 106, 323	Inspected	
Power Panel?	Yes	
Lighting		
Instance on Rooms 106, 323	Inspected	
Lighting Fixture - Fluorescent		
Instance on Rooms 106, 323	Inspected	
Pendant Mounted		
Instance on Rooms 106, 323	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on Rooms 106, 323	Does not exist	
Recessed Mounted		
Instance on Rooms 106, 323	Does not exist	
Lighting Fixture - HID		
Instance on Rooms 106, 323	Does not exist	
Lighting Fixture - Incandescent		
Instance on Rooms 106, 323	Does not exist	
Lighting Fixture - LED		
Instance on Rooms 106, 323	Does not exist	
Raceway With Receptacles	Yourselved	
Instance on Rooms 106, 323	Inspected 3- Fair	
Instance Condition	No deficiencies recorded	
Deficiency		
GYMNASIUM	Inspected	
Instance on 1st Floor	Inspected	
Lighting	Increated	
Instance on 1st Floor	Inspected	
Lighting Fixture - Fluorescent Instance on 1st Floor	Does not aviat	
	Does not exist	
Lighting Fixture - HID	Does not exist	
Instance on 1st Floor	DOES HOLEXIST	
Lighting Fixture - Incandescent		

Electrical Inspection	M167
0	D

2		
estion	Response	
GYMNASIUM		
Lighting		
Lighting Fixture - Incandescent		
Instance on 1st Floor	Does not exist	
Lighting Fixture - LED		
Instance on 1st Floor	Inspected	
Pendant Mounted		
Instance on 1st Floor	Does not exist	
Surface Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on 1st Floor	Does not exist	
Local Sound System		
Instance on 1st Floor	Inspected	
Instance Condition	5- Poor	
Installation Year	1955	
Source of Installation Year	Documented	
Deficiency	AMPLIFIER NOT OPERATIONAL	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE SYSTEM	
Urgency of Action	PRIORITY 2	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Projection System		
Instance on 1st Floor	Does not exist	
Scoreboard		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Theater Lighting System		
Instance on 1st Floor	Does not exist	
KITCHEN	Inspected	
Instance on Basement	Inspected	
Lighting		
Instance on Basement	Inspected	
Lighting Fixture - Fluorescent		
Instance on Basement	Inspected	
Pendant Mounted		
Instance on Basement	Does not exist	
Surface Mounted		
Instance on Basement	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on Basement	Does not exist	
Lighting Fixture - HID		
Instance on Basement	Does not exist	
Lighting Fixture - Incandescent		
Instance on Basement	Does not exist	
motance on pasement	Does not exist	
Lighting Fixture - LED		

trical Inspection		M10
Question	Response	
LIBRARY	Inspected	
Instance on Room 222	Inspected	
Lighting		
Instance on Room 222	Inspected	
Lighting Fixture - Fluorescent		
Instance on Room 222	Inspected	
Pendant Mounted		
Instance on Room 222	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on Room 222	Does not exist	
Recessed Mounted		
Instance on Room 222	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID		
Instance on Room 222	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 222	Does not exist	
Lighting Fixture - LED		
Instance on Room 222	Does not exist	
Raceway With Receptacles		
Instance on Room 222	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Projection System		
Instance on Room 222	Does not exist	
LOCKER ROOM	Inspected	
Instance on 1st Floor - Boys	Inspected	
· · · · · · · · · · · · · · · · · · ·		

Instance on Room 222	Does not exist	
Recessed Mounted		
Instance on Room 222	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID		
Instance on Room 222	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 222	Does not exist	
Lighting Fixture - LED		
Instance on Room 222	Does not exist	
Raceway With Receptacles		
Instance on Room 222	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Projection System		
Instance on Room 222	Does not exist	
OCKER ROOM	Inspected	
Instance on 1st Floor - Boys	Inspected	
Alternative Use	No	
Instance on 2nd Floor - Girls	Inspected	
Alternative Use	No	
Lighting		
Instance on 1st Floor - Boys	Inspected	
Instance on 2nd Floor - Girls	Inspected	
Lighting Fixture - Fluorescent		
Instance on 1st Floor - Boys	Inspected	
Instance on 2nd Floor - Girls	Inspected	
Pendant Mounted	1	
Instance on 1st Floor - Boys	Does not exist	
Instance on 2nd Floor - Girls	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on 1st Floor - Boys	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Instance on 2nd Floor - Girls	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	The deliteration recorded	
Instance on 1st Floor - Boys	Does not exist	
	Does not exist	

Building Condition Assessment Survey 2023-2024

icai inspection		IVIIO
uestion	Response	
LOCKER ROOM		
Lighting		
Lighting Fixture - Fluorescent		
Recessed Mounted		
Instance on 2nd Floor - Girls	Does not exist	
Lighting Fixture - HID		
Instance on 1st Floor - Boys	Does not exist	
Instance on 2nd Floor - Girls	Does not exist	
Lighting Fixture - Incandescent		
Instance on 1st Floor - Boys	Does not exist	
Instance on 2nd Floor - Girls	Does not exist	
Lighting Fixture - LED		
Instance on 1st Floor - Boys	Does not exist	
Instance on 2nd Floor - Girls	Does not exist	
MULTIPURPOSE ROOM	Does not exist	
SCIENCE DEMO ROOM	Inspected	
Instance on Room 306	Inspected	
Power Panel?	No	
Alternative Use	Yes	
Instance on Rooms 202, 203, 206, 302, 402, 404	Inspected	
Power Panel?	1	
<u> </u>	No	
Alternative Use	No	
Lighting	Yourself d	
Instance on Room 306	Inspected	
Instance on Rooms 202, 203, 206, 302, 402, 404	Inspected	
Lighting Fixture - Fluorescent		
Instance on Room 306	Inspected	
Instance on Rooms 202, 203, 206, 302, 402, 404	Inspected	
Pendant Mounted		
Instance on Room 306	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Instance on Rooms 202, 203, 206, 302, 402, 404	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on Room 306	Does not exist	
Instance on Rooms 202, 203, 206, 302, 402, 404	Does not exist	
Recessed Mounted		
Instance on Room 306	Does not exist	
Instance on Rooms 202, 203, 206, 302, 402, 404	Does not exist	
Lighting Fixture - HID		
Instance on Room 306	Does not exist	
Instance on Rooms 202, 203, 206, 302, 402, 404	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 306	Does not exist	
Instance on Rooms 202, 203, 206, 302, 402, 404	Does not exist	
Lighting Fixture - LED		
Instance on Room 306	Does not exist	
Instance on Rooms 202, 203, 206, 302, 402, 404	Does not exist	
Emergency Gas Shut-Off Valve		
Instance on Room 306	Does not exist	
Instance on Rooms 202, 203, 206, 302, 402, 404	Does not exist	

Building Condition Assessment Survey 2023-2024

iricai Inspection		N1107
Question	Response	
SCIENCE DEMO ROOM		
Emergency Shut-Off Power		
Instance on Room 306	Does not exist	
Instance on Rooms 202, 203, 206, 302, 402, 404	Does not exist	
Power Supply		
Instance on Room 306	Does not exist	
Instance on Rooms 202, 203, 206, 302, 402, 404	Does not exist	
Projection System		
Instance on Room 306	Does not exist	
Instance on Rooms 202, 203, 206, 302, 402, 404	Does not exist	
SCIENCE LAB	Inspected	
Instance on Room 317	Inspected	
Power Panel?	Yes	
Alternative Use	No	
Lighting	110	
Instance on Room 317	Inspected	
Lighting Fixture - Fluorescent	1	
Instance on Room 317	Inspected	
Pendant Mounted		
Instance on Room 317	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	No deficiencies recorded	
Instance on Room 317	Does not exist	
Recessed Mounted	Does not exist	
Instance on Room 317	Does not exist	
	Does not exist	
Lighting Fixture - HID	Descript mist	
Instance on Room 317	Does not exist	
Lighting Fixture - Incandescent Instance on Room 317	Description of the second	
	Does not exist	
Lighting Fixture - LED	D	
Instance on Room 317	Does not exist	
Emergency Gas Shut-Off Valve	T	
Instance on Room 317	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Emergency Shut-Off Power		
Instance on Room 317	Does not exist	
Power Supply		
Instance on Room 317	Inspected	
Instructor Unit		
Instance on Room 317	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Meter Demonstration Unit		
Instance on Room 317	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Student Unit		
Instance on Room 317	Does not exist	
Projection System		
Instance on Room 317	Does not exist	
SCIENCE PREP ROOM	Inspected	
Instance on Rooms 204, 304	Inspected	
110001100 011 10001110 20 1, 50 1		

Building Condition Assessment Survey 2023-2024

ricui inspection	
Question	Response
SCIENCE PREP ROOM	
Power Panel?	No
Alternative Use	No
Lighting	1,0
Instance on Rooms 204, 304	Inspected
Lighting Fixture - Fluorescent	1
Instance on Rooms 204, 304	Inspected
Pendant Mounted	
Instance on Rooms 204, 304	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	140 deficiencies recorded
Instance on Rooms 204, 304	Does not exist
	Does not exist
Recessed Mounted	D (')
Instance on Rooms 204, 304	Does not exist
Lighting Fixture - HID	
Instance on Rooms 204, 304	Does not exist
Lighting Fixture - Incandescent	
Instance on Rooms 204, 304	Does not exist
Lighting Fixture - LED	
Instance on Rooms 204, 304	Does not exist
Emergency Gas Shut-Off Valve	
Instance on Rooms 204, 304	Does not exist
Emergency Shut-Off Power	
Instance on Rooms 204, 304	Does not exist
Power Supply	
Instance on Rooms 204, 304	Does not exist
SWIMMING POOL	Does not exist
TOILET ROOM - STAFF	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - Heandescent Lighting Fixture - LED	Does not exist
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded

Building Condition Assessment Survey 2023-2024

rical Inspection	M16
Question	Response
TOILET ROOM - STUDENT	
Lighting	
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
EMERGENCY DC STANDBY BATTERY POWER	Does not exist
EMERGENCY GENERATOR SET	Does not exist
	Inspected
EMERGENCY LIGHT/EXIT LIGHT PANEL Condition	3- Fair
Deficiency Deficiency Location/Instance	LESS THAN 20% SPARE CIRCUIT BREAKERS Electrical Room
Deficiency Quantity	Electrical Room
Quantity Uom	EACH
Potential Action	INSTALL NEW PANEL BOARD
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded
EMERGENCY LIGHTING	Inspected
Battery Pack	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Non Battery Pack	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
EXIT LIGHT	Inspected
	Inspected
Battery Pack Condition	3- Fair
Deficiency	BATTERY NOT OPERATIONAL
Deficiency Location/Instance	Gymnasium, Corridor near Cafeteria, By Stair B/2
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE BATTERY
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded
Non Battery Pack	Does not exist
EXIT/EMERGENCY LIGHT	Does not exist
FIRE ALARM SYSTEM	Inspected
Bell/Horn	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Strobe	Does not exist
Manual Pull Station	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Fan Shutdown Control	Does not exist
Duct Smoke Detector	Does not exist
Area Smoke Detector	Does not exist
CO Detector	Does not exist
Heat Detector	Does not exist

Building Condition Assessment Survey 2023-2024

an inspection		1711(
estion	Response	
RE ALARM SYSTEM		
Magnetic Door Holder/Contactor	Does not exist	
Fused Cutout Panel	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Fire Alarm Digital Communicator	Does not exist	
Main Panel	Inspected	
Bell At Panel	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Electronic)	Does not exist	
Fire Alarm Control Panel (Standard)	Inspected	
Instance	Boiler Room	
Instance Condition	5- Poor	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	ACME	
EquipmentId	Fire Alarm	
Installation Year	1955	
Source of Installation Year	Documented	
Deficiency	PANEL DEFECTIVE	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 6	
Violations	No violations recorded	
Sub-Panel	Inspected	
Bell At Panel	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Electronic)	Does not exist	
Fire Alarm Control Panel (Standard)	Inspected	
Instance	Boiler Room	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	ACME	
EquipmentId	Sprinkler Alarm	
Installation Year	1955	
Source of Installation Year	Documented	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	Boiler Room	
Deficiency Quantity	157,000	
Quantity Uom	S.F.	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Instance	Boiler Room	
Instance Condition	3- Fair	
Instance Quantity	1	_
· · · · · · · · · · · · · · · · · · ·	EACH	
Instance Quantity Uom		
Instance Quantity Uom Manufacturer	ACME	

Building Condition Assessment Survey 2023-2024

Question	Response
FIRE ALARM SYSTEM	**************************************
Sub-Panel	
Fire Alarm Control Panel (Standard)	
Installation Year	1955
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	157,000
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Remote Annunciator	Inspected Does not exist
Display Monitor	
Panel	Does not exist
Printer	Does not exist
Punch Register	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Sprinkler Flow/Air Pressure Switch	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Tamper Flow Switch/Chain	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
GROUNDING SYSTEM	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
INTERCOM SYSTEM	Does not exist
LAN	Inspected
Local Distribution Frame (I/LDF)	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	Does not exist
MOTOR CONTROLLER	Inspected
MOTOR CONTROL CENTER	Does not exist
MOTOR STARTER/CONTACTOR	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Variable Frequency Drive	Does not exist
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Boiler Room
Deficiency Location/instance Deficiency Quantity	1
Quantity Uom	I EACH
Potential Action	
	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2

Building Condition Assessment Survey 2023-2024

uestion	Response
	Kesponse
PANEL BOARD	
Fused Disconnect Switch Type	N 11.
Violations	No violations recorded
Fused Knife Switch Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Boiler Room, Basement Mechanical Room, Gymnasium Mechanical Room
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Fused Toggle Switch Type	Does not exist
Molded Case Circuit Breaker Type	Inspected
Condition	2- Between Good and Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Kitchen, Gymnasium, 1st Floor Corridor
Deficiency Quantity	7
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	NO SPARE
Deficiency Location/Instance	Corridor near Rooms B7, 220
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	INSTALL NEW PANEL BOARD
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
PUBLIC ADDRESS SYSTEM	Inspected
Instance	General Office - Room 121
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Dukane 125
Installation Year	1995
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
SECURITY	Inspected
IPDVS/CCTV System	Inspected 3- Fair
Condition Installation Year	2011
Source of Installation Year	Documented
	No deficiencies recorded
Deficiency	
Intrusion Alarm System Control Control Bonol	Inspected Inspected
Central Control Panel	
Instance	Custodian's Office - Room 123
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH

Liectrical Inspection	MIO

uestion	Response	
SECURITY		
Intrusion Alarm System		
Central Control Panel		
Installation Year	2005	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Infrared Sensor	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Panic Switch	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Remote Annunciator	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Siren/Strobe	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Lighting - Security	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
SERVICE SWITCH	Inspected	
Instance	Electrical Room	
Instance Condition	2- Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Cutler Hammer	
EquipmentId	Main Service Disconnect	
Capacity/Size Quantity	2500	
Capacity/Size UOM	Amps	
Source of Capacity/Size	Nameplate	
Installation Year	2009	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Instance	Electrical Room	
Instance Condition	1- Good	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	All City Switchboard	
EquipmentId	Solar Switch	
Capacity/Size Quantity	800	
Capacity/Size UOM	Amps	
Source of Capacity/Size	Nameplate 2023	
Installation Year Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
SWITCHBOARD Number of Spares	Inspected 3	
Number of Spares Fused Disconnect Switch Type	Inspected	
Instance	Electrical Room	
Instance Condition	2- Between Good and Fair	
Instance Condition Instance Quantity	1	
	EACH	
Instance Quantity Uom	EACH	

Building Condition Assessment Survey 2023-2024

Question	Response	
SWITCHBOARD		
Fused Disconnect Switch Type		
EquipmentId	N/A	
Capacity/Size Quantity	2500	
Capacity/Size UOM	Amps Total	
Capacity/Size 2 Quantity	3	
Capacity/Size 2 UOM	Section(s)	
Source of Capacity/Size	Nameplate	
Installation Year	2009	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Fused Knife Switch Type	Does not exist	
Molded Case Circuit Breaker Type	Does not exist	
TELEPHONE SYSTEM	Inspected	
PBX/Intercom	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Standard	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
TRANSFORMER	Inspected	
Instance	Ejector Pump Room	
Instance Condition	1- Good	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Hammond	
EquipmentId	Solar Transformer	
Capacity/Size Quantity	225	
Capacity/Size UOM	kVA	
Source of Capacity/Size	Nameplate	
Installation Year	2023	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	