Building Condition Assessment Survey 2023-2024

Asset:	HEALTH PROFESSIONS HS (OL STY) - MANHAT	ΓAN, 345 EAST 15 ST	REET, MANHATTAN, NY, 1	0003
Inspection Id	Inspection Type		Time In	Last Edited
713	MECHANICAL		2023-11-02 08:14AM	2024-01-02 08:37PN
set Data				
Question		Answer		
Have any Syste	ms/Major Building Components been upgraded?	Systems:	Water Service	
		Years:	2023	
		Systems:	Terminal Unit Thermostatic Trap Drip Traps (~80%); Drinking Fo	* **
		Years:	2022	,
		Systems:	Electric Domestic Water Heater	n Kitchen (1 of 2)
		Years:	2021	
		Systems:	MDF Room - Dedicated A/C Equation Split Systems)	uipment Room (DX
		Years:	2019	
		Systems:	Domestic Hot Water Remote Sto	rage Tank
		Years:	2018	
		Systems:	Fixtures - Toilets, Urinals (excep Toilet Room)	t in 1st Floor Staff
		Years:	2015	
		Systems:	Sprinkler Heads (~60%)	
		Years:	2013	
Are there fuel to	anks?	No		
Total # of water	main service entries to the asset	3		
MERs/Fan Roo	oms Locations		ment - Steam Room; North Basement to Steam Room, Girls Locker Room	
Are there any s	paces with Missing or Defective CO Detectors?	Yes		
Location(s)			n 421, Science Demo Rooms 207,	
			508; Science Lab 110, 112, 309; Science Lab 110, 300; Science Lab 11	cience Prep Rooms
A 41 TO	1. 1/01 · · · 10 · · 11 · II · 10	Room 315 Yes	oB, 521B	
Are there any P Location(s)	ainted/Obstructed Sprinkler Heads?		m Stage, Auditorium Dressing Roo	ome Auditorium
Location(s)			t, Rooms 322A, 322B 421, 421A,	*
Are there any E	mergency Stop Switches with Missing Hammers?	No compo		.212 (painted, 20)
ority Conditi	ion	1		

Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image
Yes	Other	Defective (1)	Science Lab - Eye Wash	Room 309	ERIC THORESE N	Custodian	
Yes	Other	Defective (2)	Science Demo Room - Eye Wash	Rooms 207, 307	ERIC THORESE N	Custodian	
Yes	Defective Kitchen Gas System	By-pass Valve of Master Gas Control Valve is in open position	Gas System	North Basement - Steam Room	ERIC THORESE N	Custodian	

Building Condition Assessment Survey 2023-2024

Mechanical Inspection M475

Yes Other Defective Steam Relief Steam North ERIC Custodian No Photo Taken Valves (2) Supplied by Basement -THORESE External Steam Room N Sources Inspection

question	Response
Techanical	
AIR CONDITIONING	Does not exist
CENTRAL ACID WASTE NEUTRALIZING TANK	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
CLIMATE CONTROL SYSTEM	Inspected
BMS	Does not exist
Pneumatic System	Does not exist
Hybrid System	Does not exist
Electric System	Inspected
Instance	Throughout except Auditorium and Gymnasium
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Building Area Covered by Operational System	81-100%
Deficiency	DEFECTIVE TERMINAL UNIT CONTROL VALVE
Deficiency Location/Instance	Rooms 211, 515, 521 and Other Locations
Deficiency Quantity	15
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
COMPACTOR	Does not exist
CONVEYING	Inspected
Dumbwaiter	Does not exist
Elevator	Inspected
Condition	3- Fair
Are all the existing elevators operable?	Yes
Deficiency	No deficiencies recorded
Escalator	Does not exist
Non-auditorium Handicap Lift - Vertical	Does not exist
Non-auditorium Handicap Lift - Stair	Does not exist
Ash Hoist	Does not exist
Sidewalk Elevator	Does not exist
DOMESTIC WATER SYSTEM	Inspected
Domestic Cold Water System	Inspected
Gravity System	Does not exist
Pressure Booster System	Inspected
Electric Pressure Booster System	Inspected
Instance	North Basement - Workshop
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Canariis
EquipmentId	N/A
Capacity/Size Quantity	3
Capacity/Size UOM	Total # Pumps
Capacity/Size 2 Quantity	23

Mechanical Inspection		M475
Ouestion	Response	

stion	Response
OMESTIC WATER SYSTEM	
Domestic Cold Water System	
Pressure Booster System	
Electric Pressure Booster System	
Source of Capacity/Size	Documented
Installation Year	2005
Source of Installation Year	Inspector Estimate
Deficiency	DEFECTIVE MOTOR
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Hydraulic/Pneumatic Booster System	Does not exist
Water Service	Inspected
Instance	Sub-Basement - Steam Room; North Basement - Sprinkler/Water
	Meter Room
Instance Condition	1- Good
Instance Quantity	3
Instance Quantity Uom	EACH
Deficiency	No deficiencies recorded
Domestic Hot Water System	Inspected
Domestic Hot Water Remote Storage Tank	Inspected
Condition Condition	1- Good
	No deficiencies recorded
Deficiency	
Domestic Water Heat Exchanger	Inspected
Condition	5- Poor
Deficiency	DETERIORATED
Deficiency Location/Instance	North Basement - Steam Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Electric Domestic Water Heater	Inspected
Condition	2- Between Good and Fair
Deficiency	DEFECTIVE
Deficiency Location/Instance	Room 315 (1 of 2)
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Gas Fired Domestic Water Heater	Does not exist
	Does not exist Does not exist
Oil Fired Domestic Water Heater	Does not exist Does not exist
Heat Pump Domestic Water Heater	
Oomestic Water Distribution Piping	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE/LEAKS
Deficiency Location/Instance	Gymnasium - Running Track, Rooms 307
Deficiency Quantity	20
Quantity Uom	L.F.
Potential Action	REPLACE

Building Condition Assessment Survey 2023-2024

nestion	Response
DOMESTIC WATER SYSTEM	
Domestic Water Distribution Piping	
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	DEFECTIVE BACKFLOW PREVENTER
Deficiency Location/Instance	North Basement - Steam Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
DRAIN/WASTE/VENT AND STORM SYSTEM	Inspected
Interior Storm Piping	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE/LEAKS
Deficiency Location/Instance	Gymnasium - Running Track, Room 522D
Deficiency Quantity	20
Quantity Uom	L.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Sewage/Waste/Vent Piping	Inspected
Condition	3- Fair
Deficiency	SEWAGE/WASTE PIPING:DEFECTIVE/LEAKS
Deficiency Location/Instance	Gymnasium - Running Track, Rooms 213, 319, 419, 519, North
	Basement - Steam Room
Deficiency Quantity	60
Quantity Uom	L.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	INTERIOR FLOOR DRAIN: DEFECTIVE
Deficiency Location/Instance	Kitchen, North Basement - Sprinkler/Water Meter Room
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	SEWAGE/WASTE PIPING:CLOGGED
Deficiency Location/Instance	Locker Room Toilet Rooms, North Basement - Workshop Room,
,	Sprinkler/Water Meter Room
Deficiency Quantity	75
Quantity Uom	L.F.
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
	Does not exist
Sewage Ejector Pump	Inspected
Sump Pump Condition	4- Between Fair and Poor
Deficiency	DEFECTIVE/DETERIORATED

Building Condition Assessment Survey 2023-2024

estion	Response
RAIN/WASTE/VENT AND STORM SYSTEM	
Sump Pump	
Deficiency Location/Instance	Sub Basement - Steam Room, North Basement - Steam Room (2
	of 3)
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
UAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)	Does not exist
IXTURES	Inspected
Staff And Other	Inspected
Janitor Sink	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lavatory/Sink	Inspected
Condition	2- Between Good and Fair
Deficiency	CRACKED/PHYSICAL DAMAGE
Deficiency Location/Instance	Room 419B
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Toilet	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Urinal	Inspected
Condition	2- Between Good and Fair
	No deficiencies recorded
Deficiency	
Student	Inspected Inspected
Drinking Fountain	1
Condition	2- Between Good and Fair
Deficiency	DEFECTIVE AUXILIARY (FAUCET, SHUT OFF
Deficiency Location/Instance	VALVE,ETC.)
Deficiency Location/instance Deficiency Quantity	Corridor near Room 508
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	CLOGGED/LEAKING
Deficiency Location/Instance	Corridor near Room 518
Deficiency Location/instance Deficiency Quantity	Corridor near Room 518
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Purpose of Action Violations	No violations recorded
	INO VIOIAUOUS IECOIDEU
Lavatory/Sink	Inspected

Building Condition Assessment Survey 2023-2024

nicui Inspecuon	1914 /
estion	Response
IXTURES	
Student	
Lavatory/Sink	
Deficiency	DEFECTIVE AUXILIARY (FAUCET, SHUT OFF VALVE,ETC.)
Deficiency Location/Instance	4th Floor Boy's Toilet Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	CRACKED/PHYSICAL DAMAGE
Deficiency Location/Instance	2nd Floor Girl's Toilet Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Locker Room Shower	Inspected
Instance on Basement - Boys	Inaccessible
Instance on Basement - Girls	Inaccessible
Sink And Fountain Combo Unit	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Toilet	Inspected
Condition	2- Between Good and Fair
-	
Deficiency	DEFECTIVE FLUSHOMETER VALVE
Deficiency Location/Instance Deficiency Quantity	Girls Looker Room Toilet Room
	2 FACH
Quantity Uom Potential Action	EACH MAINTENANCE
	PRIORITY 3
Urgency of Action Purpose of Action	LEVEL 2
•	
Violations	No violations recorded
Urinal	Inspected
Condition	2- Between Good and Fair
Deficiency	CRACKED/PHYSICAL DAMAGE
Deficiency Location/Instance	Boys Locker Room Toilet Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
AS FIRED FURNACE	Does not exist
AS SERVICE	Inspected
Gas Distribution Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Gas Meter Room Exhaust Fan	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
	Does not exist

Building Condition Assessment Survey 2023-2024

unicui Inspeciion	1914
uestion	Response
GAS SERVICE	
Gas Pressure Booster	Does not exist
CO/Gas Leak Detection	Does not exist
HEATING	Inspected
Heating Coil In Ductwork	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Hydronic Heating	Does not exist
Radiator/Convector/Fin Tube	Inspected
Condition	3- Fair
Deficiency	AUXILIARY (VALVE, VENT): DEFECTIVE
Deficiency Location/Instance	Stairs and other locations
Deficiency Quantity	16
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	RADIATOR/CONVECTOR: DAMAGED GUARD/SHIELD
Deficiency Location/Instance	Corridor near Rooms 418, 515
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	RADIATOR/CONVECTOR:DEFECTIVE/DETERIORATED
Deficiency Location/Instance	Rooms 211, 320B, 515 and Other Location
Deficiency Quantity	12
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Steam Heating	Inspected
F&T/Steam Drip Trap	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
MER Steam and Condensate Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Steam Condensate Return Piping	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE/LEAKS
Deficiency Location/Instance	North Basement - Steam Room
Deficiency Quantity	10
Quantity Uom	L.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
	DEFECTIVE VALVE
Deficiency Location/Instance	DEFECTIVE VALVE Basement Firemen Office
Deficiency Location/Instance Deficiency Quantity	Basement Firemen Office 1
	I EACH
Quantity Uom	

Building Condition Assessment Survey 2023-2024

hanical Inspection		M47
Question	Response	
HEATING		
Steam Heating		
Steam Condensate Return Piping		
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Steam Condensate Return Pumping System	Inspected	
Condition	3- Fair	
Deficiency	DEFECTIVE PUMP	
Deficiency Location/Instance	Sub Basement - Steam Room	
Deficiency Quantity	3	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Deficiency	DEFECTIVE CONTROLS	
Deficiency Location/Instance	Sub Basement - Steam Room	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPAIR	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Deficiency	DEFECTIVE	
Deficiency Location/Instance	North Basement - Steam Room	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 3	

Deficiency	DEFECTIVE
Deficiency Location/Instance	North Basement - Steam Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Steam Piping	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE/LEAKS
Deficiency Location/Instance	4th Floor Boys and Girls Toilet Rooms, Rooms 318, 414, 503,
	507, Girl's Shower Room, Cafeteria Classroom, Basement
	Corridor near Paint Room, Girls Locker Room
Deficiency Quantity	90
Quantity Uom	L.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	DEFECTIVE VALVE
Deficiency Location/Instance	Sub Basement - Steam Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Ferminal Unit Thermostatic Trap	Inspected
Condition	1- Good

No deficiencies recorded

Inspected

Deficiency

Steam supplied by External Sources

Building Condition Assessment Survey 2023-2024

iestion		Response
HEATING		
	ed by External Sources	
Condition	ed by External Sources	3- Fair
-	ciency	DEFECTIVE STEAM RELIEF VALVE
	eficiency Location/Instance	North Basement - Steam Room
	eficiency Quantity	2
	uantity Uom	EACH
	tential Action	REPLACE
	gency of Action	PRIORITY 5
	rpose of Action	LEVEL 6
	olations	No violations recorded
	Cabinet Heater	Inspected
Condition	admet neater	4- Between Fair and Poor
-	oi am arr	DEFECTIVE
	ciency	Main Entrance, Locker Rooms
	ficiency Location/Instance efficiency Quantity	Main Entrance, Locker Rooms 8
		o EACH
	nantity Uom tential Action	MAINTENANCE
		PRIORITY 3
	gency of Action rpose of Action	LEVEL 2
	olations	No violations recorded
HEATING PLA	ANT	Does not exist
Enclosed IDF R	Room	Does not exist
KITCHEN		Inspected
Insta	nce on 2nd Floor	Inspected
CO Detector		
	nce on 2nd Floor	Inspected
	nce Condition	3- Fair
	ciency	No deficiencies recorded
	ciclicy	140 deficiencies recorded
Gas System	nce on 2nd Floor	Tuomostod
		Inspected
	nce Condition	4- Between Fair and Poor
	ciency	DEFECTIVE MASTER GAS CONTROL VALVE
	eficiency Location/Instance	North Basement - Steam Room
	eficiency Quantity	1
	aantity Uom	EACH
	tential Action	MAINTENANCE
	gency of Action	PRIORITY 5
	rpose of Action	LEVEL 6
	olations	No violations recorded
Grease Trap		
Insta	nce on 2nd Floor	Does not exist
Hood		
Insta	nce on 2nd Floor	Inspected
	nce Condition	3- Fair
Defic	ciency	No deficiencies recorded
Hood Exhaus	t Ductwork	
	nce on 2nd Floor	Inspected
Insta	nce Condition	3- Fair
	ciency	No deficiencies recorded
Hood Exhaus	-	
-	nce on 2nd Floor	Inspected
		3- Fair
	nce Condition	3- 1 411
	ciency	No deficiencies recorded

Mechanical Inspection	M475
-----------------------	------

unicui Inspection	IVIT/.
uestion	Response
KITCHEN	
Hood Fire Suppression System	
Instance on 2nd Floor	Does not exist
Hot Water Temperature Booster	
Instance on 2nd Floor	Does not exist
Kitchen Sink	
Instance on 2nd Floor	Inspected
Instance Condition	3- Fair
Deficiency	DEFECTIVE
Deficiency Location/Instance	Kitchen (2 of 3)
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	Missing Air Gap
Deficiency Location/Instance	Kitchen
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 4
Violations	SF90373
Deficiency	DEFECTIVE AUXILIARY (FAUCET, SHUT OFF
	VALVE,ETC.)
Deficiency Location/Instance	Kitchen (1 of 3)
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
MDF Room	Inspected
Instance on Room 213B	Inspected
Dedicated A/C Equipment	
Instance on Room 213B	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
SCIENCE DEMO ROOM	Inspected
Instance on Rooms 207, 307	Inspected
Alternative Use	No
Instance on Room 507	Inspected
Alternative Use	
	No
Instance on Rooms 407, 508	Inspected
Alternative Use	No
Instance on Rooms 213, 214, 313, 314	Inspected
Alternative Use	No
Acid Waste Neutralizing Tank	
Instance on Rooms 207, 307	Does not exist
Instance on Room 507	Does not exist
Instance on Rooms 407, 508	Does not exist
Instance on Rooms 213, 214, 313, 314	Does not exist
CO Detector	

Building Condition Assessment Survey 2023-2024

uestion	Response	
	Response	
SCIENCE DEMO ROOM		
CO Detector Instance Condition	4- Between Fair and Poor	
Deficiency	DEFECTIVE/MISSING	
Deficiency Location/Instance	Rooms 207, 307	
Deficiency Quantity	2	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 6	
Violations	No violations recorded	
Instance on Room 507	Not required	
Instance on Rooms 407, 508	Inspected	
Instance Condition	4- Between Fair and Poor	
Deficiency	DEFECTIVE/MISSING	
Deficiency Location/Instance	Rooms 407, 508	
Deficiency Quantity	2	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 6	
Violations	No violations recorded	
Instance on Rooms 213, 214, 313, 314	Inspected	
Instance Condition	4- Between Fair and Poor	
Deficiency	DEFECTIVE/MISSING	
Deficiency Location/Instance	Rooms 213, 214, 313, 314	
Deficiency Quantity	4	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 6	
Violations	No violations recorded	
Emergency Shower		
Instance on Rooms 207, 307	Does not exist	
Instance on Room 507	Does not exist	
Instance on Rooms 407, 508	Does not exist	
Instance on Rooms 213, 214, 313, 314	Does not exist	
Eye Wash		
Instance on Rooms 207, 307	Inspected	
Instance Condition	4- Between Fair and Poor	
Deficiency	DEFECTIVE	
Deficiency Location/Instance	Rooms 207, 307	
Deficiency Quantity	2	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 5	
Purpose of Action Violations	LEVEL 6 No violations recorded	
Instance on Room 507	Does not exist	
Instance on Rooms 407, 508	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Rooms 213, 214, 313, 314	Inspected	
Instance Condition	3- Fair	

No deficiencies recorded

Deficiency

uestion		Response	
	CE DEMO ROOM	жэронэс	
	Exhaust Ductwork		
пооц	Instance on Rooms 207, 307	Does not exist	
	Instance on Room 507	Does not exist	
	Instance on Rooms 407, 508	Does not exist	
	Instance on Rooms 213, 214, 313, 314	Does not exist	
Hood	Exhaust Fan	Does not exist	
11000	Instance on Rooms 207, 307	Does not exist	
	Instance on Room 507	Does not exist	
	Instance on Rooms 407, 508	Does not exist	
	Instance on Rooms 213, 214, 313, 314	Does not exist	
Fived	Laboratory Hood	Does not exist	
Fixeu	Instance on Rooms 207, 307	Does not exist	
	Instance on Room 507	Does not exist	
	Instance on Rooms 407, 508	Does not exist	
	Instance on Rooms 213, 214, 313, 314	Does not exist	
Lahor	ratory Sink	Does not exist	
Labor	Instance on Rooms 207, 307	Inspected	
	Instance Condition	3- Fair	
	Deficiency	No deficiencies recorded	
	Instance on Room 507	Inspected	
	Instance Condition	3- Fair	
	Deficiency	No deficiencies recorded	
	Instance on Rooms 407, 508	Inspected	
	Instance Condition	3- Fair	
	Deficiency	No deficiencies recorded	
	Instance on Rooms 213, 214, 313, 314	Inspected	
	Instance Condition	3- Fair	
	Deficiency	No deficiencies recorded	
Maka	-up Air Unit	no deficiencies recorded	
Make-	Instance on Rooms 207, 307	Does not exist	
	Instance on Room 507	Does not exist	
	Instance on Rooms 407, 508	Does not exist	
	Instance on Rooms 213, 214, 313, 314	Does not exist	
COLENA		Inspected	
SCIENC	CE LAB Instance on Room 309	-	
		Inspected	
	Alternative Use	No Ingraetad	
	Instance on Rooms 110, 112	Inspected	
	Alternative Use	No	
	Instance on Rooms 315, 521	Inspected	
	Alternative Use	No	
Acid V	Waste Neutralizing Tank	B	
	Instance on Room 309	Does not exist	
	Instance on Rooms 110, 112	Does not exist	
	Instance on Rooms 315, 521	Does not exist	
CO D	Instance on Room 309	Towns and	
		Inspected	
	Instance Condition	4- Between Fair and Poor	
	Deficiency Deficiency Location/Instance	DEFECTIVE/MISSING Room 309	
	Deficiency Location/Instance Deficiency Quantity		
		1 FACH	
	Quantity Uom Potential Action	EACH MAINTENANCE	
	LOTERIAL ACTION		

Question	Response	
SCIENCE LAB		
CO Detector		
Purpose of Action	LEVEL 6	
Violations	No violations recorded	
Instance on Rooms 110, 112	Inspected	
Instance Condition	4- Between Fair and Poor	
Deficiency	DEFECTIVE/MISSING	
Deficiency Location/Instance	Rooms 110, 112	
Deficiency Quantity	2	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 6	
Violations	No violations recorded	
Instance on Rooms 315, 521	Inspected	
	3- Fair	
Instance Condition		
Deficiency	No deficiencies recorded	
Emergency Shower		
Instance on Room 309	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Rooms 110, 112	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Rooms 315, 521	Does not exist	
Eye Wash		
Instance on Room 309	Inspected	
Instance Condition	3- Fair	
Deficiency	DEFECTIVE	
Deficiency Location/Instance	Room 309 (1 of 2)	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 6	
Violations	No violations recorded	
Instance on Rooms 110, 112	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Rooms 315, 521	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Hood Exhaust Ductwork	140 deficiences recorded	
Instance on Room 309	Does not exist	
Instance on Rooms 110, 112	Inspected 3- Fair	
Instance Condition		
Deficiency	No deficiencies recorded	
Instance on Rooms 315, 521	Does not exist	
Hood Exhaust Fan		
Instance on Room 309	Does not exist	
Instance on Rooms 110, 112	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Rooms 315, 521		

Mechanical Inspection	M475
Question	Response

Question	Response
SCIENCE LAB	
Fixed Laboratory Hood	
Instance on Room 309	Does not exist
Instance on Rooms 110, 112	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Rooms 315, 521	Does not exist
Laboratory Sink	
Instance on Room 309	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Rooms 110, 112	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Rooms 315, 521	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Make-up Air Unit	
Instance on Room 309	Does not exist
Instance on Rooms 110, 112	Inspected
Instance Condition	3- Fair
Deficiency	DEFECTIVE
Deficiency Location/Instance	Rooms 110, 112
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance on Rooms 315, 521	Does not exist
SCIENCE PREP ROOM	Inspected
Instance on Room 112A/B	Inspected
Alternative Use	No
Instance on Room 213A	Inspected
Alternative Use	Yes
Instance on Rooms 315B, 521B	Inspected
Alternative Use	No
Acid Waste Neutralizing Tank	
Instance on Room 112A/B	Does not exist
Instance on Room 213A	Does not exist
Instance on Rooms 315B, 521B	Does not exist
CO Detector	
Instance on Room 112A/B	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Instance on Room 213A	Not required
Instance on Rooms 315B, 521B	Inspected
Instance Condition	4- Between Fair and Poor
Deficiency	DEFECTIVE/MISSING
Deficiency Cuantity	Rooms 315B, 521B
Deficiency Quantity	2 FACH
Quantity Uom Potential Action	EACH MAINTENANCE
Urgency of Action	PRIORITY 5
07	

Mechanical Inspection		M475
Question	Response	

Question	Response
SCIENCE PREP ROOM	
CO Detector	
Purpose of Action	LEVEL 6
Violations	No violations recorded
Emergency Shower	
Instance on Room 112A/B	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 213A	Does not exist
Instance on Rooms 315B, 521B	Does not exist
Eye Wash	
Instance on Room 112A/B	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 213A	Does not exist
Instance on Rooms 315B, 521B	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Hood Exhaust Ductwork	No deficiencies recorded
Instance on Room 112A/B	Does not exist
Instance on Room 213A	Does not exist
Instance on Rooms 315B, 521B	Does not exist
Hood Exhaust Fan	DOCS HOT CAIST
Instance on Room 112A/B	Does not exist
Instance on Room 213A	Does not exist
Instance on Rooms 315B, 521B	Does not exist
Fixed Laboratory Hood	Does not exist
Instance on Room 112A/B	Does not exist
Instance on Room 213A	Does not exist
Instance on Rooms 315B, 521B	Does not exist
Laboratory Sink	DOCS HOT CAIST
Instance on Room 112A/B	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 213A	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Rooms 315B, 521B	Inspected
Instance Condition	3- Fair
	No deficiencies recorded
Deficiency	No deficiencies recorded
Make-up Air Unit Instance on Room 112A/B	Does not exist
	Does not exist
Instance on Room 213A	
Instance on Rooms 315B, 521B	Does not exist
SPRINKLERS, STANDPIPE, FIRE SYSTEM	Inspected
Dry Sprinkler Alarm Valve Assembly	Does not exist
Wet Sprinkler Alarm Valve Assembly	Inspected 3- Fair
Condition	
Deficiency	No deficiencies recorded
Fire Booster Pump Assembly	Under construction Does not exist
Roof Tank Siamese Connection	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
	110 deficiences recorded

Building Condition Assessment Survey 2023-2024

nestion	Response
SPRINKLERS, STANDPIPE, FIRE SYSTEM	
Sprinkler Head	Inspected
Condition	2- Between Good and Fair
Deficiency	DEFECTIVE/DETERIORATED
Deficiency Location/Instance	Auditorium Stage, Auditorium Dressing Rooms, Auditorium Stage Exit, Rooms 322A, 322B 421, 421A, 421B (painted, 20)
Deficiency Quantity	20
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
Sprinkler Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Standpipe System	Does not exist
Water Gong	Does not exist
SWIMMING POOL	Does not exist
/ENTILATION	Inspected
Is the building Mechanically ventilated?	Partial
Exhaust Fan	Inspected
Condition	3- Fair
Approximate Total # of Fans	26-50
Deficiency	NOT IN USE
Deficiency Location/Instance	Main Roof, Auditorium Roof
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	NO ACTION
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 1
Violations	No violations recorded
Deficiency	DEFECTIVE MOTOR
Deficiency Location/Instance Deficiency Quantity	Main Roof / EF #42
	1 FACIL
Quantity Uom	EACH DEDLAGE
Potential Action	REPLACE
Urgency of Action	PRIORITY 3 LEVEL 2
Purpose of Action	
Violations	No violations recorded
Deficiency	DEFECTIVE
Deficiency Location/Instance	Sub Basement - Steam Room, North Basement - Steam Room,
Deficiency Quantity	Basement Staff Locker Room, Room 112A/B
	4 EACH
Quantity Uom	EACH MADITENANCE
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3 LEVEL 2
Purpose of Action Violations	
	No violations recorded
Heating And Ventilating Unit	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE
Deficiency Location/Instance	1st Floor near Exit 1, Basement Staff Locker Room
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3

Building Condition Assessment Survey 2023-2024

and the period		
uestion	Response	
VENTILATION		
Heating And Ventilating Unit		
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Metal Ductwork	Inspected	
Condition	3- Fair	
Are there any uninsulated ductwork by design in Mechanical rooms?	Yes	
Are there chain operated dampers?	Yes	
Deficiency	DAMAGED FLEXIBLE CONNECTION	
Deficiency Location/Instance	Boys Locker Room	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Supply Fan	Inspected	
Condition	3- Fair	
Approximate Total # of Fans	1-5	
Deficiency	No deficiencies recorded	
Unit Ventilator	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	