# **Building Condition Assessment Survey 2023-2024**

#### Electrical Inspection

Inspection I	d Inspection Type				Time	In	Last Edited	
	51 ELECTRICAL				-	01-08 08:34AN		
sset Data								
Ouestion				Answer				
<b>C</b>	stems/Major Building	g Components been upgraded?		Systems:	All Electrical	Systems and Co	mnonents	
flave any sy	stems/wajor building	g components occir upgraded:		Years:	2018	by stems and co	mponents	
Type of Serv	vice			Below Gro				
	ctive Whiteboard (IWI	B) Exist?		No				
	ration In Electrical Ro			No				
DEDICAT	ED INTERCOMS	IN FIRE RESCUE AREAS						
Question				R	esponse			
Are there a your build		stance Areas, Fire Rescue Areas, an	nd/or Holding Room	ms in N	0			
riority Cond	dition							
Exist P	Priority	Condition	Component	Location	Person(s)	Person(s)	Photo	
Last Year? O	Category	Description	Affected	Description	Notified	Title	Image	
No condition	n recorded							
nspection								
Question				Response				
Electrical								
	IC FIELD			Does not e	xist			
AUDITO				Does not e				
CAFETE				Does not e				
					A15t			
		ADMINISTRATIVE SPACE		Inspected Inspected				
Lighting Does a	g a Chandelier Exist?			No				
	ing Fixture - Fluores	cent		Does not e	xist			
	ing Fixture - HID			Does not e	xist			
	ing Fixture - Incande	scent		Does not e	xist			
Lighti	ing Fixture - LED			Inspected				
Pend	dant Mounted			Inspected				
Co	ondition			2- Between	n Good and Fai	r		
	Deficiency			No deficie	ncies recorded			
Surf	face Mounted			Inspected				
Co	ondition			2- Between	n Good and Fai	r		
	Deficiency			No deficie	ncies recorded			
Rece	essed Mounted			Inspected				
Co	ondition			2- Between	n Good and Fai	r		
	Deficiency			No deficie	ncies recorded			
COMPUT	FER LAB			Does not e	xist			
GYMNAS	SIUM			Does not e	xist			
KITCHE	N			Inspected				
	Instance on 1st Floor	r		Inspected				
Lighting	-							
	Instance on 1st Floor			Inspected				
Lighti	ng Fixture - Fluores							
	Instance on 1st Floor	r		Does not e	xist			
Lighti	ng Fixture - HID							
	Instance on 1st Floor			Does not e	xist			
Lighti	ng Fixture - Incande			-	• .			
	Instance on 1st Floor	r		Does not e	x1st			

# Building Condition Assessment Survey 2023-2024

### Electrical Inspection

incui Inspection		1471
Question	Response	
KITCHEN		
Lighting		
Lighting Fixture - LED		
Instance on 1st Floor	Inspected	
Pendant Mounted		
Instance on 1st Floor	Does not exist	
Surface Mounted		
Instance on 1st Floor	Does not exist	
Recessed Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
LIBRARY	Does not exist	
LOCKER ROOM	Does not exist	
MULTIPURPOSE ROOM	Inspected	
Instance on Room 125	Inspected	
Lighting		
Instance on Room 125	Inspected	
Lighting Fixture - Fluorescent		
Instance on Room 125	Does not exist	
Lighting Fixture - HID		
Instance on Room 125	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 125	Does not exist	
Lighting Fixture - LED		
Instance on Room 125	Inspected	
Pendant Mounted		
Instance on Room 125	Does not exist	
Surface Mounted		
Instance on Room 125	Does not exist	
Recessed Mounted		
Instance on Room 125	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Local Sound System		
Instance on Room 125	Does not exist	
Projection System		
Instance on Room 125	Does not exist	
Theater Lighting System Instance on Room 125	Does not exist	
	Does not exist	
SCIENCE DEMO ROOM		
SCIENCE LAB	Does not exist	
SCIENCE PREP ROOM	Does not exist	
SWIMMING POOL	Does not exist	
TOILET ROOM - STAFF	Inspected	
Lighting	Inspected	
Lighting Fixture - Fluorescent	Does not exist	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Inspected	
Pendant Mounted	Does not exist	
Surface Mounted	Does not exist	
Recessed Mounted	Inspected	

## **Building Condition Assessment Survey 2023-2024**

### **Electrical Inspection**

rical Inspection		M49
uestion	Response	
TOILET ROOM - STAFF		
Lighting		
Lighting Fixture - LED		
Recessed Mounted		
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
TOILET ROOM - STUDENT	Inspected	
Lighting	Inspected	
Lighting Fixture - Fluorescent	Does not exist	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Inspected	
Pendant Mounted	Does not exist	
Surface Mounted	Does not exist	
Recessed Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
AUXILIARY SIGNAL/BELL SYSTEM	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
· ·		
EMERGENCY DC STANDBY BATTERY POWER	Does not exist	
EMERGENCY GENERATOR SET	Does not exist	
EMERGENCY LIGHT/EXIT LIGHT PANEL	Does not exist	
EMERGENCY LIGHTING	Inspected	
Battery Pack	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Non Battery Pack	Does not exist	
EXIT LIGHT	Inspected	
Battery Pack	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Non Battery Pack	Does not exist	
EXIT/EMERGENCY LIGHT	Does not exist	
FIRE ALARM SYSTEM	Inspected	
Bell/Horn	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Strobe	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Manual Pull Station	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Fan Shutdown Control	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Duct Smoke Detector	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Area Smoke Detector	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	

# Building Condition Assessment Survey 2023-2024

### Electrical Inspection

icai Inspection	111471
iestion	Response
FIRE ALARM SYSTEM	
CO Detector	Does not exist
Heat Detector	Does not exist
Elevator Recall	Does not exist
Magnetic Door Holder/Contactor	Does not exist
Fused Cutout Panel	Does not exist
Fire Alarm Digital Communicator	Does not exist
Main Panel	Inspected
Bell At Panel	Does not exist
Fire Alarm Control Panel (Electronic)	Inspected
Instance	Main Entrance Lobby
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Mircom
Model	N/A
EquipmentId	Fire Alarm Control Panel
Installation Year Source of Installation Year	2018
	Documented
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Standard)	Does not exist
Sub-Panel	Does not exist
Remote Annunciator	Inspected Does not exist
Display Monitor Panel	Inspected
	2- Between Good and Fair
Condition	
Deficiency	No deficiencies recorded
Printer	Inspected
Condition	5- Poor
Deficiency	PRINTER NOT OPERATIONAL
Deficiency Location/Instance Deficiency Quantity	Custodian's Office Room 114
Quantity Uom Potential Action	EACH
Urgency of Action	REPLACE PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded
Punch Register	Does not exist
Sprinkler Flow/Air Pressure Switch	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Tamper Flow Switch/Chain	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
GROUNDING SYSTEM	Does not exist
NTERCOM SYSTEM	Does not exist
LAN	Inspected
Local Distribution Frame (I/LDF)	Does not exist
Main Equipment Rack (MDF)	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	Does not exist
MOTOR CONTROLLER	Inspected
MOTOR CONTROL CENTER	Does not exist
MOTOR STARTER/CONTACTOR	Does not exist

# NYC Department of Education Building Condition Assessment Survey 2023-2024

### Electrical Inspection

	IV147
Question	Response
MOTOR CONTROLLER	
Variable Frequency Drive	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Does not exist
Fused Knife Switch Type	Does not exist
Fused Toggle Switch Type	Does not exist
Molded Case Circuit Breaker Type	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
PUBLIC ADDRESS SYSTEM	Inspected
Instance	MDF Room
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Bogen Multicom - 2000
Installation Year	2018
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
SECURITY	Inspected
IPDVS/CCTV System	Inspected
Condition	2- Between Good and Fair
Installation Year	2018
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Intrusion Alarm System	Inspected
Central Control Panel	Inspected
Instance	Custodian's Office
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista 128BPT
Installation Year	2018
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Infrared Sensor	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Panic Switch	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Remote Annunciator	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Siren/Strobe	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
	Does not exist
Lighting - Security	Inaccessible
SERVICE SWITCH	
SWITCHBOARD	Inspected
Number of Spares	5
Fused Disconnect Switch Type	Inspected
Instance	Electrical Room 115

# **Building Condition Assessment Survey 2023-2024**

### **Electrical Inspection**

uestion	Response	
SWITCHBOARD		
Fused Disconnect Switch Type		
Instance Condition	2- Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Siemens	
EquipmentId	MDP	
Capacity/Size Quantity	800	
Capacity/Size UOM	Amps Total	
Capacity/Size 2 Quantity	1	
Capacity/Size 2 UOM	Section(s)	
Source of Capacity/Size	Nameplate	
Installation Year	2018	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Fused Knife Switch Type	Does not exist	
Molded Case Circuit Breaker Type	Does not exist	
TELEPHONE SYSTEM	Inspected	
PBX/Intercom	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Standard	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
TRANSFORMER	Does not exist	