Building Condition Assessment Survey 2023-2024

	MHS SUSPENSI	ON HEARING OFFICE -	MANHATTAN,	209 WEST 125 S	STREET, MA	NHATTAN,	NY, 10027
Inspection Id	Inspection Type				Time	In	Last Edited
240	1 ELECTRICAL				2024-	01-10 09:40AN	M 2024-01-30 09:54AN
set Data							
Question				Answer			
Have any Sys	stems/Major Building C	Components been upgraded?		Systems:	Partial Exit / I	Emergency Ligh	nts
				Years:	2019		
				Systems:	All Other Elec	etrical Systems	and Components
				Years:	2005		
Type of Servi	ice			Below Gro	ound		
	ive Whiteboard (IWB)			Yes			
	ation In Electrical Room			No			
	ED INTERCOMS IN	N FIRE RESCUE AREAS		n			
Question	ny I ifa Dacqua Accieta	nce Areas, Fire Rescue Areas, ar	nd/or Holding Poo		esponse		
your buildin		nce Areas, Fire Researc Areas, ar	id/of Holding Roo.	ins in	.0		
iority Cond	_						
	riority	Condition	Component	Location	Person(s)	Person(s)	Photo
	ategory	Description	Affected	Description	Notified	Title	Image
No condition	recorded						
spection							
Question				Response			
Electrical				Kesponse			
	C FIELD			Does not e	viet		
ATHLETIC							
AUDITOR			Does not exist				
CAFETER				Does not e	xıst		
		MINISTRATIVE SPACE	Inspected				
Lighting	Chandelier Exist?			Inspected No			
-	ng Fixture - Fluorescen			Inspected			
	ant Mounted			Inspected			
	ndition			3- Fair			
-	Deficiency			No deficie	ncies recorded		
	nce Mounted			Inspected			
	ndition			3- Fair			
	Deficiency			No deficie	ncies recorded		
Recessed Mounted			Inspected				
Con	ndition			3- Fair			
Deficiency				No deficie	ncies recorded		
Lightin	g Fixture - HID			Does not e	xist		
Lightin	g Fixture - Incandesco	ent		Does not e	xist		
Lighting Fixture - LED				Inspected			
Pendant Mounted				Does not e	xist		
Surface Mounted				Inspected			
Condition				3- Fair			
Deficiency					ncies recorded		
Recessed Mounted				Does not e	xist		
COMPUTER LAB				Does not e	xist		
COMPUT	IUM			Does not e	xist		
GYMNASI	10111	KITCHEN				-	
GYMNASI				Does not e	xıst		
GYMNASI	I			Does not e			

Building Condition Assessment Survey 2023-2024

cirical Inspection	N1033
Question	Response
SCIENCE DEMO ROOM	Does not exist
SCIENCE LAB	Does not exist
SCIENCE PREP ROOM	Does not exist
SWIMMING POOL	Does not exist
TOILET ROOM - STAFF	Inspected
Lighting	Inspected
Lighting Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not exist
Surface Mounted	Does not exist
Recessed Mounted	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not exist
Surface Mounted	Does not exist
Recessed Mounted	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
EMERGENCY DC STANDBY BATTERY POWER	Does not exist
EMERGENCY GENERATOR SET	Does not exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Does not exist
EMERGENCY LIGHTING	Inspected
Battery Pack	Inspected
Condition	3- Fair No deficiencies recorded
Deficiency	
Non Battery Pack	Does not exist
EXIT LIGHT	Inspected
Battery Pack	Inspected 3- Fair
Condition	
Deficiency	No deficiencies recorded Does not exist
Non Battery Pack	
EXIT/EMERGENCY LIGHT	Inspected 2- Between Good and Fair
Condition	
Deficiency	No deficiencies recorded
FIRE ALARM SYSTEM	Inspected
Bell/Horn	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Strobe	Inspected 3- Fair
Condition	
Deficiency	No deficiencies recorded
Manual Pull Station	Inspected

Building Condition Assessment Survey 2023-2024

etti Inspection		17103
estion	Response	
TIRE ALARM SYSTEM		
Manual Pull Station		
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Fan Shutdown Control	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Duct Smoke Detector	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Area Smoke Detector	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
CO Detector	Does not exist	
Heat Detector	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Elevator Recall	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Magnetic Door Holder/Contactor	Does not exist	
Fused Cutout Panel	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Fire Alarm Digital Communicator	Does not exist	
Main Panel	Inspected	
Bell At Panel	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Electronic)	Inspected	
Instance	2nd Floor Stair Landing	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Notifier	
Model	NFS2-640	
EquipmentId	Fire Alarm Control Panel	
Installation Year	2005	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Standard)	Does not exist	-
Sub-Panel	Does not exist	
Remote Annunciator	Inspected	
Display Monitor	Does not exist	
Panel	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Printer	Does not exist	
Punch Register	Does not exist	
Sprinkler Flow/Air Pressure Switch	Inaccessible	
Tamper Flow Switch/Chain	Inaccessible	
GROUNDING SYSTEM	Inaccessible	
NTERCOM SYSTEM	Inspected	

Building Condition Assessment Survey 2023-2024

icai Inspection		17103
uestion	Response	
INTERCOM SYSTEM		
Elevator		
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Holding Area	Does not exist	
LAN	Inspected	
Local Distribution Frame (I/LDF)	Does not exist	
Main Equipment Rack (MDF)	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
LIGHTNING PROTECTION	Does not exist	
MOTOR CONTROLLER	Inspected	
MOTOR CONTROL CENTER	Does not exist	
MOTOR STARTER/CONTACTOR	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Variable Frequency Drive	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
PANEL BOARD	Inspected	
Fused Disconnect Switch Type	Does not exist	
Fused Disconnect Switch Type Fused Knife Switch Type	Does not exist	
Fused Toggle Switch Type	Does not exist	
Molded Case Circuit Breaker Type	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
PUBLIC ADDRESS SYSTEM	Does not exist	
SECURITY	Inspected	
IPDVS/CCTV System	Inspected	
Condition	4- Between Fair and Poor	
Installation Year	2005	
Source of Installation Year	Documented	
Deficiency	SYSTEM DEFECTIVE	
Deficiency Location/Instance	Room 108	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPAIR SYSTEM	
Urgency of Action	PRIORITY 4	
Purpose of Action	LEVEL 3	
Violations	No violations recorded	
Intrusion Alarm System	Inspected	
Central Control Panel	Inspected	
Instance	3rd Floor Electrical Room	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Model	Vista - 50P	
Installation Year	2005	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Infrared Sensor	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Denciency	no deficiencies recorded	

Building Condition Assessment Survey 2023-2024

rical Inspection	.VIO
uestion	Response
SECURITY	
Intrusion Alarm System	
Remote Annunciator	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Siren/Strobe	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting - Security	Does not exist
SERVICE SWITCH	Inspected
Instance	Basement - Electrical Room
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
	Electrotech
Manufacturer EquipmentId	Stanco Systems 3rd Floor
Equipment Capacity/Size Quantity	600
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2005
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
SWITCHBOARD	Inspected
Number of Spares	3
Fused Disconnect Switch Type	Inspected
Instance	3rd Floor Electrical Room
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Electrotech
EquipmentId	Stanco Systems
Capacity/Size Quantity	600
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	1
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Service Switch Size
Installation Year	2005
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not exist
Molded Case Circuit Breaker Type	Does not exist
FELEPHONE SYSTEM	Inspected
PBX/Intercom	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Standard	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
TRANSFORMER	Does not exist