Building Condition Assessment Survey 2023 - 2024

Inspection Id Inspection Type	Time In	Last Edited
EE: Q346 Electrical	2023-11-29 12:14 PM	2023-12-12 4:31 PM
sset Data		
Question	Answer	
Type of Service	Below Ground	
Does Interactive Whiteboard (IWB) Exist?	Yes	
Water Penetration in Electrical Room?	No	
Have any Systems/Major Building Components been upgraded?	Yes	
	Systems: All Electrical Systems and Con	nponents
DEDICATED DIFFER COMO DI FIDE DESCRIE ADEAS	Years: 2023	
DEDICATED INTERCOMS IN FIRE RESCUE AREAS Overtice	Dognongo	
Question Are there any Life Rescue Assistance Areas, Fire Rescue Areas,	Response No	
and/or Holding Rooms in your building?		
riority Condition		
Priority Priority Condition Component Location Condition Exist Category Description Affected Descript Last Year?	* /	PhotoImage
No condition recorded		
nspection		
Question	Response	
Electrical		
AUDITORIUM	Does not Exist	
CAFETERIA	Does not Exist	
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected	
Lighting	Inspected	
Does a Chandelier exist?	No	
Lighting Fixture - Fluorescent	Does not Exist	
Lighting Fixture - HID	Does not Exist	
Lighting Fixture - Incandescent	Does not Exist	
Lighting Fixture - LED	Inspected	
Pendant Mounted	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Surface Mounted	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Recessed Mounted	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
COMPUTER LAB	Does not Exist	
GYMNASIUM	Does not Exist	
KITCHEN	Inspected	
Instance on Basement	Inspected	
Lighting	Inspected	
Instance on Basement	Inspected	
Lighting Fixture - Fluorescent		

Building Condition Assessment Survey 2023 - 2024

Question	Response
KITCHEN	
Lighting	
Lighting Fixture - HID	
Instance on Basement	Does not Exist
Lighting Fixture - Incandescent	
Instance on Basement	Does not Exist
Lighting Fixture - LED	
Instance on Basement	Inspected
Pendant Mounted	Does not Exist
Instance on Basement	Does not Exist
Surface Mounted	Does not Exist
Instance on Basement	Does not Exist
Recessed Mounted	Inspected
Instance on Basement	Inspected
Condition	1 - Good
Deficiency LIBRARY	No deficiencies recorded Does not Exist
LOCKER ROOM	Does not Exist
	Does not Exist Does not Exist
MULTIPURPOSE ROOM	
SCIENCE DEMO ROOM	Does not Exist
SCIENCE LAB	Does not Exist
SCIENCE PREP ROOM	Does not Exist
SWIMMING POOL	Does not Exist
TOILET ROOM - STAFF	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Does not Exist
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Inspected
Pendant Mounted	Does not Exist
Surface Mounted	Does not Exist
Recessed Mounted	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Does not Exist
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Inspected
Pendant Mounted	Does not Exist
Surface Mounted	Does not Exist
Recessed Mounted	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
Replacement Quantity	15,000
Replacement Uom	S.F.

Building Condition Assessment Survey 2023 - 2024

Question	Response
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
EMERGENCY DC STANDBY BATTERY POWER	Does not Exist
EMERGENCY GENERATOR SET	Does not Exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Does not Exist
EMERGENCY LIGHTING	Inspected
Battery Pack	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Non Battery Pack	Does not Exist
EXIT LIGHT	Inspected
Battery Pack	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Non Battery Pack	Does not Exist
EXIT/EMERGENCY LIGHT	Does not Exist
FIRE ALARM SYSTEM	Inspected
Replacement Quantity	15,000
Replacement Uom	S.F.
Bell/Horn	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Strobe	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Manual Pull Station	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Fan Shutdown Control	Does not Exist
Duct Smoke Detector	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Area Smoke Detector	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
CO Detector	Does not Exist
Heat Detector	Does not Exist
Elevator Recall	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Magnetic Door Holder/Contactor	Does not Exist
Fused Cutout Panel	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Fire Alarm Digital Communicator	Does not Exist
Main Panel	Inspected
Bell At Panel	Does not Exist
Fire Alarm Control Panel (Electronic)	Inspected

Building Condition Assessment Survey 2023 - 2024

arear inspection		QU.
nestion	Response	
FIRE ALARM SYSTEM		
Main Panel		
Fire Alarm Control Panel (Electronic)		
Instance	Main Entrance Lobby	
Instance Condition	1 - Good	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Instance Manufacturer	Edwards System Technology	
Equipment	Fire Alarm Control Panel	
Model	EST	
Installation Year	2023	
Source of Installation	Documented	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Standard)	Does not Exist	
Sub-Panel	Does not Exist	
Remote Annunciator	Inspected	
Display Monitor	Does not Exist	
Panel	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Printer	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Punch Register	Does not Exist	
Sprinkler Flow/Air Pressure Switch	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Tamper Flow Switch/Chain	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
GROUNDING SYSTEM	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
INTERCOM SYSTEM	Inspected	
Elevator	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Holding Area	Does not Exist	
LAN	Inspected	
Local Distribution Frame (I/LDF)	Does not Exist	
Main Equipment Rack (MDF)	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
LIGHTNING PROTECTION	Does not Exist	
MOTOR CONTROLLER	Inspected	
Motor Control Center	Does not Exist	
Motor Starter/Contactor	Inspected	
Condition		
	1 - Good	

Building Condition Assessment Survey 2023 - 2024

arear mspection	Ye.
nestion	Response
MOTOR CONTROLLER	Inspected
Variable Frequency Drive	Does not Exist
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Does not Exist
Fused Knife Switch Type	Does not Exist
Fused Toggle Switch Type	Does not Exist
Molded Case Circuit Breaker Type	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
PUBLIC ADDRESS SYSTEM	Inspected
Replacement Quantity	15,000
Replacement Uom	S.F.
Instance	Telecom Room 202
Instance Condition	1 - Good
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Telecor XL
Installation Year	2023
Source of Installation	Documented
Deficiency	No deficiencies recorded
SECURITY	Inspected
IPDVS/CCTV System	Inspected
Replacement Quantity	15,000
Replacement Uom	S.F.
Installation Year	2023
Source of Installation	Documented
Condition	1 - Good
Deficiency	No deficiencies recorded
Intrusion Alarm System	Inspected
Replacement Quantity	15,000
Replacement Uom	S.F.
Central Control Panel	
Instance	Inspected Custodian's Office
Instance Condition	1 - Good
Instance Quantity	1
Instance Quantity Uom	EACH
Model	
Installation Year	Vista-128BPT 2023
Source of Installation	Documented
Deficiency Infrared Sensor	No deficiencies recorded
Condition	Inspected 1 - Good
Deficiency	No deficiencies recorded
Panic Switch	Inspected
Condition	1 - Good
Condition	
Deficiency	No deficiencies recorded
Deficiency Remote Annunciator	No deficiencies recorded Inspected
Deficiency Remote Annunciator Condition	No deficiencies recorded Inspected 1 - Good

Building Condition Assessment Survey 2023 - 2024

Question	Response
SECURITY	
Intrusion Alarm System	Inspected
Siren/Strobe	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Lighting - Security	Inspected
Replacement Uom	EACH
Condition	1 - Good
Deficiency	No deficiencies recorded
SERVICE SWITCH	Inspected
Instance	Electrical Room 109
Instance Condition	1 - Good
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	All City Switchboard
Equipment	800A Service Switch
Capacity/Size Quantity	800
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2023
Source of Installation	Documented
Deficiency	No deficiencies recorded
SWITCHBOARD	Inspected
Number of Spares	1
Fused Disconnect Switch Type	Inspected
Instance	Electrical Room 109
Instance Condition	1 - Good
Instance Quantity	1
Instance Quantity Uom	ЕАСН
Instance Manufacturer	All City Switchboard
Equipment	MDP
Capacity/Size Quantity	800
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	1
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Nameplate
Installation Year	2023
Source of Installation	Documented
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not Exist
Molded Case Circuit Breaker Type	Does not Exist
TELEPHONE SYSTEM	Inspected
PBX/Intercom	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Standard	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
TRANSFORMER	Does not Exist
	DOGG HOT EASIST