NYC Department of Education

Building Condition Assessment Survey 2023 - 2024

Inspection Id Inspection Type	Time In	Last Edited
EE: Q567 Electrical	2024-03-18 7:34 AM	2024-04-11 3:12 F
sset Data		
Question	Answer	
Type of Service	Below Ground	
Does Interactive Whiteboard (IWB) Exist?	No	
Water Penetration in Electrical Room?	No	
Have any Systems/Major Building Components been upgraded?	Yes	
	Systems: All Electrical Systems And Co	mponents
	Years: 2015	
DEDICATED INTERCOMS IN FIRE RESCUE AREAS Opposition	Dagnanga	
Question Are there any Life Rescue Assistance Areas, Fire Rescue Areas,	Response No	
and/or Holding Rooms in your building?	1.0	
iority Condition		
Priority Priority Condition Component Location Condition Exist Category Description Affected Description Last Year?	* /	PhotoImage
No condition recorded		
spection		
Question	Response	
Electrical		
ATHLETIC FIELD	Inspected	
Exterior Lighting	Inspected	
Replacement Uom	EACH	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Local Sound System	Does not Exist	
Scoreboard	Inspected	
Instance	Facing Baseball Field	
Instance Condition	2 - Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Deficiency	No deficiencies recorded	
Instance	Facing Football Field	
Instance Condition	2 - Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Deficiency	No deficiencies recorded	
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Does not Exist	
LOCKER ROOM	Does not Exist	
TOILET ROOM - STAFF	Does not Exist	
TOILET ROOM - STUDENT	Does not Exist	
AUXILIARY SIGNAL/BELL SYSTEM	Does not Exist	
EMERGENCY DC STANDBY BATTERY POWER	Does not Exist	
EMERGENCY GENERATOR SET	Does not Exist	
EMERGENCY LIGHT/EXIT LIGHT PANEL	Does not Exist	
EMERGENCY LIGHTING	Does not Exist	

NYC Department of Education

Building Condition Assessment Survey 2023 - 2024

Electrical Inspection Q567

Question	Response
EXIT LIGHT	
Battery Pack	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Non Battery Pack	Does not Exist
EXIT/EMERGENCY LIGHT	Does not Exist
FIRE ALARM SYSTEM	Does not Exist
GROUNDING SYSTEM	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
LAN	Does not Exist
LIGHTNING PROTECTION	Does not Exist
MOTOR CONTROLLER	Does not Exist
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Does not Exist
Fused Knife Switch Type	Does not Exist
Fused Toggle Switch Type	Does not Exist
Molded Case Circuit Breaker Type	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
PUBLIC ADDRESS SYSTEM	Does not Exist
SECURITY	Inspected
IPDVS/CCTV System	Does not Exist
Intrusion Alarm System	Does not Exist
Lighting - Security	Inspected
Replacement Uom	EACH
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
SERVICE SWITCH	Inspected
Instance	Outdoor Electrical Enclosure
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Siemens
Equipment	Main Disconnect
Capacity/Size Quantity	600
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2015
Source of Installation	Documented
Deficiency	No deficiencies recorded
SWITCHBOARD	Does not Exist
TELEPHONE SYSTEM	Does not Exist
TRANSFORMER	Inspected
Instance	Outdoor Electrical Enclosure
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH

NYC Department of Education

Building Condition Assessment Survey 2023 - 2024

Electrical Inspection Q567

Question	Response
TRANSFORMER	
Instance Manufacturer	Rex Power Magnetics
Equipment	FPP Transformer
Capacity/Size Quantity	225
Capacity/Size UOM	KVA
Source of Capacity/Size	Nameplate
Installation Year	2015
Source of Installation	Documented
Deficiency	No deficiencies recorded