Building Condition Assessment Survey 2023 - 2024

Asset:			QUEENS, 131-10	97TH AVEN	NUE, New York		
Inspection I	d Inspection	Туре				Time In	Last Edited
EE : Q8	65 Electrical					2024-02-28 10:49 AM	2024-03-27 12:37 PN
Asset Data							
Question					Answer		
Type of Service				Below Gro	ound		
Does Interactive Whiteboard (IWB) Exist?					Yes		
Water Penetration in Electrical Room? Have any Systems/Major Building Components been upgraded?					No		
Have any Sys	stems/Major Build	iing Components	been upgraded?		Yes	Conveity Lights	
					Systems:	Security Lights	
					Years: Systems:	2024 LAN	
					Years:	2023	
					Systems:	Public Address System (Clocks) (Local Sound System)	, Multipurpose Room
					Years:	2022	
					Systems:	Telephone System	
					Years:	2017	
					Systems:	Interior Lighting, Exit Lights (B	attery Pack)
					Years:	2016	· .
					Systems:	Intrusion Alarm System (Infrare	ed Sensor, Panic Switch)
					Years:	2013	,
					Systems:	Molded Case Circuit Breaker Ty	pe Panel Board
					Years:	1993, 1998	
					Systems:	All Other Electrical Systems and	d Components
					Years:	1993	
DEDICATE	D INTERCOMS	IN FIRE RESC	UE AREAS				
Question					Response		
	y Life Rescue Ass ng Rooms in you		re Rescue Areas,		No		
Priority Conditi	ion						
Priority Condition Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title Status	PhotoImage
Yes	Fire Alarm System - Components Not Operational	N/A	FIRE ALARM SYSTEM Area Smoke Detector	Room 150	Scott Cosby	Fireman Sent to DSF	
nspection							
Question					Respons	se	
Electrical							
AUDITORIU	U M				Does not	t Exist	
CAFETERIA	4				Does not	t Exist	
CLASSROO	M/CORRIDOR	/ADMINISTRA	TIVE SPACE		Inspecte	d	
Lighting					Inspecte		
	es a Chandelier e	xist?			No		
-	Fixture - Fluore				Inspecte	d	
	nt Mounted				Inspecte		
	dition					een Good and Fair	
	eficiency					riencies recorded	
	e Mounted						
	dition				Inspected	een Good and Fair	
	uruOII					CON COOR AND FAIR	
WSP (P)				Page	1 of 6		Print Date: 6/25/2024

Building Condition Assessment Survey 2023 - 2024

Question	Response
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	
Lighting	
Lighting Fixture - Fluorescent	
Surface Mounted	
Deficiency	No deficiencies recorded
Recessed Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Does not Exist
COMPUTER LAB	Does not Exist
GYMNASIUM	Does not Exist
KITCHEN	Does not Exist
LIBRARY	Does not Exist
LOCKER ROOM	Does not Exist
MULTIPURPOSE ROOM	Inspected
Instance on 1st Floor	Inspected
Lighting	
Instance on 1st Floor	Inspected
	Inspected
Lighting Fixture - Fluorescent	Tournet
Instance on 1st Floor	Inspected
Pendant Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Surface Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Recessed Mounted	Inspected
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID Instance on 1st Floor	Does not Exist
	Does not exist
Lighting Fixture - Incandescent	D
Instance on 1st Floor	Does not Exist
Lighting Fixture - LED	D
Instance on 1st Floor	Does not Exist
Local Sound System	Inspected
Instance on 1st Floor	Inspected
Installation Year	2022
Source of Installation	Documented
Condition	1 - Good
Deficiency	No deficiencies recorded
Projection System	Does not Exist
Instance on 1st Floor	Does not Exist
Theater Lighting System	Does not Exist
Instance on 1st Floor	Does not Exist
SCIENCE DEMO ROOM	Does not Exist
SCIENCE LAB	Does not Exist
SCIENCE PREP ROOM	Does not Exist

Building Condition Assessment Survey 2023 - 2024

Question	Response
SWIMMING POOL	Does not Exist
TOILET ROOM - STAFF	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not Exist
Surface Mounted	Does not Exist
Recessed Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Does not Exist
TOILET ROOM - STUDENT	Inspected
	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not Exist
Surface Mounted	
Condition Condition	Inspected 2 - Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Does not Exist
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
Replacement Quantity	12,000
Replacement Uom	S.F.
Condition	3 - Fair
Deficiency	No deficiencies recorded
EMERGENCY DC STANDBY BATTERY POWER	Does not Exist
EMERGENCY GENERATOR SET	Does not Exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected
Condition Condition	3 - Fair
Deficiency	No deficiencies recorded
EMERGENCY LIGHTING	Inspected
Battery Pack	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Non Battery Pack	Does not Exist
EXIT LIGHT	Inspected
Battery Pack	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Non Battery Pack	Does not Exist
EXIT/EMERGENCY LIGHT	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Denotone	110 deficioneres recorded

Building Condition Assessment Survey 2023 - 2024

irical hispection	· ·
nestion	Response
FIRE ALARM SYSTEM	Inspected
Replacement Quantity	12,000
Replacement Uom	S.F.
Bell/Horn	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Strobe	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Manual Pull Station	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Fan Shutdown Control	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Duct Smoke Detector	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Area Smoke Detector	Inspected
Condition	3 - Fair
Deficiency	DETECTOR NOT OPERATIONAL
Deficiency Location/Instance	Room 150
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
CO Detector	Does not Exist
Heat Detector	Does not Exist
Elevator Recall	Does not Exist
Magnetic Door Holder/Contactor	Does not Exist
Fused Cutout Panel	Does not Exist
Fire Alarm Digital Communicator	Does not Exist
Main Panel	Does not Exist
Sub-Panel Sub-Panel	Does not Exist
Remote Annunciator	Does not Exist
Sprinkler Flow/Air Pressure Switch	Does not Exist
Tamper Flow Switch/Chain	Does not Exist
ROUNDING SYSTEM	Does not Exist
NTERCOM SYSTEM	Does not Exist
AN	Inspected
Local Distribution Frame (I/LDF)	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	Does not Exist
JGHTNING PROTECTION	Does not Exist
MOTOR CONTROLLER	Inspected
(D)	Inspected Page 4 of 6 Drint Data 6/05/0

Building Condition Assessment Survey 2023 - 2024

Question	Response
MOTOR CONTROLLER	
Motor Control Center	Does not Exist
Motor Starter/Contactor	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Variable Frequency Drive	Does not Exist
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not Exist
Fused Toggle Switch Type	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Molded Case Circuit Breaker Type	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
PUBLIC ADDRESS SYSTEM	Inspected
Replacement Quantity	12,000
Replacement Uom	S.F.
Instance	Connected to Main Asset 055
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	N/A
Installation Year	1993
Source of Installation	Documented
Deficiency	No deficiencies recorded
SECURITY	Inspected
IPDVS/CCTV System	Does not Exist
Intrusion Alarm System	
Replacement Quantity	Inspected 12,000
	S.F.
Replacement Uom	
Central Control Panel	Does not Exist
Infrared Sensor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Panic Switch	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Remote Annunciator	Does not Exist
Siren/Strobe	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Lighting - Security	Inspected
Replacement Uom	EACH
Condition	1 - Good
Deficiency	No deficiencies recorded
SERVICE SWITCH	Does not Exist

Building Condition Assessment Survey 2023 - 2024

nestion	Response
SWITCHBOARD	Inspected
Number of Spares	0
Fused Disconnect Switch Type	Inspected
Instance	Electrical Closet Room 132A (Inside Mechanical Room 132)
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	All City Switchboard
Equipment	DP-1
Capacity/Size Quantity	1,200
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	1
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Switchboard Mains Size
Installation Year	1993
Source of Installation	Documented
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not Exist
Molded Case Circuit Breaker Type	Does not Exist
ELEPHONE SYSTEM	Inspected
PBX/Intercom	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Standard	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
TRANSFORMER	Does not Exist