## **NYC Department of Education**

## **Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection Q909

Inspection Id Inspection Type	Time In Last Edited
EE: Q909 Electrical	2023-12-04 12:37 PM 2023-12-21 3:18 PM
Asset Data	
Question	Answer
Type of Service	Below Ground
Does Interactive Whiteboard (IWB) Exist?	No
Water Penetration in Electrical Room?	No
Have any Systems/Major Building Components been upgraded?	Yes
	Systems: All Electrical Systems and Components Years: 2015
DEDICATED INTERCOMS IN FIRE RESCUE AREAS	rears. 2015
Question	Response
Are there any Life Rescue Assistance Areas, Fire Rescue Areas,	No
and/or Holding Rooms in your building?	
Priority Condition	
Priority Priority Condition Component Location Condition Exist Category Description Affected Description Last Year?	` ' ' ' ' ' ' ' ' ' ' ' ' ' ' ' ' ' ' '
No condition recorded	
nspection	
Question	Response
Electrical	
AUDITORIUM	Does not Exist
CAFETERIA	Does not Exist
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Does not Exist
COMPUTER LAB	Does not Exist
GYMNASIUM	Does not Exist
KITCHEN	Does not Exist
LIBRARY	Does not Exist
LOCKER ROOM	Does not Exist
MULTIPURPOSE ROOM	Does not Exist
SCIENCE DEMO ROOM	Does not Exist
SCIENCE LAB	Does not Exist
SCIENCE PREP ROOM	Does not Exist
SWIMMING POOL	Does not Exist
TOILET ROOM - STAFF	Does not Exist
TOILET ROOM - STUDENT	Does not Exist
AUXILIARY SIGNAL/BELL SYSTEM	Does not Exist
EMERGENCY DC STANDBY BATTERY POWER	Does not Exist
EMERGENCY JOHNSTON LIGHT BANKS	Does not Exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Does not Exist
EMERGENCY LIGHTING	Does not Exist
EXIT LIGHT	Does not Exist
EXIT/EMERGENCY LIGHT	Does not Exist
FIRE ALARM SYSTEM	Does not Exist
GROUNDING SYSTEM	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded

## **NYC Department of Education**

## **Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection Q909

duestion	Response
INTERCOM SYSTEM	Does not Exist
LAN	Does not Exist
LIGHTNING PROTECTION	Does not Exist
MOTOR CONTROLLER	Does not Exist
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Does not Exist
Fused Knife Switch Type	Does not Exist
Fused Toggle Switch Type	Does not Exist
Molded Case Circuit Breaker Type	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
PUBLIC ADDRESS SYSTEM	Does not Exist
SECURITY	Inspected
IPDVS/CCTV System	Does not Exist
Intrusion Alarm System	Does not Exist
Lighting - Security	Inspected
Replacement Uom	EACH
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
SERVICE SWITCH	Does not Exist
SWITCHBOARD	Does not Exist
TELEPHONE SYSTEM	Does not Exist
TRANSFORMER	Does not Exist