Building Condition Assessment Survey 2023-2024

Answer Systems: Years:	Time In 2024-03-15 07:22AM	Last Edited 2024-06-18 09:16A
Systems: Years:		2024-06-18 09:16A
Systems: Years:	Double Coming Control Day 134	
Systems: Years:	Doubled Coursing Countril Dead 134	
Years:	Double Courses Coult-1. Double 1 144	
	Partial Service Switch, Partial M Breaker Panel Boards 2023, 2004	olded Case Circuit
Systems:	Lightning Protection, IPDVS/CC	CTV System Partial
Systems.	Motor Starters, Partial Fan Shut Switchboard	•
Years:	2023	
Systems:	LAN	
Years:	2021	
Systems:	Intrusion Alarm System (Except	Panic Switch)
Years:	2017	
Systems:	Fire Alarm System (Sprinkler Flor Flow Switches), Lighting - Secu	
Years:	2014, 2009, 2004	•
Systems:	Most Exit Lights (Battery Pack)	
Years:	2014	
Systems:	Auditorium (Projection System, Theater Lighting System), Intrus (Panic Switch)	
Vears:		
Systems:	Interior Fluorescent Lighting (Ex	-
Years:	Recall), Gymnasium (Lighting)	ystem (Elevator
•		
Systems:	Emergency Light/Exit Light Pan Public Address System, Local Sc Cafeteria, Gymnasium), Partial S	ound System (Students
	Fused Disconnect Switch Type P Fluorescent Lighting	Panel Board, Recessed
	ound	
INO		
I	Resnonse	
		hoto mage
_		
Response		
Darr	aviat	
	EXIST	
Inspected		
¥ :		
-		
	Systems: Years: Systems: Years: Systems: Years: Systems: Years: Below Gr Yes No	Systems: LAN Years: 2021 Systems: Intrusion Alarm System (Except Years: 2017 Systems: Fire Alarm System (Sprinkler Flew Switches), Lighting - Secu Years: 2014, 2009, 2004 Systems: Most Exit Lights (Battery Pack) Years: 2014 Systems: Auditorium (Projection System, Theater Lighting System), Intrus (Panic Switch) Years: 2013 Systems: Interior Fluorescent Lighting (Exmounted, Library), Fire Alarm S Recall), Gymnasium (Lighting) Years: 2011 Systems: Library Years: 2009 Systems: Emergency Light/Exit Light Pan Public Address System, Local Sc Cafeteria, Gymnasium), Partial S Fused Disconnect Switch Type F Fluorescent Lighting Years: 2004 Below Ground Yes No Response No Response Does not exist Inspected Inspected Inspected

Building Condition Assessment Survey 2023-2024

icui Inspection		
uestion	Response	
AUDITORIUM		
House Lighting		
Lighting Fixture - Fluorescent		
Instance on 1st Floor	Inspected	
Pendant Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE BALLAST	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Recessed Mounted		
Instance on 1st Floor	Does not exist	
Lighting Fixture - HID	2000 1000 0.1100	
Instance on 1st Floor	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Instance on 1st Floor	Does not exist	
Lighting Fixture - LED	Does not exist	
Instance on 1st Floor	Does not exist	
	Does not exist	
Local Sound System Instance on 1st Floor	I	
	Inspected 3- Fair	
Installation Year	2013	
Source of Installation Year	2013 Documented	
Deficiency	No deficiencies recorded	
	No deficiencies recorded	
Projection System	Y 1	
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Is the projector on a cart or installed on the ceiling?	Ceiling	
Deficiency	No deficiencies recorded	
Theater Lighting System		
Instance on 1st Floor	Inspected	
Dimming System		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Theater Lighting		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
CAFETERIA	Inspected	
Instance on 1st Floor - Students	Inspected	
Instance on 1st Floor - Staff	Inspected	
	mspecced	
Lighting Instance on 1st Floor - Students	Inspected	
· · · · · · · · · · · · · · · · · · ·		
Instance on 1st Floor - Staff	Inspected	

Building Condition Assessment Survey 2023-2024

uestion	Response	
CAFETERIA		
Lighting		
Lighting Fixture - Fluorescent		
Instance on 1st Floor - Students	Inspected	
Instance on 1st Floor - Staff	Inspected	
Pendant Mounted		
Instance on 1st Floor - Students	Does not exist	
Instance on 1st Floor - Staff	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on 1st Floor - Students	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on 1st Floor - Staff	Does not exist	
Recessed Mounted		
Instance on 1st Floor - Students	Does not exist	
Instance on 1st Floor - Staff	Does not exist	
Lighting Fixture - HID		
Instance on 1st Floor - Students	Does not exist	
Instance on 1st Floor - Staff	Does not exist	
Lighting Fixture - Incandescent		
Instance on 1st Floor - Students	Does not exist	
Instance on 1st Floor - Staff	Does not exist	
Lighting Fixture - LED		
Instance on 1st Floor - Students	Does not exist	
Instance on 1st Floor - Staff	Does not exist	
Local Sound System	2000 100 51100	
Instance on 1st Floor - Students	Inspected	
Instance Condition	3- Fair	
Installation Year	2004	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Instance on 1st Floor - Staff	Does not exist	
Projection System		
Instance on 1st Floor - Students	Does not exist	
Instance on 1st Floor - Staff	Does not exist	
Theater Lighting System		
Instance on 1st Floor - Students	Does not exist	
Instance on 1st Floor - Staff	Does not exist	
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected	
Lighting	Inspected	
Does a Chandelier Exist?	No	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - HID	Does not exist	

Building Condition Assessment Survey 2023-2024

iricui Inspection		1005
Question	Response	
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE		
Lighting		
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Does not exist	
COMPUTER LAB	Inspected	
Instance on Room 145	Inspected	
Power Panel?	No	
Lighting	110	
Instance on Room 145	Inspected	
Lighting Fixture - Fluorescent	1	
Instance on Room 145	Inspected	
Pendant Mounted		
Instance on Room 145	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on Room 145	Does not exist	
Recessed Mounted	Does not that	
Instance on Room 145	Does not exist	
Lighting Fixture - HID	Does not that	
Instance on Room 145	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 145	Does not exist	
Lighting Fixture - LED	Does not that	
Instance on Room 145	Does not exist	
Raceway With Receptacles	Does not exist	
Instance on Room 145	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
GYMNASIUM	Inspected	
Instance on Basement	Inspected	
Lighting	mspecced	
Instance on Basement	Inspected	
Lighting Fixture - Fluorescent		
Instance on Basement	Inspected	
Pendant Mounted		
Instance on Basement	Does not exist	
Surface Mounted		
Instance on Basement	Does not exist	
Recessed Mounted	Does not that	
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID	1 to deficiencies recorded	
Instance on Basement	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Instance on Basement	Does not exist	
Lighting Fixture - LED	Does not exist	
Instance on Basement	Does not exist	
Local Sound System	Does not exist	
	Inspected	
	<u> </u>	
Source of Installation Year		
Instance on Basement Instance Condition Installation Year Source of Installation Year	Inspected 3- Fair 2004 Documented	

Building Condition Assessment Survey 2023-2024

Response	
No deficiencies recorded	
Does not exist	
Does not exist	
Does not exist	
Inspected	
Inspected	
Inspected	
Inspected	
Does not exist	
Inspected	
3- Fair	
No deficiencies recorded	
Does not exist	
Does not exist	
Does not exist	
Does not exist	
Inspected	
Inspected	
Inspected	
Inspected	
3- Fair	
No deficiencies recorded	
Does not exist	
Inspected	
No deficiencies recorded	
Does not exist	
Does not exist	
Does not exist	
Does not exist	
	No deficiencies recorded Does not exist Does not exist Inspected Inspected Inspected Inspected Inspected Joes not exist Inspected Does not exist Inspected Inspected Does not exist Does not exist Does not exist Does not exist Inspected Inspected Inspected Inspected Inspected Inspected Inspected Inspected Joes not exist Inspected Inspected Inspected Inspected Inspected Joes not exist Inspected Inspected Joes not exist Inspected Joes not exist Inspected Joes not exist Inspected Does not exist

Building Condition Assessment Survey 2023-2024

rical inspection	NUC
Question	Response
LIBRARY	
Projection System	
Instance on Room 138	Does not exist
LOCKER ROOM	Does not exist
MULTIPURPOSE ROOM	Does not exist
SCIENCE DEMO ROOM	Does not exist
SCIENCE LAB	Does not exist
SCIENCE PREP ROOM	Does not exist
SWIMMING POOL	Does not exist
TOILET ROOM - STAFF	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not exist
Surface Mounted	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not exist
Surface Mounted	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
EMERGENCY DC STANDBY BATTERY POWER	Does not exist
EMERGENCY GENERATOR SET	Does not exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
	Inspected
EMERGENCY LIGHTING	Inspected
Battery Pack Condition	3- Fair
Deficiency	BATTERY NOT OPERATIONAL
Deficiency Location/Instance	Corridors
Deficiency Location/Instance Deficiency Quantity	Corridors 5
Quantity Uom	5 EACH
Potential Action	REPLACE BATTERY
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2

Building Condition Assessment Survey 2023-2024

Response	
No violations recorded	
Inspected	
3- Fair	
No deficiencies recorded	
Inspected	
_	
_	
*	
<u> </u>	
5- Fair	
1	
	No violations recorded Inspected 3- Fair

Building Condition Assessment Survey 2023-2024

cirical Inspection	KUUS
Question	Response
FIRE ALARM SYSTEM	
Main Panel	
Fire Alarm Control Panel (Electronic)	
Manufacturer	Edwards System Technology
Model	EST 2
EquipmentId	N/A
Installation Year	2004
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Standard)	Does not exist
Sub-Panel	Does not exist
Remote Annunciator	Inspected
Display Monitor	Does not exist
Panel	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Printer	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
	Does not exist
Punch Register	
Sprinkler Flow/Air Pressure Switch	Inspected 3- Fair
Condition	
Deficiency	No deficiencies recorded
Tamper Flow Switch/Chain	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
GROUNDING SYSTEM	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
INTERCOM SYSTEM	Inspected
Elevator	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Holding Area	Does not exist
LAN	Inspected
Local Distribution Frame (I/LDF)	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
	Inspected
LIGHTNING PROTECTION Condition	1- Good
	No deficiencies recorded
Deficiency	
MOTOR CONTROLLER	Inspected
MOTOR CONTROL CENTER	Does not exist
MOTOR STARTER/CONTACTOR	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Variable Frequency Drive	Does not exist
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE

Building Condition Assessment Survey 2023-2024

rical Inspection	KUUJ
Question	Response
PANEL BOARD	
Fused Disconnect Switch Type	
Deficiency Location/Instance	Boiler Room and Fan Room B6
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Fused Knife Switch Type	Does not exist
Fused Toggle Switch Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Molded Case Circuit Breaker Type	Inspected 3- Fair
Condition	
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Throughout the Building
Deficiency Quantity	11
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
PUBLIC ADDRESS SYSTEM	Inspected
Instance	Main Office - Room 157
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
,	
Model	Dukane 250
Installation Year	2004
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
SECURITY	Inspected
IPDVS/CCTV System	Inspected
Condition	1- Good
Installation Year	2023
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Intrusion Alarm System	Inspected
Central Control Panel	Inspected
Instance	Custodian's Office - Room 124
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista 128BPT
Installation Year	2017
Source of Installation Year	Documented
Deficiency	No deficiencies recorded

Building Condition Assessment Survey 2023-2024

1	Response	
RITY		
sion Alarm System		
rared Sensor	Inspected	
ondition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
nic Switch	Inspected	
ondition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
mote Annunciator	Inspected	
ondition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
en/Strobe	Inspected	
ondition	-	
	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
ting - Security	Inspected 2- Between Good and Fair	
ndition		
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE	
Deficiency Location/Instance Deficiency Quantity	Perimeter of the Building	
	12 EACH	
Quantity Uom Potential Action	REPLACE BALLAST	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 3	
Violations	No violations recorded	
CE SWITCH	Inspected	
Instance	Electrical Room B1	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Delta Metal Product	
EquipmentId	N/A	
Capacity/Size Quantity	800	
Capacity/Size UOM	Amps	
Source of Capacity/Size	Nameplate	
Installation Year	2004	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Instance	Electrical Room B1	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Royal Switchboard Co.	
EquipmentId	North BLDG. Lights	
Capacity/Size Quantity	600	
Capacity/Size UOM	Amps	
Source of Capacity/Size	Fuse Size	
Installation Year	1967	
Source of Installation Year	Documented	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	Electrical Room B1	
Deficiency Quantity	1	
Deficiency Deficiency Location/Instance	BEYOND USEFUL LIFE Electrical Room B1	

Building Condition Assessment Survey 2023-2024

Electrical Inspection R003

	Response
CE SWITCH	
Violations	No violations recorded
Instance	Electrical Room B1
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Royal Switchboard Co.
EquipmentId	North BLDG. Power
Capacity/Size Quantity	600
Capacity/Size UOM	Amps
Source of Capacity/Size	Fuse Size
Installation Year	1967
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room B1
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Electrical Room B1
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Royal Switchboard Co.
EquipmentId	South BLDG. Lights
Capacity/Size Quantity	300
Capacity/Size UOM	Amps
Source of Capacity/Size	Fuse Size
Installation Year	1967
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room B1
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Electrical Room B1
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Royal Switchboard Co.
EquipmentId	South BLDG. Power
Capacity/Size Quantity	300
Capacity/Size UOM	Amps
Source of Capacity/Size	Fuse Size
Installation Year	1967
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room B1
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE

Building Condition Assessment Survey 2023-2024

uestion	Response	
SERVICE SWITCH		
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Instance	Electrical Room B1	
Instance Condition	1- Good	
Instance Quantity	1 EACH	
Instance Quantity Uom		
Manufacturer	Siemens	
EquipmentId	Main Switch 600Amps	
Capacity/Size Quantity	600	
Capacity/Size UOM	Amps	
Source of Capacity/Size	Nameplate	
Installation Year	2023	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
WITCHBOARD	Inspected	
Number of Spares	6	
Fused Disconnect Switch Type	Inspected	
Instance	Electrical Room B1	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Royal Switchboard Co.	
EquipmentId	Main SWBD	
Capacity/Size Quantity	1600	
Capacity/Size UOM	Amps Total	
Capacity/Size 2 Quantity	2	
Capacity/Size 2 UOM	Section(s)	
Source of Capacity/Size	Inspector Estimate	
Installation Year	1967	
Source of Installation Year	Documented	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	Electrical Room B1	
Deficiency Quantity	l lectrical Room B1	
Quantity Uom	EACH PER ACE	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Instance	Electrical Room B1	
Instance Condition	1- Good	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Siemens	
EquipmentId	BRDB	
Capacity/Size Quantity	600	
Capacity/Size UOM	Amps Total	
Capacity/Size 2 Quantity	1	
Capacity/Size 2 UOM	Section(s)	
Source of Capacity/Size	Nameplate	
Installation Year	2023	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
	Does not exist	
Fused Knife Switch Type Molded Case Circuit Breaker Type	Inspected	

Building Condition Assessment Survey 2023-2024

Question	Response
SWITCHBOARD	
Molded Case Circuit Breaker Type	
Instance	2004 Building Addition Electrical Closet
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Square D
EquipmentId	2004 Docu DP-C (Sec#1)
Capacity/Size Quantity	600
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	1
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Nameplate
Installation Year	2004
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
TELEPHONE SYSTEM	Inspected
PBX/Intercom	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Standard	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
TRANSFORMER	Does not exist