Asset:	P.S. 4 - STAT	TEN ISLAND, 200 NEDRA	A LANE, STATEN IS	LAND, NY, 103	12		
Inspection Id	Inspection Typ	oe .			Time	In	Last Edited
4332	2 ELECTRICAL				2024	-03-29 08:40AN	M 2024-04-22 08:48A
set Data							
Question				Answer			
Have any Syst	ems/Major Buildi	ing Components been upgrade	d?	Systems:	Most Lighting	g - Security	
	J			Years:	2019, 2014, 2	2006	
				Systems:	Partial Servic System	_	ting (Except Basement), I Switchboard, Fire Alarm
				Years:	2019	r	
				Systems:	Exit / Emerge	ency Lights	
				Years:	2017	Pattaur Daals)	
				Systems: Years:	Exit Lights (F 2012	Sattery Pack)	
				Systems:		Circuit Breaker	Panal Roard
				Years:	2011, 2007, 1		I alici Boalu
				Systems:		964 ss System, Local	Sound System
				,	Auditorium (Theater Lighting	
				Years:	2009	TV C I	A1 C
				Systems: Years:	2006	v System, mtru	sion Alarm System
				Systems:		ight/Exit Light I	Danal
				Years:	2001	igiio Exit Ligiit i	anci
				Systems:		ctrical Systems	and Components
				Years:	1984	ourour systems	and components
Type of Service	te.			Below Gr			
	ve Whiteboard (IV	WB) Exist?		Yes			
	tion In Electrical I			No			
DEDICATE	D INTERCOM	IS IN FIRE RESCUE ARI	EAS				
Question					Response		
your buildin	g?	sistance Areas, Fire Rescue Ar			l'es .		
		ailable in all of these spaces fo	or use during a fire?		Yes		
	edicated intercom	s operational?		<u> </u>	Yes		
iority Condi							
	iority togowy	Condition	Component	Location	Person(s)	Person(s)	Photo
	tegory	Description	Affected	Description	Notified	Title	Image
No condition 1	recorded						
nspection							
Question				Response			
Electrical							
ATHLETIC	FIELD			Does not o	exist		
AUDITORIUM			Inspected				
I	nstance on 1st Flo	oor		Inspected			
House Lig	hting						
_	nstance on 1st Flo	oor		Inspected			
I	Ooes a Chandelier	Exist?		No			
Lighting	g Fixture - Fluore	escent					
I	nstance on 1st Flo	oor		Does not	exist	·	
Lighting	g Fixture - HID						
	nstance on 1st Flo			Does not	exist		
_	g Fixture - Incan						
ĭ	nstance on 1st Flo	oor		Inspected			
1							

ical Inspection	R
estion	Response
AUDITORIUM	
House Lighting	
Lighting Fixture - Incandescent	
Pendant Mounted	
Instance on 1st Floor	Does not exist
Surface Mounted	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	5
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1 LEVEL 2
Purpose of Action Violations	
	No violations recorded
Recessed Mounted	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	18
Quantity Uom	EACH DEDI A CE LIBORA DE
Potential Action	REPLACE-UPGRADE
Urgency of Action Purpose of Action	PRIORITY 1 LEVEL 2
Violations	No violations recorded
	No violations recorded
Lighting Fixture - LED	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on 1st Floor	Does not exist
Recessed Mounted	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Local Sound System	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Installation Year	2009
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Projection System	
Instance on 1st Floor	Inspected
Instance Condition	5- Poor
Is the projector on a cart or installed on the ceiling?	Ceiling
Deficiency	VIDEO PROJECTOR IS NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations Theater Lighting System	No violations recorded

Building Condition Assessment Survey 2023-2024

Question	Response
	Kesponse
AUDITORIUM	
Theater Lighting System	Inspected
Instance on 1st Floor	Inspected
Dimming System	T 1
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Theater Lighting	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
CAFETERIA	Inspected
Instance on 1st Floor	Inspected
Lighting	*
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	•
Instance on 1st Floor	Does not exist
Lighting Fixture - HID	
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Inspected
Pendant Mounted	inspected
Instance on 1st Floor	Does not exist
	Does not exist
Surface Mounted	Description of the second of t
Instance on 1st Floor	Does not exist
Recessed Mounted	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	20
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Lighting Fixture - LED	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not exist
Surface Mounted	
Instance on 1st Floor	Does not exist
Recessed Mounted	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Local Sound System	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Installation Year	2009
Source of Installation Year	Documented

No deficiencies recorded

Does not exist

Deficiency

Theater Lighting System

Instance on 1st Floor

Projection System

Building Condition Assessment Survey 2023-2024

и ппересион	RU
stion	Response
AFETERIA	
Fheater Lighting System Instance on 1st Floor	Does not exist
LASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected
Lighting	Inspected
Does a Chandelier Exist?	No
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	144
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Surface Mounted	Inspected
Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	120
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action Violations	LEVEL 2
	No violations recorded Does not exist
Recessed Mounted	
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Inspected
Pendant Mounted Condition	Inspected 3- Fair
Deficiency Deficiency Quantity	LIGHTING FIXTURE BEYOND USEFUL LIFE 80
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Surface Mounted	Inspected
Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	60
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Recessed Mounted	Does not exist
Lighting Fixture - LED	Inspected
Pendant Mounted	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Inspected

Building Condition Assessment Survey 2023-2024

R004

Electrical Inspection

Surface Mounted

Recessed Mounted

Instance on 1st Floor

Instance on 1st Floor

Lighting Fixture - Incandescent
Instance on 1st Floor

Instance Condition

Deficiency Quantity

Instance on 1st Floor

Deficiency

Question Response CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE Lighting **Lighting Fixture - LED** Recessed Mounted Condition 3- Fair Deficiency No deficiencies recorded Does not exist **COMPUTER LAB GYMNASIUM** Inspected Instance on 1st Floor Inspected Lighting Instance on 1st Floor Inspected **Lighting Fixture - Fluorescent** Does not exist Instance on 1st Floor **Lighting Fixture - HID** Instance on 1st Floor Inspected **Pendant Mounted** Instance on 1st Floor Inspected Instance Condition 3- Fair Deficiency LIGHTING FIXTURE BEYOND USEFUL LIFE **Deficiency Quantity** 16 Quantity Uom **EACH** Potential Action REPLACE-UPGRADE PRIORITY 1 Urgency of Action Purpose of Action LEVEL 2 Violations No violations recorded

Does not exist

Does not exist

Inspected

3- Fair

Does not exist

LIGHTING FIXTURE BEYOND USEFUL LIFE

	Quantity Uom	EACH
	Potential Action	REPLACE-UPGRADE
	Urgency of Action	PRIORITY 1
	Purpose of Action	LEVEL 2
	Violations	No violations recorded
Lightin	ng Fixture - LED	
	Instance on 1st Floor	Does not exist

Histalice	C OII 1St 11001	Does not exist	
Local Sound Sys	stem		
Instance	e on 1st Floor	Inspected	
Instance	e Condition	3- Fair	
Installat	tion Year	2009	
Source	of Installation Year	Documented	
Deficie	ncy	No deficiencies recorded	
Projection Syste	em		

Electrical Inspection	R004

Question	Response	
GYMNASIUM		
Scoreboard		
Instance on 1st Floor	Does not exist	
Theater Lighting System		
Instance on 1st Floor	Does not exist	
KITCHEN	Inspected	
Instance on 1st Floor	Inspected	
Lighting		
Instance on 1st Floor	Inspected	
Lighting Fixture - Fluorescent		
Instance on 1st Floor	Does not exist	
Lighting Fixture - HID		
Instance on 1st Floor	Does not exist	
Lighting Fixture - Incandescent		
Instance on 1st Floor	Does not exist	
Lighting Fixture - LED		
Instance on 1st Floor	Inspected	
Pendant Mounted		
Instance on 1st Floor	Does not exist	
Surface Mounted		
Instance on 1st Floor	Does not exist	
Recessed Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
LIBRARY	Inspected	
Instance on Room 207	Inspected	
Lighting	1	
Instance on Room 207	Inspected	
Lighting Fixture - Fluorescent	*	
Instance on Room 207	Does not exist	
Lighting Fixture - HID		
Instance on Room 207	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 207	Does not exist	
Lighting Fixture - LED		
Instance on Room 207	Inspected	
Pendant Mounted	торосси	
Instance on Room 207	Does not exist	
Surface Mounted	200 100 0110	
Instance on Room 207	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	110 deficiencies recorded	
Instance on Room 207	Does not exist	
	DOES HOT CAIST	
Raceway With Receptacles Instance on Room 207	Does not exist	
Projection System	Does not exist	
Instance on Room 207	Does not exist	
LOCKER ROOM	Does not exist	
MULTIPURPOSE ROOM	Does not exist	
SCIENCE DEMO ROOM	Does not exist	

Electrical Inspection	R004

Building Condition Assessment Survey 2023-2024

icui Inspection	_	KUU'
nestion	Response	
EXIT LIGHT		
Battery Pack		
Deficiency Quantity	2	
Quantity Uom	EACH	
Potential Action	REPLACE BATTERY	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Non Battery Pack	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
EXIT/EMERGENCY LIGHT	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
FIRE ALARM SYSTEM	Inspected	
Bell/Horn	Inspected	-
Condition	1- Good	
Deficiency	No deficiencies recorded	
Strobe	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Manual Pull Station	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Fan Shutdown Control	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
·		
Duct Smoke Detector	Inspected 1- Good	
Condition		
Deficiency	No deficiencies recorded	
Area Smoke Detector	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
CO Detector	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Heat Detector	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Elevator Recall	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Magnetic Door Holder/Contactor	Does not exist	
Fused Cutout Panel	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Fire Alarm Digital Communicator	Does not exist	
Main Panel	Inspected	
Bell At Panel	Does not exist	
Fire Alarm Control Panel (Electronic)	Inspected	
Instance	Main Entrance Lobby	
Instance Condition	1- Good	
Instance Quantity	1	
Instance Quantity Uom	EACH	

Building Condition Assessment Survey 2023-2024

neui Inspection		KUUT
uestion	Response	
FIRE ALARM SYSTEM		
Main Panel		
Fire Alarm Control Panel (Electronic)		
Manufacturer	Mircom	
Model	FX - 2000	
EquipmentId	Fire Alarm Control Panel	
Installation Year	2019	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Standard)	Does not exist	
Sub-Panel	Does not exist	
Remote Annunciator	Inspected	
Display Monitor	Does not exist	
Panel	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Printer	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
	Does not exist	
Punch Register		
Sprinkler Flow/Air Pressure Switch	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Tamper Flow Switch/Chain	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
GROUNDING SYSTEM	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
INTERCOM SYSTEM	Inspected	
Elevator	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Holding Area	Does not exist	
LAN		
	Inspected Inspected	
Local Distribution Frame (I/LDF) Condition	3- Fair	
·		
Deficiency	No deficiencies recorded	
Main Equipment Rack (MDF)	Inspected 3- Fair	
Condition		
Deficiency	No deficiencies recorded	
LIGHTNING PROTECTION	Does not exist	
MOTOR CONTROLLER	Inspected	
MOTOR CONTROL CENTER	Inspected	
Instance	Boiler Room	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Gallagher	
EquipmentId	N/A	
Equipmentid Capacity/Size Quantity	400	
Capacity/Size UOM	Amps	
	•	
Capacity/Size 2 Quantity	1	

ical Inspection		R00
uestion	Response	
MOTOR CONTROLLER		
MOTOR CONTROL CENTER		
Source of Capacity/Size	Inspector Estimate	
Installation Year	1984	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
MOTOR STARTER/CONTACTOR	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Variable Frequency Drive	Does not exist	
PANEL BOARD	Inspected	
Fused Disconnect Switch Type	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Fused Knife Switch Type	Does not exist	
Fused Toggle Switch Type	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Molded Case Circuit Breaker Type	Inspected	
Condition	3- Fair	
Deficiency	NO SPARE	
Deficiency Location/Instance	Gymnasium, Corridor near Room 107	
Deficiency Quantity	2	
Quantity Uom	EACH	
Potential Action	INSTALL NEW PANEL BOARD	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
PUBLIC ADDRESS SYSTEM	Inspected	
	General Office - Room 101	
Instance	3- Fair	
Instance Condition		
Instance Quantity	1	
Instance Quantity Uom	EACH	
Model	Dukane 250	
Installation Year	2009	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
SECURITY	Inspected	
IPDVS/CCTV System	Inspected	
Condition	3- Fair	
Installation Year	2006	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Intrusion Alarm System	Inspected	
Central Control Panel	Inspected	
Instance	Custodian's Office - Room 106	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
-		
Model	Vista - 128BP	
Installation Year	2006	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Infrared Sensor	Inspected	

Building Condition Assessment Survey 2023-2024

iricui inspection	KUU ⁴
Question	Response
SECURITY	
Intrusion Alarm System	
Infrared Sensor	
Deficiency	No deficiencies recorded
Panic Switch	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Remote Annunciator	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Siren/Strobe	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting - Security	Inspected
Condition	2- Between Good and Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Location/Instance	Building Perimeters
Deficiency Quantity	13
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 3
Violations	No violations recorded
SERVICE SWITCH	Inspected
Instance	Electrical Room C23
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Gallagher
EquipmentId	Air Cond. Equipment Power Panel
Capacity/Size Quantity	800
Capacity/Size UOM	Amps
Source of Capacity/Size	Fuse Size
Installation Year	1984
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room C23
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	All City Switchboard
	Main Switch
EquipmentId	800
Capacity/Size Quantity	
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate 2019
Installation Year Source of Installation Year	Documented
	No deficiencies recorded
Deficiency	
Instance	Electrical Room C23
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Gallagher
EquipmentId	Main Switchboard
Capacity/Size Quantity	1800

Electrical Inspection	K004

Question	Response
SERVICE SWITCH	
Capacity/Size UOM	Amps
Source of Capacity/Size	Fuse Size
Installation Year	1984
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room C23
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Gallagher
EquipmentId	Heating Equipment Power Panel
Capacity/Size Quantity	350
Capacity/Size UOM	Amps
Source of Capacity/Size	Fuse Size
Installation Year	1984
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
SWITCHBOARD	Inspected
Number of Spares	3
Fused Disconnect Switch Type	Inspected
Instance	Electrical Room C23
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Gallagher Switchboard Co.
EquipmentId	N/A
Capacity/Size Quantity	1800
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	3
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Service Switch Fuse Size
Installation Year	1984
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room C23
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	All City Switchboard
EquipmentId	MDP
Capacity/Size Quantity	800
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	1
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Nameplate
Installation Year Source of Installation Year	2019
	Documented
Deficiency To a second Transfer of the second	No deficiencies recorded
Fused Knife Switch Type	Does not exist Does not exist
Molded Case Circuit Breaker Type	
TELEPHONE SYSTEM	Inspected
PBX/Intercom	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Standard	Inspected

Building Condition Assessment Survey 2023-2024

Question	Response
TELEPHONE SYSTEM	
Standard	
Condition	3- Fair
Deficiency	No deficiencies recorded
TRANSFORMER	Does not exist