Building Condition Assessment Survey 2023-2024

Inspection II I				ran•	T.,	Lost Edit-1
Inspection Id Inspection Type				Time		Last Edited
3535 ELECTRICAL				2024-	·02-27 07:18AM	2024-03-19 09:58A
set Data			A			
Question	C 1 1 1 10		Answer Systems:	Dartial Malda	d Coso Cironit Pr	reaker Panel Board
Have any Systems/Major Building Components been upgraded?			Years:	2023, 2022, 20		caker Faller Board
			Systems:		uro e Switch, Partial S	Switchboord
			·	2023, 2018	e Switch, Fartial	Switchooard
			Years: Systems:	· ·	hta Dattami Daalia	s, Partial Emergency
			Years:	Lights Battery 2023	•	s, Fartial Efficigency
			Systems:		tection Retrofitte	ed LED Lighting (Main
			Years:	Entrance Lobb 2022		Cu LED Lighting (Main
			Systems:		ergency Lights	
			Years:	2021, 2018	lergency Lights	
			Systems:		/ System, Public	Address System
			Years:			ymnasium, Room 164)
			Systems:		Disconnect Swite	ch Type Panel Board
			Years:	2020, 2001	21500111100V 2 W 100	in Type I amer Beard
			Systems:	Lighting - Sec	nurity	
			Years:	2020		
			Systems:		m System (Remo	ote Annunciator).
			Years:		Except Incandesco	
			Systems:	Intercom Syst	em (Holding Roc	om)
			Years:	2017		
			Systems:	Gymnasium (Scoreboard)	
			Years:	2016		
			Systems:	Recessed Fluo	orescent Lighting	(1st Floor Corridor)
			Years:	2013		
			Systems:	Intercom Syst	em (Elevator)	
			Years:	2012		
			Systems:	Fire Alarm Sy	vstem	
			Years:	2011		
			Systems:	Public Addres	ss System (Tuner)	, Local Sound System
			·		eteria, Gymnasiu	· ·
			Years:	2010		
			Systems:	Emergency Li	ight/Exit Light Pa	anel
			Years:	2001		
			Systems:	Interior Fluore	escent Lighting	
			Years:	1997		
Type of Service			Below Gr	ound		
Does Interactive Whiteboard (IWB)			Yes			
Water Penetration In Electrical Roo			No			
DEDICATED INTERCOMS I	IN FIRE RESCUE AREAS) o o m o		
Question Are there any Life Rescue Assistate your building?	ance Areas, Fire Rescue Areas, an	nd/or Holding Room		Response No		
iority Condition						
xist Priority	Condition	Component	Location	Person(s)	Person(s)	Photo
ast Year? Category	Description	Affected	Description	Notified		Image
No condition recorded						
nspection						
Inspection CAS Partners Version 2.0 (P)		Page 1	610			

Question	Response	
lectrical		
ATHLETIC FIELD	Does not exist	
AUDITORIUM	Inspected	
Instance on 1st Floor	Inspected	
House Lighting		
Instance on 1st Floor	Inspected	
Does a Chandelier Exist?	No	
Lighting Fixture - Fluorescent		
Instance on 1st Floor	Inspected	
Pendant Mounted		
Instance on 1st Floor	Does not exist	
Surface Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on 1st Floor	Does not exist	
Lighting Fixture - HID		
Instance on 1st Floor	Does not exist	
Lighting Fixture - Incandescent		
Instance on 1st Floor	Inspected	
Pendant Mounted		
Instance on 1st Floor	Does not exist	
Surface Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE	
Deficiency Quantity	3	
Quantity Uom	EACH	
Potential Action	REPLACE-UPGRADE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Recessed Mounted		
Instance on 1st Floor	Does not exist	
Lighting Fixture - LED		
Instance on 1st Floor	Inspected	
Pendant Mounted		
Instance on 1st Floor	Does not exist	
Surface Mounted		
Instance on 1st Floor	Does not exist	
Recessed Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Local Sound System		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Installation Year	2018	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Projection System		

Building Condition Assessment Survey 2023-2024

icai inspection	KU
uestion	Response
AUDITORIUM	
Projection System	
Is the projector on a cart or installed on the ceiling?	Ceiling
Deficiency	No deficiencies recorded
Theater Lighting System	
Instance on 1st Floor	Inspected
Dimming System	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Theater Lighting	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
CAFETERIA	Inspected
Instance on 1st Floor - Students	
	Inspected
Instance on 1st Floor - Staff	Inspected
Lighting	
Instance on 1st Floor - Students	Inspected
Instance on 1st Floor - Staff	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor - Students	Inspected
Instance on 1st Floor - Staff	Inspected
Pendant Mounted	
Instance on 1st Floor - Students	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	130
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance on 1st Floor - Staff	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	28
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Surface Mounted	
Instance on 1st Floor - Students	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	28
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance on 1st Floor - Staff	Does not exist
Recessed Mounted	
Instance on 1st Floor - Students	Does not exist

Electrical Inspection	KU/2

-		
nestion	Response	
CAFETERIA		
Lighting		
Lighting Fixture - Fluorescent		
Recessed Mounted		
Instance on 1st Floor - Staff	Does not exist	
Lighting Fixture - HID		
Instance on 1st Floor - Students	Does not exist	
Instance on 1st Floor - Staff	Does not exist	
Lighting Fixture - Incandescent		
Instance on 1st Floor - Students	Does not exist	
Instance on 1st Floor - Staff	Does not exist	
Lighting Fixture - LED		
Instance on 1st Floor - Students	Does not exist	
Instance on 1st Floor - Staff	Does not exist	
Local Sound System		
Instance on 1st Floor - Students	Inspected	
Instance Condition	3- Fair	
Installation Year	2010	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Instance on 1st Floor - Staff	Does not exist	
Projection System		
Instance on 1st Floor - Students	Does not exist	
Instance on 1st Floor - Staff	Does not exist	
Theater Lighting System		
Instance on 1st Floor - Students	Does not exist	
Instance on 1st Floor - Staff	Does not exist	
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected	
Lighting	Inspected	
Does a Chandelier Exist?	No	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Inspected	
Condition	3- Fair	
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE	
Deficiency Quantity	880	
Quantity Uom	EACH	
Potential Action	REPLACE-UPGRADE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Surface Mounted	Inspected	
Condition	3- Fair	
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE	
Deficiency Quantity	1,252	
Quantity Uom	EACH	
Potential Action	REPLACE-UPGRADE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Recessed Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Inspected	

Building Condition Assessment Survey 2023-2024

icui Inspection		10/2
Question	Response	
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE		
Lighting		
Lighting Fixture - LED		
Pendant Mounted	Does not exist	
Surface Mounted	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Recessed Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
COMPUTER LAB	Does not exist	
GYMNASIUM	Inspected	
Instance on 1st Floor	Inspected	
Lighting	nispected	
Instance on 1st Floor	Inspected	
Lighting Fixture - Fluorescent	This parties	
Instance on 1st Floor	Does not exist	
Lighting Fixture - HID		
Instance on 1st Floor	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Instance on 1st Floor	Does not exist	
Lighting Fixture - LED	Does not exist	
Instance on 1st Floor	Inspected	
Pendant Mounted	nispecteu	
Instance on 1st Floor	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
Surface Mounted	No deficiencies recorded	
Instance on 1st Floor	Does not exist	
Recessed Mounted	Does not exist	
Instance on 1st Floor	Does not exist	
	Does not exist	
Local Sound System Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Installation Year	2010	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Projection System	110 001101011010 10001000	
Instance on 1st Floor	Does not exist	
Scoreboard		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Theater Lighting System	110 001101011010 10001000	
Instance on 1st Floor	Does not exist	
KITCHEN	Inspected	
Instance on 1st Floor	Inspected	
Lighting	пърсска	
Instance on 1st Floor	Inspected	
Lighting Fixture - Fluorescent	mspecceu	
Instance on 1st Floor	Inspected	
Pendant Mounted	mspecieu	
Instance on 1st Floor	Does not exist	
Surface Mounted	DOCS HOL CAISE	

Building Condition Assessment Survey 2023-2024

circui inspection	KU/2
Question	Response
KITCHEN	
Lighting	
Lighting Fixture - Fluorescent	
Surface Mounted	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	10
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Recessed Mounted	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	43
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Lighting Fixture - HID	
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not exist
Lighting Fixture - LED	
Instance on 1st Floor	Does not exist
LIBRARY	Inspected
Instance on Room 158	Inspected
Lighting	nispected
Instance on Room 158	Inspected
Lighting Fixture - Fluorescent	nispected
Instance on Room 158	Inspected
	nispected
Pendant Mounted Instance on Room 158	Dogs not exist
	Does not exist
Surface Mounted	Y 1
Instance on Room 158	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	56
Quantity Uom	EACH REPLACE-UPGRADE
Potential Action Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
	No violations recorded
Recessed Mounted	D
Instance on Room 158	Does not exist
Lighting Fixture - HID	
Instance on Room 158	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 158	Does not exist
Lighting Fixture - LED	
Instance on Room 158	Does not exist

Building Condition Assessment Survey 2023-2024

Question	Response	
LIBRARY		
Raceway With Receptacles		
Instance on Room 158	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Projection System		
Instance on Room 158	Does not exist	
LOCKER ROOM	Inspected	
Instance on 1st Floor - Boys, 1st Floor - Girls	Inspected	
Alternative Use	No	
Lighting	110	
Instance on 1st Floor - Boys, 1st Floor - Girls	Inspected	
Lighting Fixture - Fluorescent		
Instance on 1st Floor - Boys, 1st Floor - Girls	Inspected	
Pendant Mounted	шереска	
Instance on 1st Floor - Boys, 1st Floor - Girls	Does not exist	
Surface Mounted	Does not exist	
Instance on 1st Floor - Boys, 1st Floor - Girls	Inspected	
Instance Condition	3- Fair	
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE	
Deficiency Quantity	44	
Quantity Uom	EACH	
Potential Action	REPLACE-UPGRADE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Recessed Mounted		
Instance on 1st Floor - Boys, 1st Floor - Girls	Does not exist	
Lighting Fixture - HID		
Instance on 1st Floor - Boys, 1st Floor - Girls	Does not exist	
Lighting Fixture - Incandescent		
Instance on 1st Floor - Boys, 1st Floor - Girls	Does not exist	
Lighting Fixture - LED		
Instance on 1st Floor - Boys, 1st Floor - Girls	Does not exist	
MULTIPURPOSE ROOM	Does not exist	
SCIENCE DEMO ROOM	Does not exist	
SCIENCE LAB	Inspected	
Instance on Rooms: 125, 127	Inspected	
Power Panel?	Yes	
Alternative Use	No	
Instance on Rooms: 126,134, 152	Inspected	
Power Panel?	Yes	
Alternative Use	Yes	
Instance on Room 129	Inspected	
Power Panel?	Yes	
Alternative Use	Yes	
Instance on Rooms: 128, 132, 154	Inspected	
Power Panel?	Yes	
Alternative Use	No	
Lighting	110	
Instance on Rooms: 125, 127	Inspected	
motanee on recoilly, 147, 147	mopected	
Instance on Rooms: 126,134, 152	Inspected	

Duestion	Response	
SCIENCE LAB	Tesponse .	
Lighting		
Instance on Rooms: 128, 132, 154	Inspected	
Lighting Fixture - Fluorescent	1	
Instance on Rooms: 125, 127	Inspected	
Instance on Rooms: 126,134, 152	Inspected	
Instance on Room 129	Inspected	
Instance on Rooms: 128, 132, 154	Inspected	
Pendant Mounted	пърсска	
Instance on Rooms: 125, 127	Does not exist	
Instance on Rooms: 125, 127 Instance on Rooms: 126,134, 152	Inspected	
Instance Condition	3- Fair	
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE	
Deficiency Quantity	75	
Quantity Uom	EACH	
Potential Action	REPLACE-UPGRADE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Instance on Room 129	Does not exist	
Instance on Rooms: 128, 132, 154	Inspected	
Instance Condition	3- Fair	
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE	
Deficiency Quantity	75	
Quantity Uom	EACH	
Potential Action	REPLACE-UPGRADE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Surface Mounted		
Instance on Rooms: 125, 127	Inspected	
Instance Condition	3- Fair	
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE	
Deficiency Quantity	50	
Quantity Uom	EACH	
Potential Action	REPLACE-UPGRADE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Instance on Rooms: 126,134, 152	Does not exist	
Instance on Room 129	Inspected	
Instance Condition	3- Fair	
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE	
Deficiency Quantity	25	
Quantity Uom	EACH	
Potential Action	REPLACE-UPGRADE	
Urgency of Action	PRIORITY 1 LEVEL 2	
Purpose of Action Violations	No violations recorded	
Instance on Rooms: 128, 132, 154	Does not exist	
Recessed Mounted	Dana mat coviet	
Instance on Rooms: 125, 127	Does not exist	
Instance on Rooms: 126,134, 152	Does not exist	
Instance on Room 129	Does not exist Does not exist	

Electrical Inspection	R072
Question	Response

uestion	Response	
SCIENCE LAB		
Lighting		
Lighting Fixture - HID		
Instance on Rooms: 125, 127	Does not exist	
Instance on Rooms: 126,134, 152	Does not exist	
Instance on Room 129	Does not exist	
Instance on Rooms: 128, 132, 154	Does not exist	
Lighting Fixture - Incandescent		
Instance on Rooms: 125, 127	Does not exist	
Instance on Rooms: 126,134, 152	Does not exist	
Instance on Room 129	Does not exist	
Instance on Rooms: 128, 132, 154	Does not exist	
Lighting Fixture - LED		
Instance on Rooms: 125, 127	Does not exist	
Instance on Rooms: 126,134, 152	Does not exist	
Instance on Room 129	Does not exist	
Instance on Rooms: 128, 132, 154	Does not exist	
Emergency Gas Shut-Off Valve		
Instance on Rooms: 125, 127	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Rooms: 126,134, 152	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Room 129	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Rooms: 128, 132, 154	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Emergency Shut-Off Power		
Instance on Rooms: 125, 127	Does not exist	
Instance on Rooms: 126,134, 152	Does not exist	
Instance on Room 129	Does not exist	
Instance on Rooms: 128, 132, 154	Does not exist	
Power Supply		
Instance on Rooms: 125, 127	Does not exist	
Instance on Rooms: 126,134, 152	Does not exist	
Instance on Room 129	Does not exist	
Instance on Rooms: 128, 132, 154	Does not exist	
Projection System		
Instance on Rooms: 125, 127	Does not exist	
Instance on Rooms: 126,134, 152	Does not exist	
Instance on Room 129	Does not exist	
Instance on Rooms: 128, 132, 154	Does not exist	
SCIENCE PREP ROOM	Inspected	
Instance on Room 130	Inspected	
Power Panel?	No	
Alternative Use	Yes	
Lighting	105	
Instance on Room 130	Inspected	
Lighting Fixture - Fluorescent	пороска	
anguing riadure riduitation		

Building Condition Assessment Survey 2023-2024

teat inspection	107
uestion	Response
SCIENCE PREP ROOM	
Lighting	
Lighting Fixture - Fluorescent	
Pendant Mounted	
Instance on Room 130	Does not exist
Surface Mounted	
Instance on Room 130	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	33
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Recessed Mounted	
Instance on Room 130	Does not exist
Lighting Fixture - HID	
Instance on Room 130	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 130	Does not exist
Lighting Fixture - LED	
Instance on Room 130	Does not exist
Emergency Gas Shut-Off Valve	
Instance on Room 130	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Emergency Shut-Off Power	
Instance on Room 130	Does not exist
Power Supply	
Instance on Room 130	Does not exist
SWIMMING POOL	Does not exist
TOILET ROOM - STAFF	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not exist
Surface Mounted	Inspected
Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	26
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Recessed Mounted	Does not exist
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - Incandescent Lighting Fixture - LED	Does not exist
	Inspected
TOILET ROOM - STUDENT	Inspected
Lighting	nispected
	Inspected
Lighting Fixture - Fluorescent	Inspected Does not exist
	Inspected Does not exist Inspected

Building Condition Assessment Survey 2023-2024

ricai Inspection	KU/2
Question	Response
TOILET ROOM - STUDENT	
Lighting	
Lighting Fixture - Fluorescent	
Surface Mounted	
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	80
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Recessed Mounted	Does not exist
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
Condition	5- Poor
Deficiency	BELL TRANSFORMER PANEL NOT OPERATIONAL
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE PANEL
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
EMERGENCY DC STANDBY BATTERY POWER	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
EMERGENCY GENERATOR SET	Does not exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
EMERGENCY LIGHTING	Inspected
Battery Pack	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Non Battery Pack	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
EXIT LIGHT	Inspected
-	Inspected
Battery Pack Condition	1- Good
	No deficiencies recorded
Deficiency	
Non Battery Pack	Inspected 3- Fair
Condition	
Deficiency	No deficiencies recorded
EXIT/EMERGENCY LIGHT	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
FIRE ALARM SYSTEM	Inspected
Bell/Horn	Inspected
Condition	2- Between Good and Fair
D.c.;	37 10 1 1 1
Deficiency	No deficiencies recorded

Building Condition Assessment Survey 2023-2024

estion	Response	
RE ALARM SYSTEM		
Strobe		
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Manual Pull Station	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Fan Shutdown Control	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Duct Smoke Detector	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Area Smoke Detector	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
CO Detector	Does not exist	
Heat Detector	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Elevator Recall	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Magnetic Door Holder/Contactor	Does not exist	
Fused Cutout Panel	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Fire Alarm Digital Communicator	Does not exist	
Main Panel	Inspected	
Bell At Panel	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Electronic)	Inspected	
Instance	Main Entrance Lobby	
Instance Condition	2- Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	General Electric	
Model	EST 3	
EquipmentId	Fire Alarm Control Panel	
Installation Year	2011	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Standard)	Does not exist	
Sub-Panel	Does not exist	
Remote Annunciator	Inspected	
Display Monitor	Does not exist	
Panel	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Printer	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	

Building Condition Assessment Survey 2023-2024

	1072
Response	
Inspected	
2- Between Good and Fair	
No deficiencies recorded	
Inspected	
2- Between Good and Fair	
No deficiencies recorded	
Inspected	
3- Fair	
No deficiencies recorded	
No deficiencies recorded	
Inspected	
Inspected	
Auditorium Roof Mechanical Room	
3- Fair	
1	
EACH	
Federal Pacific Electric	
N/A	
200	
Amps	
1	
Gymnasium Roof Mechanical Room	
3- Fair	
	Inspected 2. Between Good and Fair No deficiencies recorded Inspected 2. Between Good and Fair No deficiencies recorded Inspected 3. Fair No deficiencies recorded Inspected 3. Fair No deficiencies recorded Inspected 3. Fair No deficiencies recorded Inspected 2. Between Good and Fair No deficiencies recorded Inspected 1. Sepected Inspected 3. Fair No deficiencies recorded Inspected 3. Fair No deficiencies recorded Inspected 3. Fair No deficiencies recorded Inspected 1. Good No deficiencies recorded Inspected Inspected 1. Good No deficiencies recorded Inspected Inspected 1. Good No deficiencies recorded Inspected Inspected

Building Condition Assessment Survey 2023-2024

	Response	
CONTROLLER		
OR CONTROL CENTER		
Manufacturer	Federal Pacific Electric	
EquipmentId	MCC-3	
Capacity/Size Quantity	200	
Capacity/Size UOM	Amps	
Capacity/Size 2 Quantity	1	
Capacity/Size 2 UOM	Section(s)	
Source of Capacity/Size	Inspector Estimate	
Installation Year	1976	
Source of Installation Year	Documented	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	Gymnasium Roof Mechanical Room	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Instance	Main Roof Mechanical Room	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Federal Pacific Electric	
EquipmentId	MCC-2	
Capacity/Size Quantity	400	
Capacity/Size UOM	Amps	
Capacity/Size 2 Quantity	2	
Capacity/Size 2 Quantity Capacity/Size 2 UOM	Section(s)	
Source of Capacity/Size	Inspector Estimate	
Installation Year	1976	
Source of Installation Year	Documented	
Deficiency	BEYOND USEFUL LIFE	
· · · · · · · · · · · · · · · · · · ·		
Deficiency Location/Instance	Main Roof Mechanical Room	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Instance	Mechanical Room B15	
Instance Condition	3- Fair	
Instance Quantity	1	
	EACH	
Instance Quantity Uom		
Manufacturer	Federal Pacific Electric	
EquipmentId	MCC-1	
Capacity/Size Quantity	400	
Capacity/Size UOM	Amps	
Capacity/Size 2 Quantity	2	
Capacity/Size 2 UOM	Section(s)	
Source of Capacity/Size	Inspector Estimate	
Installation Year	1976	
Source of Installation Year	Documented	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	Mechanical Room B15	
Deficiency Quantity	1	
Quantity Uom	EACH	

Electrical Inspection	RU/2

Response
REPLACE
PRIORITY 1
LEVEL 2
No violations recorded
Inspected
3- Fair
No deficiencies recorded
Does not exist
Inspected
Inspected
3- Fair
PANEL BOARD BEYOND USEFUL LIFE
Auditorium Roof Mechanical Room, Gymnasium Roof Mechanical Room, Main Roof Mechanical Room, Mechanical Room B15
8
EACH
REPLACE-UPGRADE
PRIORITY 1
LEVEL 2
No violations recorded
Does not exist
Inspected
3- Fair
PANEL BOARD BEYOND USEFUL LIFE
Electrical Room B11
1 Decre
EACH
REPLACE-UPGRADE PRIORITY 1
LEVEL 2
No violations recorded
Inspected
3- Fair
PANEL BOARD BEYOND USEFUL LIFE
Throughout the Building
32
EACH
REPLACE-UPGRADE
PRIORITY 1
LEVEL 2
No violations recorded
Inspected
MDF Room 161B
3- Fair
1
EACH
QSC ISA 300Ti
1976
Documented
MASTER CLOCK NOT OPERATIONAL
MASTER CLOCK NOT OPERATIONAL Main Office
MASTER CLOCK NOT OPERATIONAL Main Office 1

Ouestion	Response
PUBLIC ADDRESS SYSTEM	
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	CLOCK NOT OPERATIONAL
Deficiency Location/Instance	Throughout the Building
Deficiency Quantity	27
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	SPEAKER NOT OPERATIONAL
Deficiency Location/Instance Deficiency Quantity	4th and 2nd Floor 2
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	MDF Room 161B
Deficiency Quantity	174,000
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
SECURITY	Inspected
IPDVS/CCTV System	Inspected
Condition	1- Good
Installation Year	2021
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Intrusion Alarm System	Inspected
Central Control Panel	Inspected
Instance	Custodian Office - Room 103
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista - 50P
Installation Year	1990
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Custodian Office - Room 103
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 3
Violations	No violations recorded
Infrared Sensor	Inspected
Condition	4- Between Fair and Poor
Deficiency	SENSOR NOT OPERATIONAL

Building Condition Assessment Survey 2023-2024

icai ins	peciion		KU/
uestion		Response	
SECURIT			
	n Alarm System		
Infrare	d Sensor	21	
	Deficiency Quantity	31 FACIL	
	Quantity Uom Potential Action	EACH REPLACE	
	Urgency of Action	PRIORITY 4	
	Purpose of Action	LEVEL 3	
	Violations	No violations recorded	
Panic S		Inspected	
Cond		3- Fair	
	Deficiency	No deficiencies recorded	
	e Annunciator	Inspected	
Cond		2- Between Good and Fair	
		No deficiencies recorded	
	Deficiency		
Siren/S		Inspected	
Cond		3- Fair	
	Deficiency	No deficiencies recorded	
	- Security	Inaccessible	
SERVICE	SWITCH	Inspected	
	Instance	Electrical Room B11	
	Instance Condition	1- Good	
	Instance Quantity	1	
	Instance Quantity Uom	EACH	
	Manufacturer	Siemens	
	EquipmentId	1200A Main Disconnect	
	Capacity/Size Quantity	1200	
	Capacity/Size UOM	Amps	
	Source of Capacity/Size	Nameplate	
	Installation Year	2023	
	Source of Installation Year	Documented	
	Deficiency	No deficiencies recorded	
	Instance	Electrical Room B11	
	Instance Condition	2- Between Good and Fair	
	Instance Quantity	1	
	Instance Quantity Uom	EACH	
	Manufacturer	Square D	
	EquipmentId	ACDP	
	Capacity/Size Quantity	400	
	Capacity/Size UOM Source of Capacity/Size	Amps Nameplate	
	Installation Year	2018	
	Source of Installation Year	Documented	
	Deficiency	No deficiencies recorded	
	Instance	Electrical Room B11	
	Instance Condition	3- Fair	
	Instance Quantity	1	
	· · · · · · · · · · · · · · · · · · ·	EACH	
	Instance Quantity Uom		
	Manufacturer	Federal Pacific Electric	
	EquipmentId Capacity/Size Quantity	SER SW #1 5000	
	Capacity/Size Quantity Capacity/Size UOM		
	Capacity/Size UOM Source of Capacity/Size	Amps Nameplate	
	Installation Year	Namepiate 1976	
	Installation Voor		

Building Condition Assessment Survey 2023-2024

Question	Response
SERVICE SWITCH	
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room B11
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Electrical Room B11
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	I.T.E.
EquipmentId	SER SW #2
Capacity/Size Quantity	800
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1976
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room B11
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Electrical Room B11 3- Fair
Instance Condition	
Instance Quantity	1 EACH
Instance Quantity Uom	
Manufacturer	Federal Electric Panel
EquipmentId	SER SW #4
Capacity/Size Quantity	400
Capacity/Size UOM Source of Capacity/Size	Amps Nameplate
Installation Year	1976
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room B11
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
SWITCHBOARD	Inspected
Number of Spares	6
Fused Disconnect Switch Type	Inspected
Instance	Electrical Room B11
Instance Condition	2- Between Good and Fair
Instance Quantity	1
	EACH
Instance Quantity Uom	
M. C.	
Manufacturer EquipmentId	Siemens ACDP

Building Condition Assessment Survey 2023-2024

uestion	Response
SWITCHBOARD	
Fused Disconnect Switch Type	
Capacity/Size Quantity	400
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	1
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Service Switch Size
Installation Year	2018
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room B11
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Federal Pacific Electric
EquipmentId	N/A
Capacity/Size Quantity	5000
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	5
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Service Switch Size
Installation Year	1976
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room B11
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Fused Knife Switch Type	Does not exist
Molded Case Circuit Breaker Type	Does not exist
TELEPHONE SYSTEM	Inspected
PBX/Intercom	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Standard	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
TRANSFORMER	Does not exist
IKANSFUKMEK	DOGS HOT CYIST