## **Building Condition Assessment Survey 2023-2024**

Asset:		@ 841 FATHER CAPODANN D, STATEN ISLAND, NY, 1030		D - STATEN ISI	LAND, 841 FA	ATHER CAPO	ODANNO
Inspection Id Inspection Type				Time In 2024-03-06 11:34AM		Last Edited	
3727 MECHANICAL						-03-06 11:34AN	M 2024-03-06 01:25PM
set Data							
Question				Answer			
Have any Sv	Systems/Major Buildi	ng Components been upgraded?		No System	n Upgraded		
Are there fu	•			No	10		
Total # of water main service entries to the asset				1			
	Rooms Locations			None			
Are there ar	ny spaces with Missi	ng or Defective CO Detectors?		No			
	ny Painted/Obstructe			No			
Are there ar	ny Emergency Stop S	Switches with Missing Hammers?		No compo	onents		
iority Cond	dition						
xist l	Priority	Condition	Component	Location	Person(s)	Person(s)	Photo
ast Year?	Category	Description	Affected	Description	Notified	Title	Image
No conditio	on recorded						
spection							
Question				Response	<b>,</b>		
Mechanica	 il			•			
AIR CON	NDITIONING			Inspected			
	l Water System			Does not			
-		tion: Piping, Pumps and Auxiliarie	es	Does not			
-	g Coil in Ductwork	F 9/ 1 F 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	-	Does not	exist		
	g Tower		Does not exist				
DX Spli	lit System		Inspected				
Indoo	or Unit		Inspected				
Con	ndition		1- Good				
	Deficiency		No deficiencies recorded				
Outdo	oor Unit			Inspected			
Con	ndition			1- Good			
	Deficiency		No deficiencies recorded				
Dry Co	ooler		Does not exist				
Package	ged / Rooftop Unit			Does not	exist		
	ged Terminal A/C			Does not			
	erant Leak Detection	1 System		Does not			
	erant Piping			Inspected 1- Good			
Condi					: 1.1		
	Deficiency				encies recorded		
Return				Does not			
		EUTRALIZING TANK		Does not			
CLIMAT	TE CONTROL SYS	ГЕМ		Does not			
COMPACTOR				Does not	exist		
CONVEYING				Inspected			
Dumbwaiter				Does not			
Elevator				Inspected			
Condition				1- Good			
Are al	ll the existing elevator	ors operable?		No			
	Deficiency				encies recorded		
Escalator				Does not			
Non-auditorium Handicap Lift - Vertical				Does not			
Non-auditorium Handicap Lift - Stair				Does not			
Ash Ho	oist			Does not	ex1st		

## **Building Condition Assessment Survey 2023-2024**

Mechanical Inspection R113

municui Inspeciion		KIIS
Question	Response	
DOMESTIC WATER SYSTEM	Inspected	
Domestic Cold Water System	Inspected	
Gravity System	Does not exist	
Pressure Booster System	Does not exist	
Water Service	Inspected	
Instance	Sprinkler/Water Meter Room B5	
Instance Condition	1- Good	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Deficiency	No deficiencies recorded	
Domestic Hot Water System	Inspected	
Domestic Hot Water Remote Storage Tank	Does not exist	
Domestic Water Heat Exchanger	Does not exist	
Electric Domestic Water Heater	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Gas Fired Domestic Water Heater	Does not exist	
Oil Fired Domestic Water Heater	Does not exist	
Heat Pump Domestic Water Heater	Does not exist	
Domestic Water Distribution Piping	Inspected	
Condition	1- Good	
Deficiency	DAMAGED/MISSING INSULATION	
Deficiency Location/Instance	Room 202	
Deficiency Quantity	50	
Quantity Uom	L.F.	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
DRAIN/WASTE/VENT AND STORM SYSTEM	Inspected	
Interior Storm Piping	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Sewage/Waste/Vent Piping	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Sewage Ejector Pump	Does not exist	
Sump Pump	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
DUAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)	Does not exist	
FIXTURES	Inspected	
Staff And Other	Inspected	
Janitor Sink	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Lavatory/Sink	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
	Inspected	
Toilet		
Condition	1- Good	
Deficiency	No deficiencies recorded	
Urinal	Does not exist	
Student	Inspected	
		_

## **Building Condition Assessment Survey 2023-2024**

Mechanical Inspection R113

Question	Response
FIXTURES	<u> </u>
Student	
Drinking Fountain	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Lavatory/Sink	Inspected
Condition	1- Good
	No deficiencies recorded
Deficiency	Does not exist
Locker Room Shower	
Sink And Fountain Combo Unit	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Toilet	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Urinal	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
GAS FIRED FURNACE	Does not exist
	Does not exist
GAS SERVICE	
HEATING	Inspected
Heating Coil In Ductwork	Does not exist
Hydronic Heating	Does not exist
Radiator/Convector/Fin Tube	Does not exist
Steam Heating	Does not exist
Steam supplied by External Sources	Does not exist
Unit Heater/Cabinet Heater Condition	Inspected 1- Good
	No deficiencies recorded
Deficiency	
HEATING PLANT	Does not exist
Enclosed IDF Room	Does not exist
KITCHEN	Inspected
Instance on 1st Floor	Inspected
CO Detector	
Instance on 1st Floor	Not required
Gas System	
Instance on 1st Floor	Does not exist
Grease Trap	
Instance on 1st Floor	Does not exist
Hood	
Instance on 1st Floor	Does not exist
Hood Exhaust Ductwork	
Instance on 1st Floor	Does not exist
Hood Exhaust Fan	
Instance on 1st Floor	Does not exist
Hood Fire Suppression System	
Instance on 1st Floor	Does not exist
Hot Water Temperature Booster	
Instance on 1st Floor	Does not exist
Kitchen Sink	
Instance on 1st Floor	Inspected
Instance Condition	1- Good
Deficiency	MISSING INDIRECT WASTE
Deficiency Location/Instance	Kitchen
•	

## **Building Condition Assessment Survey 2023-2024**

Mechanical Inspection R113

uestion	Response	
KITCHEN		
Kitchen Sink		
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	INSTALL	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
MDF Room	Inspected	
Instance on Room 200	Inspected	
Dedicated A/C Equipment		
Instance on Room 200	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
SCIENCE DEMO ROOM	Does not exist	
SCIENCE LAB	Does not exist	
SCIENCE PREP ROOM	Does not exist	
SPRINKLERS, STANDPIPE, FIRE SYSTEM	Inspected	
Dry Sprinkler Alarm Valve Assembly	Does not exist	
Wet Sprinkler Alarm Valve Assembly	Does not exist	
Fire Booster Pump Assembly	Does not exist	
Roof Tank	Does not exist	
Siamese Connection	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Sprinkler Head	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Sprinkler Piping	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Standpipe System	Does not exist	
Water Gong	Does not exist	
SWIMMING POOL	Does not exist	
VENTILATION	Inspected	
Is the building Mechanically ventilated?	Yes	
Exhaust Fan	Inspected	
Condition	1- Good	
Approximate Total # of Fans	1-25	
Deficiency	No deficiencies recorded	
Heating And Ventilating Unit	Does not exist	
Metal Ductwork	Inspected	
Condition	1- Good	
Are there any uninsulated ductwork by design in Mechanical rooms?	No	
Are there chain operated dampers?	No	
Deficiency	No deficiencies recorded	
Supply Fan	Does not exist	