Building Condition Assessment Survey 2023-2024

lectrical Inspe	ection						R8
Asset:	P.S. 42 ANNEX -	STATEN ISLAND, 25 AU	GUSTA AVENU	E, STATEN ISL	AND, NY, 10312		
Inspection Id	Inspection Type				Time In		Last Edited
3170	ELECTRICAL				2024-02-13	10:10AN	1 2024-03-06 12:44PM
sset Data							
Question				Answer			
Have any Syste	ms/Major Building Co	omponents been upgraded?		Systems:	LAN (IDF)		
				Years:	2022		
				Systems:	Intrusion Alarm Syst	tem (Parti	al Remote Annunciator)
				Years:	2021		
				Systems:	Exit Lights (Battery	Pack)	
				Years:	2020		
				Systems:	Telephone System		
				Years:	2018		
				Systems:	Lighting - Security		
				Years:	2014, 2005		
				Systems:	Interior Lighting		
				Years:	2014		
				Systems:	IPDVS/CCTV Syste	m	
				Years:	2012		
				Systems:	Public Address Syste	em, Local	Sound System, Fire
					Alarm System		
				Years:	2007	· D 1	D 1D 1
				Systems:	Molded Case Circuit	t Breaker	Panel Board
				Years:	2006, 2002, 2000		
				Systems:	•	tem, Servi	ice Switch, Switchboard
				Years:	2006		
				Systems:	Emergency Light/Ex	at Light P	anel
				Years:	2001		
Type of Service				Below Gr	ouna		
	e Whiteboard (IWB) E on In Electrical Room			Yes No			
		FIRE RESCUE AREAS		NO			
Question	TITERCOMS III	TIKE RESCUE AREAS		ī	Response		
	Life Rescue Assistan	ce Areas, Fire Rescue Areas, an	nd/or Holding Rooi		No		
your building							
riority Conditi							
Exist Prio Last Year? Cate	ority egory	Condition Description	Component Affected	Location Description	Person(s) Person	son(s)	Photo Image
No condition re		Description	Ancticu	Description	Notified Title		Image
nspection							
Question				Response			
Electrical							
ATHLETIC	FIELD			Does not	exist		
AUDITORIUM			Does not o	exist			
CAFETERIA			Does not	exist			
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE			Inspected				
Lighting				Inspected			
	nandelier Exist?			No			
	Fixture - Fluorescent			Inspected			
-	t Mounted			Inspected	C 1 1F:		
Condi					n Good and Fair		
	eficiency				encies recorded		
	Mounted			Inspected			
Condi	tion			2- Betwee	n Good and Fair		

Building Condition Assessment Survey 2023-2024

Electrical Inspection	R848
	_

Question	Response
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	
Lighting	
Lighting Fixture - Fluorescent	
Surface Mounted	
Deficiency	No deficiencies recorded
Recessed Mounted	Does not exist
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
COMPUTER LAB	Does not exist
GYMNASIUM	Does not exist
KITCHEN	Does not exist
LIBRARY	Does not exist
	Does not exist
LOCKER ROOM	
MULTIPURPOSE ROOM	Inspected
Instance on 1st Floor	Inspected
Lighting	Y 1
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	*
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not exist
Surface Mounted	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on 1st Floor	Does not exist
Lighting Fixture - HID	
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not exist
Lighting Fixture - LED	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not exist
Surface Mounted	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE NOT OPERATIONAL
Deficiency Quantity	8
Quantity Uom	EACH PEN AGE
Potential Action	REPLACE PRIORITY 3
Urgency of Action Purpose of Action	LEVEL 2
Violations	No violations recorded
	No violations recorded
Recessed Mounted Instance on 1st Floor	Does not exist
	Does not exist
Local Sound System Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Installation Year	2007
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
·	
C Daytung Vancion 2.0 (D)	Print Data: 9/9/2024

Building Condition Assessment Survey 2023-2024

ricai Inspection	N04
Question	Response
MULTIPURPOSE ROOM	
Projection System	
Instance on 1st Floor	Does not exist
Theater Lighting System	
Instance on 1st Floor	Does not exist
SCIENCE DEMO ROOM	Does not exist
SCIENCE LAB	Does not exist
SCIENCE PREP ROOM	Does not exist
	Does not exist
SWIMMING POOL	
TOILET ROOM - STAFF	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not exist
Surface Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not exist
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not exist
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
Condition	3- Fair
Deficiency	DOOR PUSH BUTTON NOT OPERATIONAL
Deficiency Location/Instance	Kitchen Back Door
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
EMERGENCY DC STANDBY BATTERY POWER	Does not exist
EMERGENCY GENERATOR SET	Does not exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
EMERGENCY LIGHTING	Inspected
Battery Pack	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Non Battery Pack	Inspected

Building Condition Assessment Survey 2023-2024

icui Inspection		1040
uestion	Response	
EMERGENCY LIGHTING		
Non Battery Pack		
Condition	3- Fair	
Deficiency	No deficiencies recorded	
EXIT LIGHT	Inspected	
Battery Pack	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Non Battery Pack	Does not exist	
EXIT/EMERGENCY LIGHT	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
FIRE ALARM SYSTEM	Inspected	
Bell/Horn	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Strobe	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Manual Pull Station	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Fan Shutdown Control	Does not exist	
Duct Smoke Detector	Does not exist	
Area Smoke Detector	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
CO Detector	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Heat Detector	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Elevator Recall	Does not exist	
Magnetic Door Holder/Contactor	Does not exist	
Fused Cutout Panel	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Fire Alarm Digital Communicator	Does not exist	
Main Panel	Inspected	
Bell At Panel	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Electronic)	Inspected	
Instance	Main Entrance Lobby	
Instance Condition	2- Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	ЕАСН	
Manufacturer	Edwards System Technology	
Model	EST 2	
EquipmentId	Fire Alarm Control Panel	
Installation Year	2007	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	

Building Condition Assessment Survey 2023-2024

incui inspection		1040
Question	Response	
FIRE ALARM SYSTEM		
Main Panel		
Fire Alarm Control Panel (Standard)	Does not exist	
Sub-Panel	Does not exist	
Remote Annunciator	Inspected	
Display Monitor	Does not exist	
Panel	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Printer	Does not exist	
Punch Register	Does not exist	
Sprinkler Flow/Air Pressure Switch	Does not exist	
Tamper Flow Switch/Chain	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
GROUNDING SYSTEM	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
INTERCOM SYSTEM	Does not exist	
LAN	Inspected	
Local Distribution Frame (I/LDF)	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Main Equipment Rack (MDF)	Does not exist	
LIGHTNING PROTECTION	Does not exist	
MOTOR CONTROLLER	Inspected	
MOTOR CONTROL CENTER	Does not exist Inspected	
MOTOR STARTER/CONTACTOR Condition	3- Fair	
Deficiency	No deficiencies recorded	
Variable Frequency Drive	Does not exist	
PANEL BOARD	Inspected	
	Does not exist	
Fused Disconnect Switch Type Fused Knife Switch Type	Does not exist	
Fused Toggle Switch Type	Does not exist	
Molded Case Circuit Breaker Type	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
PUBLIC ADDRESS SYSTEM	Inspected	
Instance	Room 107	
Instance Condition	3- Fair	
Instance Quantity	1	
	EACH	
Instance Quantity Uom Model		
	Dukane 250 2007	
Installation Year Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
SECURITY	Inspected	
IPDVS/CCTV System	Inspected 2- Between Good and Fair	
Condition Installation Year		
Installation Year Source of Installation Year	2012 Documented	
Deficiency	No deficiencies recorded	
Deficiency	NO deficiencies recorded	

Building Condition Assessment Survey 2023-2024

. tem impresses		
Question	Response	
SECURITY		
Intrusion Alarm System		
Central Control Panel	Inspected	
Instance	Room B57	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Model	Vista - 128BP	
Installation Year	2006	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Infrared Sensor	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Panic Switch	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Remote Annunciator	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Siren/Strobe	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Lighting - Security	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
SERVICE SWITCH	Inspected	
Instance	Electrical Room 2- Between Good and Fair	
Instance Condition		
Instance Quantity	1 EACH	
Instance Quantity Uom		
Manufacturer	All City Switchboard	
EquipmentId	Main Disconnect 800	
Capacity/Size Quantity Capacity/Size UOM		
Source of Capacity/Size	Amps Nameplate	
Installation Year	2006	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
SWITCHBOARD	Inspected	
Number of Spares	0	
Fused Disconnect Switch Type	Inspected	
Instance	Electrical Room	
Instance Condition	2- Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	All City Switchboard	
EquipmentId	MDP Section 1, 2	
Capacity/Size Quantity	800	
Capacity/Size UOM	Amps Total	
Capacity/Size 2 Quantity	2	
Capacity/Size 2 UOM	Section(s)	
Source of Capacity/Size	Service Switch Size	
Installation Year	2006	
Source of Installation Year	Documented	

Building Condition Assessment Survey 2023-2024

Question	Response	
SWITCHBOARD		
Fused Disconnect Switch Type		
Deficiency	No deficiencies recorded	
Fused Knife Switch Type	Does not exist	
Molded Case Circuit Breaker Type	Does not exist	
TELEPHONE SYSTEM	Inspected	
PBX/Intercom	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Standard	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
TRANSFORMER	Does not exist	