Building Condition Assessment Survey 2023-2024

Electrical In	spection	X022
Asset:	I.S. 22 - BRONX, 270 EAST 167 STREET, BRONX, NY, 10456	

Inspection Id Inspection Type			Time In	Last Edited	
2637 ELECTRICAL			2024-01-24 08:27AM	2024-06-05 12:53PM	
sset Data					
Question		Answer			
Have any Systems/Major Building Components been upgraded?		Systems:	Gymnasiums (LED Lighting and Emergency Lights)	d Non Battery	
		Years:	2023		
		Systems:	Partial Molded Case Circuit Bre	aker Panel Boards	
		Years:	2022, 2013, 2000, 1998		
		Systems:	: IPDVS/CCTV System		
		Years:	2019		
		Systems:	Security Lighting		
		Years:	2018, 1999		
		Systems:	Exit Lights (Battery Pack), Inter 2nd and 3rd Floor Corridors)	ior Lighting (Except	
		Years:	2016		
		Systems:	Fire Alarm System, Public Addr. Sound System	ess System, Local	
		Years:	2015		
		Systems:	Telephone System		
		Years:	2014		
		Systems:	Fluorescent Lighting (2nd, 3rd F	Floor Corridors)	
		Years:	2009		
		Systems:	Intrusion Alarm System		
		Years:	2004		
Type of Service		Below Gr	ound		
Does Interactive Whiteboard (IWB) Exist?		Yes			
Water Penetration In Electrical Room?		No			
DEDICATED INTERCOMS IN FIRE RESCUE AREAS					
Question			Response		
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, a your building?	nd/or Holding Roon	ns in N	No		
riority Condition					
Exist Priority Condition	Component	Location	Person(s) Person(s) F	Photo	
Last Year? Category Description	Affected	Description		mage	

Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image
No	Fire Alarm System - Components Not Operational	Not Operational	Fire Alarm System - Area Smoke	Outside Room B37	Andrew McKenna	Custodian	No Photo Taken
			Detector				

Inspection

specuon	
Question	Response
Electrical	
ATHLETIC FIELD	Does not exist
AUDITORIUM	Inspected
Instance on 1st Floor	Inspected
House Lighting	
Instance on 1st Floor	Inspected
Does a Chandelier Exist?	No
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not exist
Surface Mounted	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair

Building Condition Assessment Survey 2023-2024

Question	Response
AUDITORIUM	•
House Lighting	
Lighting Fixture - Fluorescent	
Surface Mounted	
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on 1st Floor	Does not exist
Lighting Fixture - HID	Does not exist
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	DOGS HOT CALST
Instance on 1st Floor	Does not exist
Lighting Fixture - LED	DOCS HOT CAIST
Instance on 1st Floor	Inspected
Pendant Mounted	inspected
	Description of the second seco
Instance on 1st Floor	Does not exist
Surface Mounted	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Local Sound System	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Installation Year	2015
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Projection System	
Instance on 1st Floor	Does not exist
Theater Lighting System	
Instance on 1st Floor	Inspected
Dimming System	
Instance on 1st Floor	Inspected
Instance Condition	5- Poor
Deficiency	DIMMING RACK/LIGHT CONSOLE NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Theater Lighting	
Instance on 1st Floor	Inspected
Instance Condition	5- Poor
Deficiency	LIGHTING FIXTURE NOT OPERATIONAL
Deficiency Quantity	96
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
CAFETERIA	Inspected

Building Condition Assessment Survey 2023-2024

Electrical InspectionX022QuestionResponse

Question	Response
CAFETERIA	
Lighting	
Instance on Basement	Inspected
Lighting Fixture - Fluorescent	
Instance on Basement	Inspected
Pendant Mounted	
Instance on Basement	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Basement	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Basement	Does not exist
Lighting Fixture - HID	
Instance on Basement	Does not exist
Lighting Fixture - Incandescent	
Instance on Basement	Does not exist
Lighting Fixture - LED	
Instance on Basement	Does not exist
Local Sound System	
Instance on Basement	Inspected
Instance Condition	2- Between Good and Fair
Installation Year	2015
Source of Installation Year	Documented 1.1
Deficiency	No deficiencies recorded
Projection System Instance on Basement	Does not exist
Theater Lighting System	Does not exist
Instance on Basement	Does not exist
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected
Lighting	Inspected
Does a Chandelier Exist?	No
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
COMPUTER LAB	Does not exist
GYMNASIUM	Inspected
Instance on Basement - East	Inspected
Instance on Basement - West	Inspected
Lighting	<u> </u>
Instance on Basement - East	Inspected
Instance on Basement - West	Inspected
	-

Building Condition Assessment Survey 2023-2024

uestion	Response	
·	Керине	
GYMNASIUM		
Lighting		
Lighting Fixture - Fluorescent	D	
Instance on Basement - East	Does not exist	
Instance on Basement - West	Does not exist	
Lighting Fixture - HID		
Instance on Basement - East	Does not exist	
Instance on Basement - West	Does not exist	
Lighting Fixture - Incandescent		
Instance on Basement - East	Does not exist	
Instance on Basement - West	Does not exist	
Lighting Fixture - LED		
Instance on Basement - East	Inspected	
Instance on Basement - West	Inspected	
Pendant Mounted		
Instance on Basement - East	Does not exist	
Instance on Basement - West	Does not exist	
Surface Mounted		
Instance on Basement - East	Does not exist	
Instance on Basement - West	Does not exist	
Recessed Mounted		
Instance on Basement - East	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
Instance on Basement - West	Inspected	
Instance Condition	1- Good	
	No deficiencies recorded	
Deficiency	No deficiencies recorded	
Local Sound System Instance on Basement - East	I 1	
	Inspected 2- Between Good and Fair	
Instance Condition Installation Year	2015	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Instance on Basement - West	Inspected 2- Between Good and Fair	
Instance Condition		
Installation Year Source of Installation Year	2015 Documented	
Deficiency	No deficiencies recorded	
	No deficiencies recorded	
Projection System Instance on Basement - East	Does not exist	
Instance on Basement - West	Does not exist	
Scoreboard Instance on Possement Foot	D	
Instance on Basement - East	Does not exist	
Instance on Basement - West	Inspected	
Instance Condition	5- Poor	
Deficiency	NOT OPERATIONAL	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	

Does not exist

Theater Lighting System

Instance on Basement - East

Building Condition Assessment Survey 2023-2024

ricai inspection	XU
Question	Response
GYMNASIUM	
Theater Lighting System	
Instance on Basement - West	Does not exist
KITCHEN	Inspected
Instance on Basement	Inspected
Lighting	
Instance on Basement	Inspected
Lighting Fixture - Fluorescent	
Instance on Basement	Inspected
Pendant Mounted	
Instance on Basement	Does not exist
Surface Mounted	
Instance on Basement	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Basement	Does not exist
Lighting Fixture - HID	
Instance on Basement	Does not exist
Lighting Fixture - Incandescent	
Instance on Basement	Does not exist
Lighting Fixture - LED	
Instance on Basement	Does not exist
LIBRARY	Inspected
Instance on Room 215	Inspected
Lighting	mapetee
Instance on Room 215	Inspected
Lighting Fixture - Fluorescent	шерене
Instance on Room 215	Inspected
Pendant Mounted	map*****
Instance on Room 215	Does not exist
Surface Mounted	DOGS HOT CAIST
Instance on Room 215	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	No deficiencies recorded
Instance on Room 215	Does not exist
	Does not exist
Lighting Fixture - HID Instance on Room 215	Does not exist
	Does not exist
Lighting Fixture - Incandescent	Does not exist
Instance on Room 215	Does not exist
Lighting Fixture - LED	Door and wind
Instance on Room 215	Does not exist
Raceway With Receptacles Instance on Room 215	Does not exist
	Does not exist
Projection System Instance on Room 215	Does not exist
LOCKER ROOM	Inspected
Instance on Room B35 - Girls	Inaccessible
MULTIPURPOSE ROOM	Does not exist
SCIENCE DEMO ROOM	Inspected
Instance on Room 338	Inspected

Building Condition Assessment Survey 2023-2024

Duestion	Response	
SCIENCE DEMO ROOM		
Alternative Use	Yes	
Lighting	105	
Instance on Room 338	Inspected	
Lighting Fixture - Fluorescent		
Instance on Room 338	Inspected	
Pendant Mounted	1	
Instance on Room 338	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on Room 338	Does not exist	
Recessed Mounted		
Instance on Room 338	Does not exist	
Lighting Fixture - HID		
Instance on Room 338	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 338	Does not exist	
Lighting Fixture - LED		
Instance on Room 338	Does not exist	
Emergency Gas Shut-Off Valve		
Instance on Room 338	Does not exist	
Emergency Shut-Off Power		
Instance on Room 338	Does not exist	
Power Supply		
Instance on Room 338	Does not exist	
Projection System		
Instance on Room 338	Does not exist	
SCIENCE LAB	Inspected	
Instance on Rooms 234, 238	Inspected	
Power Panel?	No	
Alternative Use	No	
Lighting		
Instance on Rooms 234, 238	Inspected	
Lighting Fixture - Fluorescent		
Instance on Rooms 234, 238	Inspected	
Pendant Mounted		
Instance on Rooms 234, 238	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on Rooms 234, 238	Does not exist	
Recessed Mounted		
Instance on Rooms 234, 238	Does not exist	
Lighting Fixture - HID		
Instance on Rooms 234, 238	Does not exist	
Lighting Fixture - Incandescent		
Instance on Rooms 234, 238	Does not exist	
Lighting Fixture - LED		
Instance on Rooms 234, 238	Does not exist	
Emergency Gas Shut-Off Valve		
Instance on Rooms 234, 238	Inspected	

Building Condition Assessment Survey 2023-2024

ciricai Inspection		AUZZ
Question	Response	
SCIENCE LAB		
Emergency Shut-Off Power		
Instance on Rooms 234, 238	Does not exist	
Power Supply		
Instance on Rooms 234, 238	Does not exist	
Projection System		
Instance on Rooms 234, 238	Does not exist	
SCIENCE PREP ROOM	Inspected	
Instance on Rooms 236, 237	Inspected	
Power Panel?	No	
Alternative Use	Yes	
Lighting		
Instance on Rooms 236, 237	Inspected	
Lighting Fixture - Fluorescent		
Instance on Rooms 236, 237	Inspected	
Pendant Mounted		
Instance on Rooms 236, 237	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on Rooms 236, 237	Does not exist	
Recessed Mounted		
Instance on Rooms 236, 237	Does not exist	
Lighting Fixture - HID		
Instance on Rooms 236, 237	Does not exist	
Lighting Fixture - Incandescent		
Instance on Rooms 236, 237	Does not exist	
Lighting Fixture - LED		
Instance on Rooms 236, 237	Does not exist	
Emergency Gas Shut-Off Valve		
Instance on Rooms 236, 237	Does not exist	
Emergency Shut-Off Power		
Instance on Rooms 236, 237	Does not exist	
Power Supply		
Instance on Rooms 236, 237	Does not exist	
SWIMMING POOL	Does not exist	
TOILET ROOM - STAFF	Inspected	
Lighting	Inspected	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Does not exist	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - Healiusecht Lighting Fixture - LED	Does not exist	
TOILET ROOM - STUDENT	Inspected	
	Inspected	
Lighting Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Inspected	
Condition	2- Between Good and Fair	
Collulion	2- Detween Good and Fan	

Building Condition Assessment Survey 2023-2024

rical Inspection	X
uestion	Response
TOILET ROOM - STUDENT	
Lighting	
Lighting Fixture - Fluorescent	
Pendant Mounted	
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not exist
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
Condition	5- Poor
Deficiency	BELL TRANSFORMER PANEL NOT OPERATIONAL
Deficiency Location/Instance	Electrical Room B11
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE PANEL
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
EMERGENCY DC STANDBY BATTERY POWER	Does not exist
EMERGENCY GENERATOR SET	Does not exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
EMERGENCY LIGHTING	Inspected
Battery Pack	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Non Battery Pack	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
EXIT LIGHT	Inspected
Battery Pack	Inspected
Condition	3- Fair
Deficiency	FIXTURE NOT OPERATIONAL
Deficiency Location/Instance	Staircase G/3
Deficiency Quantity	Staticase 0/3
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 4
Violations	35663343R
Holatons	35663344Z
Non Battery Pack	Does not exist
EXIT/EMERGENCY LIGHT	Does not exist
FIRE ALARM SYSTEM	Inspected
Bell/Horn	Inspected
Rell/Horn Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
	Inspected
Strobe	півресісц

Building Condition Assessment Survey 2023-2024

-		
estion	Response	
IRE ALARM SYSTEM		
Strobe		
Deficiency	No deficiencies recorded	
Manual Pull Station	Inspected	-
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Fan Shutdown Control	Inspected	
Condition	2- Between Good and Fair	-
Deficiency	No deficiencies recorded	
Duct Smoke Detector	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	-
Area Smoke Detector	Inspected	
Condition	2- Between Good and Fair	
Deficiency	DETECTOR NOT OPERATIONAL	
Deficiency Location/Instance	Outside Room B37	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 6	
Violations	No violations recorded	
CO Detector	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
<u> </u>	Inspected	
Heat Detector Condition	2- Between Good and Fair	
	No deficiencies recorded	
Deficiency	Does not exist	
Elevator Recall	Does not exist Does not exist	
Magnetic Door Holder/Contactor Fused Cutout Panel	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
	Does not exist	
Fire Alarm Digital Communicator	Inspected	
Main Panel	Does not exist	
Bell At Panel	Inspected	
Fire Alarm Control Panel (Electronic)	*	
Instance	Main Entrance Lobby	
Instance Condition	2- Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Edwards System Technology	
Model	EST3X	
EquipmentId	Fire Alarm Control Panel	
Installation Year	2015	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Standard)	Does not exist	
Sub-Panel	Does not exist	
Remote Annunciator	Inspected	
Display Monitor	Does not exist	
Panel	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Printer	Inspected	

Building Condition Assessment Survey 2023-2024

Question	Response
FIRE ALARM SYSTEM	
Remote Annunciator	
Printer	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Punch Register	Does not exist
Sprinkler Flow/Air Pressure Switch	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Tamper Flow Switch/Chain	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
GROUNDING SYSTEM	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
INTERCOM SYSTEM	Does not exist
LAN	Inspected
Local Distribution Frame (I/LDF)	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	Does not exist
MOTOR CONTROLLER	Inspected
MOTOR CONTROL CENTER	Does not exist
MOTOR STARTER/CONTACTOR	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Variable Frequency Drive	Does not exist
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Does not exist
Fused Knife Switch Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Mechanical Rooms 220, 240, 252 and Boiler Room
Deficiency Quantity	5
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action Violations	LEVEL 2
	No violations recorded Inspected
Fused Toggle Switch Type Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room B11
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Molded Case Circuit Breaker Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE

Building Condition Assessment Survey 2023-2024

estion	Response	
PANEL BOARD		
Molded Case Circuit Breaker Type		
Deficiency Location/Instance	Throughout the Building	
Deficiency Quantity	25	
Quantity Uom	EACH	
Potential Action	REPLACE-UPGRADE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
PUBLIC ADDRESS SYSTEM	Inspected	
Instance	Room 143	
Instance Condition	2- Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Model	Telecor XL	
Installation Year	2015	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
SECURITY	Inspected	
IPDVS/CCTV System	Inspected	
Condition	2- Between Good and Fair	
Installation Year	2019	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Intrusion Alarm System	Inspected	
Central Control Panel	Inspected	
Instance	Custodian's Office	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Model	Vista - 128B	
Installation Year	2004	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Infrared Sensor	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Panic Switch	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Remote Annunciator	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Siren/Strobe	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Lighting - Security	Inspected	
Condition	2- Between Good and Fair	
Deficiency	TIME CLOCK NOT OPERATIONAL	
Deficiency Location/Instance	Electrical Room B11	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 3	

Building Condition Assessment Survey 2023-2024

rical Inspection		X022
Question	Response	
SECURITY		
Lighting - Security		
Purpose of Action	LEVEL 3	
Violations	No violations recorded	
SERVICE SWITCH	Inspected	
Instance	Electrical Room B11	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	I.T.E.	
EquipmentId	N/A	
Capacity/Size Quantity	1600	
Capacity/Size UOM	Amps	
Source of Capacity/Size	Nameplate	
Installation Year Source of Installation Year	1974 Documented	
	BEYOND USEFUL LIFE	
Deficiency Deficiency Location/Instance	Electrical Room B11	
Deficiency Quantity	l	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Instance	Electrical Room B11	
Instance Condition	3- Fair	
Instance Quantity		
	1 EACH	
Instance Quantity Uom		
Manufacturer	I.T.E.	
EquipmentId	N/A 3000	
Capacity/Size Quantity		
Capacity/Size UOM Source of Capacity/Size	Amps	
Installation Year	Nameplate 1974	
Source of Installation Year	Documented	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	Electrical Room B11	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Instance	Electrical Room B11	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	I.T.E.	
	N/A	
EquipmentId Capacity/Size Quantity	1200	
Capacity/Size Quantity Capacity/Size UOM	Amps	
Source of Capacity/Size	Amps Nameplate	
Installation Year	1974	
Source of Installation Year	Documented	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	Electrical Room B11	

Building Condition Assessment Survey 2023-2024

Electrical Inspection	X022

trical Inspection	X02
Question	Response
SERVICE SWITCH	
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
SWITCHBOARD	Inspected
Number of Spares	3
Fused Disconnect Switch Type	Inspected
Instance	Electrical Room B11
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	I.T.E. Imperial Corp.
	DP-C
EquipmentId	600
Capacity/Size Quantity	
Capacity/Size UOM Capacity/Size 2 Quantity	Amps Total
	Section(s)
Capacity/Size 2 UOM	· · · · · · · · · · · · · · · · · · ·
Source of Capacity/Size Installation Year	Nameplate 1974
Installation Year Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room B11
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Electrical Room B11
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	I.T.E. Imperial Corp.
EquipmentId	DP-D
Capacity/Size Quantity	800
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	1
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Nameplate
Installation Year	1974
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room B11
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Electrical Room B33A
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH

Building Condition Assessment Survey 2023-2024

Question	Response
SWITCHBOARD	
Fused Disconnect Switch Type	
Manufacturer	I.T.E. Imperial Corp.
EquipmentId	DP-A
Capacity/Size Quantity	1000
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	2
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Nameplate
Installation Year	1974
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room B33A
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Fused Knife Switch Type	Does not exist
Molded Case Circuit Breaker Type	Does not exist
TELEPHONE SYSTEM	Inspected
PBX/Intercom	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Standard	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
TRANSFORMER	Does not exist