Building Condition Assessment Survey 2023-2024

Electrical Inspection

Asset:	P.S. 25 - BRON	X, 811 EAST 149 STREET,	BRONX, NY, 10	J455			
Inspectio	n Id Inspection Type				Time	In	Last Edited
	2721 ELECTRICAL				2024	-01-26 09:00A	M 2024-05-05 02:47PM
sset Data							
Questior	1			Answer			
Have any	Systems/Major Building	Components been upgraded?		Systems:		arm System (Pi	rinter)
				Years:	2023		
				Systems:	With Recepta		y Pack), Library (Raceway
				Years:	2020, 2009	* • •	
				Systems:	Partial Groun		ting (Non Battery Pack), nterior Lighting
				Years:	2016		
				Systems:		stem	
				Years:	2015	m Sustam (Ca	ntral Control Panel),
				Systems:		ch, Switchboard	
				Years:	2009	, 5	, Tuner Dourd
				Systems:	Security Ligh	ting	
				Years:	2008		
				Systems:			ddress System, Local
				Years:	Sound System 2003	n	
				Systems:		ctrical Systems	/Components
				Years:	1998	2	1
Type of S	Service			Below G	round		
Does Inte	eractive Whiteboard (IWB)) Exist?		Yes			
	netration In Electrical Roo			Yes			
		N FIRE RESCUE AREAS			D		
Question		ance Areas, Fire Rescue Areas, a	and/or Holding Roo		Response No		
	uilding?						
Priority Co	ondition						
Exist	Priority	Condition	Component	Location	Person(s)	Person(s)	Photo
Last Year?	Category	Description	Affected	Description	Notified	Title	Image
Yes	Water Penetration in Electrical Room	N/A	Electrical Equipment	Electrical Room in Cafeteria	Paul Santana	Fireman	
No	Water Leaks onto	N/A	Electrical	Original	Paul	Fireman	
	Electrical Equipment		Outlet	Basement West Wall	Santana		
Inspection	n						
Question	1			Respons	e		
Electric	al						
ATHL	ETIC FIELD			Does not	exist		
AUDI	FORIUM			Inspected			
	Instance on 3rd Floor			Inspected	1		
Hous	se Lighting			×	1		
	Instance on 3rd Floor			Inspected	1		

Does a Chandelier Exist?

No

Building Condition Assessment Survey 2023-2024

Electrical Inspection

uestion	Response	
AUDITORIUM		
House Lighting		
Lighting Fixture - Fluorescent		
Instance on 3rd Floor	Inspected	
Pendant Mounted	<u>^</u>	
Instance on 3rd Floor	Does not exist	
Surface Mounted		
Instance on 3rd Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on 3rd Floor	Does not exist	
Lighting Fixture - HID		
Instance on 3rd Floor	Does not exist	
Lighting Fixture - Incandescent		
Instance on 3rd Floor	Does not exist	
Lighting Fixture - LED		
Instance on 3rd Floor	Inspected	
Pendant Mounted		
Instance on 3rd Floor	Does not exist	
Surface Mounted		
Instance on 3rd Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on 3rd Floor	Does not exist	
Local Sound System		
Instance on 3rd Floor	Inspected	
Instance Condition	3- Fair	
Installation Year	2003	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Projection System		
Instance on 3rd Floor	Does not exist	
Theater Lighting System	N	
Instance on 3rd Floor	Does not exist	
AFETERIA	Inspected	
Instance on Basement	Inspected	
Lighting	·	
Instance on Basement	Inspected	
Lighting Fixture - Fluorescent	Y 1	
Instance on Basement	Inspected	
Pendant Mounted		
Instance on Basement	Does not exist	
Surface Mounted	·	
Instance on Basement	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on Basement	Does not exist	
Lighting Fixture - HID		
Instance on Basement	Does not exist	
Lighting Fixture - Incandescent		
Instance on Basement	Does not exist	

Building Condition Assessment Survey 2023-2024

Electrical Inspection

uestion	Response	
CAFETERIA	*	
Lighting		
Lighting Fixture - LED		
Instance on Basement	Does not exist	
Local Sound System		
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Installation Year	2003	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Projection System		
Instance on Basement	Does not exist	
Theater Lighting System		
Instance on Basement	Does not exist	
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected	
Lighting	Inspected	
Does a Chandelier Exist?	Yes	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Inspected 2- Between Good and Fair	
Condition		
Deficiency	No deficiencies recorded	
Surface Mounted		
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Does not exist	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Inspected Does not exist	
Pendant Mounted		
Surface Mounted Condition	Inspected 3- Fair	
	No deficiencies recorded	
Deficiency	Does not exist	
Recessed Mounted	Inspected	
Lighting Fixture - LED		
Pendant Mounted	Inspected 2- Between Good and Fair	
Condition	No deficiencies recorded	
Deficiency	Does not exist	
Surface Mounted	Does not exist	
Recessed Mounted		
COMPUTER LAB	Does not exist	
GYMNASIUM	Inspected	
Instance on 4th Floor	Inspected	
Lighting		
Instance on 4th Floor	Inspected	
Lighting Fixture - Fluorescent		
Instance on 4th Floor	Does not exist	
Lighting Fixture - HID		
Instance on 4th Floor	Does not exist	
Lighting Fixture - Incandescent		
Instance on 4th Floor	Does not exist	
Lighting Fixture - LED	· · · ·	
Instance on 4th Floor	Inspected	
Pendant Mounted		
Instance on 4th Floor Surface Mounted	Does not exist	

Building Condition Assessment Survey 2023-2024

Electrical Inspection

		A025
Question	Response	
GYMNASIUM		
Lighting		
Lighting Fixture - LED		
Surface Mounted		
Instance on 4th Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on 4th Floor	Does not exist	
Local Sound System		
Instance on 4th Floor	Inspected	
Instance Condition	3- Fair	
Installation Year	2003	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Projection System		
Instance on 4th Floor	Does not exist	
Scoreboard		
Instance on 4th Floor	Does not exist	
Theater Lighting System		
Instance on 4th Floor	Does not exist	
KITCHEN	Inspected	
Instance on Basement	Inspected	
Lighting	inspected	
Instance on Basement	Inspected	
Lighting Fixture - Fluorescent	hispected	
Instance on Basement	Inspected	
	hispecieu	
Pendant Mounted	Turner et al	
Instance on Basement	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on Basement	Does not exist	
Recessed Mounted		
Instance on Basement	Does not exist	
Lightin <u>g</u> Fixture - HID		
Instance on Basement	Does not exist	
Lighting Fixture - Incandescent		
Instance on Basement	Does not exist	
Lighting Fixture - LED		
Instance on Basement	Does not exist	
LIBRARY	Inspected	
Instance on Room 306	Inspected	
Lighting	1	
Instance on Room 306	Inspected	
Lighting Fixture - Fluorescent	1	
Instance on Room 306	Inspected	
Pendant Mounted	mspected	
Instance on Room 306	Inspected	
	Inspected 2- Between Good and Fair	
Instance Condition		
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on Room 306	Does not exist	
Recessed Mounted		

Building Condition Assessment Survey 2023-2024

Electrical Inspection

		AU25
Question	Response	
LIBRARY		
Lighting		
Lighting Fixture - Fluorescent		
Recessed Mounted		
Instance on Room 306	Does not exist	
Lighting Fixture - HID		
Instance on Room 306	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 306	Does not exist	
Lighting Fixture - LED		
Instance on Room 306	Does not exist	
Raceway With Receptacles		
Instance on Room 306	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Projection System		
Instance on Room 306	Does not exist	
LOCKER ROOM	Does not exist	
MULTIPURPOSE ROOM	Inspected	
Instance on 1st Floor	Inspected	
Lighting		
Instance on 1st Floor	Inspected	
Lighting Fixture - Fluorescent		
Instance on 1st Floor	Inspected	
Pendant Mounted		
Instance on 1st Floor	Does not exist	
Surface Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on 1st Floor	Does not exist	
Lighting Fixture - HID		
Instance on 1st Floor	Does not exist	
Lighting Fixture - Incandescent		
Instance on 1st Floor	Does not exist	
Lighting Fixture - LED		
Instance on 1st Floor	Does not exist	
Local Sound System		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Installation Year	2003	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Projection System		
Instance on 1st Floor	Does not exist	
Theater Lighting System		
Instance on 1st Floor	Does not exist	
SCIENCE DEMO ROOM	Does not exist	
SCIENCE LAB	Does not exist	
SCIENCE PREP ROOM	Does not exist	
SWIMMING POOL	Does not exist	
TOILET ROOM - STAFF	Inspected	
Lighting	Inspected	

NYC Department of Education Building Condition Assessment Survey 2023-2024

Electrical Inspection

ricui Inspection		AU2
Question	Response	
TOILET ROOM - STAFF		
Lighting		
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Inspected	
Condition	2- Between Good and Fair	-
Deficiency	No deficiencies recorded	
Recessed Mounted	Does not exist	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Does not exist	
TOILET ROOM - STUDENT	Inspected	
	Inspected	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Does not exist	
	Does not exist	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED		
AUXILIARY SIGNAL/BELL SYSTEM	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
EMERGENCY DC STANDBY BATTERY POWER	Does not exist	
EMERGENCY GENERATOR SET	Does not exist	
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
EMERGENCY LIGHTING	Inspected	
Battery Pack	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Non Battery Pack	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
EXIT LIGHT	Inspected	
	Inspected	
Battery Pack Condition	2- Between Good and Fair	
	FIXTURE NOT OPERATIONAL	
Deficiency Deficiency Location/Instance	Exit 1 Vestibule	
Deficiency Quantity	1	
Quantity Uom	1 EACH	
Potential Action	REPAIR	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Non Battery Pack	Does not exist	

NYC Department of Education Building Condition Assessment Survey 2023-2024

Electrical Inspection

	Λι
estion	Response
CXIT/EMERGENCY LIGHT	Does not exist
TIRE ALARM SYSTEM	Inspected
Bell/Horn	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Strobe	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Manual Pull Station	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Fan Shutdown Control	Does not exist
Duct Smoke Detector	Does not exist
Area Smoke Detector	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
CO Detector	Does not exist
Heat Detector	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Elevator Recall	Does not exist
Magnetic Door Holder/Contactor	Does not exist
Fused Cutout Panel	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Fire Alarm Digital Communicator	Does not exist
Main Panel	Inspected
Bell At Panel	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Electronic)	Inspected
Instance	Main Entrance Lobby
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Edwards System Technology
Madulacturer	EST 2
EquipmentId	Fire Alarm Control Panel
Installation Year	2003
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Standard)	Does not exist
Sub-Panel	Does not exist
Remote Annunciator	Inspected
Display Monitor	Does not exist
Panel	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Printer	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Punch Register	Does not exist
Sprinkler Flow/Air Pressure Switch	Inspected 3- Fair

Building Condition Assessment Survey 2023-2024

Electrical Inspection

	Δ
Question	Response
FIRE ALARM SYSTEM	
Sprinkler Flow/Air Pressure Switch	
Deficiency	No deficiencies recorded
Tamper Flow Switch/Chain	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
GROUNDING SYSTEM	Inspected
	3- Fair
Condition	
Deficiency	No deficiencies recorded
INTERCOM SYSTEM	Does not exist
LAN	Inspected
Local Distribution Frame (I/LDF)	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	Does not exist
MOTOR CONTROLLER	Inspected
MOTOR CONTROL CENTER	Does not exist
MOTOR STARTER/CONTACTOR	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Variable Frequency Drive	Does not exist
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Does not exist
Fused Knife Switch Type	Does not exist
Fused Toggle Switch Type	Does not exist
Molded Case Circuit Breaker Type	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
PUBLIC ADDRESS SYSTEM	Inspected
Instance	General Office
Instance Condition	3- Fair
Instance Quantity	
	1 EACH
Instance Quantity Uom	
Model	Dukane 250
Installation Year	2003
Source of Installation Year	Documented
Deficiency	SPEAKER NOT OPERATIONAL
Deficiency Location/Instance	Cafeteria, Boiler Room
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded
SECURITY	Inspected
IPDVS/CCTV System	Does not exist
Intrusion Alarm System	Inspected
Central Control Panel	Inspected
Instance	Custodian's Office
Instance Condition	3- Fair
Instance Quantity	1

Building Condition Assessment Survey 2023-2024

Electrical Inspection

rical Inspection	XU
uestion	Response
SECURITY	
Intrusion Alarm System	
Central Control Panel	
Instance Quantity Uom	EACH
Model	Vista - 128B
Installation Year	2009
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Infrared Sensor	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Panic Switch	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Remote Annunciator	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Siren/Strobe	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting - Security	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
SERVICE SWITCH	Inspected
Instance	Electrical Room in Cafeteria
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	All City Switchboard
EquipmentId	N/A
Capacity/Size Quantity	1600
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2009
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
SWITCHBOARD	Inspected
Number of Spares	0
Fused Disconnect Switch Type	Inspected
Instance	Electrical Room in Boiler Room
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	All City Switchboard
EquipmentId	N/A
Capacity/Size Quantity	1600
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	2
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Service Switch Size 2009
Installation Year Source of Installation Year	2009 Documented
Deficiency	No deficiencies recorded
	Does not exist
Fused Knife Switch Type	Does not exist

NYC Department of Education Building Condition Assessment Survey 2023-2024

Electrical Inspection

-		
uestion	Response	
TELEPHONE SYSTEM	Inspected	
PBX/Intercom	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Standard	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
TRANSFORMER	Does not exist	