

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X048

Asset: P.S. 48 - BRONX, 1290 SPOFFORD AVENUE, BRONX, NY, 10474

| Inspection Id | Inspection Type | Time In | Last Edited |
|---------------|-----------------|--------------------|--------------------|
| 2954 | ELECTRICAL | 2024-02-05 09:21AM | 2024-02-05 06:38PM |

Asset Data

| Question | Answer |
|---|--|
| Have any Systems/Major Building Components been upgraded? | Systems: IPDVS/CCTV System, Fire Alarm System (Duct Smoke Detector) Years: 2023 Systems: Security Lights Years: 2022 Systems: Cafeteria, Multipurpose Rooms and Partial Boiler Room LED Lighting Years: 2021 Systems: Partial Molded Case Circuit Breaker Panel Boards Years: 2019, 2007, 1992 Systems: Battery Pack Exit Lights, Fire Alarm System Elevator Recall, Elevator and Fire Rescue Area Intercoms, Fused Disconnect Panel Board, Partial Service Switch and Switchboard, Variable Frequency Drives Years: 2019 Systems: Partial Battery Pack Emergency Lights Years: 2017 Systems: Interior Lighting Years: 2015 Systems: Intrusion Alarm System (Panic Switch and Remote Annunciator) Years: 2013 Systems: Library Years: 2007 Systems: Public Address System, Local Sound System in Cafeteria and Auditorium Years: 2006 Systems: Fire Alarm System Years: 2004 Systems: Auditorium Theater Lights Years: 2000 Systems: Intrusion Alarm System Years: 1997 Systems: Emergency/Exit Lights Panel Years: 1992 Type of Service Below Ground Does Interactive Whiteboard (IWB) Exist? Yes Water Penetration In Electrical Room? No |

DEDICATED INTERCOMS IN FIRE RESCUE AREAS

| Question | Response |
|---|----------|
| Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building? | Yes |
| Are dedicated intercoms available in all of these spaces for use during a fire? | Yes |
| Are all dedicated intercoms operational? | Yes |

Priority Condition

| Exist Last Year? | Priority Category | Condition Description | Component Affected | Location Description | Person(s) Notified | Person(s) Title | Photo Image |
|-----------------------|-------------------|-----------------------|--------------------|----------------------|--------------------|-----------------|-------------|
| No condition recorded | | | | | | | |

Inspection

| Question | Response |
|------------|----------|
| Electrical | |

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X048

| Question | Response |
|--|--------------------------|
| ATHLETIC FIELD | Does not exist |
| AUDITORIUM | Inspected |
| Instance on 1st Floor | Inspected |
| House Lighting | |
| Instance on 1st Floor | Inspected |
| Does a Chandelier Exist? | No |
| Lighting Fixture - Fluorescent | |
| Instance on 1st Floor | Does not exist |
| Lighting Fixture - HID | |
| Instance on 1st Floor | Does not exist |
| Lighting Fixture - Incandescent | |
| Instance on 1st Floor | Does not exist |
| Lighting Fixture - LED | |
| Instance on 1st Floor | Inspected |
| Pendant Mounted | |
| Instance on 1st Floor | Does not exist |
| Surface Mounted | |
| Instance on 1st Floor | Inspected |
| Instance Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Recessed Mounted | |
| Instance on 1st Floor | Does not exist |
| Local Sound System | |
| Instance on 1st Floor | Inspected |
| Instance Condition | 4- Between Fair and Poor |
| Installation Year | 2006 |
| Source of Installation Year | Documented |
| Deficiency | SYSTEM DEFECTIVE |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | REPAIR SYSTEM |
| Urgency of Action | PRIORITY 2 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Projection System | |
| Instance on 1st Floor | Does not exist |
| Theater Lighting System | |
| Instance on 1st Floor | Inspected |
| Dimming System | |
| Instance on 1st Floor | Does not exist |
| Theater Lighting | |
| Instance on 1st Floor | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| CAFETERIA | Inspected |
| Instance on Basement | Inspected |
| Lighting | |
| Instance on Basement | Inspected |
| Lighting Fixture - Fluorescent | |
| Instance on Basement | Inspected |
| Pendant Mounted | |
| Instance on Basement | Inspected |
| Instance Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X048

| Question | Response |
|--|--------------------------|
| CAFETERIA | |
| Lighting | |
| Lighting Fixture - Fluorescent | |
| Surface Mounted | |
| Instance on Basement | Does not exist |
| Recessed Mounted | |
| Instance on Basement | Does not exist |
| Lighting Fixture - HID | |
| Instance on Basement | Does not exist |
| Lighting Fixture - Incandescent | |
| Instance on Basement | Does not exist |
| Lighting Fixture - LED | |
| Instance on Basement | Inspected |
| Pendant Mounted | |
| Instance on Basement | Inspected |
| Instance Condition | 1- Good |
| Deficiency | No deficiencies recorded |
| Surface Mounted | |
| Instance on Basement | Does not exist |
| Recessed Mounted | |
| Instance on Basement | Inspected |
| Instance Condition | 1- Good |
| Deficiency | No deficiencies recorded |
| Local Sound System | |
| Instance on Basement | Inspected |
| Instance Condition | 3- Fair |
| Installation Year | 2006 |
| Source of Installation Year | Documented |
| Deficiency | No deficiencies recorded |
| Projection System | |
| Instance on Basement | Does not exist |
| Theater Lighting System | |
| Instance on Basement | Does not exist |
| CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE | |
| Lighting | Inspected |
| Does a Chandelier Exist? | No |
| Lighting Fixture - Fluorescent | |
| Pendant Mounted | |
| Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Surface Mounted | |
| Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Recessed Mounted | |
| Does not exist | Does not exist |
| Lighting Fixture - HID | |
| Does not exist | Does not exist |
| Lighting Fixture - Incandescent | |
| Does not exist | Does not exist |
| Lighting Fixture - LED | |
| Inspected | Inspected |
| Pendant Mounted | |
| Condition | 1- Good |
| Deficiency | No deficiencies recorded |
| Surface Mounted | |
| Condition | 1- Good |
| Deficiency | No deficiencies recorded |
| Recessed Mounted | |
| Does not exist | Does not exist |

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X048

| Question | Response |
|--|--------------------------|
| COMPUTER LAB | Inspected |
| Instance on Room 509 | Inspected |
| Power Panel? | Yes |
| Lighting | |
| Instance on Room 509 | Inspected |
| Lighting Fixture - Fluorescent | |
| Instance on Room 509 | Inspected |
| Pendant Mounted | |
| Instance on Room 509 | Inspected |
| Instance Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Surface Mounted | |
| Instance on Room 509 | Does not exist |
| Recessed Mounted | |
| Instance on Room 509 | Does not exist |
| Lighting Fixture - HID | |
| Instance on Room 509 | Does not exist |
| Lighting Fixture - Incandescent | |
| Instance on Room 509 | Does not exist |
| Lighting Fixture - LED | |
| Instance on Room 509 | Does not exist |
| Raceway With Receptacles | |
| Instance on Room 509 | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| GYMNASIUM | Does not exist |
| KITCHEN | Inspected |
| Instance on Basement | Inspected |
| Lighting | |
| Instance on Basement | Inspected |
| Lighting Fixture - Fluorescent | |
| Instance on Basement | Inspected |
| Pendant Mounted | |
| Instance on Basement | Inspected |
| Instance Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Surface Mounted | |
| Instance on Basement | Does not exist |
| Recessed Mounted | |
| Instance on Basement | Does not exist |
| Lighting Fixture - HID | |
| Instance on Basement | Does not exist |
| Lighting Fixture - Incandescent | |
| Instance on Basement | Does not exist |
| Lighting Fixture - LED | |
| Instance on Basement | Does not exist |
| LIBRARY | Inspected |
| Instance on Room 306 | Inspected |
| Lighting | |
| Instance on Room 306 | Inspected |
| Lighting Fixture - Fluorescent | |
| Instance on Room 306 | Inspected |
| Pendant Mounted | |

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X048

| Question | Response |
|--|--------------------------|
| LIBRARY | |
| Lighting | |
| Lighting Fixture - Fluorescent | |
| Pendant Mounted | |
| Instance on Room 306 | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Surface Mounted | |
| Instance on Room 306 | Does not exist |
| Recessed Mounted | |
| Instance on Room 306 | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Lighting Fixture - HID | |
| Instance on Room 306 | Does not exist |
| Lighting Fixture - Incandescent | |
| Instance on Room 306 | Does not exist |
| Lighting Fixture - LED | |
| Instance on Room 306 | Does not exist |
| Raceway With Receptacles | |
| Instance on Room 306 | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Projection System | |
| Instance on Room 306 | Does not exist |
| LOCKER ROOM | Does not exist |
| MULTIPURPOSE ROOM | Inspected |
| Instance on 1st Floor East | Inspected |
| Instance on 1st Floor West | Inspected |
| Lighting | |
| Instance on 1st Floor East | Inspected |
| Instance on 1st Floor West | Inspected |
| Lighting Fixture - Fluorescent | |
| Instance on 1st Floor East | Does not exist |
| Instance on 1st Floor West | Does not exist |
| Lighting Fixture - HID | |
| Instance on 1st Floor East | Does not exist |
| Instance on 1st Floor West | Does not exist |
| Lighting Fixture - Incandescent | |
| Instance on 1st Floor East | Does not exist |
| Instance on 1st Floor West | Does not exist |
| Lighting Fixture - LED | |
| Instance on 1st Floor East | Inspected |
| Instance on 1st Floor West | Inspected |
| Pendant Mounted | |
| Instance on 1st Floor East | Inspected |
| Instance Condition | 1- Good |
| Deficiency | No deficiencies recorded |
| Instance on 1st Floor West | Inspected |
| Instance Condition | 1- Good |
| Deficiency | No deficiencies recorded |
| Surface Mounted | |
| Instance on 1st Floor East | Does not exist |

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X048

| Question | Response |
|--|---------------------------|
| MULTIPURPOSE ROOM | |
| Lighting | |
| Lighting Fixture - LED | |
| Surface Mounted | |
| Instance on 1st Floor West | Does not exist |
| Recessed Mounted | |
| Instance on 1st Floor East | Inspected |
| Instance Condition | 1- Good |
| Deficiency | No deficiencies recorded |
| Instance on 1st Floor West | Inspected |
| Instance Condition | 1- Good |
| Deficiency | No deficiencies recorded |
| Local Sound System | |
| Instance on 1st Floor East | Does not exist |
| Instance on 1st Floor West | Inspected |
| Instance Condition | 5- Poor |
| Installation Year | 1970 |
| Source of Installation Year | Documented |
| Deficiency | AMPLIFIER NOT OPERATIONAL |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | REPLACE SYSTEM |
| Urgency of Action | PRIORITY 2 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Projection System | |
| Instance on 1st Floor East | Does not exist |
| Instance on 1st Floor West | Does not exist |
| Theater Lighting System | |
| Instance on 1st Floor East | Does not exist |
| Instance on 1st Floor West | Does not exist |
| SCIENCE DEMO ROOM | |
| Instance on Room 507 | Inspected |
| Power Panel? | No |
| Alternative Use | No |
| Lighting | |
| Instance on Room 507 | Inspected |
| Lighting Fixture - Fluorescent | |
| Instance on Room 507 | Inspected |
| Pendant Mounted | |
| Instance on Room 507 | Inspected |
| Instance Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Surface Mounted | |
| Instance on Room 507 | Does not exist |
| Recessed Mounted | |
| Instance on Room 507 | Does not exist |
| Lighting Fixture - HID | |
| Instance on Room 507 | Does not exist |
| Lighting Fixture - Incandescent | |
| Instance on Room 507 | Does not exist |
| Lighting Fixture - LED | |
| Instance on Room 507 | Does not exist |
| Emergency Gas Shut-Off Valve | |

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X048

| Question | Response |
|---|--------------------------|
| SCIENCE DEMO ROOM | |
| Emergency Gas Shut-Off Valve Instance on Room 507 | Does not exist |
| Emergency Shut-Off Power Instance on Room 507 | Does not exist |
| Power Supply Instance on Room 507 | Does not exist |
| Projection System Instance on Room 507 | Does not exist |
| SCIENCE LAB | Does not exist |
| SCIENCE PREP ROOM | Does not exist |
| SWIMMING POOL | Does not exist |
| TOILET ROOM - STAFF | Inspected |
| Lighting | Inspected |
| Lighting Fixture - Fluorescent | Inspected |
| Pendant Mounted | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Surface Mounted | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Recessed Mounted | Does not exist |
| Lighting Fixture - HID | Does not exist |
| Lighting Fixture - Incandescent | Does not exist |
| Lighting Fixture - LED | Does not exist |
| TOILET ROOM - STUDENT | Inspected |
| Lighting | Inspected |
| Lighting Fixture - Fluorescent | Inspected |
| Pendant Mounted | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Surface Mounted | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Recessed Mounted | Does not exist |
| Lighting Fixture - HID | Does not exist |
| Lighting Fixture - Incandescent | Does not exist |
| Lighting Fixture - LED | Does not exist |
| AUXILIARY SIGNAL/BELL SYSTEM | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| EMERGENCY DC STANDBY BATTERY POWER | Does not exist |
| EMERGENCY GENERATOR SET | Does not exist |
| EMERGENCY LIGHT/EXIT LIGHT PANEL | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| EMERGENCY LIGHTING | Inspected |
| Battery Pack | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Non Battery Pack | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X048

| Question | Response |
|--|---------------------------|
| EXIT LIGHT | Inspected |
| Battery Pack | Inspected |
| Condition | 1- Good |
| Deficiency | No deficiencies recorded |
| Non Battery Pack | Does not exist |
| EXIT/EMERGENCY LIGHT | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| FIRE ALARM SYSTEM | Inspected |
| Bell/Horn | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Strobe | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Manual Pull Station | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Fan Shutdown Control | Does not exist |
| Duct Smoke Detector | Inspected |
| Condition | 1- Good |
| Deficiency | No deficiencies recorded |
| Area Smoke Detector | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| CO Detector | Does not exist |
| Heat Detector | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Elevator Recall | Inspected |
| Condition | 1- Good |
| Deficiency | No deficiencies recorded |
| Magnetic Door Holder/Contactor | Does not exist |
| Fused Cutout Panel | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Fire Alarm Digital Communicator | Does not exist |
| Main Panel | Inspected |
| Bell At Panel | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Fire Alarm Control Panel (Electronic) | Inspected |
| Instance | Main Entrance Lobby |
| Instance Condition | 3- Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Manufacturer | Edwards System Technology |
| Model | EST 2 |
| EquipmentId | Fire Alarm Control Panel |
| Installation Year | 2004 |
| Source of Installation Year | Documented |
| Deficiency | No deficiencies recorded |
| Fire Alarm Control Panel (Standard) | Does not exist |
| Sub-Panel | Does not exist |

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X048

| Question | Response |
|---|--------------------------------|
| FIRE ALARM SYSTEM | |
| Remote Annunciator | Inspected |
| Display Monitor | Does not exist |
| Panel | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Printer | Does not exist |
| Punch Register | Does not exist |
| Sprinkler Flow/Air Pressure Switch | Does not exist |
| Tamper Flow Switch/Chain | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| GROUNDING SYSTEM | |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| INTERCOM SYSTEM | |
| Elevator | Inspected |
| Condition | 1- Good |
| Deficiency | No deficiencies recorded |
| Holding Area | Does not exist |
| LAN | |
| Local Distribution Frame (L/DF) | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Main Equipment Rack (MDF) | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| LIGHTNING PROTECTION | |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| MOTOR CONTROLLER | |
| MOTOR CONTROL CENTER | Does not exist |
| MOTOR STARTER/CONTACTOR | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Variable Frequency Drive | Inspected |
| Condition | 1- Good |
| Deficiency | No deficiencies recorded |
| PANEL BOARD | |
| Fused Disconnect Switch Type | Inspected |
| Condition | 1- Good |
| Deficiency | No deficiencies recorded |
| Fused Knife Switch Type | Does not exist |
| Fused Toggle Switch Type | Does not exist |
| Molded Case Circuit Breaker Type | Inspected |
| Condition | 3- Fair |
| Deficiency | PANEL BOARD BEYOND USEFUL LIFE |
| Deficiency Location/Instance | Throughout the Building |
| Deficiency Quantity | 19 |
| Quantity Uom | EACH |
| Potential Action | REPLACE-UPGRADE |
| Urgency of Action | PRIORITY 1 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X048

| Question | Response |
|---|----------------------------------|
| PANEL BOARD | |
| Molded Case Circuit Breaker Type | |
| Deficiency | PANEL BOARD DOOR LOCK IS MISSING |
| Deficiency Location/Instance | Computer Lab Room 509 |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | MAINTENANCE |
| Urgency of Action | PRIORITY 2 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| PUBLIC ADDRESS SYSTEM | |
| | Inspected |
| Instance | General Office |
| Instance Condition | 3- Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Model | Dukane 250 |
| Installation Year | 2006 |
| Source of Installation Year | Documented |
| Deficiency | No deficiencies recorded |
| SECURITY | |
| | Inspected |
| IPDVS/CCTV System | |
| | Inspected |
| Condition | 1- Good |
| Installation Year | 2023 |
| Source of Installation Year | Documented |
| Deficiency | No deficiencies recorded |
| Intrusion Alarm System | |
| | Inspected |
| Central Control Panel | |
| | Inspected |
| Instance | Custodian's Office |
| Instance Condition | 3- Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Model | Vista - 50P |
| Installation Year | 1997 |
| Source of Installation Year | Documented |
| Deficiency | BEYOND USEFUL LIFE |
| Deficiency Location/Instance | Custodian's Office |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 1 |
| Purpose of Action | LEVEL 3 |
| Violations | No violations recorded |
| Infrared Sensor | |
| | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Panic Switch | |
| | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Remote Annunciator | |
| | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Siren/Strobe | |
| | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Lighting - Security | |
| | Inspected |

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X048

| Question | Response |
|-------------------------------------|--------------------------|
| SECURITY | |
| Lighting - Security | |
| Condition | 1- Good |
| Deficiency | No deficiencies recorded |
| SERVICE SWITCH | |
| Instance | Inspected |
| Instance Condition | Electrical Room Basement |
| Instance Quantity | 3- Fair |
| Instance Quantity Uom | 1 |
| Manufacturer | EACH |
| EquipmentId | Metropolitan |
| Capacity/Size Quantity | Main Service Switch |
| Capacity/Size UOM | 1200 |
| Source of Capacity/Size | Amps |
| Installation Year | Nameplate |
| Source of Installation Year | 1960 |
| Deficiency | Documented |
| Deficiency Location/Instance | BEYOND USEFUL LIFE |
| Deficiency Quantity | Electrical Room Basement |
| Quantity Uom | 1 |
| Potential Action | EACH |
| Urgency of Action | REPLACE |
| Purpose of Action | PRIORITY 1 |
| Violations | LEVEL 2 |
| Instance | No violations recorded |
| Instance Condition | Room Inside Boiler Room |
| Instance Quantity | 1- Good |
| Instance Quantity Uom | 1 |
| Manufacturer | EACH |
| EquipmentId | EATON |
| Capacity/Size Quantity | MDP - A |
| Capacity/Size UOM | 800 |
| Source of Capacity/Size | Amps |
| Installation Year | Nameplate |
| Source of Installation Year | 2019 |
| Deficiency | Documented |
| Deficiency | No deficiencies recorded |
| SWITCHBOARD | |
| Number of Spares | Inspected |
| Fused Disconnect Switch Type | 2 |
| Instance | Inspected |
| Instance Condition | Electrical Room Basement |
| Instance Quantity | 3- Fair |
| Instance Quantity Uom | 1 |
| Manufacturer | EACH |
| EquipmentId | Federal Pacific Electric |
| Capacity/Size Quantity | N/A |
| Capacity/Size UOM | 1200 |
| Capacity/Size 2 Quantity | Amps Total |
| Capacity/Size 2 UOM | 2 |
| Source of Capacity/Size | Section(s) |
| Installation Year | Service Switch Size |
| Source of Installation Year | 1960 |
| Deficiency | Documented |
| Deficiency Location/Instance | BEYOND USEFUL LIFE |
| Deficiency Quantity | Electrical Room Basement |
| Quantity Uom | 1 |
| | EACH |

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X048

| Question | Response |
|---|--------------------------|
| SWITCHBOARD | |
| Fused Disconnect Switch Type | |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 1 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Instance | Room Inside Boiler Room |
| Instance Condition | 1- Good |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Manufacturer | All City Switchboard |
| EquipmentId | MDP - A |
| Capacity/Size Quantity | 800 |
| Capacity/Size UOM | Amps Total |
| Capacity/Size 2 Quantity | 1 |
| Capacity/Size 2 UOM | Section(s) |
| Source of Capacity/Size | Nameplate |
| Installation Year | 2019 |
| Source of Installation Year | Documented |
| Deficiency | No deficiencies recorded |
| Fused Knife Switch Type | Does not exist |
| Molded Case Circuit Breaker Type | Does not exist |
| TELEPHONE SYSTEM | Inspected |
| PBX/Intercom | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Standard | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| TRANSFORMER | Does not exist |