### **Building Condition Assessment Survey 2023-2024**

#### Electrical Inspection

Asset:	P.S. 107 - BRO	NX, 1695 SEWARD AVE	ENUE, BRONX, NY,	10473		
Inspection Id	Inspection Type				Time In	Last Edited
156	9 ELECTRICAL				2023-12-11 09:11AN	1 2024-02-26 12:34PM
sset Data						
Question				Answer		
Have any Sys	tems/Major Building	Components been upgraded	1?	Systems:	LAN, Auditorium (LED Light	ting)
				Years:	2023	
				Systems:		
				Years:	2019, 2006	
				Systems:	(Battery Pack)	attery Pack), Exit Lights
				Years:	2018	A 1'4 ' (F1 4
				Systems:	Lighting)	Auditorium (Fluorescent
				Years:	2015	
				Systems:		reaker Panel Boards
				Years:	2012, 1990 Telenhone System	
				Systems: Years:	Telephone System 2012	
				Systems:		System)
				Years:	2008	5,50011)
				Systems:		
				Years:	2005	
				Systems:		-
				Years:	2001	
				Systems:	Intrusion Alarm System	
				Years:	1996	
Type of Servi	ce			Below G	cound	
	ive Whiteboard (IWE			Yes		
	tion In Electrical Ro			No		
DEDICATE Question	ED INTERCOMS	IN FIRE RESCUE ARE	LAS		D	
-	ny Life Rescue Assist	tance Areas, Fire Rescue Are	eas. and/or Holding Root		Response No	
your buildir	2	unoo mous, me nosouo me	us, und of fiolding fool			
Priority Condi	ition					
•	riority	Condition	Component	Location	Person(s) Person(s)	Photo
	ategory	Description	Affected	Description	Notified Title	Image
No condition	recorded					
Inspection						
Question				Response	2	
Electrical						
ATHLETI	C FIELD			Does not	exist	
AUDITOR				Inspected	l	
-	Instance on 1st Floor			Inspected	l	
House Li	ghting					
-	Instance on 1st Floor			Inspected		
]	Does a Chandelier Ex	xist?		No		
Lightin	g Fixture - Fluoresc	ent				
	Instance on 1st Floor			Inspected		
Penda	ant Mounted					
	Instance on 1st Floor	,		Does not	exist	
Surfa	ce Mounted					
]	Instance on 1st Floor			Inspected		
				2 D (	on Cood and Fain	

Instance Condition

2- Between Good and Fair

### **Building Condition Assessment Survey 2023-2024**

#### **Electrical Inspection**

estion	Response
UDITORIUM	•
House Lighting	
Lighting Fixture - Fluorescent	
Surface Mounted	
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on 1st Floor	Does not exist
Lighting Fixture - HID	
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not exist
Lighting Fixture - LED	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on 1st Floor	Does not exist
Recessed Mounted	
Instance on 1st Floor	Does not exist
Local Sound System	
Instance on 1st Floor	Inspected
Instance Condition	5- Poor
Installation Year	2001
Source of Installation Year	Documented
Deficiency	AMPLIFIER NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE SYSTEM
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
Projectio <u>n System</u>	
Instance on 1st Floor	Does not exist
Theater Lighting System	
Instance on 1st Floor	Inspected
Dimming System	
Instance on 1st Floor	Inspected
Instance Condition	4- Between Fair and Poor
Deficiency	DIMMING RACK/LIGHT CONSOLE NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Theater Lighting	Y / Y
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
AFETERIA	Inspected
Instance on 1st Floor	Inspected
Lighting	

### **Building Condition Assessment Survey 2023-2024**

#### Electrical Inspection

	Response	
	response	
RIA		
ng Fixture - Fluorescent		
Instance on 1st Floor	Inspected	
ant Mounted		
Instance on 1st Floor	Does not exist	
ace Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
ssed Mounted		
Instance on 1st Floor	Does not exist	
ng Fixture - HID		
Instance on 1st Floor	Does not exist	
ng Fixture - Incandescent		
Instance on 1st Floor	Does not exist	
ng Fixture - LED		
Instance on 1st Floor	Does not exist	
und System		
Instance on 1st Floor	Inspected	
Instance Condition	5- Poor	
Installation Year	2001	
Source of Installation Year	Documented	
	EACH	
Potential Action	REPLACE SYSTEM	
Urgency of Action	PRIORITY 2	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
on System		
Instance on 1st Floor	Does not exist	
Lighting System		
Instance on 1st Floor	Does not exist	
OOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected	
	Inspected	
Chandelier Exist?	Yes	
ng Fixture - Fluorescent	Inspected	
ant Mounted	Inspected	
ndition	3- Fair	
Deficiency	No deficiencies recorded	
ace Mounted	Inspected	
ndition	3- Fair	
Deficiency	No deficiencies recorded	
-		
-		
	Does not exist	
ssed Mounted		
	DOUS HOL CAISE	
	Does not exist	
ng Fixture - LED ER LAB	Does not exist Inspected	
Urgency of Action Purpose of Action Violations  Daystem Instance on 1st Floor Lighting System Instance on 1st Floor DOM/CORRIDOR/ADMINISTRATIVE SPACE Chandelier Exist? Ing Fixture - Fluorescent ant Mounted Indition Deficiency Ace Mounted Indition Deficiency Sseed Mounted Ing Fixture - HID Ing Fixture - Incandescent ant Mounted Indition Deficiency Instance Incandescent Intervention Interventio	REPLACE SYSTEM         PRIORITY 2         LEVEL 2         No violations recorded         Does not exist         Does not exist         Inspected         Yes         Inspected         Inspected         3- Fair         No deficiencies recorded         Inspected         3- Fair         No deficiencies recorded         Does not exist         Does not exist         Inspected         Jose state         No deficiencies recorded         Inspected         Joses not exist         Does not exist         Inspected	

# NYC Department of Education **Building Condition Assessment Survey 2023-2024**

#### **Electrical Inspection**

estion	Response	
COMPUTER LAB	response	
Instance on Room 423	Inspected	
Power Panel?	No	
	1N0	
Lighting Instance on Room 423	Inspected	
	hispected	
Lighting Fixture - Fluorescent Instance on Room 423	Insuranta d	
	Inspected	
Pendant Mounted	т. , 1	
Instance on Room 423	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on Room 423	Does not exist	
Recessed Mounted		
Instance on Room 423	Does not exist	
Lighting Fixture - HID		
Instance on Room 423	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 423	Does not exist	
Lighting Fixture - LED		
Instance on Room 423	Does not exist	
Raceway With Receptacles		
Instance on Room 423	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
GYMNASIUM	Inspected	
Instance on 3rd Floor	Inspected	
Lighting	Inspected	
Instance on 3rd Floor	Inspected	
Lighting Fixture - Fluorescent	inspected	
Instance on 3rd Floor	Does not exist	
Lighting Fixture - HID		
Instance on 3rd Floor	Does not exist	
	Does not exist	
Lighting Fixture - Incandescent	De constantist	
Instance on 3rd Floor	Does not exist	
Lighting Fixture - LED		
Instance on 3rd Floor	Inspected	
Pendant Mounted		
Instance on 3rd Floor	Does not exist	
Surface Mounted		
Instance on 3rd Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on 3rd Floor	Does not exist	
Local Sound System		
Instance on 3rd Floor	Inspected	
Instance Condition	3- Fair	
Installation Year	2001	
Source of Installation Year	Documented	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	Gymnasium-3rd Floor	
Deficiency Quantity	1	
Quantity Uom	EACH	

### **Building Condition Assessment Survey 2023-2024**

#### **Electrical Inspection**

irical Inspection	Δ
Question	Response
GYMNASIUM	
Local Sound System	
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Projection System	
Instance on 3rd Floor	Does not exist
Scoreboard	
Instance on 3rd Floor	Does not exist
Theater Lighting System	
Instance on 3rd Floor	Does not exist
KITCHEN	Inspected
Instance on 1st Floor	Inspected
Lighting	
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not exist
Surface Mounted	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on 1st Floor	Does not exist
Lighting Fixture - HID	
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not exist
Lighting Fixture - LED	
Instance on 1st Floor	Does not exist
LIBRARY	Inspected
Instance on Room 419	Inspected
Lighting	inspected
Instance on Room 419	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 419	Does not exist
Lighting Fixture - HID	
Instance on Room 419	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 419	Does not exist
Lighting Fixture - LED	
Instance on Room 419	Inspected
Pendant Mounted	inspected
Instance on Room 419	Inspected
	2- Between Good and Fair
Instance Condition	
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Room 419	Does not exist
Recessed Mounted	
Instance on Room 419	Does not exist
Raceway With Receptacles	
Instance on Room 419	Inspected

## **Building Condition Assessment Survey 2023-2024**

#### Electrical Inspection

rical Inspection	X10
uestion	Response
LIBRARY	
Raceway With Receptacles	
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Projection System	
Instance on Room 419	Does not exist
LOCKER ROOM	Does not exist
MULTIPURPOSE ROOM	Does not exist
SCIENCE DEMO ROOM	Does not exist
	Does not exist
SCIENCE LAB	
SCIENCE PREP ROOM	Does not exist
SWIMMING POOL	Does not exist
TOILET ROOM - STAFF	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not exist
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
TOILET ROOM - STUDENT	Inspected
	Inspected
Lighting Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	3- Fair
	No deficiencies recorded
Deficiency	
Surface Mounted	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
Condition	5- Poor
Deficiency	BELL TRANSFORMER PANEL NOT OPERATIONAL
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE PANEL
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
	Does not exist
EMERGENCY DC STANDBY BATTERY POWER	D deb not entot
EMERGENCY DC STANDBY BATTERY POWER EMERGENCY GENERATOR SET	Does not exist

### **Building Condition Assessment Survey 2023-2024**

#### Electrical Inspection

-		AIG
iestion	Response	
EMERGENCY LIGHT/EXIT LIGHT PANEL		
Condition	3- Fair	
Deficiency	No deficiencies recorded	
EMERGENCY LIGHTING	Inspected	
Battery Pack	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Non Battery Pack	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
EXIT LIGHT	Inspected	
	Inspected	
Battery Pack Condition	1- Good	
Deficiency	No deficiencies recorded	
Non Battery Pack	Inspected 3- Fair	
Condition		
Deficiency	No deficiencies recorded	
XIT/EMERGENCY LIGHT	Does not exist	
FIRE ALARM SYSTEM	Inspected	
Bell/Horn	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Strobe	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Manual Pull Station	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Fan Shutdown Control	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Duct Smoke Detector	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Area Smoke Detector	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
CO Detector	Does not exist	
Heat Detector	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Elevator Recall	Does not exist	
Magnetic Door Holder/Contactor	Does not exist	
Fused Cutout Panel	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Fire Alarm Digital Communicator	Does not exist	
Main Panel	Inspected	
Bell At Panel	Inspected	
Condition	3- Fair	
	No deficiencies recorded	
Fire Alarm Control Panel (Electronic)	Inspected	
Instance	Main Entrance Lobby	

### **Building Condition Assessment Survey 2023-2024**

#### Electrical Inspection

-		
Question	Response	
FIRE ALARM SYSTEM		
Main Panel		
Fire Alarm Control Panel (Electronic)		
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Edwards System Technology	
Model	EST 2	
EquipmentId	Fire Alarm Control Panel	
Installation Year	2005	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Standard)	Does not exist	
Sub-Panel	Does not exist	
Remote Annunciator	Inspected	
Display Monitor	Does not exist	
Panel	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Printer	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Punch Register	Does not exist	
Sprinkler Flow/Air Pressure Switch	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Tamper Flow Switch/Chain	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
GROUNDING SYSTEM	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
INTERCOM SYSTEM	Does not exist	
LAN	Inspected	
	Inspected	
Local Distribution Frame (I/LDF) Condition	1- Good	
Deficiency	No deficiencies recorded	
	Inspected	
Main Equipment Rack (MDF) Condition	1- Good	
Deficiency	No deficiencies recorded	
LIGHTNING PROTECTION	Does not exist	
MOTOR CONTROLLER	Inspected	
MOTOR CONTROL CENTER	Does not exist	
MOTOR STARTER/CONTACTOR	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Variable Frequency Drive	Does not exist	
PANEL BOARD	Inspected	
Fused Disconnect Switch Type	Does not exist	
Fused Knife Switch Type	Does not exist	
Fused Toggle Switch Type	Inspected	
Condition	3- Fair	
Deficiency	PANEL BOARD BEYOND USEFUL LIFE	
Deficiency Location/Instance Deficiency Quantity	Electrical Room 1	

### **Building Condition Assessment Survey 2023-2024**

#### **Electrical Inspection**

	ΛΙ
iestion	Response
PANEL BOARD	
Fused Toggle Switch Type	
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Molded Case Circuit Breaker Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Throughout the Building
Deficiency Quantity	19
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
UBLIC ADDRESS SYSTEM	Inspected
Instance	General Office - Room 209
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Dukane 250
Installation Year	2001
Source of Installation Year	Documented
Deficiency	CLOCK NOT OPERATIONAL
Deficiency Location/Instance	Throughout the Building
Deficiency Quantity	30
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
ECURITY	Inspected
IPDVS/CCTV System	Does not exist
Intrusion Alarm System	Inspected
Central Control Panel	Inspected
Instance	Custodian's Office
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista - 50P
Installation Year	1996
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Custodian's Office
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 3
Violations	No violations recorded
Infrared Sensor	Inspected
Condition	3- Fair
	No deficiencies recorded

# NYC Department of Education **Building Condition Assessment Survey 2023-2024**

#### **Electrical Inspection**

Duestion	Response	
SECURITY		
Intrusion Alarm System		
Panic Switch	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Remote Annunciator	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Siren/Strobe	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Lighting - Security	Inaccessible	
SERVICE SWITCH	Inspected	
Instance	Electrical Room	
Instance Condition	3- Fair	
Instance Quantity	1	
	EACH	
Instance Quantity Uom Manufacturer	Empire Switchboard	
Manufacturer EquipmentId	Main Switch	
Capacity/Size Quantity	1600	
Capacity/Size UOM	Amps	
Source of Capacity/Size	Nameplate	
Installation Year	1961	
Source of Installation Year	Documented	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	Electrical Room	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
SWITCHBOARD	Inspected	
Number of Spares	4	
Fused Disconnect Switch Type	Inspected	
Instance	Electrical Room	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Empire Switchboard	
EquipmentId	N/A	
Capacity/Size Quantity	1600	
Capacity/Size UOM	Amps Total	
Capacity/Size 2 Quantity	3	
Capacity/Size 2 UOM	Section(s)	
Source of Capacity/Size	Nameplate	
Installation Year	1961 Decomposited	
Source of Installation Year Deficiency	Documented BEYOND USEFUL LIFE	
Deficiency Deficiency Location/Instance	Electrical Room	
Deficiency Location/Instance Deficiency Quantity	Liectrical Room	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	

# NYC Department of Education Building Condition Assessment Survey 2023-2024

#### Electrical Inspection

Question	Response	
SWITCHBOARD		
Fused Knife Switch Type	Does not exist	
Molded Case Circuit Breaker Type	Does not exist	
TELEPHONE SYSTEM	Inspected	
PBX/Intercom	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Standard	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
TRANSFORMER	Does not exist	