

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X120

Asset: I.S. 301 - BRONX, 890 CAULDWELL AVENUE, BRONX, NY, 10456

Inspection Id	Inspection Type	Time In	Last Edited
1696	ELECTRICAL	2023-12-15 08:43AM	2024-01-03 12:43PM

Asset Data

Question	Answer
Have any Systems/Major Building Components been upgraded?	Systems: Auditorium (Local Sound System), Gymnasium (Scoreboard) Years: 2023 Systems: Roof Security Lights, Variable Frequency Drive, LED Lighting (Room 207), Partial Non Battery Pack Emergency Lights Years: 2021 Systems: LED Lighting (1st Floor Parents Lounge) Years: 2018 Systems: Exit Light (Battery Pack), Partial Emergency Lighting (Battery Pack), Locker Rooms Years: 2014 Systems: LED Lighting (Gymnasium) Years: 2013 Systems: Library, Science Lab Room 201, Science Prep Room 201A Years: 2010 Systems: Public Address System, Local Sound System, Intrusion Alarm System (Remote Annunciator), Molded Case Circuit Breaker Panel Board, Most Fused Disconnect Panel Boards, Service Switch, Switchboard Years: 2009 Systems: Interior Lighting Except (Library, Locker Rooms, Gymnasium) Years: 2004 Systems: Intrusion Alarm System Except (Remote Annunciator), Emergency Light/Exit Light Panel Years: 1999
Type of Service	Below Ground
Does Interactive Whiteboard (IWB) Exist?	Yes
Water Penetration In Electrical Room?	No

DEDICATED INTERCOMS IN FIRE RESCUE AREAS

Question	Response
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building?	Yes
Are dedicated intercoms available in all of these spaces for use during a fire?	Yes
Are all dedicated intercoms operational?	Yes

Priority Condition

Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image
No		No condition recorded					

Inspection

Question	Response
Electrical	
ATHLETIC FIELD	Does not exist
AUDITORIUM	Inspected
Instance on 1st Floor	Inspected
House Lighting	
Instance on 1st Floor	Inspected
Does a Chandelier Exist?	No
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X120

Question	Response
AUDITORIUM	
House Lighting	
Lighting Fixture - Fluorescent	
Pendant Mounted	
Instance on 1st Floor	Does not exist
Surface Mounted	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not exist
Lighting Fixture - LED	
Instance on 1st Floor	Does not exist
Local Sound System	
Instance on 1st Floor	Inspected
Instance Condition	1- Good
Installation Year	2023
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Projection System	
Instance on 1st Floor	Does not exist
Theater Lighting System	
Instance on 1st Floor	Inspected
Dimming System	
Instance on 1st Floor	Inspected
Instance Condition	5- Poor
Deficiency	DIMMING RACK/LIGHT CONSOLE NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Theater Lighting	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	94
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
CAFETERIA	
Instance on Basement	Inspected
Lighting	
Instance on Basement	Inspected
Lighting Fixture - Fluorescent	
Instance on Basement	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X120

Question	Response
CAFETERIA	
Lighting	
Lighting Fixture - Fluorescent	
Pendant Mounted	
Instance on Basement	Does not exist
Surface Mounted	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Basement	Does not exist
Lighting Fixture - HID	
Instance on Basement	Does not exist
Lighting Fixture - Incandescent	
Instance on Basement	Does not exist
Lighting Fixture - LED	
Instance on Basement	Does not exist
Local Sound System	
Instance on Basement	Inspected
Instance Condition	3- Fair
Installation Year	2009
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Projection System	
Instance on Basement	Does not exist
Theater Lighting System	
Instance on Basement	Does not exist
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	
	Inspected
Lighting	
Does a Chandelier Exist?	No
Lighting Fixture - Fluorescent	
	Inspected
Pendant Mounted	
Condition	3- Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Condition	3- Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
	Does not exist
Lighting Fixture - Incandescent	
	Does not exist
Lighting Fixture - LED	
	Inspected
Pendant Mounted	
Condition	1- Good
Deficiency	No deficiencies recorded
Surface Mounted	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
	Does not exist
COMPUTER LAB	
	Inspected
Instance on Room 337	Inspected
Power Panel?	Yes
Lighting	

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X120

Question	Response
COMPUTER LAB	
Lighting	
Instance on Room 337	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 337	Inspected
Pendant Mounted	
Instance on Room 337	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Room 337	Does not exist
Recessed Mounted	
Instance on Room 337	Does not exist
Lighting Fixture - HID	
Instance on Room 337	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 337	Does not exist
Lighting Fixture - LED	
Instance on Room 337	Does not exist
Raceway With Receptacles	
Instance on Room 337	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
GYMNASIUM	Inspected
Instance on 1st Floor	Inspected
Lighting	
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Does not exist
Lighting Fixture - HID	
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not exist
Lighting Fixture - LED	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not exist
Surface Mounted	
Instance on 1st Floor	Does not exist
Recessed Mounted	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Local Sound System	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Installation Year	2009
Source of Installation Year	Documented

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X120

Question	Response
GYMNASIUM	
Local Sound System	
Deficiency	No deficiencies recorded
Projection System	
Instance on 1st Floor	Does not exist
Scoreboard	
Instance on 1st Floor	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Theater Lighting System	
Instance on 1st Floor	Does not exist
KITCHEN	Inspected
Instance on Basement	Inspected
Lighting	
Instance on Basement	Inspected
Lighting Fixture - Fluorescent	
Instance on Basement	Inspected
Pendant Mounted	
Instance on Basement	Does not exist
Surface Mounted	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Basement	Does not exist
Lighting Fixture - HID	
Instance on Basement	Does not exist
Lighting Fixture - Incandescent	
Instance on Basement	Does not exist
Lighting Fixture - LED	
Instance on Basement	Does not exist
LIBRARY	Inspected
Instance on 2nd Floor	Inspected
Lighting	
Instance on 2nd Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 2nd Floor	Inspected
Pendant Mounted	
Instance on 2nd Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on 2nd Floor	Does not exist
Recessed Mounted	
Instance on 2nd Floor	Does not exist
Lighting Fixture - HID	
Instance on 2nd Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 2nd Floor	Does not exist
Lighting Fixture - LED	
Instance on 2nd Floor	Does not exist
Raceway With Receptacles	
Instance on 2nd Floor	Does not exist
Projection System	

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X120

Question	Response
LIBRARY	
Projection System	
Instance on 2nd Floor	Does not exist
LOCKER ROOM	
	Inspected
Instance on Basement - Boys	Inaccessible
Instance on 2nd Floor - Girls	Inspected
Alternative Use	Yes
Lighting	
Instance on 2nd Floor - Girls	Inspected
Lighting Fixture - Fluorescent	
Instance on 2nd Floor - Girls	Inspected
Pendant Mounted	
Instance on 2nd Floor - Girls	Does not exist
Surface Mounted	
Instance on 2nd Floor - Girls	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on 2nd Floor - Girls	Does not exist
Lighting Fixture - HID	
Instance on 2nd Floor - Girls	Does not exist
Lighting Fixture - Incandescent	
Instance on 2nd Floor - Girls	Does not exist
Lighting Fixture - LED	
Instance on 2nd Floor - Girls	Does not exist
MULTIPURPOSE ROOM	
	Does not exist
SCIENCE DEMO ROOM	
	Inspected
Instance on Room 203	Inspected
Power Panel?	No
Alternative Use	No
Lighting	
Instance on Room 203	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 203	Inspected
Pendant Mounted	
Instance on Room 203	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Room 203	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Room 203	Does not exist
Lighting Fixture - HID	
Instance on Room 203	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 203	Does not exist
Lighting Fixture - LED	
Instance on Room 203	Does not exist
Emergency Gas Shut-Off Valve	
Instance on Room 203	Does not exist
Emergency Shut-Off Power	

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X120

Question	Response
SCIENCE DEMO ROOM	
Emergency Shut-Off Power	
Instance on Room 203	Does not exist
Power Supply	
Instance on Room 203	Does not exist
Projection System	
Instance on Room 203	Does not exist
SCIENCE LAB	
Instance on Room 201	Inspected
Power Panel?	Yes
Alternative Use	No
Lighting	
Instance on Room 201	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 201	Inspected
Pendant Mounted	
Instance on Room 201	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Room 201	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Room 201	Does not exist
Lighting Fixture - HID	
Instance on Room 201	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 201	Inspected
Pendant Mounted	
Instance on Room 201	Does not exist
Surface Mounted	
Instance on Room 201	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Room 201	Does not exist
Lighting Fixture - LED	
Instance on Room 201	Does not exist
Emergency Gas Shut-Off Valve	
Instance on Room 201	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Emergency Shut-Off Power	
Instance on Room 201	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Power Supply	
Instance on Room 201	Inspected
Instructor Unit	
Instance on Room 201	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Meter Demonstration Unit	

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X120

Question	Response
SCIENCE LAB	
Power Supply	
Meter Demonstration Unit	
Instance on Room 201	Does not exist
Student Unit	
Instance on Room 201	Does not exist
Projection System	
Instance on Room 201	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
SCIENCE PREP ROOM	
Instance on Room 201A	Inspected
Power Panel?	No
Alternative Use	Yes
Lighting	
Instance on Room 201A	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 201A	Inspected
Pendant Mounted	
Instance on Room 201A	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Room 201A	Does not exist
Recessed Mounted	
Instance on Room 201A	Does not exist
Lighting Fixture - HID	
Instance on Room 201A	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 201A	Does not exist
Lighting Fixture - LED	
Instance on Room 201A	Does not exist
Emergency Gas Shut-Off Valve	
Instance on Room 201A	Does not exist
Emergency Shut-Off Power	
Instance on Room 201A	Does not exist
Power Supply	
Instance on Room 201A	Does not exist
SWIMMING POOL	
	Does not exist
TOILET ROOM - STAFF	
	Inspected
Lighting	
	Inspected
Lighting Fixture - Fluorescent	
	Inspected
Pendant Mounted	
	Does not exist
Surface Mounted	
Condition	3- Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
	Does not exist
Lighting Fixture - HID	
	Does not exist
Lighting Fixture - Incandescent	
	Does not exist
Lighting Fixture - LED	
	Does not exist
TOILET ROOM - STUDENT	
	Inspected
Lighting	
	Inspected
Lighting Fixture - Fluorescent	
	Inspected
Pendant Mounted	
	Does not exist

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X120

Question	Response
TOILET ROOM - STUDENT	
Lighting	
Lighting Fixture - Fluorescent	
Surface Mounted	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not exist
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
EMERGENCY DC STANDBY BATTERY POWER	Does not exist
EMERGENCY GENERATOR SET	Does not exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
EMERGENCY LIGHTING	Inspected
Battery Pack	Inspected
Condition	2- Between Good and Fair
Deficiency	BATTERY NOT OPERATIONAL
Deficiency Location/Instance	Auditorium
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE BATTERY
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 4
Violations	35672128Z
Non Battery Pack	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
EXIT LIGHT	Inspected
Battery Pack	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Non Battery Pack	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
EXIT/EMERGENCY LIGHT	Does not exist
FIRE ALARM SYSTEM	Inspected
Bell/Horn	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Strobe	Does not exist
Manual Pull Station	Inspected
Condition	3- Fair
Deficiency	PULL STATION COVER IS MISSING
Deficiency Location/Instance	Main Entrance Lobby
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL COVER
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X120

Question	Response
FIRE ALARM SYSTEM	
Manual Pull Station	
Violations	No violations recorded
Fan Shutdown Control	Does not exist
Duct Smoke Detector	Does not exist
Area Smoke Detector	Does not exist
CO Detector	Does not exist
Heat Detector	Does not exist
Elevator Recall	Does not exist
Magnetic Door Holder/Contactor	Does not exist
Fused Cutout Panel	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Fire Alarm Digital Communicator	Does not exist
Main Panel	Inspected
Bell At Panel	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Electronic)	Does not exist
Fire Alarm Control Panel (Standard)	Inspected
Instance	Boiler Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	ACME
EquipmentId	N/A
Installation Year	1955
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	115,000
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Sub-Panel	Inspected
Bell At Panel	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Electronic)	Does not exist
Fire Alarm Control Panel (Standard)	Inspected
Instance	Boiler Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	ACME
EquipmentId	N/A
Installation Year	1955
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	115,000
Quantity Uom	S.F.
Potential Action	REPLACE

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X120

Question	Response
FIRE ALARM SYSTEM	
Sub-Panel	
Fire Alarm Control Panel (Standard)	
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Boiler Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	ACME
EquipmentId	N/A
Installation Year	1955
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	115,000
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Remote Annunciator	Inspected
Display Monitor	Does not exist
Panel	Does not exist
Printer	Does not exist
Punch Register	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Sprinkler Flow/Air Pressure Switch	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Tamper Flow Switch/Chain	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
GROUNDING SYSTEM	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
INTERCOM SYSTEM	Does not exist
LAN	Inspected
Local Distribution Frame (I/LDF)	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	Does not exist
MOTOR CONTROLLER	Inspected
MOTOR CONTROL CENTER	Does not exist
MOTOR STARTER/CONTACTOR	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Variable Frequency Drive	Inspected
Condition	1- Good

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X120

Question	Response
MOTOR CONTROLLER	
Variable Frequency Drive	
Deficiency	No deficiencies recorded
PANEL BOARD	
	Inspected
Fused Disconnect Switch Type	
Condition	2- Between Good and Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Fused Knife Switch Type	
	Does not exist
Fused Toggle Switch Type	
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Auditorium Stage
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Molded Case Circuit Breaker Type	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
PUBLIC ADDRESS SYSTEM	
	Inspected
Instance	Room 120
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Rauland MPA 250
Installation Year	2009
Source of Installation Year	Custodial Staff
Deficiency	CLOCK NOT OPERATIONAL
Deficiency Location/Instance	Throughout the Building
Deficiency Quantity	20
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	SPEAKER NOT OPERATIONAL
Deficiency Location/Instance	Kitchen, Rooms 339, 226
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded
SECURITY	
	Inspected
IPDVS/CCTV System	
	Does not exist
Intrusion Alarm System	
	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X120

Question	Response
SECURITY	
Intrusion Alarm System	
Central Control Panel	Inspected
Instance	Custodian's Office
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista - 128B
Installation Year	1999
Source of Installation Year	Inspector Estimate
Deficiency	No deficiencies recorded
Infrared Sensor	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Panic Switch	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Remote Annunciator	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Siren/Strobe	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting - Security	Inspected
Condition	2- Between Good and Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Location/Instance	Building Perimeters
Deficiency Quantity	23
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 3
Violations	No violations recorded
SERVICE SWITCH	Inspected
Instance	Electrical Room B5
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Electrotech
EquipmentId	N/A
Capacity/Size Quantity	1600
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2009
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
SWITCHBOARD	Inspected
Number of Spares	3
Fused Disconnect Switch Type	Inspected
Instance	Electrical Room B5
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Electrotech

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X120

Question	Response
SWITCHBOARD	
Fused Disconnect Switch Type	
EquipmentId	Sections 1, 2, 3
Capacity/Size Quantity	1600
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	3
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Service Switch Size
Installation Year	2009
Source of Installation Year	Custodial Staff
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not exist
Molded Case Circuit Breaker Type	Does not exist
TELEPHONE SYSTEM	Inspected
PBX/Intercom	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Standard	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
TRANSFORMER	Does not exist