Building Condition Assessment Survey 2023-2024

Electrical Inspection X192

A	sset:	I.S. 192 - BRONX, 650 HOLLYWOOD AVENUE, BRONX, NY, 10465				
Ir	spection Id	Inspection Type	Time In	Last Edited		
	4769	ELECTRICAL	2024-04-16 09:27AM	2024-05-22 09:09AM		

As

Question	Answer
Have any Systems/Major Building Components been upgraded?	Systems: IPDVS/CCTV System
nave any systems major building components occil apgraded.	Years: 2024
	Systems: Partial Molded Case Circuit Breaker Type Panel Boar
	Years: 2023, 2016, 2010, 2001, 1997
	Systems: LAN
	Years: 2022
	Systems: Exit Light (Battery Pack)
	Years: 2018
	Systems: Transformer, Partial Service Switch
	Years: 2016
	Systems: Interior Lighting including LED Lighting in Basemen Auditorium and Dance Room
	Years: 2015
	Systems: Telephone System, Intercom System (Holding Rooms
	Years: 2013
	Systems: Fire Alarm System, Security Lighting
	Years: 2011
	Systems: Public Address System, Local Sound System, Intrusic Alarm System
	Years: 2010
	Systems: Library
	Years: 2009
	Systems: Emergency Light/Exit Light Panel
	Years: 1997
Type of Service	Below Ground
Does Interactive Whiteboard (IWB) Exist?	Yes

DEDICATED INTERCOMS IN FIRE RESCUE AREAS

Water Penetration In Electrical Room?

PEDICHTED EXTENSIONS EXTINE RESCOED THE PEDICE		
Question	Response	
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in	No	
your building?		

Yes

Priority Condition

Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image
No	Intercom - Not Operational	N/A	Intercom System - Elevator	Elevator - Device ID: 2P4548	Juan Rodriguez	Fireman	
No	Water Penetration in Electrical Room	N/A	Electrical Equipment	Electrical Room B33	Juan Rodriguez	Fireman	

Inspection

Question	Response
Electrical	
ATHLETIC FIELD	Does not exist

Building Condition Assessment Survey 2023-2024

ical Inspection	XI
nestion	Response
AUDITORIUM	Inspected
Instance on 1st Floor	Inspected
House Lighting	
Instance on 1st Floor	Inspected
Does a Chandelier Exist?	No
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on 1st Floor	Does not exist
Recessed Mounted	
Instance on 1st Floor	Does not exist
Lighting Fixture - HID	
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not exist
Lighting Fixture - LED	
Instance on 1st Floor	Inspected
Pendant Mounted	·
Instance on 1st Floor	Does not exist
Surface Mounted	
Instance on 1st Floor	Does not exist
Recessed Mounted	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	5
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Local Sound System	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Installation Year	2010
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Projection System	
Instance on 1st Floor	Does not exist
Theater Lighting System	
Instance on 1st Floor	Inspected
Dimming System	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	DIMMING RACK/LIGHT CONSOLE BEYOND USEFUL LIFE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded

Building Condition Assessment Survey 2023-2024

uestion	Response
AUDITORIUM	
Theater Lighting System	
Theater Lighting	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	104
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
CAFETERIA	Inspected
Instance on 1st Floor - Staff	Inspected
Instance on 1st Floor - Students	Inspected
Lighting	
Instance on 1st Floor - Staff	Inspected
Instance on 1st Floor - Students	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor - Students	Inspected
Instance on 1st Floor - Staff	Inspected
Pendant Mounted	
Instance on 1st Floor - Students	Does not exist
Instance on 1st Floor - Staff	Does not exist
Surface Mounted	
Instance on 1st Floor - Students	Does not exist
Instance on 1st Floor - Staff	Does not exist
Recessed Mounted	
Instance on 1st Floor - Students	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on 1st Floor - Staff	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	The deficiences recorded
Instance on 1st Floor - Students	Does not exist
Instance on 1st Floor - Staff	Does not exist Does not exist
	DOES HOL CAISE
Lighting Fixture - Incandescent Instance on 1st Floor - Students	Does not exist
	Does not exist Does not exist
Instance on 1st Floor - Staff	Does not exist
Lighting Fixture - LED	Does not exist
Instance on 1st Floor - Students Instance on 1st Floor - Staff	Does not exist Does not exist
	Does not exist
Local Sound System Instance on 1st Floor - Staff	Does not exist
Instance on 1st Floor - Students	Inspected
Instance Condition	3- Fair
Installation Year Source of Installation Year	2010 Documented
Deficiency	No deficiencies recorded
	ino deficiencies recorded
Projection System Instance on 1st Floor - Staff	Does not exist
Instance on 1st Floor - Students Theater Lighting System	Does not exist

Building Condition Assessment Survey 2023-2024

neu Inspection	Ai
Question	Response
CAFETERIA	
Theater Lighting System	
Instance on 1st Floor - Staff	Does not exist
Instance on 1st Floor - Students	Does not exist
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected
Lighting	Inspected
Does a Chandelier Exist?	No
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Inspected
Pendant Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Surface Mounted	Does not exist
Recessed Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
COMPUTER LAB	Does not exist
GYMNASIUM	Inspected
Instance on 1st Floor	Inspected
Lighting	1
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	•
Instance on 1st Floor	Does not exist
Lighting Fixture - HID	
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not exist
Lighting Fixture - LED	
Instance on 1st Floor	Inspected
Pendant Mounted	1
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE BALLAST

Building Condition Assessment Survey 2023-2024

Duestion	Response	
GYMNASIUM	- Copolist	
Lighting		
Lighting Fixture - LED		
Pendant Mounted		
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Surface Mounted		
Instance on 1st Floor	Does not exist	
Recessed Mounted		
Instance on 1st Floor	Does not exist	
Local Sound System		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Installation Year	2010	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Projection System		
Instance on 1st Floor	Does not exist	
Scoreboard		
Instance on 1st Floor	Does not exist	
Theater Lighting System		
Instance on 1st Floor	Does not exist	
KITCHEN	Inspected	
Instance on 1st Floor	Inspected	
Lighting		
Instance on 1st Floor	Inspected	
Lighting Fixture - Fluorescent		
Instance on 1st Floor	Inspected	
Pendant Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID		
Instance on 1st Floor	Does not exist	
Lighting Fixture - Incandescent		
Instance on 1st Floor	Does not exist	
Lighting Fixture - LED		
Instance on 1st Floor	Does not exist	
LIBRARY	Inspected	
Instance on Room 103A	Inspected	
Lighting		
Instance on Room 103A	Inspected	
Lighting Fixture - Fluorescent		
Instance on Room 103A	Inspected	
	-	

Building Condition Assessment Survey 2023-2024

icui Inspection	1
uestion	Response
LIBRARY	
Lighting	
Lighting Fixture - Fluorescent	
Surface Mounted	
Instance on Room 103A	Does not exist
Recessed Mounted	
Instance on Room 103A	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Lighting Fixture - HID	
Instance on Room 103A	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 103A	Does not exist
Lighting Fixture - LED	
Instance on Room 103A	Does not exist
Raceway With Receptacles	
Instance on Room 103A	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Projection System	
Instance on Room 103A	Does not exist
LOCKER ROOM	Inspected
Instance on 1st Floor - Girls	Inaccessible
MULTIPURPOSE ROOM	Does not exist
SCIENCE DEMO ROOM	Inspected
Instance on Rooms 317, 417	Inspected
Power Panel?	No
Alternative Use	Yes
Lighting	
Instance on Rooms 317, 417	Inspected
Lighting Fixture - Fluorescent	
Instance on Rooms 317, 417	Inspected
Pendant Mounted	
Instance on Rooms 317, 417	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Rooms 317, 417	Does not exist
Recessed Mounted	
Instance on Rooms 317, 417	Does not exist
Lighting Fixture - HID	Does not Oalst
Instance on Rooms 317, 417	Does not exist
	DOCS HOL CAISE
Lighting Fixture - Incandescent Instance on Rooms 317, 417	Does not exist
Instance on Rooms 317, 417	Does not exist
Lighting Fixture - LED	Does not aviet
Instance on Rooms 317, 417	Does not exist
Emergency Gas Shut-Off Valve	Does not exist
Instance on Rooms 317, 417	DOCS HOT CYIST

Building Condition Assessment Survey 2023-2024

estion	Response	
CIENCE DEMO ROOM		
Emergency Shut-Off Power		
Instance on Rooms 317, 417	Does not exist	
Power Supply		
Instance on Rooms 317, 417	Does not exist	
Projection System		
Instance on Rooms 317, 417	Does not exist	
CIENCE LAB	Inspected	
Instance on Room 210	Inspected	
Power Panel?	Yes	
Alternative Use	Yes	
Instance on Room 212	Inspected	
Power Panel?	No	
Alternative Use	Yes	
Instance on Rooms 310, 410	Inspected	
Power Panel?	Yes	
Alternative Use	No	
Instance on Room 412	Inspected	
Power Panel?	No	
Alternative Use	No	
Instance on Room 312	Inspected	
Power Panel?	No	
Alternative Use	Yes	
Lighting		-
Instance on Room 210	Inspected	
Instance on Room 212	Inspected	
Instance on Rooms 310, 410	Inspected	
Instance on Room 412	Inspected	
Instance on Room 312	Inspected	
Lighting Fixture - Fluorescent		
Instance on Room 210	Inspected	
Instance on Room 212	Inspected	
Instance on Rooms 310, 410	Inspected	
Instance on Room 412	Inspected	
Instance on Room 312	Inspected	
Pendant Mounted		
Instance on Room 210	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Instance on Room 212	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Instance on Rooms 310, 410	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Instance on Room 412	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Instance on Room 312	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Sui fact Mounted		

Building Condition Assessment Survey 2023-2024

Electrical Inspection	X192
Question	Response

Question	Response
SCIENCE LAB	
Lighting	
Lighting Fixture - Fluorescent	
Surface Mounted	
Instance on Room 212	Does not exist
Instance on Rooms 310, 410	Does not exist
Instance on Room 412	Does not exist
Instance on Room 312	Does not exist
Recessed Mounted	
Instance on Room 210	Does not exist
Instance on Room 212	Does not exist
Instance on Rooms 310, 410	Does not exist
Instance on Room 412	Does not exist
Instance on Room 312	Does not exist
Lighting Fixture - HID	
Instance on Room 210	Does not exist
Instance on Room 212	Does not exist
Instance on Rooms 310, 410	Does not exist
Instance on Room 412	Does not exist
Instance on Room 312	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 210	Does not exist
Instance on Room 212	Does not exist
Instance on Rooms 310, 410	Does not exist
Instance on Room 412	Does not exist
Instance on Room 312	Does not exist
Lighting Fixture - LED	
Instance on Room 210	Does not exist
Instance on Room 212	Does not exist
Instance on Rooms 310, 410	Does not exist
Instance on Room 412	Does not exist
Instance on Room 312	Does not exist
Emergency Gas Shut-Off Valve	
Instance on Room 210	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 212	Does not exist
Instance on Rooms 310, 410	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 412	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 312	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Emergency Shut-Off Power	The deficiency recorded
Instance on Room 210	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 212	Does not exist
Instance on Rooms 310, 410	Inspected

Building Condition Assessment Survey 2023-2024

	24172
Response	
No deficiencies recorded	
Inspected	
3- Fair	
No deficiencies recorded	
Inspected	
3- Fair	
No deficiencies recorded	
Does not exist	
Does not exist	
Inspected	
Inspected	
No	
Inspected	
Inspected	
Inspected	
2- Between Good and Fair	
No deficiencies recorded	
Does not exist	
Does not exist	
Does not exist	
Does not exist	
Does not exist	
Does not exist	
Does not exist	
	
Does not exist	
Does not exist Does not exist	
Does not exist	
	No deficiencies recorded Inspected 3- Fair No deficiencies recorded Inspected 3- Fair No deficiencies recorded Does not exist Inspected Inspected Inspected Inspected Inspected Does not exist

Building Condition Assessment Survey 2023-2024

Response	
Does not exist	
Inspected	
2- Between Good and Fair	
No deficiencies recorded	
Does not exist	
Inspected	
<u>-</u>	
_	
3- Fair	
PANEL BOARD DOOR LOCK IS MISSING	
Electrical Room B33 - Section "B"	
-	
•	
<u>-</u>	
5- Fair	
DIVINITION IN COLUMN ASSESSMENT OF	
FIXTURE LENS MISSING 2nd Floor by Stair E	
	Does not exist Inspected 2- Between Good and Fair No deficiencies recorded Does not exist Does not exist Does not exist Inspected Inspected Inspected Inspected Inspected 2- Between Good and Fair No deficiencies recorded Inspected 2- Between Good and Fair No deficiencies recorded Inspected 2- Between Good and Fair No deficiencies recorded Does not exist Inspected 3- Fair No deficiencies recorded Does not exist Inspected 3- Fair No deficiencies recorded Does not exist Does not exist Inspected 3- Fair

Building Condition Assessment Survey 2023-2024

icui Inspection	-	X1)2
uestion	Response	
EMERGENCY LIGHTING		
Non Battery Pack		
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	INSTALL LENS	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
EXIT LIGHT	Inspected	
Battery Pack	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Non Battery Pack	Inspected	
Condition	3- Fair	
Deficiency	FIXTURE LAMP NOT OPERATIONAL	
Deficiency Location/Instance	Boiler Room - Mechanical Room	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
EXIT/EMERGENCY LIGHT	Does not exist	
FIRE ALARM SYSTEM	Inspected	
Bell/Horn	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Strobe	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Manual Pull Station	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Fan Shutdown Control	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Duct Smoke Detector	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Area Smoke Detector	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
	Does not exist	
CO Detector	Inspected	
Heat Detector	2- Between Good and Fair	
Condition		
Deficiency	No deficiencies recorded	
Elevator Recall	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Magnetic Door Holder/Contactor	Does not exist	
Fused Cutout Panel	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Fire Alarm Digital Communicator	Does not exist	
Main Panel	Inspected	

Building Condition Assessment Survey 2023-2024

incui inspection		11112
Question	Response	
FIRE ALARM SYSTEM		
Main Panel		
Bell At Panel	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Electronic)	Inspected	
Instance	Main Entrance Lobby	
Instance Condition	2- Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Edwards System Technology	
Model	EST 2	
EquipmentId	Fire Alarm Control Panel	
Installation Year	2011	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Standard)	Does not exist	
Sub-Panel	Does not exist	
Remote Annunciator	Inspected	
Display Monitor	Does not exist	
Panel	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Printer	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Punch Register	Does not exist	
Sprinkler Flow/Air Pressure Switch	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Tamper Flow Switch/Chain	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
GROUNDING SYSTEM	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
<u> </u>		
INTERCOM SYSTEM	Inspected	
Elevator	Inspected 4- Between Fair and Poor	
Condition	INTERCOM CABINET NOT OPERATIONAL	
Deficiency Deficiency Location/Instance	Elevator - Device ID: 2P4548	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 6	
Violations	No violations recorded	
Holding Area	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
<u> </u>	Inspected	
Lan Land Distribution France (I/I DE)	Inspected	
Local Distribution Frame (I/LDF)	1- Good	
Condition	No deficiencies recorded	
Deficiency	no deficiencies recorded	

Building Condition Assessment Survey 2023-2024

rical Inspection	X19
uestion	Response
LAN	
Main Equipment Rack (MDF)	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	Does not exist
MOTOR CONTROLLER	Inspected
MOTOR CONTROL CENTER	Does not exist
MOTOR STARTER/CONTACTOR	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Variable Frequency Drive	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Boiler Room, Boiler Room - Mechanical Area, Mechanical Room
Benefolicy Essentials installed	228
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Fused Knife Switch Type	Does not exist
Fused Toggle Switch Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room B33
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Molded Case Circuit Breaker Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Throughout the Building
Deficiency Quantity	20
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	PANEL BOARD DOOR LOCK IS MISSING
Deficiency Location/Instance	By Room B26
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	NO SPARE
Deficiency Location/Instance	By Cafeteria, By Rooms (416, 310, 134)

Building Condition Assessment Survey 2023-2024

in Inspection	
estion	Response
ANEL BOARD	
Molded Case Circuit Breaker Type	
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	REPLACE PANEL BOARD
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
UBLIC ADDRESS SYSTEM	Inspected
Instance	Room 220
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Rauland MPA 250
Installation Year	2010
Source of Installation Year	Documented
Deficiency	CLOCK NOT OPERATIONAL
Deficiency Location/Instance	Throughout the Building
Deficiency Quantity	7
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
ECURITY	Inspected
IPDVS/CCTV System	Inspected
Condition	1- Good
Installation Year	2024
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Intrusion Alarm System	Inspected
Central Control Panel	Inspected
Instance	Custodian's Office - Room 125
Instance Condition	3- Fair
Instance Quantity	
	1 EACH
Instance Quantity Uom	
Model	Vista - 128BP
Installation Year Source of Installation Year	2010 Documented
Deficiency Deficiency Quantity	PANEL NOT CONNECTED TO DOE CENTRAL STATION
Quantity Uom	l EACH
Potential Action	INSTALL CONNECTION
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 3
Violations	No violations recorded
Infrared Sensor	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Panic Switch	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Remote Annunciator	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded

Building Condition Assessment Survey 2023-2024

SECURITY SECURITY System Intrusion Alarm System Siren/Strobe Inspected Condition 3 - Fair Deficiency No deficiencies recorded Underline Security Inspected Condition 3 - Fair Deficiency Location/Instance Electrical Room B33 Deficiency Quantity 1 I plantil Action EACH Polential Action ERPLACE Purpose of Action LEVEL 3 Violations No violations recorded Deficiency Location/Instance Exterior Walls - Building Perimeter Deficiency Location/Instance Instance Condition REPLACE BALLAST PRIORITY 3 Instance Condition	
Intrustion Alarm System	
Siren/Strobe Condition OPticiency No deficiencies recorded Lighting - Security Imspected Condition Deficiency Deficiency Time CLOCK NOT OPERATIONAL Deficiency Location/Instance Deficiency Location/Instance Deficiency Quantity I 1 Quantity Uom EACH Potential Action Urgency of Action Deficiency Action Deficiency Location/Instance Deficiency Quantity I 1 Quantity Uom EACH Potential Action Urgency of Action Urgency of Action Urgency of Action Deficiency Ucantify Uom Deficiency Ucantify Uom Deficiency Deficiency Deficiency Quantify I 13 Quantity Uom EACH Potential Action Urgency of Acti	
Deficiency No deficiencies recorded Lighting - Security Inspected	
Deficiency Inspected Inspected Condition 3-Fair Deficiency TIME CLOCK NOT OPERATIONAL Electrical Room B33 Deficiency Quantity 1 Quantity Uom EACH Protesting Protes	
Lighting - Security	
Condition Deficiency Deficiency Location/Instance Deficiency Quantity Quantity Uom Perential Action Potential Action Purpose of Action Perential Action Deficiency Quantity Iugency of Action Perential Action Purpose of Action Perential Action Deficiency Deficiency Deficiency Deficiency Location/Instance Deficiency Quantity Instance Action Perential Action Per	
Deficiency Deficiency Deficiency Deficiency Deficiency Deficiency Quantity 1 1 1 1 1 1 1 1 1	
Deficiency Location/Instance Deficiency Quantity Quantity Uom EACH Potential Action Urgency of Action Urgency of Action Urgency of Action LEVEL 3 Violations Deficiency Deficie	
Deficiency Quantity Uom EACH Potential Action REPLACE Urgency of Action PRIORITY 3 Purpose of Action LEVEL 3 Violations No violations recorded Deficiency LIGHTING FIXTURE BALLAST DEFECTIVE Deficiency LOCATION EXTERNAL STOPPENTIVE Deficiency Quantity 13 Quantity Uom EACH Potential Action REPLACE BALLAST Urgency of Action LEVEL 3 Violations No violations recorded SERVICE SWITCH Instance Electrical Room B33 Instance Quantity Instance Installation Year Year Year Year Year Year Year Year	
Quantity Uom REPLACE Potential Action REPLACE Urgency of Action PRIORITY 3 Purpose of Action LEVEL 3 Violations No violations recorded Deficiency Deficiency Exterior Walls - Building Perimeter Deficiency Quantity 13 Quantity Uom EACH Potential Action PRIORITY 3 Purpose of Action PRIORITY 3 Purpose of Action PRIORITY 3 Purpose of Action PRIORITY 3 Possible SWITCH Inspected Deficiency Quantity 13 REPLACE BALLAST DEFECTIVE EXEMPLE SWITCH Inspected Instance Priority 13 Instance Quantity 14 Instance Priority 15 Instance Priority 15 Instance Priority 16 Instance Priority 16 Instance Priority 17 Instance Quantity 11 Instance Quantity 11 Instance Quantity 11 Instance Quantity 11 Instance Quantity 1600 Capacity/Size Quantity 1600 Capacity/Size Quantity 1600 Capacity/Size Quantity 1972 Source of Capacity/Size Installation Year 1972 Source of Installation Year 1972 Source of Installation Year Documented Deficiency BEYOND USEFUL LIFE Deficiency Quantity 11 Quantity Uom EACH Potential Action REPLACE Potential Action PRIORITY 1 Purpose of Action LEVEL 2 Violations No violations recorded	
Potential Action Urgency of Action PRIORITY Purpose of Action LEVEL 3 Violations Poficiency Deficiency Deficiency Location/Instance Deficiency Countity 13 Quantity Uom Potential Action Priority Purpose of Action Purpose of Actio	
Urgency of Action Purpose of Action Purpose of Action Purpose of Action Deficiency Deficiency Deficiency Location/Instance Deficiency Quantity Deficiency Deficiency Quantity Deficiency Deficiency Deficiency Quantity Deficiency Defic	
Purpose of Action LEVEL 3 Violations No violations recorded Deficiency LIGHTING FIXTURE BALLAST DEFECTIVE Deficiency Location/Instance Exterior Walls - Building Perimeter Deficiency Quantity 13 Quantity Uom EACH Potential Action REPLACE BALLAST Urgency of Action PRIORITY 3 Purpose of Action LEVEL 3 Violations No violations recorded SERVICE SWITCH Inspected Instance Instance Condition Instance Condition 3 - Fair Instance Quantity 1 Instance Quantity Uom EACH Manufacturer Empire Switchboard EquipmentId N/A Capacity/Size Quantity 1600 Capacity/Size Quantity 1600 Capacity/Size Quantity 1972 Source of Capacity/Size Nameplate Installation Year Decine Properties of Pr	
Violations No violations recorded Deficiency LIGHTING FIXTURE BALLAST DEFECTIVE Deficiency Location/Instance Exterior Walls - Building Perimeter Deficiency Quantity 13 Quantity Uom EACH Potential Action REPLACE BALLAST Urgency of Action LEVEL 3 Purpose of Action LEVEL 3 Violations No violations recorded SERVICE SWITCH Instance Electrical Room B33 Instance Quantity 1 Instance Quantity 1 Instance Quantity Uom EACH Manufacturer Empire Switchboard EquipmentId N/A Capacity/Size Quantity 1600 Capacity/Size Quantity 1600 Capacity/Size Quantity Amps Source of Installation Year Documented Deficiency BEVOND USEFUL LIFE Deficiency Quantity 1 Quantity Uom EACH Potential Action REPLACE Urgency of Action PRIORITY 1	
Deficiency Deficiency Location/Instance Deficiency Quantity Deficiency Quantity 13 Quantity Uom EACH Potential Action Potential Action Potential Action Potential Action Potential Action Prioring Instance Action Prioring Action Prioring Action Prioring Action Prioring Action Prioring Instance Prioring Action Prioring Action Prioring Instance	
Deficiency Location/Instance Deficiency Quantity Deficiency Quantity Quantity Uom EACH Potential Action Potential Potenti	
Deficiency Quantity 13	
Quantity Uom Potential Action Potential Action Preserved Action Preserved Action Preserved Action Preserved Action Preserved Action Preserved BALLAST Preserved Action Preserved BALLAST Preserv	
Potential Action Urgency of Action PRIORITY 3 Purpose of Action Purpose of Action Purpose of Action Violations No violations recorded EVEL 3 No violations recorded Instance Instance Instance Condition Instance Quantity Instance Quantity Instance Quantity Uom EACH Manufacturer Equipmentld Capacity/Size Quantity Instance of Capacity/Size UOM Amps Source of Capacity/Size Installation Year Deficiency Deficiency Deficiency Deficiency Deficiency Quantity Deficiency Quantity Deficiency Quantity Deficiency Putpose of Action Purpose of Action Purpose of Action Violations recorded REPLACE BALLAST PRIORITY 1 LEVEL 2 Violations No violations recorded	
Urgency of Action	
Purpose of Action LEVEL 3 Violations No violations recorded SERVICE SWITCH Inspected Instance Electrical Room B33 Instance Condition 3 - Fair Instance Quantity 1 Instance Quantity Uom EACH Manufacturer Empire Switchboard EquipmentId N/A Capacity/Size Quantity 1600 Capacity/Size UOM Amps Source of Capacity/Size Nameplate Installation Year 1972 Source of Installation Year Documented Deficiency BEYOND USEFUL LIFE Deficiency Quantity 1 Quantity Uom EaCH Potential Action REPLACE Urgency of Action PRIORITY 1 Purpose of Action PRIORITY 1 Purpose of Action No violations recorded	
Violations No violations recorded	
Instance Electrical Room B33 Instance Condition 3- Fair Instance Quantity 1 Instance Quantity Uom EACH Manufacturer Empire Switchboard EquipmentId N/A Capacity/Size Quantity 1600 Capacity/Size UOM Amps Source of Capacity/Size Nameplate Installation Year 1972 Source of Installation Year Documented Deficiency BEYOND USEFUL LIFE Deficiency Location/Instance Electrical Room B33 Deficiency Quantity 1 Quantity Uom EACH Potential Action REPLACE Urgency of Action PRIORITY 1 Purpose of Action Purpose of Action Violations No violations recorded	
Instance Condition 3- Fair Instance Quantity 1 Instance Quantity Uom EACH Manufacturer Empire Switchboard EquipmentId N/A Capacity/Size Quantity 1600 Capacity/Size UOM Amps Source of Capacity/Size Nameplate Installation Year 1972 Source of Installation Year Decumented Deficiency BEYOND USEFUL LIFE Deficiency Quantity 1 Quantity Uom EACH Potential Action REPLACE Urgency of Action PRIORITY 1 Purpose of Action LEVEL 2 Violations No violations recorded	
Instance Condition Instance Quantity Instance Quantity Uom EACH Manufacturer EquipmentId Capacity/Size Quantity Capacity/Size UOM Source of Capacity/Size Installation Year Installation Year Deficiency Deficiency Deficiency Location/Instance Deficiency Quantity Quantity Uom Potential Action Urgeney of Action Urgeney of Action Purpose of Action Ver Violations 3 - Fair 1 LEVEL 2 Lacch EACH EACH EACH EACH EACH EACH EACH EACH	
Instance Quantity Uom EACH Manufacturer Empire Switchboard EquipmentId N/A Capacity/Size Quantity 1600 Capacity/Size UOM Source of Capacity/Size Installation Year Installation Year Source of Installation Year Deficiency Deficiency BEYOND USEFUL LIFE Deficiency Location/Instance Electrical Room B33 Deficiency Quantity Quantity Uom EACH Potential Action Urgency of Action Purpose of Action Purpose of Action Purpose of Action No violations recorded	
Instance Quantity Uom Manufacturer Empire Switchboard N/A Capacity/Size Quantity 1600 Capacity/Size UOM Amps Source of Capacity/Size Nameplate Installation Year Installation Year Documented Deficiency Deficiency Deficiency Location/Instance Deficiency Quantity Quantity Uom EACH Potential Action Prepose of Action Purpose of Action Purpose of Action V/A Empire Switchboard N/A Empire Switchboard N/A Empire Switchboard N/A Empire Switchboard N/A Empire Switchboard Name Empire Switchboard Name Empire Switchboard Name I 600 Empire Switchboard I 972 Source of Installation EFYOND USEFUL LIFE Deficiency Quantity I EACH Potential Action REPLACE Urgency of Action PRIORITY I Purpose of Action LEVEL 2 Violations	
Instance Quantity Uom Manufacturer Empire Switchboard N/A Capacity/Size Quantity 1600 Capacity/Size UOM Amps Source of Capacity/Size Nameplate Installation Year Installation Year Documented Deficiency Deficiency Deficiency Location/Instance Deficiency Quantity Quantity Uom EACH Potential Action Prepose of Action Purpose of Action Purpose of Action V/A Empire Switchboard N/A Empire Switchboard N/A Empire Switchboard N/A Empire Switchboard N/A Empire Switchboard Name Empire Switchboard Name Empire Switchboard Name I 600 Empire Switchboard I 972 Source of Installation EFYOND USEFUL LIFE Deficiency Quantity I EACH Potential Action REPLACE Urgency of Action PRIORITY I Purpose of Action LEVEL 2 Violations	
Manufacturer EquipmentId N/A Capacity/Size Quantity 1600 Capacity/Size UOM Amps Source of Capacity/Size Installation Year Source of Installation Year Deficiency Deficiency Deficiency Location/Instance Deficiency Quantity Quantity Uom EACH Potential Action Urgency of Action Purpose of Action Purpose of Action No violations recorded	
EquipmentId Capacity/Size Quantity 1600 Capacity/Size UOM Amps Source of Capacity/Size Nameplate Installation Year Source of Installation Year Deficiency Deficiency Deficiency Location/Instance Deficiency Quantity 1 Quantity Uom EACH Potential Action Protential Action Urgency of Action Purpose of Action Purpose of Action Violations No violations recorded	
Capacity/Size Quantity Capacity/Size UOM Amps Source of Capacity/Size Installation Year Installation Year Source of Installation Year Deficiency BEYOND USEFUL LIFE Deficiency Location/Instance Deficiency Quantity I Quantity Uom EACH Potential Action REPLACE Urgency of Action Purpose of Action LEVEL 2 Violations No violations recorded	
Capacity/Size UOM Source of Capacity/Size Installation Year Installation Year Source of Installation Year Deficiency Deficiency Deficiency Location/Instance Deficiency Quantity I Quantity Uom Potential Action Potential Action Urgency of Action Purpose of Action Purpose of Action No violations recorded Amps Nameplate Namepla	
Source of Capacity/Size Installation Year Source of Installation Year Documented Deficiency Deficiency Deficiency Location/Instance Deficiency Quantity I Quantity Uom Deficiency Action Potential Action Urgency of Action Purpose of Action Purpose of Action No violations recorded	
Source of Installation Year Deficiency Deficiency Location/Instance Deficiency Quantity Quantity Uom Potential Action Urgency of Action Purpose of Action Purpose of Action Voil attention Voil attent	
Deficiency Deficiency Location/Instance Deficiency Quantity Deficiency Quantity Quantity Uom EACH Potential Action REPLACE Urgency of Action Purpose of Action LEVEL 2 Violations BEYOND USEFUL LIFE Electrical Room B33 REPLACE Plectrical Room B33 LEVEL 2 No violations REPLACE PRIORITY 1 REPLACE No violations recorded	
Deficiency Location/Instance Electrical Room B33 Deficiency Quantity 1 Quantity Uom EACH Potential Action REPLACE Urgency of Action PRIORITY 1 Purpose of Action LEVEL 2 Violations No violations recorded	
Deficiency Quantity Quantity Uom EACH Potential Action REPLACE Urgency of Action PRIORITY 1 Purpose of Action LEVEL 2 Violations No violations recorded	
Quantity UomEACHPotential ActionREPLACEUrgency of ActionPRIORITY 1Purpose of ActionLEVEL 2ViolationsNo violations recorded	
Potential Action REPLACE Urgency of Action PRIORITY 1 Purpose of Action LEVEL 2 Violations No violations recorded	
Urgency of Action PRIORITY 1 Purpose of Action LEVEL 2 Violations No violations recorded	
Purpose of Action LEVEL 2 Violations No violations recorded	
Violations No violations recorded	
Y . The Dag	
Instance Electrical Room B33	
Instance Condition 2- Between Good and Fair	
Instance Quantity 1	
Instance Quantity Uom EACH	
Manufacturer Square D	
EquipmentId N/A	
Capacity/Size Quantity 400	
Capacity/Size UOM Amps	
Source of Capacity/Size Nameplate	
Installation Year 2016	
Source of Installation Year Documented	
Deficiency No deficiencies recorded	
Instance Electrical Room B33	_

Building Condition Assessment Survey 2023-2024

iricui mspi		A	
Question		Response	
SERVICE S	WITCH		
In	stance Condition	3- Fair	
In	stance Quantity	1	
In	stance Quantity Uom	EACH	
·	anufacturer	Empire Switchboard	
	quipmentId	N/A	
	apacity/Size Quantity	3000	
Ca	apacity/Size UOM	Amps	
Sc	ource of Capacity/Size	Nameplate	
In	stallation Year	1972	
Sc	ource of Installation Year	Documented	
	eficiency	BEYOND USEFUL LIFE	
	Deficiency Location/Instance	Electrical Room B33	
	Deficiency Quantity	1	
	Quantity Uom	EACH	
	Potential Action	REPLACE	
	Urgency of Action	PRIORITY 1	
	Purpose of Action	LEVEL 2	
	Violations	No violations recorded	
In	stance	Electrical Room B33	
In	stance Condition	2- Between Good and Fair	
In	stance Quantity	1	
In	stance Quantity Uom	EACH	
M	anufacturer	Square D	
	quipmentId	Solar Disconnect/89L Disconnect	
	apacity/Size Quantity	600	
	apacity/Size UOM	Amps	
	ource of Capacity/Size	Nameplate	
In	stallation Year	2016	
Sc	ource of Installation Year	Documented	
D	eficiency	No deficiencies recorded	
In	stance	Mechanical Room by Stair E Exit 4	
In	stance Condition	3- Fair	
In	stance Quantity	1	
_	stance Quantity Uom	EACH	
_	anufacturer	Empire Switchboard	
	quipmentId	N/A	
	apacity/Size Quantity	2000	
	apacity/Size UOM	Amps	
	ource of Capacity/Size	Nameplate	
	stallation Year	1972	
	ource of Installation Year	Documented	
D	eficiency	BEYOND USEFUL LIFE	
	Deficiency Location/Instance	Mechanical Room by Stair E Exit 4	
	Deficiency Quantity	1	
	Quantity Uom	EACH	
	Potential Action	REPLACE	
	Urgency of Action	PRIORITY 1	
	Purpose of Action	LEVEL 2	
	Violations	No violations recorded	
SWITCHBO	ARD	Inspected	-
Number of		0	
	onnect Switch Type	Inspected	
_	stance	Electrical Room B33	
	stance Condition	3- Fair	
In			

Building Condition Assessment Survey 2023-2024

uestion	Response	
SWITCHBOARD		
Fused Disconnect Switch Type		
Instance Quantity Uom	EACH	
Manufacturer	Empire Switchboard	
EquipmentId	N/A	
Capacity/Size Quantity	3000	
Capacity/Size UOM	Amps Total	
Capacity/Size 2 Quantity	4	
Capacity/Size 2 UOM	Section(s)	
Source of Capacity/Size	Nameplate	
Installation Year	1972	
Source of Installation Year	Documented	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	Electrical Room B33	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Instance	Mechanical Room by Stair E Exit 4	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Electric Switchboard	
EquipmentId	N/A	
Capacity/Size Quantity	1875	
Capacity/Size UOM	Amps Total	
Capacity/Size 2 Quantity	2	
Capacity/Size 2 UOM	Section(s)	
Source of Capacity/Size	Nameplate	
Installation Year	1972	
Source of Installation Year	Documented	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	Mechanical Room by Stair E Exit 4	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Fused Knife Switch Type	Does not exist	
Molded Case Circuit Breaker Type	Does not exist	
TELEPHONE SYSTEM	Inspected	
PBX/Intercom	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
· · · · · · · · · · · · · · · · · · ·		
Standard	Inspected 2- Between Good and Fair	
Condition		
Deficiency	No deficiencies recorded	
TRANSFORMER	Inspected	
Instance	Basement - Phone Room B29	
Instance Condition	2- Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Hammond	

Building Condition Assessment Survey 2023-2024

Question	Response
TRANSFORMER	
EquipmentId	N/A
Capacity/Size Quantity	150
Capacity/Size UOM	kVA
Source of Capacity/Size	Nameplate
Installation Year	2016
Source of Installation Year	Documented
Deficiency	No deficiencies recorded