

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X455

Asset: HARRY S. TRUMAN HS - BRONX, 750 BAYCHESTER AVENUE, BRONX, NY, 10475

Inspection Id	Inspection Type	Time In	Last Edited
1517	ELECTRICAL	2023-12-04 08:13AM	2024-05-16 11:40AM

Asset Data

Question	Answer
Have any Systems/Major Building Components been upgraded?	<p>Systems: One Transformer in Room CB07</p> <p>Years: 2023</p> <p>Systems: LED Retrofit Lighting</p> <p>Years: 2022</p> <p>Systems: LAN</p> <p>Years: 2021</p> <p>Systems: IPDVS/CCTV System, Fire Alarm System</p> <p>Years: 2019</p> <p>Systems: Telephone System, Security Lights (Light Poles), Partial Emergency Lights (Battery Packs), Exit Lights (Battery Packs), Auditorium (LED Lighting), Gymnasium 1A/1B/1C (Lighting), Retrofitted LED Lighting (Gymnasium 2A/2B, Gymnasium 3A/3B)</p> <p>Years: 2016</p> <p>Systems: Intrusion Alarm System Except (Partial Infrared Sensors)</p> <p>Years: 2014</p> <p>Systems: Emergency Generator Set (Battery Charger)</p> <p>Years: 2013</p> <p>Systems: Partial Transformers</p> <p>Years: 2011, 2008, 2003, 1995</p> <p>Systems: Competition Swimming Pool, Exit/Emergency Lights, Student Toilet Rooms (Surface Fluorescent Lighting), Variable Frequency Drive</p> <p>Years: 2011</p> <p>Systems: Partial Molded Case Circuit Breaker Panel Board</p> <p>Years: 2007, 2000, 1996</p> <p>Systems: Locker Room G79 (Fluorescent Lighting), Science Rooms (407, 408, 410, 607, 707)</p> <p>Years: 2007</p> <p>Systems: Auditoriums (Local Sound System), Planetarium (Theatre Lighting System)</p> <p>Years: 2003</p> <p>Systems: Partial Emergency Generator Set (Automatic Transfer Switch)</p> <p>Years: 2002</p> <p>Systems: 1st Floor Cafeteria (Fluorescent Lighting), Public Address System, Local Sound System (Cafeteria, Gymnasium 1A/1B/1C, Gymnasium 2A/2B)</p> <p>Years: 2000</p> <p>Systems: Emergency Light/Exit Light Panel, Partial Fused Disconnect Switch Type Panel Board</p> <p>Years: 1997</p> <p>Systems: HID Lighting (Pool Mechanical Room)</p> <p>Years: 1995</p> <p>Below Ground</p>
Type of Service	Below Ground
Does Interactive Whiteboard (IWB) Exist?	Yes
Water Penetration In Electrical Room?	No

DEDICATED INTERCOMS IN FIRE RESCUE AREAS


Question	Response
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building?	No

Priority Condition

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X455

Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image
No	Exposed Electrical Wires	Electrical outlet cover is missing and wires are exposed.	Raceway With Receptacles	Computer Lab - Room 762	Roy Paolucci	Fireman	
Yes	Emergency Generator Components - Not Operational	ATS does not return to Normal Mode after test.	Emergency Generator - ATS	Main Electrical Room CB01	Roy Paolucci	Fireman	No Photo Taken

Inspection

Question	Response
Electrical	
ATHLETIC FIELD	Does not exist
AUDITORIUM	Inspected
Instance on 1st Floor	Inspected
Instance on 1st Floor - Planetarium	Inspected
House Lighting	
Instance on 1st Floor	Inspected
Does a Chandelier Exist?	No
Instance on 1st Floor - Planetarium	Inspected
Does a Chandelier Exist?	No
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Does not exist
Instance on 1st Floor - Planetarium	Does not exist
Lighting Fixture - HID	
Instance on 1st Floor	Does not exist
Instance on 1st Floor - Planetarium	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not exist
Instance on 1st Floor - Planetarium	Inspected
Pendant Mounted	
Instance on 1st Floor - Planetarium	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	6
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Surface Mounted	
Instance on 1st Floor - Planetarium	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	14
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Recessed Mounted	
Instance on 1st Floor - Planetarium	Inspected
Instance Condition	3- Fair

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X455

Question	Response
AUDITORIUM	
House Lighting	
Lighting Fixture - Incandescent	
Recessed Mounted	
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	48
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Lighting Fixture - LED	
Instance on 1st Floor	Inspected
Instance on 1st Floor - Planetarium	Does not exist
Pendant Mounted	
Instance on 1st Floor	Does not exist
Surface Mounted	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Local Sound System	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Installation Year	2003
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance on 1st Floor - Planetarium	Inspected
Instance Condition	3- Fair
Installation Year	2003
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Projection System	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Is the projector on a cart or installed on the ceiling?	Ceiling
Deficiency	No deficiencies recorded
Instance on 1st Floor - Planetarium	Inspected
Instance Condition	3- Fair
Is the projector on a cart or installed on the ceiling?	Ceiling
Deficiency	No deficiencies recorded
Theater Lighting System	
Instance on 1st Floor	Inspected
Instance on 1st Floor - Planetarium	Inspected
Dimming System	
Instance on 1st Floor	Inspected
Instance Condition	5- Poor
Deficiency	DIMMING RACK/LIGHT CONSOLE NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3

NYC Department of Education
Building Condition Assessment Survey 2023-2024

Electrical Inspection

X455

Question	Response
AUDITORIUM	
Theater Lighting System	
Dimming System	
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance on 1st Floor - Planetarium	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Theater Lighting	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	202
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance on 1st Floor - Planetarium	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
CAFETERIA	
Instance on 1st Floor - Students	Inspected
Instance on 3rd Floor - Students	Inspected
Instance on 4th Floor - Students	Inspected
Lighting	
Instance on 1st Floor - Students	Inspected
Instance on 3rd Floor - Students	Inspected
Instance on 4th Floor - Students	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor - Students	Inspected
Instance on 3rd Floor - Students	Inspected
Instance on 4th Floor - Students	Inspected
Pendant Mounted	
Instance on 1st Floor - Students	Does not exist
Instance on 3rd Floor - Students	Does not exist
Instance on 4th Floor - Students	Does not exist
Surface Mounted	
Instance on 1st Floor - Students	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on 3rd Floor - Students	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	64
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance on 4th Floor - Students	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	64

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X455

Question	Response
CAFETERIA	
Lighting	
Lighting Fixture - Fluorescent	
Surface Mounted	
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Recessed Mounted	
Instance on 1st Floor - Students	Does not exist
Instance on 3rd Floor - Students	Does not exist
Instance on 4th Floor - Students	Does not exist
Lighting Fixture - HID	
Instance on 1st Floor - Students	Does not exist
Instance on 3rd Floor - Students	Does not exist
Instance on 4th Floor - Students	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor - Students	Inspected
Instance on 3rd Floor - Students	Does not exist
Instance on 4th Floor - Students	Does not exist
Pendant Mounted	
Instance on 1st Floor - Students	Does not exist
Surface Mounted	
Instance on 1st Floor - Students	Does not exist
Recessed Mounted	
Instance on 1st Floor - Students	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	9
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Lighting Fixture - LED	
Instance on 1st Floor - Students	Does not exist
Instance on 3rd Floor - Students	Does not exist
Instance on 4th Floor - Students	Does not exist
Local Sound System	
Instance on 1st Floor - Students	Inspected
Instance Condition	3- Fair
Installation Year	2000
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Cafeteria-1st Floor - Students
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance on 3rd Floor - Students	Inspected
Instance Condition	3- Fair
Installation Year	2000

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X455

Question	Response
CAFETERIA	
Local Sound System	
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Cafeteria-3rd Floor - Students
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance on 4th Floor - Students	Inspected
Instance Condition	3- Fair
Installation Year	2000
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Cafeteria-4th Floor - Students
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Projection System	
Instance on 1st Floor - Students	Does not exist
Instance on 3rd Floor - Students	Does not exist
Instance on 4th Floor - Students	Does not exist
Theater Lighting System	
Instance on 1st Floor - Students	Does not exist
Instance on 3rd Floor - Students	Does not exist
Instance on 4th Floor - Students	Does not exist
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	
Lighting	Inspected
Does a Chandelier Exist?	No
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	188
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Surface Mounted	Inspected
Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	6,230
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Recessed Mounted	Inspected
Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X455

Question	Response
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	
Lighting	
Lighting Fixture - Fluorescent	
Recessed Mounted	
Deficiency Quantity	1,980
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Lighting Fixture - HID	
Inspected	
Pendant Mounted	
Inspected	
Condition	3- Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Inspected	
Condition	3- Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Does not exist	
Lighting Fixture - Incandescent	
Inspected	
Pendant Mounted	
Inspected	
Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	48
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Surface Mounted	
Inspected	
Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	76
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Recessed Mounted	
Inspected	
Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	211
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Lighting Fixture - LED	
Inspected	
Pendant Mounted	
Inspected	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Inspected	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Inspected	
Condition	2- Between Good and Fair

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X455

Question	Response
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	
Lighting	
Lighting Fixture - LED	
Recessed Mounted	
Deficiency	No deficiencies recorded
COMPUTER LAB	
Instance on Room 110	Inspected
Power Panel?	Yes
Instance on Room 441	Inspected
Power Panel?	No
Instance on Room 523	Inspected
Power Panel?	Yes
Instance on Room 662	Inspected
Power Panel?	Yes
Instance on Room 762	Inspected
Power Panel?	Yes
Lighting	
Instance on Room 110	Inspected
Instance on Room 441	Inspected
Instance on Room 523	Inspected
Instance on Room 662	Inspected
Instance on Room 762	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 110	Inspected
Instance on Room 441	Inspected
Instance on Room 523	Inspected
Instance on Room 662	Inspected
Instance on Room 762	Inspected
Pendant Mounted	
Instance on Room 110	Does not exist
Instance on Room 441	Does not exist
Instance on Room 523	Does not exist
Instance on Room 662	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	24
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance on Room 762	Does not exist
Surface Mounted	
Instance on Room 110	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	36
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance on Room 441	Inspected
Instance Condition	3- Fair

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X455

Question	Response
COMPUTER LAB	
Lighting	
Lighting Fixture - Fluorescent	
Surface Mounted	
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	25
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance on Room 523	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	29
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance on Room 662	Does not exist
Instance on Room 762	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	28
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Recessed Mounted	
Instance on Room 110	Does not exist
Instance on Room 441	Does not exist
Instance on Room 523	Does not exist
Instance on Room 662	Does not exist
Instance on Room 762	Does not exist
Lighting Fixture - HID	
Instance on Room 110	Does not exist
Instance on Room 441	Does not exist
Instance on Room 523	Does not exist
Instance on Room 662	Does not exist
Instance on Room 762	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 110	Does not exist
Instance on Room 441	Does not exist
Instance on Room 523	Does not exist
Instance on Room 662	Does not exist
Instance on Room 762	Does not exist
Lighting Fixture - LED	
Instance on Room 110	Does not exist
Instance on Room 441	Inspected
Instance on Room 523	Does not exist
Instance on Room 662	Does not exist
Instance on Room 762	Does not exist
Pendant Mounted	

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X455

Question	Response
COMPUTER LAB	
Lighting	
Lighting Fixture - LED	
Pendant Mounted	
Instance on Room 441	Does not exist
Surface Mounted	
Instance on Room 441	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Room 441	Does not exist
Raceway With Receptacles	
Instance on Room 110	Does not exist
Instance on Room 441	Does not exist
Instance on Room 523	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 662	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 762	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
GYMNASIUM	Inspected
Instance on Basement - Room 1A/1B/1C	Inspected
Instance on Basement - Room 2A/2B	Inspected
Instance on Basement - Room 3A/3B	Inspected
Lighting	
Instance on Basement - Room 1A/1B/1C	Inspected
Instance on Basement - Room 2A/2B	Inspected
Instance on Basement - Room 3A/3B	Inspected
Lighting Fixture - Fluorescent	
Instance on Basement - Room 1A/1B/1C	Inspected
Instance on Basement - Room 2A/2B	Does not exist
Instance on Basement - Room 3A/3B	Inspected
Pendant Mounted	
Instance on Basement - Room 1A/1B/1C	Does not exist
Instance on Basement - Room 3A/3B	Does not exist
Surface Mounted	
Instance on Basement - Room 1A/1B/1C	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Basement - Room 3A/3B	Does not exist
Recessed Mounted	
Instance on Basement - Room 1A/1B/1C	Does not exist
Instance on Basement - Room 3A/3B	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X455

Question	Response
GYMNASIUM	
Lighting	
Lighting Fixture - HID	
Instance on Basement - Room 1A/1B/1C	Does not exist
Instance on Basement - Room 2A/2B	Does not exist
Instance on Basement - Room 3A/3B	Does not exist
Lighting Fixture - Incandescent	
Instance on Basement - Room 1A/1B/1C	Does not exist
Instance on Basement - Room 2A/2B	Does not exist
Instance on Basement - Room 3A/3B	Does not exist
Lighting Fixture - LED	
Instance on Basement - Room 1A/1B/1C	Inspected
Instance on Basement - Room 2A/2B	Inspected
Instance on Basement - Room 3A/3B	Inspected
Pendant Mounted	
Instance on Basement - Room 1A/1B/1C	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE NOT OPERATIONAL
Deficiency Quantity	26
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance on Basement - Room 2A/2B	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Basement - Room 3A/3B	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Basement - Room 1A/1B/1C	Does not exist
Instance on Basement - Room 2A/2B	Does not exist
Instance on Basement - Room 3A/3B	Does not exist
Recessed Mounted	
Instance on Basement - Room 1A/1B/1C	Does not exist
Instance on Basement - Room 2A/2B	Does not exist
Instance on Basement - Room 3A/3B	Does not exist
Local Sound System	
Instance on Basement - Room 1A/1B/1C	Inspected
Instance Condition	3- Fair
Installation Year	2000
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Gymnasium-Basement - Room 1A/1B/1C
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance on Basement - Room 2A/2B	Inspected
Instance Condition	3- Fair
Installation Year	2000
Source of Installation Year	Documented

NYC Department of Education
Building Condition Assessment Survey 2023-2024

Electrical Inspection

X455

Question	Response
GYMNASIUM	
Local Sound System	
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Gymnasium-Basement - Room 2A/2B
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance on Basement - Room 3A/3B	Inspected
Instance Condition	3- Fair
Installation Year	1973
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Gymnasium-Basement - Room 3A/3B
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Projection System	
Instance on Basement - Room 1A/1B/1C	Does not exist
Instance on Basement - Room 2A/2B	Does not exist
Instance on Basement - Room 3A/3B	Does not exist
Scoreboard	
Instance on Basement - Room 1A/1B/1C	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Basement - Room 2A/2B	Does not exist
Instance on Basement - Room 3A/3B	Does not exist
Theater Lighting System	
Instance on Basement - Room 1A/1B/1C	Does not exist
Instance on Basement - Room 2A/2B	Does not exist
Instance on Basement - Room 3A/3B	Does not exist
KITCHEN	
Instance on 1st Floor, 3rd Floor, 4th Floor	Inspected
Lighting	
Instance on 1st Floor, 3rd Floor, 4th Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor, 3rd Floor, 4th Floor	Inspected
Pendant Mounted	
Instance on 1st Floor, 3rd Floor, 4th Floor	Does not exist
Surface Mounted	
Instance on 1st Floor, 3rd Floor, 4th Floor	Does not exist
Recessed Mounted	
Instance on 1st Floor, 3rd Floor, 4th Floor	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	72
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X455

Question	Response
KITCHEN	
Lighting	
Lighting Fixture - Fluorescent	
Recessed Mounted	
Violations	No violations recorded
Lighting Fixture - HID	
Instance on 1st Floor, 3rd Floor, 4th Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor, 3rd Floor, 4th Floor	Does not exist
Lighting Fixture - LED	
Instance on 1st Floor, 3rd Floor, 4th Floor	Does not exist
LIBRARY	
	Inspected
Instance on Room 140	Inspected
Instance on Room 625	Inspected
Lighting	
Instance on Room 140	Inspected
Instance on Room 625	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 140	Inspected
Instance on Room 625	Inspected
Pendant Mounted	
Instance on Room 140	Does not exist
Instance on Room 625	Does not exist
Surface Mounted	
Instance on Room 140	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	100
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance on Room 625	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	34
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Recessed Mounted	
Instance on Room 140	Does not exist
Instance on Room 625	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	17
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Lighting Fixture - HID	
Instance on Room 140	Does not exist

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X455

Question	Response
LIBRARY	
Lighting	
Lighting Fixture - HID	
Instance on Room 625	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 140	Does not exist
Instance on Room 625	Does not exist
Lighting Fixture - LED	
Instance on Room 140	Does not exist
Instance on Room 625	Does not exist
Raceway With Receptacles	
Instance on Room 140	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 625	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Projection System	
Instance on Room 140	Does not exist
Instance on Room 625	Does not exist
LOCKER ROOM	
	Inspected
Instance on Basement Room 2L - Girls	Inspected
Alternative Use	No
Instance on Basement Room G75 - Girls	Inspected
Alternative Use	No
Instance on Basement Room G79 - Boys	Inspected
Alternative Use	No
Instance on Basement Rooms: 4AL - Girls, 4BL - Boys	Inspected
Alternative Use	No
Lighting	
Instance on Basement Room 2L - Girls	Inspected
Instance on Basement Room G75 - Girls	Inspected
Instance on Basement Room G79 - Boys	Inspected
Instance on Basement Rooms: 4AL - Girls, 4BL - Boys	Inspected
Lighting Fixture - Fluorescent	
Instance on Basement Room 2L - Girls	Inspected
Instance on Basement Room G75 - Girls	Inspected
Instance on Basement Room G79 - Boys	Inspected
Instance on Basement Rooms: 4AL - Girls, 4BL - Boys	Inspected
Pendant Mounted	
Instance on Basement Room 2L - Girls	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	28
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance on Basement Room G75 - Girls	Does not exist
Instance on Basement Room G79 - Boys	Does not exist
Instance on Basement Rooms: 4AL - Girls, 4BL - Boys	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X455

Question	Response
LOCKER ROOM	
Lighting	
Lighting Fixture - Fluorescent	
Pendant Mounted	
Deficiency Quantity	78
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Surface Mounted	
Instance on Basement Room 2L - Girls	Does not exist
Instance on Basement Room G75 - Girls	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	10
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance on Basement Room G79 - Boys	Does not exist
Instance on Basement Rooms: 4AL - Girls, 4BL - Boys	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	33
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Recessed Mounted	
Instance on Basement Room 2L - Girls	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance on Basement Room G75 - Girls	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance on Basement Room G79 - Boys	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	12
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X455

Question	Response
LOCKER ROOM	
Lighting	
Lighting Fixture - Fluorescent	
Recessed Mounted	
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance on Basement Rooms: 4AL - Girls, 4BL - Boys	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	42
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Lighting Fixture - HID	
Instance on Basement Room 2L - Girls	Does not exist
Instance on Basement Room G75 - Girls	Does not exist
Instance on Basement Room G79 - Boys	Does not exist
Instance on Basement Rooms: 4AL - Girls, 4BL - Boys	Does not exist
Lighting Fixture - Incandescent	
Instance on Basement Room 2L - Girls	Does not exist
Instance on Basement Room G75 - Girls	Inspected
Instance on Basement Room G79 - Boys	Inspected
Instance on Basement Rooms: 4AL - Girls, 4BL - Boys	Does not exist
Pendant Mounted	
Instance on Basement Room G75 - Girls	Does not exist
Instance on Basement Room G79 - Boys	Does not exist
Surface Mounted	
Instance on Basement Room G75 - Girls	Does not exist
Instance on Basement Room G79 - Boys	Does not exist
Recessed Mounted	
Instance on Basement Room G75 - Girls	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance on Basement Room G79 - Boys	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Lighting Fixture - LED	
Instance on Basement Room 2L - Girls	Does not exist
Instance on Basement Room G75 - Girls	Does not exist
Instance on Basement Room G79 - Boys	Does not exist

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X455

Question	Response
LOCKER ROOM	
Lighting	
Lighting Fixture - LED	
Instance on Basement Rooms: 4AL - Girls, 4BL - Boys	Does not exist
MULTIPURPOSE ROOM	
	Does not exist
SCIENCE DEMO ROOM	
Instance on Room 309	Inspected
Power Panel?	No
Alternative Use	Yes
Instance on Room 409	Inspected
Power Panel?	No
Alternative Use	Yes
Instance on Room 608	Inspected
Power Panel?	No
Alternative Use	No
Instance on Room 609	Inspected
Power Panel?	No
Alternative Use	Yes
Instance on Rooms: 610, 708, 709, 710	Inspected
Power Panel?	No
Alternative Use	No
Lighting	
Instance on Room 309	Inspected
Instance on Room 409	Inspected
Instance on Room 608	Inspected
Instance on Room 609	Inspected
Instance on Rooms: 610, 708, 709, 710	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 309	Inspected
Instance on Room 409	Inspected
Instance on Room 608	Inspected
Instance on Room 609	Inspected
Instance on Rooms: 610, 708, 709, 710	Inspected
Pendant Mounted	
Instance on Room 309	Does not exist
Instance on Room 409	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	8
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance on Room 608	Does not exist
Instance on Room 609	Does not exist
Instance on Rooms: 610, 708, 709, 710	Does not exist
Surface Mounted	
Instance on Room 309	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	25
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X455

Question	Response
SCIENCE DEMO ROOM	
Lighting	
Lighting Fixture - Fluorescent	
Surface Mounted	
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance on Room 409	Does not exist
Instance on Room 608	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	25
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance on Room 609	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	25
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance on Rooms: 610, 708, 709, 710	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	100
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Recessed Mounted	
Instance on Room 309	Does not exist
Instance on Room 409	Does not exist
Instance on Room 608	Does not exist
Instance on Room 609	Does not exist
Instance on Rooms: 610, 708, 709, 710	Does not exist
Lighting Fixture - HID	
Instance on Room 309	Does not exist
Instance on Room 409	Does not exist
Instance on Room 608	Does not exist
Instance on Room 609	Does not exist
Instance on Rooms: 610, 708, 709, 710	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 309	Does not exist
Instance on Room 409	Inspected
Instance on Room 608	Does not exist
Instance on Room 609	Inspected
Instance on Rooms: 610, 708, 709, 710	Inspected
Pendant Mounted	
Instance on Room 409	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X455

Question	Response
SCIENCE DEMO ROOM	
Lighting	
Lighting Fixture - Incandescent	
Pendant Mounted	
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance on Room 609	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance on Rooms: 610, 708, 709, 710	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	8
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Surface Mounted	
Instance on Room 409	Does not exist
Instance on Room 609	Does not exist
Instance on Rooms: 610, 708, 709, 710	Does not exist
Recessed Mounted	
Instance on Room 409	Does not exist
Instance on Room 609	Does not exist
Instance on Rooms: 610, 708, 709, 710	Does not exist
Lighting Fixture - LED	
Instance on Room 309	Does not exist
Instance on Room 409	Does not exist
Instance on Room 608	Does not exist
Instance on Room 609	Does not exist
Instance on Rooms: 610, 708, 709, 710	Does not exist
Emergency Gas Shut-Off Valve	
Instance on Room 309	Does not exist
Instance on Room 409	Does not exist
Instance on Room 608	Does not exist
Instance on Room 609	Does not exist
Instance on Rooms: 610, 708, 709, 710	Does not exist
Emergency Shut-Off Power	
Instance on Room 309	Does not exist
Instance on Room 409	Does not exist
Instance on Room 608	Does not exist
Instance on Room 609	Does not exist

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X455

Question	Response
SCIENCE DEMO ROOM	
Emergency Shut-Off Power	
Instance on Rooms: 610, 708, 709, 710	Does not exist
Power Supply	
Instance on Room 309	Does not exist
Instance on Room 409	Does not exist
Instance on Room 608	Does not exist
Instance on Room 609	Does not exist
Instance on Rooms: 610, 708, 709, 710	Does not exist
Projection System	
Instance on Room 309	Does not exist
Instance on Room 409	Does not exist
Instance on Room 608	Does not exist
Instance on Room 609	Does not exist
Instance on Rooms: 610, 708, 709, 710	Does not exist
SCIENCE LAB	Inspected
Instance on Room 604	Inspected
Power Panel?	Yes
Alternative Use	No
Instance on Room 520	Inspected
Power Panel?	Yes
Alternative Use	No
Instance on Rooms: 407, 410, 607, 707	Inspected
Power Panel?	Yes
Alternative Use	No
Instance on Rooms 404, 704	Inspected
Power Panel?	Yes
Alternative Use	No
Lighting	
Instance on Room 604	Inspected
Instance on Room 520	Inspected
Instance on Rooms: 407, 410, 607, 707	Inspected
Instance on Rooms 404, 704	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 604	Inspected
Instance on Rooms: 407, 410, 607, 707	Inspected
Instance on Rooms 404, 704	Inspected
Instance on Room 520	Inspected
Pendant Mounted	
Instance on Room 604	Does not exist
Instance on Rooms: 407, 410, 607, 707	Does not exist
Instance on Rooms 404, 704	Does not exist
Instance on Room 520	Does not exist
Surface Mounted	
Instance on Room 604	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	25
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance on Rooms: 407, 410, 607, 707	Does not exist

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X455

Question	Response
SCIENCE LAB	
Lighting	
Lighting Fixture - Fluorescent	
Surface Mounted	
Instance on Rooms 404, 704	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	50
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance on Room 520	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	20
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Recessed Mounted	
Instance on Room 604	Does not exist
Instance on Rooms: 407, 410, 607, 707	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Rooms 404, 704	Does not exist
Instance on Room 520	Does not exist
Lighting Fixture - HID	
Instance on Room 604	Does not exist
Instance on Rooms: 407, 410, 607, 707	Does not exist
Instance on Rooms 404, 704	Does not exist
Instance on Room 520	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 604	Does not exist
Instance on Rooms: 407, 410, 607, 707	Does not exist
Instance on Rooms 404, 704	Inspected
Instance on Room 520	Does not exist
Pendant Mounted	
Instance on Rooms 404, 704	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Surface Mounted	
Instance on Rooms 404, 704	Does not exist
Recessed Mounted	
Instance on Rooms 404, 704	Does not exist
Lighting Fixture - LED	
Instance on Room 604	Does not exist

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X455

Question	Response
SCIENCE LAB	
Lighting	
Lighting Fixture - LED	
Instance on Rooms: 407, 410, 607, 707	Does not exist
Instance on Rooms 404, 704	Does not exist
Instance on Room 520	Does not exist
Emergency Gas Shut-Off Valve	
Instance on Room 604	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 520	Does not exist
Instance on Rooms: 407, 410, 607, 707	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Rooms 404, 704	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Emergency Shut-Off Power	
Instance on Room 604	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 520	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Rooms: 407, 410, 607, 707	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Rooms 404, 704	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Power Supply	
Instance on Room 604	Does not exist
Instance on Room 520	Does not exist
Instance on Rooms: 407, 410, 607, 707	Inspected
Instance on Rooms 404, 704	Does not exist
Instructor Unit	
Instance on Rooms: 407, 410, 607, 707	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Meter Demonstration Unit	
Instance on Rooms: 407, 410, 607, 707	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Student Unit	
Instance on Rooms: 407, 410, 607, 707	Does not exist
Projection System	
Instance on Room 604	Does not exist
Instance on Room 520	Does not exist
Instance on Rooms: 407, 410, 607, 707	Does not exist
Instance on Rooms 404, 704	Does not exist
SCIENCE PREP ROOM	
	Inspected
Instance on Room 606	Inspected
Power Panel?	No

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X455

Question	Response
SCIENCE PREP ROOM	
Alternative Use	No
Instance on Room 408	Inspected
Power Panel?	Yes
Alternative Use	No
Lighting	
Instance on Room 606	Inspected
Instance on Room 408	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 408	Inspected
Instance on Room 606	Inspected
Pendant Mounted	
Instance on Room 408	Does not exist
Instance on Room 606	Does not exist
Surface Mounted	
Instance on Room 408	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 606	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	23
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Recessed Mounted	
Instance on Room 408	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 606	Does not exist
Lighting Fixture - HID	
Instance on Room 408	Does not exist
Instance on Room 606	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 408	Does not exist
Instance on Room 606	Inspected
Pendant Mounted	
Instance on Room 606	Does not exist
Surface Mounted	
Instance on Room 606	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Recessed Mounted	
Instance on Room 606	Does not exist
Lighting Fixture - LED	
Instance on Room 408	Does not exist

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X455

Question	Response
SCIENCE PREP ROOM	
Lighting	
Lighting Fixture - LED	
Instance on Room 606	Does not exist
Emergency Gas Shut-Off Valve	
Instance on Room 606	Does not exist
Instance on Room 408	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Emergency Shut-Off Power	
Instance on Room 606	Does not exist
Instance on Room 408	Does not exist
Power Supply	
Instance on Room 606	Does not exist
Instance on Room 408	Does not exist
SWIMMING POOL	
	Inspected
Instance on Basement - Training	Under construction
Instance on Basement - Competition	Under construction
TOILET ROOM - STAFF	
	Inspected
Lighting	
	Inspected
Lighting Fixture - Fluorescent	
Pendant Mounted	
	Does not exist
Surface Mounted	
Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	8
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Recessed Mounted	
	Inspected
Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	28
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Lighting Fixture - HID	
	Does not exist
Lighting Fixture - Incandescent	
	Does not exist
Lighting Fixture - LED	
	Does not exist
TOILET ROOM - STUDENT	
	Inspected
Lighting	
	Inspected
Lighting Fixture - Fluorescent	
Pendant Mounted	
	Does not exist
Surface Mounted	
Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	22
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X455

Question	Response
TOILET ROOM - STUDENT	
Lighting	
Lighting Fixture - Fluorescent	
Surface Mounted	
Violations	No violations recorded
Recessed Mounted	Inspected
Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	98
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
Condition	3- Fair
Deficiency	BELL NOT OPERATIONAL
Deficiency Location/Instance	Throughout the Building
Deficiency Quantity	7
Quantity Uom	EACH
Potential Action	REPLACE BELL
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
EMERGENCY DC STANDBY BATTERY POWER	Does not exist
EMERGENCY GENERATOR SET	Inspected
Automatic Transfer Switch (ATS)	Inspected
Instance	Main Electrical Room CB01
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	ASCO
EquipmentId	Emg. Elevator Trans SW.CAR 1 2 6
Capacity/Size Quantity	300
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1973
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Main Electrical Room CB01
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Main Electrical Room CB01
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	ASCO
EquipmentId	Emg. Elevator Trans SW. CAR 3 4 5

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X455

Question	Response
EMERGENCY GENERATOR SET	
Automatic Transfer Switch (ATS)	
Capacity/Size Quantity	400
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1973
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Main Electrical Room CB01
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Main Electrical Room CB01
Instance Condition	5- Poor
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	ASCO
EquipmentId	Emg. Power Trans SW. B Service
Capacity/Size Quantity	300
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1973
Source of Installation Year	Documented
Deficiency	ATS NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
Instance	Main Electrical Room CB01
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	ASCO
EquipmentId	Emg. Power Trans. SW. A Service
Capacity/Size Quantity	300
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1973
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Main Electrical Room CB01
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Main Electrical Room CB01
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X455

Question	Response
EMERGENCY GENERATOR SET	
Automatic Transfer Switch (ATS)	
Manufacturer	ASCO
EquipmentId	Fire Alarm Automatic Transfer Switch
Capacity/Size Quantity	100
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2002
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Battery Charger	Inspected
Instance	Room CB56
Instance Condition	2- Between Good and Fair
Instance Quantity	2
Instance Quantity Uom	EACH
Manufacturer	SENS
EquipmentId	Battery Charger
Capacity/Size Quantity	10
Capacity/Size UOM	AmpsDC
Capacity/Size 2 Quantity	24
Capacity/Size 2 UOM	VDC
Source of Capacity/Size	Nameplate
Installation Year	2013
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Emergency Distribution Board	Inspected
Number of Spares	4
Fused Disconnect Switch Type	Does not exist
Molded Case Circuit Breaker Type	Inspected
Instance	Main Electrical Room CB01
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Federal Pacific Electric
EquipmentId	Emg. Main Fist. PNL. A
Capacity/Size Quantity	400
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	3
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Nameplate
Installation Year	1973
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Main Electrical Room CB01
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Main Electrical Room CB01
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Federal Pacific Electric
EquipmentId	Emg. Main Dist. PNL. B HV
Capacity/Size Quantity	400

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X455

Question	Response
EMERGENCY GENERATOR SET	
Emergency Distribution Board	
Molded Case Circuit Breaker Type	
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	2
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Nameplate
Installation Year	1973
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Main Electrical Room CB01
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Diesel	Inspected
Instance	Room CB56
Instance Condition	3- Fair
Instance Quantity	2
Instance Quantity Uom	EACH
Manufacturer	Cummins Onan
EquipmentId	Service A, Service B
Capacity/Size Quantity	500
Capacity/Size UOM	kVA
Capacity/Size 2 Quantity	400
Capacity/Size 2 UOM	kW
Capacity/Size 3 Quantity	600
Capacity/Size 3 UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1973
Source of Installation Year	Documented
Deficiency	DEFECTIVE ENGINE LUBRICATION SYSTEM
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Room CB56
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Natural Gas	Does not exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	
Condition	3- Fair
Deficiency	No deficiencies recorded
EMERGENCY LIGHTING	
Condition	Inspected
Battery Pack	
Condition	3- Fair
Deficiency	BATTERY NOT OPERATIONAL
Deficiency Location/Instance	Throughout the Building

NYC Department of Education
Building Condition Assessment Survey 2023-2024

Electrical Inspection

X455

Question	Response
EMERGENCY LIGHTING	
Battery Pack	
Deficiency Quantity	21
Quantity Uom	EACH
Potential Action	REPLACE BATTERY
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 4
Violations	35655002Z
Non Battery Pack	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
EXIT LIGHT	
Inspected	
Battery Pack	
Inspected	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Non Battery Pack	
Inspected	
Condition	3- Fair
Deficiency	FIXTURE LAMP NOT OPERATIONAL
Deficiency Location/Instance	Gymnasium 4A/B, Locker Room 2L, Planetarium
Deficiency Quantity	5
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 4
Violations	E511685
EXIT/EMERGENCY LIGHT	
Inspected	
Condition	3- Fair
Deficiency	No deficiencies recorded
FIRE ALARM SYSTEM	
Inspected	
Bell/Horn	
Inspected	
Condition	1- Good
Deficiency	No deficiencies recorded
Strobe	
Inspected	
Condition	1- Good
Deficiency	No deficiencies recorded
Manual Pull Station	
Inspected	
Condition	1- Good
Deficiency	No deficiencies recorded
Fan Shutdown Control	
Inspected	
Condition	1- Good
Deficiency	No deficiencies recorded
Duct Smoke Detector	
Inspected	
Condition	1- Good
Deficiency	No deficiencies recorded
Area Smoke Detector	
Inspected	
Condition	1- Good
Deficiency	No deficiencies recorded
CO Detector	
Inspected	
Condition	1- Good
Deficiency	No deficiencies recorded
Heat Detector	
Inspected	
Condition	1- Good
Deficiency	No deficiencies recorded
Elevator Recall	
Inspected	
Condition	1- Good

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X455

Question	Response
FIRE ALARM SYSTEM	
Elevator Recall	
Deficiency	No deficiencies recorded
Magnetic Door Holder/Contactor	Does not exist
Fused Cutout Panel	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Fire Alarm Digital Communicator	Does not exist
Main Panel	Inspected
Bell At Panel	Does not exist
Fire Alarm Control Panel (Electronic)	Inspected
Instance	Vestibule by Exit 7
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Edwards System Technology
Model	EST 3
EquipmentId	Fire Command Center
Installation Year	2019
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Standard)	Does not exist
Sub-Panel	Inspected
Bell At Panel	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Electronic)	Inspected
Instance	Auditorium
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Edwards System Technology
Model	EST3X
EquipmentId	EVAC Panel
Installation Year	2019
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Auditorium
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	System Sensor
Model	PDRP-2001
EquipmentId	Deluge Panel
Installation Year	2019
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Standard)	Does not exist
Remote Annunciator	Inspected
Display Monitor	Does not exist
Panel	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Printer	Inspected
Condition	1- Good

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X455

Question	Response
FIRE ALARM SYSTEM	
Remote Annunciator	
Printer	
Deficiency	No deficiencies recorded
Punch Register	Does not exist
Sprinkler Flow/Air Pressure Switch	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Tamper Flow Switch/Chain	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
GROUNDING SYSTEM	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
INTERCOM SYSTEM	Inspected
Elevator	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Holding Area	Does not exist
LAN	Inspected
Local Distribution Frame (L/DF)	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	Does not exist
MOTOR CONTROLLER	Inspected
MOTOR CONTROL CENTER	Inspected
Instance	Penthouse 1 - North
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Cutler Hammer
EquipmentId	MB-7E
Capacity/Size Quantity	200
Capacity/Size UOM	Amps
Capacity/Size 2 Quantity	1
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Inspector Estimate
Installation Year	1973
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Penthouse 1 - North
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Penthouse 1 - South
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Cutler Hammer

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X455

Question	Response
MOTOR CONTROLLER	
MOTOR CONTROL CENTER	
EquipmentId	MB-6E
Capacity/Size Quantity	200
Capacity/Size UOM	Amps
Capacity/Size 2 Quantity	1
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Inspector Estimate
Installation Year	1973
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Penthouse 1 - South
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Penthouse Mechanical Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Cutler Hammer
EquipmentId	MB-8E
Capacity/Size Quantity	200
Capacity/Size UOM	Amps
Capacity/Size 2 Quantity	1
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Inspector Estimate
Installation Year	1973
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Penthouse Mechanical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Pool Mechanical Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Cutler Hammer
EquipmentId	MB-4E
Capacity/Size Quantity	200
Capacity/Size UOM	Amps
Capacity/Size 2 Quantity	1
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Nameplate
Installation Year	1973
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Pool Mechanical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X455

Question	Response
MOTOR CONTROLLER	
MOTOR CONTROL CENTER	
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Room CB06
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Cutler Hammer
EquipmentId	MB-3E
Capacity/Size Quantity	200
Capacity/Size UOM	Amps
Capacity/Size 2 Quantity	1
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Nameplate
Installation Year	1973
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Room CB06
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Room CB34
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Cutler Hammer
EquipmentId	MB-2E
Capacity/Size Quantity	200
Capacity/Size UOM	Amps
Capacity/Size 2 Quantity	1
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Inspector Estimate
Installation Year	1973
Source of Installation Year	Inspector Estimate
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Room CB34
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Room CB52
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Cutler Hammer
EquipmentId	N/A
Capacity/Size Quantity	600
Capacity/Size UOM	Amps
Capacity/Size 2 Quantity	3

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X455

Question	Response
MOTOR CONTROLLER	
MOTOR CONTROL CENTER	
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Inspector Estimate
Installation Year	1973
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Room CB52
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
MOTOR STARTER/CONTACTOR	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Variable Frequency Drive	Inspected
Condition	5- Poor
Deficiency	Variable Frequency Drive Not Operational
Deficiency Location/Instance	Swimming Pool Mechanical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Main Electrical Room CB01
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Fused Knife Switch Type	Does not exist
Fused Toggle Switch Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Main Electrical Room CB01
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Molded Case Circuit Breaker Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Throughout Building
Deficiency Quantity	110
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE

NYC Department of Education
Building Condition Assessment Survey 2023-2024

Electrical Inspection

X455

Question	Response
PANEL BOARD	
Molded Case Circuit Breaker Type	
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
PUBLIC ADDRESS SYSTEM	
	Inspected
Instance	Room Inside Room 103C
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Telecor II
Installation Year	2000
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
SECURITY	
	Inspected
IPDVS/CCTV System	
	Inspected
Condition	2- Between Good and Fair
Installation Year	2019
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Intrusion Alarm System	
	Inspected
Central Control Panel	
	Inspected
Instance	Room CB44E
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista 128BPT
Installation Year	2014
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Infrared Sensor	
	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Panic Switch	
	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Remote Annunciator	
	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Siren/Strobe	
	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting - Security	
	Under construction
SERVICE SWITCH	
	Does not exist
SWITCHBOARD	
	Inspected
Number of Spares	1
Fused Disconnect Switch Type	
	Inspected
Instance	Main Electrical Room CB01
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Federal Pacific Electric
EquipmentId	N/A
Capacity/Size Quantity	4000

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X455

Question	Response
SWITCHBOARD	
Fused Disconnect Switch Type	
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	6
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Switchboard Mains Size
Installation Year	1973
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Main Electrical Room CB01
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Main Electrical Room CB01
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Federal Pacific Electric
EquipmentId	N/A
Capacity/Size Quantity	3000
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	4
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Nameplate
Installation Year	1973
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Main Electrical Room CB01
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Main Electrical Room CB01
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Federal Pacific Electric
EquipmentId	N/A
Capacity/Size Quantity	5000
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	5
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Switchboard Mains Size
Installation Year	1973
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Main Electrical Room CB01
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X455

Question	Response
SWITCHBOARD	
Fused Disconnect Switch Type	
Violations	No violations recorded
Instance	Main Electrical Room CB01
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Federal Pacific Electric
EquipmentId	N/A
Capacity/Size Quantity	3000
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	4
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Switchboard Mains Size
Installation Year	1973
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Main Electrical Room CB01
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Fused Knife Switch Type	Does not exist
Molded Case Circuit Breaker Type	Does not exist
TELEPHONE SYSTEM	
	Inspected
PBX/Intercom	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Standard	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
TRANSFORMER	
	Inspected
Instance	Room C109
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Federal Pacific
EquipmentId	N/A
Capacity/Size Quantity	500
Capacity/Size UOM	kVA
Source of Capacity/Size	Nameplate
Installation Year	1973
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Room C109
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Room C141
Instance Condition	2- Between Good and Fair
Instance Quantity	1

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X455

Question	Response
TRANSFORMER	
Instance Quantity Uom	EACH
Manufacturer	Hammond
EquipmentId	N/A
Capacity/Size Quantity	75
Capacity/Size UOM	kVA
Source of Capacity/Size	Nameplate
Installation Year	2008
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Room C509
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Federal Pacific
EquipmentId	N/A
Capacity/Size Quantity	300
Capacity/Size UOM	kVA
Source of Capacity/Size	Nameplate
Installation Year	1973
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Room C509
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	C537
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Federal Pacific
EquipmentId	N/A
Capacity/Size Quantity	500
Capacity/Size UOM	kVA
Source of Capacity/Size	Nameplate
Installation Year	1973
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	C537
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	CB01
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	MGM Transformer Company
EquipmentId	Fire Alarm Transformer
Capacity/Size Quantity	30
Capacity/Size UOM	kVA

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X455

Question	Response
TRANSFORMER	
Source of Capacity/Size	Nameplate
Installation Year	2003
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Room CB01
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	ACME
EquipmentId	N/A
Capacity/Size Quantity	113
Capacity/Size UOM	kVA
Source of Capacity/Size	Nameplate
Installation Year	1995
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Room CB01, Gymnasium 1BS, Penthouse 1 - North, Penthouse 1 - South, Penthouse Mechanical Room
Instance Condition	3- Fair
Instance Quantity	5
Instance Quantity Uom	EACH
Manufacturer	Federal Pacific
EquipmentId	N/A
Capacity/Size Quantity	45
Capacity/Size UOM	kVA
Source of Capacity/Size	Nameplate
Installation Year	1973
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Room CB01, Gymnasium 1BS, Penthouse 1 - North, Penthouse 1 - South, Penthouse Mechanical Room
Deficiency Quantity	5
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Room CB05A
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Federal Pacific
EquipmentId	N/A
Capacity/Size Quantity	225
Capacity/Size UOM	kVA
Source of Capacity/Size	Nameplate
Installation Year	1973
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Room CB05A
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X455

Question	Response
TRANSFORMER	
Violations	No violations recorded
Instance	Room CB37A
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Sylvania
EquipmentId	N/A
Capacity/Size Quantity	30
Capacity/Size UOM	kVA
Source of Capacity/Size	Nameplate
Installation Year	1995
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Rooms: C141, C251
Instance Condition	3- Fair
Instance Quantity	2
Instance Quantity Uom	EACH
Manufacturer	Federal Pacific
EquipmentId	N/A
Capacity/Size Quantity	150
Capacity/Size UOM	kVA
Source of Capacity/Size	Nameplate
Installation Year	1973
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Rooms: C141, C251
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Rooms: C217, C409, C609, C709, Swimming Pool Mechanical Room
Instance Condition	3- Fair
Instance Quantity	5
Instance Quantity Uom	EACH
Manufacturer	Federal Pacific
EquipmentId	N/A
Capacity/Size Quantity	75
Capacity/Size UOM	kVA
Source of Capacity/Size	Nameplate
Installation Year	1973
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Rooms: C217, C409, C609, C709, Swimming Pool Mechanical Room
Deficiency Quantity	5
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Rooms: CB01, CB33, CB37A, C103, C309, C337, C437, C637, C737

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X455

Question	Response
TRANSFORMER	
Instance Condition	3- Fair
Instance Quantity	10
Instance Quantity Uom	EACH
Manufacturer	Federal Pacific
EquipmentId	N/A
Capacity/Size Quantity	113
Capacity/Size UOM	kVA
Source of Capacity/Size	Nameplate
Installation Year	1973
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Rooms: CB01, CB33, CB37A, C103, C309, C337, C437, C637, C737
Deficiency Quantity	10
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Rooms: CB01, CB44D, C137, CB52
Instance Condition	3- Fair
Instance Quantity	4
Instance Quantity Uom	EACH
Manufacturer	Federal Pacific
EquipmentId	N/A
Capacity/Size Quantity	30
Capacity/Size UOM	kVA
Source of Capacity/Size	Nameplate
Installation Year	1973
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Rooms: CB01, CB44D, C137, CB52
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Swimming Pool Mechanical Room
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Rex Power Magnetics
EquipmentId	N/A
Capacity/Size Quantity	30
Capacity/Size UOM	kVA
Source of Capacity/Size	Nameplate
Installation Year	2011
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Room CB07
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Siemens

NYC Department of Education
Building Condition Assessment Survey 2023-2024

Electrical Inspection

X455

Question	Response
TRANSFORMER	
EquipmentId	N/A
Capacity/Size Quantity	113
Capacity/Size UOM	kVA
Source of Capacity/Size	Nameplate
Installation Year	2023
Source of Installation Year	Documented
Deficiency	No deficiencies recorded