### **Building Condition Assessment Survey 2023-2024**

Electrical Ins	pection						X49
Asset:	DISTRICT 12 NY, 10459	PRE-K CENTER @ 122	22 PROSPECT AVEN	IUE - BRONX, 1	222 PROSPE	CT AVENUE	, BRONX,
Inspection Id	d Inspection Type				Time 1	<b>I</b> n	Last Edited
461	17 ELECTRICAL				2024-	04-09 12:33PM	2024-04-09 11:26PM
Asset Data							
Question				Answer			
Have any Sys	stems/Major Building	g Components been upgrade	d?	Systems:	All Other Elec	trical Systems a	and Components
, ,	,			Years:	2020		
				Systems:	Service Switch	h	
				Years:	2011		
Type of Serv	rice			Below Gr	ound		
	tive Whiteboard (IW)			Yes			
	ration In Electrical Ro			No			
	ED INTERCOMS	IN FIRE RESCUE ARI	EAS				
Question Are there a	nny Life Rescue Assis	stance Areas, Fire Rescue Ar	eas, and/or Holding Room		Response No		
your buildi	ing?	James Treas, The Research	cus, and of Holding Root				
Priority Cond	lition riority	Condition	Component	Location	Person(s)	Person(s)	Photo
	Category	Description	Affected	Description	Notified	Title	Image
No condition	recorded						
Inspection							
Question				Response			
Electrical							
ATHLETI	IC FIELD			Does not o	exist		
AUDITOR	RIUM			Does not o	exist		
CAFETE	RIA			Does not o	exist		
CLASSRO	OOM/CORRIDOR/A	ADMINISTRATIVE SPAC	E	Inspected			
Lighting				Inspected			
Does a Chandelier Exist?				Yes			
	ng Fixture - Fluores	cent		Does not o			
	ng Fixture - HID			Does not o			
	ng Fixture - Incande	escent		Does not o	exist		
· · · · · · · · · · · · · · · · · · ·	ng Fixture - LED			Inspected			
Pendant Mounted				Inspected 1- Good			
	ndition Deficiency				encies recorded		
	ace Mounted			Does not o			
-	ssed Mounted			Inspected			
	ndition			1- Good			
	Deficiency			No deficie	encies recorded		
COMPUT	ER LAB			Does not o	exist		
GYMNASIUM				Does not o	exist		
KITCHEN			Inspected				
Instance on Room 103				Inspected			
Lighting							
Instance on Room 103				Inspected			
Lighting Fixture - Fluorescent				Da	wist		
Instance on Room 103				Does not o	EXIST		
Lighting Fixture - HID  Instance on Room 103				Does not o	exist		
	ng Fixture - Incande			2003 1101			
	Instance on Room 10			Does not o	exist		
Lightin	ng Fixture - LED						

### **Building Condition Assessment Survey 2023-2024**

Question  KITCHEN	Response	
KITCHEN		
Lighting		
Lighting Fixture - LED	T	
Instance on Room 103	Inspected	
Pendant Mounted		
Instance on Room 103	Does not exist	
Surface Mounted		
Instance on Room 103	Does not exist	
Recessed Mounted		
Instance on Room 103	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
LIBRARY	Does not exist	
LOCKER ROOM	Does not exist	
MULTIPURPOSE ROOM	Inspected	
Instance on Room 112	Inspected	
Lighting		
Instance on Room 112	Inspected	
Lighting Fixture - Fluorescent		
Instance on Room 112	Does not exist	
Lighting Fixture - HID		
Instance on Room 112	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 112	Does not exist	
Lighting Fixture - LED		
Instance on Room 112	Inspected	
Pendant Mounted	1	
Instance on Room 112	Does not exist	
Surface Mounted		
Instance on Room 112	Does not exist	
Recessed Mounted		
Instance on Room 112	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
Local Sound System	140 deficiences recorded	
Instance on Room 112	Inspected	
Instance Condition	2- Between Good and Fair	
Installation Year	2020	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Projection System		
Instance on Room 112	Does not exist	
Theater Lighting System		
Instance on Room 112	Does not exist	
SCIENCE DEMO ROOM	Does not exist	
SCIENCE LAB	Does not exist	
	Does not exist	
SCIENCE PREP ROOM		
SWIMMING POOL	Does not exist	
TOILET ROOM - STAFF	Inspected	
Lighting	Inspected	
Lighting Fixture - Fluorescent	Does not exist	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	

### **Building Condition Assessment Survey 2023-2024**

iricai Inspection		A493
Question	Response	
TOILET ROOM - STAFF		
Lighting		
Lighting Fixture - LED	Inspected	
Pendant Mounted	Does not exist	
Surface Mounted	Does not exist	
Recessed Mounted	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
TOILET ROOM - STUDENT	Inspected	
Lighting	Inspected	
Lighting Fixture - Fluorescent	Does not exist	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Inspected	
Pendant Mounted	Does not exist	
Surface Mounted	Does not exist	
Recessed Mounted	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
	Inspected	
AUXILIARY SIGNAL/BELL SYSTEM Condition	1- Good	
	No deficiencies recorded	
Deficiency		
EMERGENCY DC STANDBY BATTERY POWER	Does not exist	
EMERGENCY GENERATOR SET	Does not exist	
EMERGENCY LIGHT/EXIT LIGHT PANEL	Does not exist	
EMERGENCY LIGHTING	Inspected	
Battery Pack	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Non Battery Pack	Does not exist	
EXIT LIGHT	Inspected	
Battery Pack	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Non Battery Pack	Does not exist	
EXIT/EMERGENCY LIGHT	Does not exist	
FIRE ALARM SYSTEM	Inspected	
Bell/Horn	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Strobe	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Manual Pull Station	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Fan Shutdown Control	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Duct Smoke Detector	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
	Inspected	
Area Smoke Detector	шъресиси	

### **Building Condition Assessment Survey 2023-2024**

iricai inspection		A493
Question	Response	
FIRE ALARM SYSTEM		
Area Smoke Detector		
Condition	1- Good	
Deficiency	No deficiencies recorded	
CO Detector	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Heat Detector	Does not exist	
Elevator Recall	Does not exist	
Magnetic Door Holder/Contactor	Does not exist	
Fused Cutout Panel	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Fire Alarm Digital Communicator	Does not exist	
Main Panel	Inspected	
Bell At Panel	Does not exist	
Fire Alarm Control Panel (Electronic)	Inspected	
Instance	Main Entrance Lobby	
Instance Condition	1- Good	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Mircom	
Model	FX - 2000	
EquipmentId	Fire Alarm Control Panel	
Installation Year	2020	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Standard)	Does not exist	
Sub-Panel Sub-Panel	Does not exist	
Remote Annunciator	Inspected	
Display Monitor	Does not exist	
Panel	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Printer	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Punch Register	Does not exist	
Sprinkler Flow/Air Pressure Switch	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Tamper Flow Switch/Chain	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
GROUNDING SYSTEM	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
INTERCOM SYSTEM	Does not exist	
	Inspected	
Lan Land Distribution Evano (I/I DE)	Does not exist	
Local Distribution Frame (I/LDF)  Main Equipment Book (MDF)	Inspected	
Main Equipment Rack (MDF)  Condition	1- Good	
Deficiency	No deficiencies recorded	
LIGHTNING PROTECTION	Does not exist	

### **Building Condition Assessment Survey 2023-2024**

Λ4:
Response
Inspected
Does not exist
Inspected
1- Good
No deficiencies recorded
Inspected
1- Good
No deficiencies recorded
Inspected
Does not exist
Does not exist
Does not exist
Inspected
1- Good
No deficiencies recorded
Inspected
Telecom Room 123
1- Good
1
EACH
Bogen HTA250A
2020
Documented
No deficiencies recorded
Inspected
Inspected
1- Good
2020
Documented
CAMERA NOT OPERATIONAL
Back of the Building
1
EACH
REPLACE
PRIORITY 4
LEVEL 3
No violations recorded
Inspected
Inspected
Custodian's Office - Room 100
1- Good
1
EACH
Vista 128BPT
2020
Documented
No deficiencies recorded
Inspected
1- Good
No deficiencies recorded
Inspected
1- Good
No deficiencies recorded

### **Building Condition Assessment Survey 2023-2024**

Electrical Inspection	X493
-----------------------	------

uestion	Response
SECURITY	
Intrusion Alarm System	
Remote Annunciator	
Condition	1- Good
Deficiency	No deficiencies recorded
Siren/Strobe	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Lighting - Security	Inspected
Condition	1- Good
Deficiency	TIME CLOCK NOT OPERATIONAL
Deficiency Location/Instance	Electrical Room 122
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 3
Violations	No violations recorded
SERVICE SWITCH	Inspected
Instance	Basement - Electrical Room
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Siemens
EquipmentId	Store Service Switch #3
Capacity/Size Quantity	600
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2011
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
SWITCHBOARD	Inspected
Number of Spares	8
Fused Disconnect Switch Type	Does not exist
Fused Knife Switch Type	Does not exist
Molded Case Circuit Breaker Type	Inspected
Instance	Electrical Room 122
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Electrotech
EquipmentId	DP-A Panel
Capacity/Size Quantity	600
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	1
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Nameplate
Installation Year	2020
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
TELEPHONE SYSTEM	Inspected
PBX/Intercom	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Standard	Inspected

# **Building Condition Assessment Survey 2023-2024**

Question	Response		
TELEPHONE SYSTEM			
Standard			
Condition	1- Good		
Deficiency	No deficiencies recorded		
TRANSFORMER	Does not exist		