## **Building Condition Assessment Survey 2023-2024**

Asset: P.S. @ 268 EAST 207 STREET - BRONX, 268 EAST 207	STREET, BRONX, NY, 10467
Inspection Id Inspection Type	Time In Last Edited
2068 MECHANICAL	2024-01-02 01:28PM 2024-05-16 07:52PM
sset Data	2021 01 02 01:201111 2021 03 10 07:321111
Question	Answer
Have any Systems/Major Building Components been upgraded?	No System Upgraded
Are there fuel tanks?	No
Total # of water main service entries to the asset	1
MERs/Fan Rooms Locations	Cafeteria MER, Cafeteria Fan Room, Gymnasium MER
Are there any spaces with Missing or Defective CO Detectors?	No
Are there any Painted/Obstructed Sprinkler Heads?	No
Are there any Emergency Stop Switches with Missing Hammers?	No components
riority Condition	A
Exist Priority Condition Component	Location Person(s) Person(s) Photo
Last Year? Category Description Affected	Description Notified Title Image
No condition recorded	
Inspection	
Question	Response
Mechanical	Кезрине
AIR CONDITIONING	Inspected
	Does not exist
Chilled Water System	Does not exist  Does not exist
Condenser Water Distribution: Piping, Pumps and Auxiliaries Cooling Coil in Ductwork	Does not exist
Cooling Tower	Does not exist
DX Split System	Inspected
Indoor Unit	Inspected
Condition	1- Good
Deficiency	OVER 5 TONS:NOT IN USE
Deficiency Location/Instance	Cafeteria MER, Gymnasium MER (2 of 12)
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	NO ACTION
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 1
Violations	No violations recorded
Outdoor Unit	Inspected
Condition	1- Good
Deficiency	OVER 5 TONS:NOT IN USE
Deficiency Location/Instance	Lower Roof (2 of 12)
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	NO ACTION
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 1
Violations	No violations recorded
Dry Cooler	Does not exist
Packaged / Rooftop Unit	Does not exist
Packaged Terminal A/C	Does not exist
Refrigerant Leak Detection System	Does not exist
Refrigerant Piping	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Return Fan	Does not exist
CENTRAL ACID WASTE NEUTRALIZING TANK	Does not exist

## **Building Condition Assessment Survey 2023-2024**

Mechanical Inspection	X780
	X/8

chanical Inspection	Λ/00
Question	Response
COMPACTOR	Does not exist
CONVEYING	Does not exist
DOMESTIC WATER SYSTEM	Inspected
Domestic Cold Water System	Inspected
Gravity System	Does not exist
Pressure Booster System	Does not exist
Water Service	Inspected
Instance	Cafeteria
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Deficiency	WATER MAIN: MISSING BACKFLOW PREVENTION DEVICE
Deficiency Location/Instance Deficiency Quantity	Cafeteria 1
Quantity Uom	EACH
Potential Action	INSTALL
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Domestic Hot Water System	Inspected
Domestic Hot Water Remote Storage Tank	Does not exist
Domestic Water Heat Exchanger	Does not exist
Electric Domestic Water Heater	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Gas Fired Domestic Water Heater	Does not exist
Oil Fired Domestic Water Heater	Does not exist
Heat Pump Domestic Water Heater	Does not exist
Domestic Water Distribution Piping  Condition	Inspected 3- Fair
Deficiency	No deficiencies recorded
DRAIN/WASTE/VENT AND STORM SYSTEM	Inspected
Interior Storm Piping	Inspected 3- Fair
Condition  Deficiency	No deficiencies recorded
	Inspected
Sewage/Waste/Vent Piping Condition	3- Fair
Deficiency	No deficiencies recorded
Sewage Ejector Pump	Does not exist
Sump Pump	Does not exist
DUAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)	Does not exist
FIXTURES	Inspected
Staff And Other	Inspected
Janitor Sink	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lavatory/Sink	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Toilet	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Urinal	Does not exist
Cimai	_ 000 100 0.1100

## **Building Condition Assessment Survey 2023-2024**

Mechanical Inspection X780

aunicui Inspeciion		A/00
Question	Response	
FIXTURES		
Student	Inspected	
Drinking Fountain	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Lavatory/Sink	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Locker Room Shower	Does not exist	
Sink And Fountain Combo Unit	Does not exist	
Toilet	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Urinal	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
GAS FIRED FURNACE	Does not exist	
GAS SERVICE	Inspected	
Gas Distribution Piping	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Gas Meter Room Exhaust Fan	Does not exist	
Gas Meter Room Vent	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Gas Pressure Booster	Does not exist	
CO/Gas Leak Detection	Does not exist	
HEATING	Inspected	
Heating Coil In Ductwork	Does not exist	
Hydronic Heating	Does not exist	
Radiator/Convector/Fin Tube	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Steam Heating	Inspected	
F&T/Steam Drip Trap	Does not exist	
MER Steam and Condensate Piping	Does not exist	
Steam Condensate Return Piping	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Steam Condensate Return Pumping System	Does not exist	
Steam Piping	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Terminal Unit Thermostatic Trap	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Steam supplied by External Sources	Does not exist	
Unit Heater/Cabinet Heater	Does not exist	
HEATING PLANT	Does not exist	
Enclosed IDF Room	Does not exist	
KITCHEN	Inspected	
Instance on Basement  CO Detector	Inspected	

### **Building Condition Assessment Survey 2023-2024**

Question	Response	
	Response	
KITCHEN CO Potoston		
CO Detector  Instance on Basement	Not required	
Gas System	rvot required	
Instance on Basement	Does not exist	
Grease Trap	Does not east	
Instance on Basement	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
Hood	Two deficiences recorded	
Instance on Basement	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
Hood Exhaust Ductwork	140 deficiences recorded	
Instance on Basement	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
Hood Exhaust Fan	No deficiencies recorded	
Instance on Basement	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
	No deficiencies recorded	
Hood Fire Suppression System Instance on Basement	Does not exist	
Hot Water Temperature Booster	DOES HOL CAISE	
Instance on Basement	Does not exist	
Kitchen Sink	2000 100 0.1100	
Instance on Basement	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
MDF Room	Inspected	
Instance on Room B103	Inspected	
Dedicated A/C Equipment	Inspected	
Instance on Room B103	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
SCIENCE DEMO ROOM	Does not exist	
	Does not exist	
SCIENCE LAB	Does not exist  Does not exist	
SCIENCE PREP ROOM		
SPRINKLERS, STANDPIPE, FIRE SYSTEM	Does not exist	
SWIMMING POOL	Does not exist	
VENTILATION	Inspected	
Is the building Mechanically ventilated?	Partial	
Exhaust Fan	Inspected	
Condition	1- Good	
Approximate Total # of Fans	1-25	
Deficiency	NOT IN USE	
Deficiency Location/Instance	Cafeteria Fan Room	

1

EACH

NO ACTION

PRIORITY 1

No violations recorded

Does not exist

LEVEL 1

**Deficiency Quantity** 

Quantity Uom

Potential Action

Urgency of Action

Purpose of Action

Violations

**Heating And Ventilating Unit** 

## **Building Condition Assessment Survey 2023-2024**

Mechanical Inspection X780

uestion	Response	
VENTILATION		
Metal Ductwork	Inspected	
Condition	3- Fair	
Are there any uninsulated ductwork by design in Mechanical rooms?	No	
Are there chain operated dampers?	No	
Deficiency	No deficiencies recorded	
Supply Fan	Does not exist	
Unit Ventilator	Does not exist	