Building Condition Assessment Survey 2023-2024

Electrical Inspection

Asset: P.S. 59 ANNEX - BRONX, 2120 QUARRY	KUAD, BRUNX	., 18 1, 1045 /		
Inspection Id Inspection Type			Time In	Last Edited
1746 ELECTRICAL			2023-12-18 10:58AM	2024-01-16 08:25AN
sset Data				
Question		Answer		
Have any Systems/Major Building Components been upgraded?		Systems:	LAN, Staff Toilet Room LED I	Recessed Lighting
		Years:	2022	
		Systems:		
			Molded Case Circuit Breaker P	,
			Disconnect Switch Type Panel System, Switchboard	Board, Fire Alarin
		Years:	2007	
		Systems:	Most Security Lights	
		Years:	2005	
		Systems:		
		Years:	2003	
Type of Service		Below G		
Does Interactive Whiteboard (IWB) Exist?		Yes		
Water Penetration In Electrical Room?		No		
DEDICATED INTERCOMS IN FIRE RESCUE AREAS				
Question		1	Response	
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, a	and/or Holding Room	ms in	No	
your building?				
iority Condition				
Exist Priority Condition	Component	Location	Person(s) Person(s)	Photo
ast Year? Category Description	Affected	Description	Notified Title	Image
nspection		P		
Question		Response	2	
Electrical			• .	
ATHLETIC FIELD		Does not		
AUDITORIUM		Does not		
CAFETERIA		Does not		
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE		Inspected		
Lighting		Inspected		
Does a Chandelier Exist?		No	1	
Lighting Fixture - Fluorescent		Inspected		
Pendant Mounted		Inspected 3- Fair		
Condition			· 11	
Deficiency			encies recorded	
Surface Mounted		Inspected		
Condition		3- Fair		
Deficiency			encies recorded	
Recessed Mounted		Does not		
Lighting Fixture - HID		Does not		
		Does not		
Lighting Fixture - Incandescent			exist	
Lighting Fixture - LED		Does not		
		Does not Does not	exist	
Lighting Fixture - LED				
Lighting Fixture - LED COMPUTER LAB		Does not	exist	
Lighting Fixture - LED COMPUTER LAB GYMNASIUM		Does not Does not	exist	
Lighting Fixture - LED COMPUTER LAB GYMNASIUM KITCHEN		Does not Does not Inspected	exist	
Lighting Fixture - LED COMPUTER LAB GYMNASIUM KITCHEN Instance on 1st Floor		Does not Does not Inspected	exist	

Building Condition Assessment Survey 2023-2024

Electrical Inspection

		A033
Question	Response	
KITCHEN		
Lighting		
Lighting Fixture - Fluorescent		
Instance on 1st Floor	Inspected	
Pendant Mounted		
Instance on 1st Floor	Does not exist	
Surface Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on 1st Floor	Does not exist	
Lighting Fixture - HID		
Instance on 1st Floor	Does not exist	
Lighting Fixture - Incandescent		
Instance on 1st Floor	Does not exist	
Lighting Fixture - LED		
Instance on 1st Floor	Does not exist	
LIBRARY	Does not exist	
LOCKER ROOM	Does not exist	
MULTIPURPOSE ROOM	Does not exist	
SCIENCE DEMO ROOM	Does not exist	
SCIENCE LAB	Does not exist	
SCIENCE PREP ROOM	Does not exist	
SWIMMING POOL	Does not exist	
TOILET ROOM - STAFF	Inspected	
Lighting	Inspected	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Does not exist	
Surface Mounted	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Does not exist	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Inspected	
Pendant Mounted	Does not exist	
Surface Mounted	Does not exist	
Recessed Mounted	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
TOILET ROOM - STUDENT	Inspected	
Lighting	Inspected	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Does not exist	
Surface Mounted	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Does not exist	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Does not exist	
AUXILIARY SIGNAL/BELL SYSTEM	Inspected	
	1	

Building Condition Assessment Survey 2023-2024

Electrical Inspection

		A0 3
Question	Response	
AUXILIARY SIGNAL/BELL SYSTEM		
Condition	3- Fair	
Deficiency	No deficiencies recorded	
EMERGENCY DC STANDBY BATTERY POWER	Does not exist	
EMERGENCY GENERATOR SET	Does not exist	
	Inspected	
EMERGENCY LIGHT/EXIT LIGHT PANEL Condition	2- Between Good and Fair	
	No deficiencies recorded	
Deficiency		
EMERGENCY LIGHTING	Inspected	
Battery Pack	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Non Battery Pack	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
EXIT LIGHT	Inspected	
Battery Pack	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Non Battery Pack	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
EXIT/EMERGENCY LIGHT	Does not exist	
FIRE ALARM SYSTEM	Inspected	
Bell/Horn	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Strobe	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Manual Pull Station	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Fan Shutdown Control	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Duct Smoke Detector	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Area Smoke Detector	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
CO Detector	Does not exist	
Heat Detector	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Elevator Recall	Does not exist	
Magnetic Door Holder/Contactor	Does not exist	
Magnetic Door Holder/Contactor Fused Cutout Panel	Inaccessible	
Fused Cutout Panel Fire Alarm Digital Communicator	Does not exist	
Main Panel	Inspected	
Bell At Panel	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	

Building Condition Assessment Survey 2023-2024

Electrical Inspection

Duestion	Response	A03.
	Response	
FIRE ALARM SYSTEM		
Main Panel	Inspected	
Fire Alarm Control Panel (Electronic)	-	
Instance Instance Condition	Main Entrance Lobby 2- Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Edwards System Technology	
Model	EST 2	
EquipmentId	Fire Alarm Control Panel	
Installation Year Source of Installation Year	2007 Documented	
	No deficiencies recorded	
Fire Alarm Control Panel (Standard)	Does not exist	
Sub-Panel	Does not exist	
Remote Annunciator	Inspected Does not exist	
Display Monitor		
Panel	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Printer	Inspected	
Condition	5- Poor	
Deficiency	PRINTER NOT OPERATIONAL	
Deficiency Location/Instance	Custodian's Office - Room H	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Punch Register	Does not exist	
Sprinkler Flow/Air Pressure Switch	Does not exist	
Tamper Flow Switch/Chain	Does not exist	
GROUNDING SYSTEM	Inaccessible	
INTERCOM SYSTEM	Does not exist	
	Inspected	
Local Distribution Frame (I/LDF)	Does not exist	
Main Equipment Rack (MDF)	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
LIGHTNING PROTECTION	Does not exist	
MOTOR CONTROLLER	Inspected	
MOTOR CONTROL CENTER	Does not exist	
MOTOR STARTER/CONTACTOR	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Variable Frequency Drive	Does not exist	
PANEL BOARD	Inspected	
	Inspected	
Fused Disconnect Switch Type Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Fused Knife Switch Type	Does not exist	
Fused Toggle Switch Type	Does not exist	
Molded Case Circuit Breaker Type	Inspected	

Building Condition Assessment Survey 2023-2024

Electrical Inspection

	Δ
Question	Response
PANEL BOARD	
Molded Case Circuit Breaker Type	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
PUBLIC ADDRESS SYSTEM	Does not exist
SECURITY	Inspected
IPDVS/CCTV System	Does not exist
Intrusion Alarm System	Inspected
Central Control Panel	Inspected
Instance	Custodian's Office - Room H
Instance Condition	3- Fair
Instance Quantity	1
	EACH
Instance Quantity Uom Model	
	Vista - 128B 2003
Installation Year Source of Installation Year	Documented
Deficiency	No deficiencies recorded
	Inspected
Infrared Sensor	
Condition	3- Fair
Deficiency	No deficiencies recorded
Panic Switch	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Remote Annunciator	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Siren/Strobe	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting - Security	Inaccessible
SERVICE SWITCH	Inaccessible
SWITCHBOARD	Inspected
Number of Spares	4
Fused Disconnect Switch Type	Inspected
Instance	Electrical Room E
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
	All City Switchboard
Manufacturer	MDB Section #1/#2
EquipmentId Capacity/Size Quantity	1000
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	2
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Inspector Estimate
Installation Year	2007
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not exist
Molded Case Circuit Breaker Type	Does not exist
TELEPHONE SYSTEM	Inspected
PBX/Intercom	Does not exist
Standard	Inspected
Condition	3- Fair

Building Condition Assessment Survey 2023-2024

trical Inspection		X853
Question	Response	
TELEPHONE SYSTEM		
Standard		
Deficiency	No deficiencies recorded	
TRANSFORMER	Does not exist	