Building Condition Assessment Survey 2023-2024

Electrical Ir	nspection							X92
Asset:	SOUTH BR	ONX HS TRANSPORTABLE -	BRONX, 701 S	T ANNS AVENU	JE, BRONX, I	NY, 10455		
Inspection	Id Inspection Ty	rpe			Time	In	Last Edited	
1	356 ELECTRICAL	L			2023-	-11-30 12:42PM	<i>A</i> 2023-12-18	03:51PM
Asset Data								
Question				Answer				
Have any S	Systems/Major Build	ling Components been upgraded?		Systems:	Intrusion Ala	rm System (Infra	ared Sensor)	
				Years:	2021			
				Systems:	Exit/Emergen	ncy Lights		
				Years:	2018			
				Systems:	All Other Ele	ctrical Systems	and Components	
				Years:	1997			
Type of Se				Below G	round			
	active Whiteboard (I			No				
	etration In Electrical			No				
	TED INTERCON	MS IN FIRE RESCUE AREAS			Dagmanga			
Question Are there	e any Life Rescue As	ssistance Areas, Fire Rescue Areas, an	Response and/or Holding Rooms in No					
your buil	•	and the second recast, and the second recast, and	ia of Holding 1000					
Priority Con								
	Priority	Condition	Component	Location	Person(s)	Person(s)	Photo	
	Category	Description	Affected	Description	Notified	Title	Image	
No condition	on recorded			<u> </u>				
Inspection								
				Dogwong				
Question				Response	<u> </u>			
Electrical								
ATHLETIC FIELD			Does not exist					
AUDITORIUM			Does not exist					
CAFET	ERIA		Does not exist					
CLASSI	ROOM/CORRIDO	R/ADMINISTRATIVE SPACE		Inspected				
Lighting			Inspected					
	s a Chandelier Exist?			No				
Lighting Fixture - Fluorescent			Inspected					
Pendant Mounted			Does not exist					
Surface Mounted			Inspected					
Condition				3- Fair				
Deficiency Deficiency Quantity			LIGHTING FIXTURE BEYOND USEFUL LIFE					
	· ·	mitty		60 EACH				
Quantity Uom Potential Action Urgency of Action Purpose of Action				EACH DEDLAC	E-UPGRADE			
				PRIORIT				
				LEVEL 2				
	Violations	- 			tions recorded			
Recessed Mounted Lighting Fixture - HID Lighting Fixture - Incandescent				Does not				
				Does not				
				Does not				
	ting Fixture - LED			Does not				
	g I IAGUIC - LED							

Does not exist

COMPUTER LAB

LOCKER ROOM
MULTIPURPOSE ROOM

SCIENCE DEMO ROOM

GYMNASIUM KITCHEN

LIBRARY

Building Condition Assessment Survey 2023-2024

rical Inspection	
uestion	Response
SCIENCE LAB	Does not exist
SCIENCE PREP ROOM	Does not exist
SWIMMING POOL	Does not exist
TOILET ROOM - STAFF	Does not exist
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not exist
Surface Mounted	Inspected
Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Recessed Mounted	Does not exist
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
AUXILIARY SIGNAL/BELL SYSTEM	Does not exist
EMERGENCY DC STANDBY BATTERY POWER	Does not exist
EMERGENCY GENERATOR SET	Does not exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Does not exist
EMERGENCY LIGHTING	Does not exist
EXIT LIGHT	Does not exist
EXIT/EMERGENCY LIGHT	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
FIRE ALARM SYSTEM	Inspected
Bell/Horn Condition	Inspected 3- Fair
	No deficiencies recorded
Deficiency	
Strobe Condition	Inspected 3- Fair
Deficiency	No deficiencies recorded
	Inspected
Manual Pull Station Condition	3- Fair
Deficiency	No deficiencies recorded
-	Does not exist
Fan Shutdown Control Duct Smoke Detector	Does not exist Does not exist
Area Smoke Detector	Does not exist
CO Detector	Does not exist
Heat Detector	Does not exist
Elevator Recall	Does not exist
Magnetic Door Holder/Contactor	Does not exist
Fused Cutout Panel	Inspected
Constitue	2 Enin

3- Fair

Does not exist

Inspected
Does not exist

Inspected

No deficiencies recorded

Condition

Main Panel

Bell At Panel

Deficiency

Fire Alarm Digital Communicator

Fire Alarm Control Panel (Electronic)

Building Condition Assessment Survey 2023-2024

Electrical Inspection X920

incui inspection		11)20
Question	Response	
FIRE ALARM SYSTEM	-	
Main Panel		
Fire Alarm Control Panel (Electronic)		
Instance	Room T4	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Edwards System Technology	
Model	EST	
EquipmentId	Fire Alarm Control Panel	
Installation Year	1997	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Standard)	Does not exist	
Sub-Panel	Does not exist	
Remote Annunciator	Does not exist	
Sprinkler Flow/Air Pressure Switch	Does not exist	
Tamper Flow Switch/Chain	Does not exist	
GROUNDING SYSTEM	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
INTERCOM SYSTEM	Does not exist	
LAN	Inspected	
Local Distribution Frame (I/LDF)	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Main Equipment Rack (MDF)	Does not exist	
LIGHTNING PROTECTION	Does not exist	
MOTOR CONTROLLER	Does not exist	
PANEL BOARD	Inspected	
Fused Disconnect Switch Type	Does not exist	
Fused Knife Switch Type	Does not exist	
Fused Toggle Switch Type	Does not exist	
Molded Case Circuit Breaker Type	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
PUBLIC ADDRESS SYSTEM	Inspected	
Instance	Connected to Main Asset X470	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Model	N/A	
Installation Year	1997	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
SECURITY	Inspected	
IPDVS/CCTV System	Does not exist	
Intrusion Alarm System	Inspected	
Central Control Panel	Does not exist	
Infrared Sensor	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Panic Switch	Does not exist	
Remote Annunciator	Does not exist	

Building Condition Assessment Survey 2023-2024

Electrical Inspection X920

ricai Inspection		A920
uestion	Response	
SECURITY		
Intrusion Alarm System		
Siren/Strobe	Does not exist	
Lighting - Security	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
SERVICE SWITCH	Inspected	
Instance	Outdoor Electrical Enclosure	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Siemens	
EquipmentId	Main	
Capacity/Size Quantity	400	
Capacity/Size UOM	Amps	
Source of Capacity/Size	Nameplate	
Installation Year	1997	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
SWITCHBOARD	Inspected	
	4	
Number of Spares	Does not exist	
Fused Disconnect Switch Type	Does not exist Does not exist	
Fused Knife Switch Type Molded Case Circuit Breaker Type	Inspected	
Instance	Outdoor Electrical Enclosure	
Instance Condition	3- Fair	
Instance Quantity	1 EACH	
Instance Quantity Uom		
Manufacturer	Siemens	
EquipmentId	N/A	
Capacity/Size Quantity	400	
Capacity/Size UOM	Amps Total	
Capacity/Size 2 Quantity	1	
Capacity/Size 2 UOM	Section(s)	
Source of Capacity/Size	Service Switch Size	
Installation Year	1997	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
TELEPHONE SYSTEM	Inspected	
PBX/Intercom	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Standard	Does not exist	
TRANSFORMER	Does not exist	