

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Mechanical Inspection

**K496**

**Asset:** SHEEPSHEAD BAY AF - BROOKLYN, 3000 AVENUE X, New York, 11235

Inspection Id	Inspection Type	Time In	Last Edited
ME : K496	Mechanical	2024-02-13 12:19 PM	2024-02-20 2:30 PM

Asset Data

Question	Answer
Are there fuel tanks?	No
Total # of water main service entries to the asset	0
MERs/Fan Rooms Locations	None
Are there any spaces with Missing or Defective CO Detectors?	No
Are there any Emergency Stop Switches with Missing Hammers?	No
Are there any Painted/Obstructed Sprinkler Heads?	No
Have any Systems/Major Building Components been upgraded?	No

Priority Condition

Priority Condition Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Status	PhotoImage
No condition recorded								

Inspection

Question	Response
<b>Mechanical</b>	
<b>AIR CONDITIONING</b>	Does not Exist
<b>CLIMATE CONTROL SYSTEM</b>	Does not Exist
<b>COMPACTOR</b>	Does not Exist
<b>CONVEYING</b>	Does not Exist
<b>DOMESTIC WATER SYSTEM</b>	Does not Exist
<b>DRAIN/WASTE/VENT AND STORM SYSTEM</b>	Does not Exist
<b>DUAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)</b>	Does not Exist
<b>FIXTURES</b>	Does not Exist
<b>GAS FIRED FURNACE</b>	Does not Exist
<b>GAS SERVICE</b>	Does not Exist
<b>HEATING</b>	Does not Exist
<b>HEATING PLANT</b>	Does not Exist
<b>Enclosed IDF Room</b>	Does not Exist
<b>MDF Room</b>	Does not Exist
<b>SPRINKLERS, STANDPIPE, FIRE SYSTEM</b>	Does not Exist
<b>VENTILATION</b>	Does not Exist