

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

M143

Asset: I.S. 143 - MANHATTAN, 511 WEST 182 STREET, MANHATTAN, NY, 10033

Inspection Id	Inspection Type	Time In	Last Edited
188	ELECTRICAL	2023-10-11 08:06AM	2023-12-22 09:52AM

Asset Data

Question	Answer
Have any Systems/Major Building Components been upgraded?	Systems: Auditorium (LED Lighting), IPDVS/CCTV System, Gymnasium (Projection System), Partial Service Switch Years: 2022 Systems: Auditorium (Theater Lighting System, Projection System) Years: 2021 Systems: Intrusion Alarm System Years: 2020 Systems: Security Lighting Years: 2018 Systems: Interior Lighting, Science Rooms (Except Rooms 300, 302) Years: 2016 Systems: Gymnasium (Scoreboard) Years: 2014 Systems: Telephone System, Intercom System (Elevator) Years: 2010 Systems: Molded Case Circuit Breaker Panel Board Years: 2006, 2016 Systems: Partial Fused Disconnect Switch Type Panel Board, Fire Alarm System, Local Sound System Years: 2006 Systems: Emergency Light/Exit Light Panel Years: 2003
Type of Service	Below Ground
Does Interactive Whiteboard (IWB) Exist?	Yes
Water Penetration In Electrical Room?	No

DEDICATED INTERCOMS IN FIRE RESCUE AREAS

Question	Response
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building?	Yes
Are dedicated intercoms available in all of these spaces for use during a fire?	Yes
Are all dedicated intercoms operational?	Yes

Priority Condition

Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image
------------------	-------------------	-----------------------	--------------------	----------------------	--------------------	-----------------	-------------

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

M143

No	Water Leaks onto Electrical Equipment	N/A	Electrical Junction Box, Lighting fixtures, and photovoltaic transformer for solar panels.	Music Room 139, Corridor at Room 401, Room 403 (Electrical Junction Box and Lighting fixtures respectively affected by Roof Leaks); Gymnasium Office (photovoltaic transformer for solar panels affected by Wall Leak)	Ernest Tricomi	Custodian
----	---------------------------------------	-----	--	--	----------------	-----------



Inspection

Question	Response
Electrical	
ATHLETIC FIELD	Does not exist
AUDITORIUM	Inspected
Instance on Basement	Inspected
House Lighting	
Instance on Basement	Inspected
Does a Chandelier Exist?	No
Lighting Fixture - Fluorescent	
Instance on Basement	Inspected
Pendant Mounted	
Instance on Basement	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Basement	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Basement	Does not exist
Lighting Fixture - HID	
Instance on Basement	Does not exist
Lighting Fixture - Incandescent	
Instance on Basement	Does not exist
Lighting Fixture - LED	
Instance on Basement	Inspected
Pendant Mounted	
Instance on Basement	Does not exist
Surface Mounted	
Instance on Basement	Does not exist
Recessed Mounted	
Instance on Basement	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Local Sound System	
Instance on Basement	Inspected
Instance Condition	3- Fair

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

M143

Question	Response
AUDITORIUM	
Local Sound System	
Installation Year	2006
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Projection System	
Instance on Basement	Inspected
Instance Condition	1- Good
Is the projector on a cart or installed on the ceiling?	Ceiling
Deficiency	No deficiencies recorded
Theater Lighting System	
Instance on Basement	Inspected
Dimming System	
Instance on Basement	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Theater Lighting	
Instance on Basement	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
CAFETERIA	
Instance on 1st Floor - Students	Inspected
Instance on 1st Floor - Staff	Inspected
Lighting	
Instance on 1st Floor - Students	Inspected
Instance on 1st Floor - Staff	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor - Students	Inspected
Instance on 1st Floor - Staff	Inspected
Pendant Mounted	
Instance on 1st Floor - Students	Does not exist
Instance on 1st Floor - Staff	Does not exist
Surface Mounted	
Instance on 1st Floor - Students	Does not exist
Instance on 1st Floor - Staff	Does not exist
Recessed Mounted	
Instance on 1st Floor - Students	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on 1st Floor - Staff	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on 1st Floor - Students	Does not exist
Instance on 1st Floor - Staff	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor - Students	Does not exist
Instance on 1st Floor - Staff	Does not exist
Lighting Fixture - LED	
Instance on 1st Floor - Students	Does not exist
Instance on 1st Floor - Staff	Does not exist
Local Sound System	
Instance on 1st Floor - Students	Inspected
Instance Condition	3- Fair

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

M143

Question	Response
CAFETERIA	
Local Sound System	
Installation Year	2006
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance on 1st Floor - Staff	Does not exist
Projection System	
Instance on 1st Floor - Students	Does not exist
Instance on 1st Floor - Staff	Does not exist
Theater Lighting System	
Instance on 1st Floor - Students	Does not exist
Instance on 1st Floor - Staff	Does not exist
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	
	Inspected
Lighting	
Does a Chandelier Exist?	No
Lighting Fixture - Fluorescent	
Pendant Mounted	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
	Does not exist
Lighting Fixture - Incandescent	
	Does not exist
Lighting Fixture - LED	
	Does not exist
COMPUTER LAB	
	Inspected
Instance on Rooms 321, 453	Inspected
Power Panel?	Yes
Lighting	
Instance on Rooms 321, 453	Inspected
Lighting Fixture - Fluorescent	
Instance on Rooms 321, 453	Inspected
Pendant Mounted	
Instance on Rooms 321, 453	Does not exist
Surface Mounted	
Instance on Rooms 321, 453	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Rooms 321, 453	Does not exist
Lighting Fixture - HID	
Instance on Rooms 321, 453	Does not exist
Lighting Fixture - Incandescent	
Instance on Rooms 321, 453	Does not exist
Lighting Fixture - LED	
Instance on Rooms 321, 453	Does not exist
Raceway With Receptacles	
Instance on Rooms 321, 453	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
GYMNASIUM	
	Inspected

NYC Department of Education
Building Condition Assessment Survey 2023-2024

Electrical Inspection

M143

Question	Response
GYMNASIUM	
Instance on 1st Floor	Inspected
Lighting	
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not exist
Surface Mounted	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on 1st Floor	Does not exist
Lighting Fixture - HID	
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not exist
Lighting Fixture - LED	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on 1st Floor	Does not exist
Recessed Mounted	
Instance on 1st Floor	Does not exist
Local Sound System	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Installation Year	2006
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Projection System	
Instance on 1st Floor	Inspected
Instance Condition	1- Good
Is the projector on a cart or installed on the ceiling?	Ceiling
Deficiency	No deficiencies recorded
Scoreboard	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Theater Lighting System	
Instance on 1st Floor	Does not exist
KITCHEN	
Instance on 1st Floor	Inspected
Lighting	
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not exist
Surface Mounted	

NYC Department of Education
Building Condition Assessment Survey 2023-2024

Electrical Inspection

M143

Question	Response
KITCHEN	
Lighting	
Lighting Fixture - Fluorescent	
Surface Mounted	
Instance on 1st Floor	Does not exist
Recessed Mounted	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not exist
Lighting Fixture - LED	
Instance on 1st Floor	Does not exist
LIBRARY	
Instance on Room 236	Inspected
Lighting	
Instance on Room 236	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 236	Does not exist
Lighting Fixture - HID	
Instance on Room 236	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 236	Does not exist
Lighting Fixture - LED	
Instance on Room 236	Inspected
Pendant Mounted	
Instance on Room 236	Does not exist
Surface Mounted	
Instance on Room 236	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Room 236	Does not exist
Raceway With Receptacles	
Instance on Room 236	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Projection System	
Instance on Room 236	Does not exist
LOCKER ROOM	
	Does not exist
MULTIPURPOSE ROOM	
	Does not exist
SCIENCE DEMO ROOM	
Instance on Room 300	Inspected
Power Panel?	No
Alternative Use	Yes
Lighting	
Instance on Room 300	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 300	Inspected
Pendant Mounted	
Instance on Room 300	Does not exist

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

M143

Question	Response
SCIENCE DEMO ROOM	
Lighting	
Lighting Fixture - Fluorescent	
Surface Mounted	
Instance on Room 300	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Room 300	Does not exist
Lighting Fixture - HID	
Instance on Room 300	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 300	Does not exist
Lighting Fixture - LED	
Instance on Room 300	Does not exist
Emergency Gas Shut-Off Valve	
Instance on Room 300	Does not exist
Emergency Shut-Off Power	
Instance on Room 300	Does not exist
Power Supply	
Instance on Room 300	Does not exist
Projection System	
Instance on Room 300	Does not exist
SCIENCE LAB	
Instance on Room 301	Inspected
Power Panel?	No
Alternative Use	No
Instance on Room 305	Inspected
Power Panel?	No
Alternative Use	No
Instance on Room 401	Inspected
Power Panel?	No
Alternative Use	No
Instance on Room 405	Inspected
Power Panel?	No
Alternative Use	No
Lighting	
Instance on Room 301	Inspected
Instance on Room 305	Inspected
Instance on Room 401	Inspected
Instance on Room 405	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 301	Inspected
Instance on Room 305	Inspected
Instance on Room 401	Inspected
Instance on Room 405	Inspected
Pendant Mounted	
Instance on Room 301	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 305	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

M143

Question	Response
SCIENCE LAB	
Lighting	
Lighting Fixture - Fluorescent	
Pendant Mounted	
Instance on Room 401	Does not exist
Instance on Room 405	Does not exist
Surface Mounted	
Instance on Room 301	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 305	Does not exist
Instance on Room 401	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 405	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Room 301	Does not exist
Instance on Room 305	Does not exist
Instance on Room 401	Does not exist
Instance on Room 405	Does not exist
Lighting Fixture - HID	
Instance on Room 301	Does not exist
Instance on Room 305	Does not exist
Instance on Room 401	Does not exist
Instance on Room 405	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 301	Does not exist
Instance on Room 305	Does not exist
Instance on Room 401	Does not exist
Instance on Room 405	Does not exist
Lighting Fixture - LED	
Instance on Room 301	Does not exist
Instance on Room 305	Does not exist
Instance on Room 401	Does not exist
Instance on Room 405	Does not exist
Emergency Gas Shut-Off Valve	
Instance on Room 301	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 305	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 401	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 405	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Emergency Shut-Off Power	
Instance on Room 301	Inspected
Instance Condition	2- Between Good and Fair

NYC Department of Education
Building Condition Assessment Survey 2023-2024

Electrical Inspection

M143

Question	Response
SCIENCE LAB	
Emergency Shut-Off Power	
Deficiency	No deficiencies recorded
Instance on Room 305	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 401	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 405	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Power Supply	
Instance on Room 301	Does not exist
Instance on Room 305	Does not exist
Instance on Room 401	Inspected
Instance on Room 405	Does not exist
Instructor Unit	
Instance on Room 401	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Meter Demonstration Unit	
Instance on Room 401	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Student Unit	
Instance on Room 401	Does not exist
Projection System	
Instance on Room 301	Does not exist
Instance on Room 305	Does not exist
Instance on Room 401	Does not exist
Instance on Room 405	Does not exist
SCIENCE PREP ROOM	
Instance on Room 302	Inaccessible
Instance on Room 303	Inspected
Power Panel?	Yes
Alternative Use	Yes
Instance on Room 403	Inspected
Power Panel?	Yes
Alternative Use	No
Lighting	
Instance on Room 303	Inspected
Instance on Room 403	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 303	Inspected
Instance on Room 403	Inspected
Pendant Mounted	
Instance on Room 303	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 403	Does not exist
Surface Mounted	
Instance on Room 303	Does not exist

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

M143

Question	Response
SCIENCE PREP ROOM	
Lighting	
Lighting Fixture - Fluorescent	
Surface Mounted	
Instance on Room 403	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Room 303	Does not exist
Instance on Room 403	Does not exist
Lighting Fixture - HID	
Instance on Room 303	Does not exist
Instance on Room 403	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 303	Does not exist
Instance on Room 403	Does not exist
Lighting Fixture - LED	
Instance on Room 303	Does not exist
Instance on Room 403	Does not exist
Emergency Gas Shut-Off Valve	
Instance on Room 303	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 403	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Emergency Shut-Off Power	
Instance on Room 303	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 403	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Power Supply	
Instance on Room 303	Does not exist
Instance on Room 403	Does not exist
SWIMMING POOL	
	Does not exist
TOILET ROOM - STAFF	
	Inspected
Lighting	
	Inspected
Lighting Fixture - Fluorescent	
	Inspected
Pendant Mounted	
	Does not exist
Surface Mounted	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
	Does not exist
Lighting Fixture - HID	
	Does not exist
Lighting Fixture - Incandescent	
	Does not exist
Lighting Fixture - LED	
	Does not exist
TOILET ROOM - STUDENT	
	Inspected
Lighting	
	Inspected
Lighting Fixture - Fluorescent	
	Inspected
Pendant Mounted	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

M143

Question	Response
TOILET ROOM - STUDENT	
Lighting	
Lighting Fixture - Fluorescent	
Surface Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not exist
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
EMERGENCY DC STANDBY BATTERY POWER	Does not exist
EMERGENCY GENERATOR SET	Does not exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
EMERGENCY LIGHTING	Inspected
Battery Pack	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Non Battery Pack	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
EXIT LIGHT	Inspected
Battery Pack	Inspected
Condition	3- Fair
Deficiency	FIXTURE LENS MISSING
Deficiency Location/Instance	1st Floor by Stairwell D (5)
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL LENS
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded
Non Battery Pack	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
EXIT/EMERGENCY LIGHT	Does not exist
FIRE ALARM SYSTEM	Under construction
GROUNDING SYSTEM	Under construction
INTERCOM SYSTEM	Inspected
Elevator	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Holding Area	Does not exist
LAN	Inspected
Local Distribution Frame (I/LDF)	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	Inspected
Condition	3- Fair

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

M143

Question	Response
LAN	
Main Equipment Rack (MDF)	
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	Does not exist
MOTOR CONTROLLER	Inspected
MOTOR CONTROL CENTER	Does not exist
MOTOR STARTER/CONTACTOR	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Variable Frequency Drive	Does not exist
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Fused Knife Switch Type	Does not exist
Fused Toggle Switch Type	Does not exist
Molded Case Circuit Breaker Type	Inspected
Condition	2- Between Good and Fair
Deficiency	NO SPARE
Deficiency Location/Instance	By Rooms (109, 119, 328, 428)
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	INSTALL NEW PANEL BOARD
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
PUBLIC ADDRESS SYSTEM	Under construction
SECURITY	Inspected
IPDVS/CCTV System	Inspected
Condition	1- Good
Installation Year	2022
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Intrusion Alarm System	Inspected
Central Control Panel	Inspected
Instance	Custodian's Office - Room 112
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista 128BPT
Installation Year	2020
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Infrared Sensor	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Panic Switch	Inspected
Condition	1- Good

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

M143

Question	Response
SECURITY	
Intrusion Alarm System	
Panic Switch	
Deficiency	No deficiencies recorded
Remote Annunciator	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Siren/Strobe	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Lighting - Security	Inaccessible
SERVICE SWITCH	Inspected
Instance	Electrical Room B26
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Lexington
EquipmentId	Main Service Switch 2500A Fuse
Capacity/Size Quantity	2500
Capacity/Size UOM	Amps
Source of Capacity/Size	Fuse Size
Installation Year	1965
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room B26
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Electrical Room B26
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Siemens
EquipmentId	Rapid Shutdown Switch for Solar PV System
Capacity/Size Quantity	600
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2022
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
SWITCHBOARD	Inspected
Number of Spares	1
Fused Disconnect Switch Type	Inspected
Instance	Electrical Room B26
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Lexington
EquipmentId	N/A
Capacity/Size Quantity	2500
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	4

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

M143

Question	Response
SWITCHBOARD	
Fused Disconnect Switch Type	
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Service Switch Fuse Size
Installation Year	1965
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room B26
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Fused Knife Switch Type	Does not exist
Molded Case Circuit Breaker Type	Does not exist
TELEPHONE SYSTEM	Inspected
PBX/Intercom	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Standard	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
TRANSFORMER	Does not exist