NYC Department of Education

Building Condition Assessment Survey 2023-2024

	P.S. 200 (TAIN)	DEM M010) - MANHATTAI	N, 2589 / I H AV E	LNUE, MANHA	ITAN, NY, 10)039		
Inspection Id					Time	In	Last Edited	
170	3 ELECTRICAL				2023	-12-14 09:04A	M 2023-12-15 0	2:19PM
sset Data								
Question				Answer				
Have any Systems/Major Building Components been upgraded?				-	n Upgraded			
Type of Service Does Interactive Whiteboard (IWB) Exist?				Below Gr Yes	ound			
	ation In Electrical Ro	,		No				
		IN FIRE RESCUE AREAS		110				
Question]	Response			
Are there a your buildi	•	stance Areas, Fire Rescue Areas, a	and/or Holding Roo	ms in	No			
riority Cond	ition							
	riority	Condition	Component	Location	Person(s)	Person(s)	Photo	
	ategory	Description	Affected	Description	Notified	Title	Image	
No condition	recorded							
Inspection								
Question				Response				
Electrical								
ATHLETIC FIELD				Not requi	red			
AUDITORIUM				Not required				
CAFETER	CAFETERIA			Not requi	red			
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE			Not required					
COMPUTER LAB			Not required					
GYMNASIUM			Not required					
KITCHEN			Not required					
LIBRARY				Not requi	red			
LOCKER	ROOM			Not requi	red			
MULTIPU	RPOSE ROOM			Not requi	red			
SCIENCE	DEMO ROOM			Not requi	red			
SCIENCE LAB			Not required					
SCIENCE PREP ROOM			Not required					
SWIMMING POOL				Not requi	red			
TOILET F	ROOM - STAFF			Not requi	red			
TOILET F	ROOM - STUDENT	•		Not requi	red			
AUXILIA	RY SIGNAL/BELL	SYSTEM		Not requi	red			
EMERGE	NCY DC STANDBY	Y BATTERY POWER		Not requi	red			
	NCY GENERATOI			Not requi	red			
EMERGE	NCY LIGHT/EXIT	LIGHT PANEL		Not requi	red			
EMERGE	NCY LIGHTING			Not requi	red			
EXIT LIG	НТ			Not requi	red			
EXIT/EM	ERGENCY LIGHT	,		Not requi	red			
FIRE ALARM SYSTEM				Not requi	red			
	ING SYSTEM			Not requi				
-	M SYSTEM			Not requi				
LAN				Not requi				
-	NG PROTECTION	[Not requi				
	CONTROLLER			Not requi				
PANEL BO				Not requi				
	ADDRESS SYSTEM	1		Not requi				

NYC Department of Education

Building Condition Assessment Survey 2023-2024

trical Inspection	M200	
Question	Response	
SECURITY	Not required	
SERVICE SWITCH	Not required	
SWITCHBOARD	Not required	
TELEPHONE SYSTEM	Not required	
TRANSFORMER	Not required	