

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Mechanical Inspection

M200

Asset: P.S. 200 (TANDEM M010) - MANHATTAN, 2589 7TH AVENUE, MANHATTAN, NY, 10039

| Inspection Id | Inspection Type | Time In | Last Edited |
|---------------|-----------------|--------------------|--------------------|
| 1714 | MECHANICAL | 2023-12-14 09:21AM | 2023-12-14 09:22AM |

Asset Data

| Question | Answer |
|--|--------------------|
| Have any Systems/Major Building Components been upgraded? | No System Upgraded |
| Are there fuel tanks? | No |
| Total # of water main service entries to the asset | 0 |
| MERs/Fan Rooms Locations | None |
| Are there any spaces with Missing or Defective CO Detectors? | No |
| Are there any Painted/Obstructed Sprinkler Heads? | No |
| Are there any Emergency Stop Switches with Missing Hammers? | No components |

Priority Condition

| Exist Last Year? | Priority Category | Condition Description | Component Affected | Location Description | Person(s) Notified | Person(s) Title | Photo Image |
|-----------------------|-------------------|-----------------------|--------------------|----------------------|--------------------|-----------------|-------------|
| No condition recorded | | | | | | | |

Inspection

| Question | Response |
|--|--------------|
| Mechanical | |
| AIR CONDITIONING | Not required |
| CENTRAL ACID WASTE NEUTRALIZING TANK | Not required |
| CLIMATE CONTROL SYSTEM | Not required |
| COMPACTOR | Not required |
| CONVEYING | Not required |
| DOMESTIC WATER SYSTEM | Not required |
| DRAIN/WASTE/VENT AND STORM SYSTEM | Not required |
| DUAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER) | Not required |
| FIXTURES | Not required |
| GAS FIRED FURNACE | Not required |
| GAS SERVICE | Not required |
| HEATING | Not required |
| HEATING PLANT | Not required |
| Enclosed IDF Room | Not required |
| KITCHEN | Not required |
| MDF Room | Not required |
| SCIENCE DEMO ROOM | Not required |
| SCIENCE LAB | Not required |
| SCIENCE PREP ROOM | Not required |
| SPRINKLERS, STANDPIPE, FIRE SYSTEM | Not required |
| SWIMMING POOL | Not required |
| VENTILATION | Not required |