NYC Department of Education

Building Condition Assessment Survey 2023-2024

P.S. 207 (TANDEM M149) - MANHATTAN, 41 WEST 117 STREET, MANHATTAN, NY, 10026

Electrical Inspection

Asset:

Asset.	1.5. 207 (12	(1) (1)				1,10020		
Inspectio	n Id Inspection Ty	уре			Time	In	Last Edited	
	2005 ELECTRICA	L			2023	-12-29 08:36A	M 2023-12-29 11:03AM	
lsset Data								
Question	l			Answer				
-		ding Components been upgraded?		No System Upgraded				
Type of S			Below Ground					
	ractive Whiteboard (· · · · · · · · · · · · · · · · · · ·		Yes				
	netration In Electrical			No				
Question		MS IN FIRE RESCUE AREAS		R	lesponse			
	ere any Life Rescue A	ssistance Areas, Fire Rescue Areas, an	d/or Holding Roo		lo			
riority Co								
Exist	Priority	Condition	Component	Location	Person(s)	Person(s)	Photo	
Last Year?	Category	Description	Affected	Description	Notified	Title	Image	
No condi	tion recorded	•		-				
Inspection	1							
Question	I			Response				
Electrica	ıl							
ATHL	ETIC FIELD			Not requir	ed			
AUDITORIUM			Not required					
CAFETERIA			Not required					
CLASS	SROOM/CORRIDO	PR/ADMINISTRATIVE SPACE		Not requir	ed			
COMPUTER LAB				Not requir	ed			
GYMNASIUM			Not required					
KITCHEN				Not requir				
LIBRARY				Not requir				
LIDKART LOCKER ROOM			Not required					
MULTIPURPOSE ROOM			Not required					
SCIENCE DEMO ROOM				Not requir				
	ICE LAB			Not requir				
-	CE PREP ROOM			Not requir				
				Not requir				
SWIMMING POOL TOILET ROOM - STAFF			Not required					
-		NTE		Not requir				
-	ET ROOM - STUDE							
	LIARY SIGNAL/BE			Not requir				
EMERGENCY DC STANDBY BATTERY POWER			Not required Not required					
-	GENCY GENERAT							
		XIT LIGHT PANEL		Not requir				
	GENCY LIGHTIN	G		Not requir				
EXIT LIGHT			Not required					
EXIT/EMERGENCY LIGHT			Not required					
	ALARM SYSTEM			Not requir				
	NDING SYSTEM			Not requir				
	RCOM SYSTEM			Not requir				
LAN				Not requir				
LIGHT	INING PROTECTI	ON		Not requir				
мото	OR CONTROLLER			Not requir				
PANEI	L BOARD			Not requir	ed			
PUBLI	C ADDRESS SYST	EM		Not requir	ed			
CAS Partners	s Version 2.0 (P)		Page 1	of 2			Print Date: 8/8/2024	

M207

NYC Department of Education **Building Condition Assessment Survey 2023-2024**

Electrical Inspection

ctrical Inspection				
Response				
Not required				
	Not required Not required Not required Not required Not required			