### **Building Condition Assessment Survey 2023-2024**

Inspection Id	Inspection Type		Time In	Last Edited
	MECHANICAL		2024-02-27 08:25AM	2024-05-14 11:07AN
et Data				
Question		Answer		
Have any System	ms/Major Building Components been upgraded?	Systems: Years:	Climate Control System - Electric System); Drinking Fountain (~90 Dedicated A/C Equipment: Room System); Enclosed IDF Room - Equipment: Room 404A (DX Sp Steam Drip Trap (~50%) 2023	0%); MDF Room - m 410A (DX Split Dedicated A/C
		Years: Systems:		
		Years:	2019	
		Systems:		<i>'</i>
		Years:	2018	
		Systems:	Fixtures - Toilets (~70%)	
		Years:	2017	
		Systems:	Water Service; Electric Pressure	Booster System
		Years:	2016	
		Systems:	Boiler Safety Valves (2 of 4)	
		Years:	2014	
Are there fuel to	anks?	Yes		
Total # of al	bove ground tanks	2		
Total capaci	ity of all above ground tanks in gal.	8,000		
Total # of bo	elow ground tanks	0		
Total capaci	ity of all below ground tanks in gal.	0		
Total # of water	main service entries to the asset	2		
MERs/Fan Roo	ms Locations	Basement Room	t - Boiler Room Mechanical Area, I	Penthouse Tank
Are there any sp	paces with Missing or Defective CO Detectors?	Yes		
Location(s)		Science I Room	Demo Rooms 314, 414; Science Lal	b 413, Science Prep
Are there any P	ainted/Obstructed Sprinkler Heads?	No		
Are there any E	mergency Stop Switches with Missing Hammers?	No compo	onents	
ority Conditi	ion			

Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image
No	Defective Boiler Safety Auxiliary	(1)	Boiler Safety Valve	Boiler Room @ Boiler #2	Charlie Gomez	Fireman	
No	Other	Defective	Gas Meter Room Exhaust Fan	Basement - Gas Meter Room	Charlie Gomez	Fireman	

•		. •	
Ins	nec	ction	И
III	vec	ıwı	

Question	Response
Mechanical	
AIR CONDITIONING	Inspected

### **Building Condition Assessment Survey 2023-2024**

unicui Inspeciion	IVIO
uestion	Response
AIR CONDITIONING	
Chilled Water System	Does not exist
Condenser Water Distribution: Piping, Pumps and Auxiliaries	Does not exist
Cooling Coil in Ductwork	Does not exist
Cooling Tower	Does not exist
DX Split System	Inspected
Indoor Unit	Inspected
Condition	3- Fair
Deficiency	UP TO 5 TONS:DEFECTIVE
Deficiency Location/Instance	Room 103 (2 of 5)
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Outdoor Unit	Inspected
Condition	2- Between Good and Fair
<u> </u>	
Deficiency	No deficiencies recorded
Dry Cooler	Does not exist
Packaged / Rooftop Unit	Does not exist
Packaged Terminal A/C	Does not exist
Refrigerant Leak Detection System	Does not exist
Refrigerant Piping	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Return Fan	Does not exist
CENTRAL ACID WASTE NEUTRALIZING TANK	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
CLIMATE CONTROL SYSTEM	Inspected
BMS	Does not exist
Pneumatic System	Inspected
Instance	Throughout (except Room 103)
Instance Condition	5- Poor
	<u> </u>
Instance Quantity	1
Instance Quantity Uom	EACH
Building Area Covered by Operational System	0-20%
Deficiency	DEFECTIVE TEMPERATURE CONTROL THERMOSTAT
Deficiency Location/Instance	Throughout (except Room 103)
Deficiency Quantity	43
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	DEFECTIVE TERMINAL UNIT CONTROL VALVE
Deficiency Location/Instance	Throughout (except Room 103)
Deficiency Quantity	100
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	DEFECTIVE DAMPER ACTUATOR

### **Building Condition Assessment Survey 2023-2024**

Question	Response
CLIMATE CONTROL SYSTEM	
Pneumatic System	
Deficiency Location/Instance	Roof
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	DEFECTIVE TEMPERATURE CONTROL ZONE VALVE
Deficiency Location/Instance	Roof
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	DEFECTIVE AIR COMPRESSOR
Deficiency Location/Instance	Boiler Room Mechanical Area
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Hybrid System	Does not exist
Electric System	Inspected
Instance	Throughout (Heat Timer System)
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Building Area Covered by Operational System	81-100%
Deficiency	No deficiencies recorded
COMPACTOR	Does not exist
CONVEYING	Does not exist
DOMESTIC WATER SYSTEM	Inspected
Domestic Cold Water System	Inspected
Gravity System	Inspected
Supply Pump	Does not exist
Roof Tank	Inaccessible
Pressure Booster System	Inspected
Electric Pressure Booster System	Inspected
Instance	Basement - South Water Main Area 3- Fair
Instance Condition	
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Liquitrol
EquipmentId	N/A
Capacity/Size Quantity	2
Capacity/Size UOM	Total # Pumps
Capacity/Size 2 Quantity	15
Capacity/Size 2 UOM	Total Pumps HP
Source of Capacity/Size	Documented
Installation Year	2016
Source of Installation Year	Custodial Staff
Deficiency	PRE-CHARGED TANK RUSTY/LEAK

# **Building Condition Assessment Survey 2023-2024**

hanical Inspection  Duestion	Response
	кезрине
DOMESTIC WATER SYSTEM	
Domestic Cold Water System	
Pressure Booster System	
Electric Pressure Booster System	1
Deficiency Quantity	1 FACH
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	DEFECTIVE PUMP
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Hydraulic/Pneumatic Booster System	Inspected
Water Pressure Booster - Compressor	Inspected
Condition	3- Fair
Deficiency	NOT IN USE
Deficiency Location/Instance	Boiler Room Mechanical Area
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	NO ACTION
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 1
Violations	No violations recorded
Pressure Booster Pump	Inspected
Condition	3- Fair
Deficiency	NOT IN USE
Deficiency Location/Instance	Boiler Room Mechanical Area
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	NO ACTION
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 1
Violations	No violations recorded
Domestic Cold Water Tank	Inspected
Condition	3- Fair
Deficiency	NOT IN USE
Deficiency Location/Instance	Boiler Room Mechanical Area
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	NO ACTION
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 1
Violations	No violations recorded
Water Service	Inspected
Instance	Basement - South Water Main Area, Boiler Room Mechanical Area
Instance Condition	Area 1- Good
Instance Quantity	2 FACH
Instance Quantity Uom	EACH
Deficiency	No deficiencies recorded
D C III (III) ( C )	In an art of

Inspected

**Domestic Hot Water System** 

Mechanical Inspection	M615
Question	Dosnonso

Question	Response	
DOMESTIC WATER SYSTEM		
Domestic Hot Water System		
Domestic Hot Water Remote Storage Tank	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Domestic Water Heat Exchanger	Does not exist	
Electric Domestic Water Heater	Does not exist	
Gas Fired Domestic Water Heater	Inspected	
Instance	Boiler Room Mechanical Area	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Rheem / Ruud	
EquipmentId	N/A	
Capacity/Size Quantity	576	
Capacity/Size UOM	MBH Input	
Capacity/Size 2 Quantity	0	
Capacity/Size 2 UOM	Gallons	
Source of Capacity/Size	Documented	
Installation Year Source of Installation Year	1994 Custodial Staff	
	DEFECTIVE FLUE EXHAUST	
Deficiency Deficiency Location/Instance	Boiler Room Mechanical Area	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Oil Fired Domestic Water Heater	Does not exist	
Heat Pump Domestic Water Heater	Does not exist	
Domestic Water Distribution Piping	Inspected	
Condition	3- Fair	
Deficiency	DEFECTIVE VALVE	
Deficiency Location/Instance	Boiler Room Mechanical Area near Remote Storage Tank	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Deficiency	DEFECTIVE/LEAKS	
Deficiency Location/Instance	Room 214	
Deficiency Quantity	10 L.F.	
Quantity Uom Potential Action	L.F. REPLACE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
DRAIN/WASTE/VENT AND STORM SYSTEM	Inspected	
	Inspected	
Interior Storm Piping Condition	3- Fair	
Deficiency	No deficiencies recorded	
<u></u>	Inspected	
Sewage/Waste/Vent Piping Condition	3- Fair	
Deficiency	SEWAGE/WASTE PIPING:DEFECTIVE/LEAKS	
Deficiency	SE WASTE I II INS.DETECTIVE/LEARS	

### **Building Condition Assessment Survey 2023-2024**

4:	D	
stion	Response	
AAIN/WASTE/VENT AND STORM SYSTEM		
ewage/Waste/Vent Piping		
Deficiency Location/Instance	Basement, Room 510	
Deficiency Quantity	70	
Quantity Uom	L.F.	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Deficiency	SEWAGE/WASTE PIPING:CLOGGED	
Deficiency Location/Instance	Rooms 409, 509	
Deficiency Quantity	30	
Quantity Uom	L.F.	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
ewage Ejector Pump	Does not exist	
ump Pump	Inspected	
Condition	3- Fair	
Deficiency	DEFECTIVE	
Deficiency Location/Instance	Boiler Room Mechanical Area (2 of 4)	
Deficiency Quantity	2	
Quantity Uom	EACH	
Potential Action	REPAIR	
Urgency of Action	PRIORITY 3	
Urgency of Action Purpose of Action	PRIORITY 3 LEVEL 2	
Purpose of Action Violations	LEVEL 2	
Purpose of Action Violations UAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)	LEVEL 2 No violations recorded  Does not exist	
Purpose of Action Violations  UAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)  XTURES	LEVEL 2 No violations recorded  Does not exist  Inspected	
Purpose of Action Violations  UAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)  Extra Mand Other	LEVEL 2 No violations recorded  Does not exist  Inspected  Inspected	
Purpose of Action Violations  UAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)  Extra Staff And Other  Janitor Sink	LEVEL 2 No violations recorded  Does not exist  Inspected Inspected Inspected	
Purpose of Action Violations  UAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)  KTURES  Staff And Other  Janitor Sink  Condition	LEVEL 2 No violations recorded  Does not exist Inspected Inspected Inspected 3- Fair	
Purpose of Action Violations  VAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)  XTURES  Staff And Other  Janitor Sink  Condition Deficiency	LEVEL 2 No violations recorded  Does not exist  Inspected  Inspected  Inspected  3- Fair  No deficiencies recorded	
Purpose of Action Violations  VAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)  Extra Staff And Other  Janitor Sink  Condition Deficiency  Lavatory/Sink	LEVEL 2 No violations recorded  Does not exist  Inspected Inspected Inspected 3- Fair No deficiencies recorded Inspected	
Purpose of Action Violations  VAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)  Extra Staff And Other  Janitor Sink  Condition  Deficiency  Lavatory/Sink  Condition	LEVEL 2 No violations recorded  Does not exist  Inspected  Inspected  Inspected  3- Fair  No deficiencies recorded  Inspected  3- Fair	
Purpose of Action Violations  UAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)  EXTURES  Staff And Other  Janitor Sink  Condition  Deficiency  Lavatory/Sink  Condition  Deficiency	LEVEL 2 No violations recorded  Does not exist  Inspected Inspected Inspected 3- Fair No deficiencies recorded Inspected 3- Fair No deficiencies recorded	
Purpose of Action Violations  VAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)  XTURES  Staff And Other  Janitor Sink  Condition Deficiency  Lavatory/Sink  Condition Deficiency  Toilet	LEVEL 2 No violations recorded  Does not exist  Inspected  Inspected  Inspected  3- Fair  No deficiencies recorded  Inspected  3- Fair  No deficiencies recorded  Inspected	
Purpose of Action Violations  UAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)  EXTURES  Staff And Other  Janitor Sink  Condition  Deficiency  Lavatory/Sink  Condition  Deficiency	LEVEL 2 No violations recorded  Does not exist  Inspected Inspected Inspected 3- Fair No deficiencies recorded Inspected 3- Fair No deficiencies recorded	
Purpose of Action Violations  VAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)  XTURES  Staff And Other  Janitor Sink  Condition Deficiency  Lavatory/Sink  Condition Deficiency  Toilet	LEVEL 2 No violations recorded  Does not exist  Inspected  Inspected  Inspected  3- Fair  No deficiencies recorded  Inspected  3- Fair  No deficiencies recorded  Inspected	
Purpose of Action Violations  VAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)  Extra Staff And Other  Janitor Sink  Condition Deficiency  Lavatory/Sink  Condition Deficiency  Toilet Condition	LEVEL 2 No violations recorded  Does not exist  Inspected Inspected Inspected 3- Fair No deficiencies recorded Inspected 3- Fair No deficiencies recorded Inspected 1- Good	
Purpose of Action Violations  VAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)  XTURES  Staff And Other  Janitor Sink  Condition  Deficiency  Lavatory/Sink  Condition  Deficiency  Toilet  Condition  Deficiency	LEVEL 2 No violations recorded  Does not exist  Inspected Inspected Inspected 3- Fair No deficiencies recorded Inspected 3- Fair No deficiencies recorded Inspected 1- Good No deficiencies recorded	
Purpose of Action Violations  VAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)  XTURES  Staff And Other  Janitor Sink  Condition  Deficiency  Lavatory/Sink  Condition  Deficiency  Toilet  Condition  Deficiency  Urinal  Condition	LEVEL 2 No violations recorded  Does not exist  Inspected  Inspected  Inspected  3- Fair  No deficiencies recorded  Inspected  3- Fair  No deficiencies recorded  Inspected  1- Good  No deficiencies recorded  Inspected	
Purpose of Action Violations  VIAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)  XTURES  Staff And Other  Janitor Sink  Condition Deficiency  Lavatory/Sink  Condition Deficiency  Toilet  Condition Deficiency  Urinal  Condition Deficiency	LEVEL 2 No violations recorded  Does not exist  Inspected  Inspected  Inspected  3- Fair  No deficiencies recorded  Inspected  3- Fair  No deficiencies recorded  Inspected  1- Good  No deficiencies recorded  Inspected  1- Good  No deficiencies recorded  Inspected  1- Good  No deficiencies recorded  Inspected  3- Fair  DEFECTIVE FLUSHOMETER VALVE	
Purpose of Action Violations  VIAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)  XTURES  Staff And Other  Janitor Sink  Condition Deficiency  Lavatory/Sink  Condition Deficiency  Toilet  Condition Deficiency  Urinal  Condition Deficiency Deficiency Deficiency Deficiency Deficiency	LEVEL 2 No violations recorded  Does not exist  Inspected  Inspected  Inspected  3- Fair  No deficiencies recorded  Inspected  3- Fair  No deficiencies recorded  Inspected  1- Good  No deficiencies recorded  Inspected  1- Good  No deficiencies recorded  Inspected  1- Fair	
Purpose of Action Violations  VIAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)  XTURES  Staff And Other  Janitor Sink  Condition Deficiency  Lavatory/Sink  Condition Deficiency  Toilet  Condition Deficiency  Urinal  Condition Deficiency  Deficiency Deficiency  Deficiency  Deficiency  Deficiency Deficiency Deficiency Deficiency Deficiency Deficiency Quantity	LEVEL 2 No violations recorded  Does not exist  Inspected  Inspected  Inspected  3- Fair  No deficiencies recorded  Inspected  3- Fair  No deficiencies recorded  Inspected  1- Good  No deficiencies recorded  Inspected  1- Fair  DEFECTIVE FLUSHOMETER VALVE  Toilet Room 406B  1	
Purpose of Action Violations  VAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)  XTURES  Staff And Other  Janitor Sink  Condition  Deficiency  Lavatory/Sink  Condition  Deficiency  Toilet  Condition  Deficiency  Urinal  Condition  Deficiency  Deficiency  Deficiency  Upinal  Condition  Deficiency  Deficiency  Quantity Uom	LEVEL 2 No violations recorded  Does not exist  Inspected  Inspected  Inspected  3- Fair  No deficiencies recorded  Inspected  3- Fair  No deficiencies recorded  Inspected  1- Good  No deficiencies recorded  Inspected  1- Fair  DEFECTIVE FLUSHOMETER VALVE  Toilet Room 406B  1  EACH	
Purpose of Action Violations  VAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)  XTURES  Staff And Other  Janitor Sink  Condition  Deficiency  Lavatory/Sink  Condition  Deficiency  Toilet  Condition  Deficiency  Urinal  Condition  Deficiency  Deficiency  Deficiency  Urinal  Condition  Deficiency  Output  Deficiency  Deficiency  Output  Deficiency  Deficiency Quantity  Quantity Uom  Potential Action	LEVEL 2 No violations recorded  Does not exist  Inspected  Inspected  Inspected  3- Fair  No deficiencies recorded  Inspected  3- Fair  No deficiencies recorded  Inspected  1- Good  No deficiencies recorded  Inspected  3- Fair  DEFECTIVE FLUSHOMETER VALVE  Toilet Room 406B  1  EACH  MAINTENANCE	
Purpose of Action Violations  VAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)  XTURES  Staff And Other  Janitor Sink  Condition  Deficiency  Lavatory/Sink  Condition  Deficiency  Toilet  Condition  Deficiency  Urinal  Condition  Deficiency  Deficiency  Output  Deficiency  Urinal  Condition  Deficiency  Deficiency  Deficiency Quantity  Quantity Uom  Potential Action  Urgency of Action	LEVEL 2 No violations recorded  Does not exist  Inspected  Inspected  Inspected  3- Fair  No deficiencies recorded  Inspected  3- Fair  No deficiencies recorded  Inspected  1- Good  No deficiencies recorded  Inspected  3- Fair  DEFECTIVE FLUSHOMETER VALVE  Toilet Room 406B  1  EACH  MAINTENANCE  PRIORITY 3	
Purpose of Action Violations  VAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)  XTURES  Staff And Other  Janitor Sink  Condition  Deficiency  Lavatory/Sink  Condition  Deficiency  Toilet  Condition  Deficiency  Urinal  Condition  Deficiency  Deficiency Location/Instance Deficiency Quantity Quantity Uom Potential Action Urgency of Action Purpose of Action Purpose of Action	LEVEL 2 No violations recorded  Does not exist  Inspected  Inspected  Inspected  3- Fair  No deficiencies recorded  Inspected  3- Fair  No deficiencies recorded  Inspected  1- Good  No deficiencies recorded  Inspected  1- Fair  DEFECTIVE FLUSHOMETER VALVE  Toilet Room 406B  1  EACH  MAINTENANCE  PRIORITY 3  LEVEL 2	
Purpose of Action Violations  VIAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)  XTURES  Staff And Other  Janitor Sink  Condition  Deficiency  Lavatory/Sink  Condition  Deficiency  Toilet  Condition  Deficiency  Urinal  Condition  Deficiency  Deficiency  Deficiency  Urinal  Condition  Deficiency  Deficiency  Urinal  Condition  Deficiency  Deficiency Jocation/Instance  Deficiency Quantity  Quantity Uom  Potential Action  Urgency of Action  Purpose of Action  Violations	LEVEL 2 No violations recorded  Does not exist  Inspected  Inspected  Inspected  3- Fair  No deficiencies recorded  Inspected  3- Fair  No deficiencies recorded  Inspected  1- Good  No deficiencies recorded  Inspected  1- Good  No deficiencies recorded  Inspected  1- Good  No deficiencies recorded  Inspected  1- Fair  DEFECTIVE FLUSHOMETER VALVE  Toilet Room 406B  1  EACH  MAINTENANCE  PRIORITY 3  LEVEL 2  No violations recorded	
Purpose of Action Violations  JAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)  KTURES  Staff And Other  Janitor Sink  Condition  Deficiency  Lavatory/Sink  Condition  Deficiency  Toilet  Condition  Deficiency  Urinal  Condition  Deficiency  Deficiency Location/Instance Deficiency Quantity Quantity Uom Potential Action Urgency of Action Purpose of Action Violations  Student	LEVEL 2 No violations recorded  Does not exist  Inspected  Inspected  Inspected  3- Fair  No deficiencies recorded  Inspected  3- Fair  No deficiencies recorded  Inspected  1- Good  No deficiencies recorded  Inspected  3- Fair  DEFECTIVE FLUSHOMETER VALVE  Toilet Room 406B  1  EACH  MAINTENANCE  PRIORITY 3  LEVEL 2  No violations recorded  Inspected  Inspected  Inspected	
Purpose of Action Violations  JAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)  KTURES  Staff And Other  Janitor Sink  Condition  Deficiency  Lavatory/Sink  Condition  Deficiency  Toilet  Condition  Deficiency  Urinal  Condition  Deficiency  Deficiency Location/Instance Deficiency Quantity Quantity Uom Potential Action Urgency of Action Purpose of Action Violations  Student  Drinking Fountain	LEVEL 2 No violations recorded  Does not exist  Inspected  Inspected  Inspected  3- Fair  No deficiencies recorded  Inspected  3- Fair  No deficiencies recorded  Inspected  1- Good  No deficiencies recorded  Inspected  3- Fair  DEFECTIVE FLUSHOMETER VALVE  Toilet Room 406B  1  EACH  MAINTENANCE  PRIORITY 3  LEVEL 2  No violations recorded  Inspected  Inspected  Inspected  Inspected	
Purpose of Action Violations  VAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)  XTURES  Staff And Other  Janitor Sink  Condition  Deficiency  Lavatory/Sink  Condition  Deficiency  Toilet  Condition  Deficiency  Urinal  Condition  Deficiency Location/Instance Deficiency Quantity Quantity Uom Potential Action Urgency of Action Purpose of Action Violations  Student  Drinking Fountain  Condition  Condition	LEVEL 2 No violations recorded  Does not exist  Inspected  Inspected  Inspected  3- Fair  No deficiencies recorded  Inspected  3- Fair  No deficiencies recorded  Inspected  1- Good  No deficiencies recorded  Inspected  3- Fair  DEFECTIVE FLUSHOMETER VALVE  Toilet Room 406B  1  EACH  MAINTENANCE  PRIORITY 3  LEVEL 2  No violations recorded  Inspected	
Purpose of Action Violations  JAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)  KTURES  Staff And Other  Janitor Sink  Condition  Deficiency  Lavatory/Sink  Condition  Deficiency  Toilet  Condition  Deficiency  Urinal  Condition  Deficiency  Deficiency Location/Instance Deficiency Quantity Quantity Uom Potential Action Urgency of Action Purpose of Action Violations  Student  Drinking Fountain	LEVEL 2 No violations recorded  Does not exist  Inspected  Inspected  Inspected  3- Fair  No deficiencies recorded  Inspected  3- Fair  No deficiencies recorded  Inspected  1- Good  No deficiencies recorded  Inspected  3- Fair  DEFECTIVE FLUSHOMETER VALVE  Toilet Room 406B  1  EACH  MAINTENANCE  PRIORITY 3  LEVEL 2  No violations recorded  Inspected  Inspected  Inspected  Inspected	

### **Building Condition Assessment Survey 2023-2024**

estion	Response	
IXTURES		
Student		
Lavatory/Sink		
Condition	3- Fair	
Deficiency	CRACKED/PHYSICAL DAMAGE	
Deficiency Location/Instance	Toilet Room 503A	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Locker Room Shower	Does not exist	
Sink And Fountain Combo Unit	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Toilet	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Urinal	Inspected	
Condition	3- Fair	
Deficiency	CRACKED/PHYSICAL DAMAGE	
Deficiency Location/Instance	Cafeteria - Boy's Toilet Room	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Deficiency	DEFECTIVE FLUSHOMETER VALVE	
Deficiency Location/Instance	Cafeteria - Boy's Toilet Room	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
AS FIRED FURNACE	Does not exist	
AS SERVICE	Inspected	
Gas Distribution Piping	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Gas Meter Room Exhaust Fan	Inspected 4- Between Fair and Poor	
Condition		
Deficiency	DEFECTIVE Basement - Gas Meter Room	
Deficiency Location/Instance		
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 6	
Violations	No violations recorded	
Gas Meter Room Vent	Inspected	
Condition	3- Fair	

### **Building Condition Assessment Survey 2023-2024**

euestion	Response
GAS SERVICE	
Gas Pressure Booster	Inspected
Instance	Basement - Gas Meter Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Eclipse
EquipmentId	GB-1
Capacity/Size Quantity	18000
Capacity/Size UOM	SCFH
Source of Capacity/Size	Documented
Installation Year	1997
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
CO/Gas Leak Detection	Inspected
Instance	Basement - Boiler Room, Boiler Room Mechanical Area, Gas Meter Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Installation Year	2011
Source of Installation Year	Custodial Staff
Deficiency	No deficiencies recorded
HEATING	Inspected
Heating Coil In Ductwork	Does not exist
Hydronic Heating	Does not exist
Radiator/Convector/Fin Tube	Inspected
Condition	3- Fair
Deficiency	RADIATOR/CONVECTOR: DEFECTIVE
Deficiency Location/Instance	Multipurpose Room; Corridor near Rooms 213, 310, 512; Rooms
	302, 514
Deficiency Quantity	6
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	RADIATOR/CONVECTOR:MISSING GUARD/SHIELD
Deficiency Location/Instance	Multipurpose Room, 1st Floor Corridors, Rooms 204, 410,
	Corridor near Room 410
Deficiency Quantity	20
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	AUXILIARY (VALVE, VENT): DEFECTIVE
Deficiency Location/Instance	Corridors near Rooms 103, 202, 309, 313, 402
Deficiency Quantity	5
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	RADIATOR/CONVECTOR:DEFECTIVE/DETERIORATED
Deficiency Location/Instance	Room 303A

### **Building Condition Assessment Survey 2023-2024**

nicai Inspection	IVIO
estion	Response
EATING	
Radiator/Convector/Fin Tube	
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Steam Heating	Inspected
F&T/Steam Drip Trap	Inspected
Condition	2- Between Good and Fair
Deficiency	DEFECTIVE
Deficiency Location/Instance	Basement
Deficiency Quantity	10
Quantity Uom	EACH
Potential Action	MAINTENANCE
	PRIORITY 3
Urgency of Action	
Purpose of Action	LEVEL 2
Violations	No violations recorded
MER Steam and Condensate Piping	Does not exist
Steam Condensate Return Piping	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE/LEAKS
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	10
Quantity Uom	L.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	DEFECTIVE VALVE
Deficiency Location/Instance	Basement Corridor
Deficiency Quantity	3
	EACH
Quantity Uom	
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Steam Condensate Return Pumping System	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Steam Piping	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE/LEAKS
Deficiency Location/Instance	Basement Storage Room
Deficiency Quantity	10
Quantity Uom	L.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Terminal Unit Thermostatic Trap	Inspected
Condition	5- Poor
Deficiency	DEFECTIVE/DETERIORATED
Deficiency Location/Instance	Throughout
Deficiency Quantity	150

### **Building Condition Assessment Survey 2023-2024**

micui Inspection	14101.
estion	Response
IEATING	
Steam Heating	
Terminal Unit Thermostatic Trap	
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Steam supplied by External Sources	Does not exist
Unit Heater/Cabinet Heater	Inspected
Condition	5- Poor
Deficiency	DEFECTIVE/DETERIORATED
Deficiency Location/Instance	Toilet Room near Room 103A, Room 103A, 5th Floor Office
•	Space, Penthouse - Electrical Room
Deficiency Quantity	6
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
IEATING PLANT	Inspected
Instance on Basement	Inspected
Is there a water meter on the boiler make-up water piping?	Yes
Observed Operational?	Yes
Burner Manufacturer	KEWANEE
Burner Model	200-KFP-5.0-1162-G02
Burner Type	Dual Fuel (Gas/Oil)
Heating Plant Oil Number	2(B10)
Boiler Auxiliaries	2(D10)
Instance on Basement	Inspected
Boiler Auxiliary Piping	mspected
Instance on Basement	Inspected
	3- Fair
Instance Condition	
Deficiency	No deficiencies recorded
Boiler Emergency Stop Switch	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Boiler Feedwater System	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Boiler Feedwater Treatment(Automatic)	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	DEFECTIVE
Deficiency Location/Instance	Boiler Room (1 of 2)
Deficiency Quantity	
	1 EACH
Quantity Uom Potential Action	
	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Boiler Flue Exhaust	
Instance on Basement	Inspected
Instance Condition	3- Fair

Mechanical Inspection	M615
Question	Response

Question	Response
HEATING PLANT	
Boiler Auxiliaries	
Boiler Flue Exhaust	
Deficiency	No deficiencies recorded
Boiler Make-up Water Backflow Preventer	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Boiler Room Steam And Condensate Piping	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Boiler Safety Valve	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	DEFECTIVE
Deficiency Location/Instance	Boiler Room @ Boiler #2
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
Boiler System	
Instance on Basement	Inspected
Coal-fired Boiler	*
Instance on Basement	Does not exist
Hot Water Boiler	
Instance on Basement	Does not exist
Modular Boiler	
Instance on Basement	Does not exist
Steam Boiler	
Instance on Basement	Inspected
Instance on Basement	Inspected
Instance	Boiler Room
Instance Condition	3- Fair
Instance Quantity	5,431
	MBH NET
Instance Quantity Uom	No
Cast Iron Boiler?  Manufacturer	Kewanee Boiler Corporation
EquipmentId	520-01
Equipmentid Capacity/Size Quantity	6995
Capacity/Size Quantity  Capacity/Size UOM	MBH Gross
Source of Capacity/Size	Custodial Staff
Installation Year	1997
Source of Installation Year	Custodial Staff
Deficiency	No deficiencies recorded
Instance	Boiler Room
Instance Condition	3- Fair
Instance Quantity	5,198
Instance Quantity Uom	MBH NET
	No
Cast Iron Boiler?  Manufacturer	Kewanee Boiler Corporation
EquipmentId	520-02
Capacity/Size Quantity	6695
Paythaus Vausian 2.0 (P)	a 11 of 19 Print Data: 9/9/2024

### **Building Condition Assessment Survey 2023-2024**

estion	Response
EATING PLANT	
Boiler System	
Steam Boiler	
Capacity/Size UOM	MBH Gross
Source of Capacity/Size	Custodial Staff
Installation Year	1997
Source of Installation Year	Custodial Staff
Deficiency	LEAKY/PLUGGED TUBES
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Fuel System	
Instance on Basement	Inspected
Boiler Fresh Air Louver/Damper	
Instance on Basement	Inspected
Instance Condition	3- Fair
Туре	Automatic
Deficiency	DEFECTIVE DAMPER
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Burner/Burner Control Panel	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	DUAL FUEL (OIL/GAS) BURNER:DEFECTIVE
Deficiency Location/Instance	Boiler Room @ Boiler #1
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	DUAL FUEL (OIL/GAS) BURNER:DEFECTIVE
Deficiency Location/Instance	Boiler Room @ Boiler #2
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
	TWO VIOLANDIIS ICCOLUCU
Fuel Oil Storage/Supply System	Townseld
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Gas Trains And Vent At The Boiler	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
nclosed IDF Room	Inspected

Mechanical Inspection	M615

peettett	1/10
uestion	Response
Enclosed IDF Room	
Instance on Room 404A	Inspected
Dedicated A/C Equipment	-
Instance on Room 404A	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
KITCHEN	Inspected
Instance on 1st Floor	
	Inspected
CO Detector	Y 4.1
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Gas System	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Grease Trap	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Hood	
Instance on 1st Floor	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
	ivo deficiencies recorded
Hood Exhaust Ductwork Instance on 1st Floor	Inspected
	1- Good
Instance Condition	
Deficiency	No deficiencies recorded
Hood Exhaust Fan	
Instance on 1st Floor	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Hood Fire Suppression System	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Hot Water Temperature Booster	
Instance on 1st Floor	Does not exist
Kitchen Sink	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	Missing Air Gap
Deficiency Location/Instance	Kitchen
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	MISSING INDIRECT WASTE
Deficiency Location/Instance	MISSING INDIRECT WASTE  Kitchen
Deficiency Location/Instance Deficiency Quantity	
	1 EACH
Quantity Uom	EACH INSTALL
Potential Astion	
Potential Action Urgency of Action	PRIORITY 3

Mechanical Inspection	M615

Question	Response
KITCHEN	
Kitchen Sink	
Purpose of Action	LEVEL 2
Violations	No violations recorded
MDF Room	Inspected
Instance on Room 101A	Inspected
Instance on Room 410A	Inspected
Dedicated A/C Equipment	1
Instance on Room 101A	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 410A	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
SCIENCE DEMO ROOM	Inspected
Instance on Rooms 314, 414	Inspected
Alternative Use	
Instance on Room 511	No Inspected
	Inspected
Alternative Use	No
Instance on Room 514	Inspected
Alternative Use	Yes
Acid Waste Neutralizing Tank	
Instance on Rooms 314, 414	Does not exist
Instance on Room 511	Does not exist
Instance on Room 514	Does not exist
CO Detector	
Instance on Rooms 314, 414	Inspected
Instance Condition	4- Between Fair and Poor
Deficiency	DEFECTIVE/MISSING
Deficiency Location/Instance Deficiency Quantity	Rooms 314, 414
Quantity Uom	2 EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
Instance on Room 511	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 514	Not required
Emergency Shower	Not required
Instance on Rooms 314, 414	Does not exist
Instance on Room 511	Does not exist
Instance on Room 514	Does not exist
Eye Wash	DOCS HOT CAIST
Instance on Rooms 314, 414	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 511	
	Inspected 3- Fair
Instance Condition	
Deficiency	No deficiencies recorded
Instance on Room 514	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded

Question	Response	
SCIENCE DEMO ROOM	The sponse	
Hood Exhaust Ductwork		
Instance on Rooms 314, 414	Does not exist	
Instance on Room 511	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Room 514	Does not exist	
Hood Exhaust Fan		
Instance on Rooms 314, 414	Does not exist	
Instance on Room 511	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Room 514	Does not exist	
Fixed Laboratory Hood		
Instance on Rooms 314, 414	Does not exist	
Instance on Room 511	Does not exist	
Instance on Room 514	Does not exist	
Laboratory Sink		
Instance on Rooms 314, 414	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Room 511	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Room 514	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Make-up_Air Unit		
Instance on Rooms 314, 414	Does not exist	
Instance on Room 511	Does not exist	
Instance on Room 514	Does not exist	
SCIENCE LAB	Inspected	
Instance on Room 313	Inspected	
Alternative Use	Yes	
Instance on Room 413	Inspected	
Alternative Use	No	
Acid Waste Neutralizing Tank		
Instance on Room 313	Does not exist	
Instance on Room 413	Does not exist	
CO Detector		
Instance on Room 313	Not required	

	Instance on Rooms 314, 414	Does not exist	
	Instance on Room 511	Does not exist	
	Instance on Room 514	Does not exist	
CIENCE	LAB	Inspected	
	Instance on Room 313	Inspected	
	Alternative Use	Yes	
	Instance on Room 413	Inspected	
	Alternative Use	No	
Acid Wa	ste Neutralizing Tank		
	Instance on Room 313	Does not exist	
	Instance on Room 413	Does not exist	
CO Dete	ctor		
	Instance on Room 313	Not required	
	Instance on Room 413	Inspected	
	Instance Condition	4- Between Fair and Poor	
	Deficiency	DEFECTIVE/MISSING	
	Deficiency Location/Instance	Room 413	
	Deficiency Quantity	1	
	Quantity Uom	EACH	
	Potential Action	MAINTENANCE	
	Urgency of Action	PRIORITY 5	
	Purpose of Action	LEVEL 6	
	Violations	No violations recorded	
Emergen	ncy Shower		
	Instance on Room 313	Does not exist	
	Instance on Room 413	Inspected	
urtnare Vai	rsion 2.0 (P)	Page 15 of 18 Print Date: 8/8/	/202

Mechanical Inspection	M615
Question	Response

euestion	Response	
SCIENCE LAB		
<b>Emergency Shower</b>		
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Eye Wash		
Instance on Room 313	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Room 413	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Hood Exhaust Ductwork	Y 1	
Instance on Room 313	Inspected 3- Fair	
Instance Condition		
Deficiency	No deficiencies recorded	
Instance on Room 413	Inspected 3- Fair	
Instance Condition		
Deficiency	No deficiencies recorded	
Hood Exhaust Fan	Y 4. d	
Instance on Room 313	Inspected 3- Fair	
Instance Condition	No deficiencies recorded	
Deficiency A12		
Instance on Room 413	Inspected 3- Fair	
Instance Condition	No deficiencies recorded	
Deficiency	No deliciencies recorded	
Fixed Laboratory Hood Instance on Room 313	Does not exist	
Instance on Room 413	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Laboratory Sink	ivo deficiencies recorded	
Instance on Room 313	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Room 413	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Make-up Air Unit	1 to deficiencies recorded	
Instance on Room 313	Does not exist	
Instance on Room 413	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
SCIENCE PREP ROOM	Inspected	
Instance on Room 411A	Inspected	
Alternative Use	No	
Acid Waste Neutralizing Tank	110	
Instance on Room 411A	Does not exist	
CO Detector	2000 1000 20100	
Instance on Room 411A	Inspected	
Instance Condition	4- Between Fair and Poor	
Deficiency	DEFECTIVE/MISSING	
Deficiency Location/Instance	Room 411A	
Deficiency Quantity	1	
Quantity Uom	EACH	

### **Building Condition Assessment Survey 2023-2024**

<b>F</b>		
estion	Response	-
SCIENCE PREP ROOM		
CO Detector		
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 6	
Violations	No violations recorded	
Emergency Shower		
Instance on Room 411A	Does not exist	
Eye Wash		
Instance on Room 411A	Does not exist	
Hood Exhaust Ductwork		
Instance on Room 411A	Does not exist	
Hood Exhaust Fan		
Instance on Room 411A	Does not exist	
Fixed Laboratory Hood		
Instance on Room 411A	Does not exist	
Laboratory Sink		
Instance on Room 411A	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
	No deficiencies recorded	
Make-up Air Unit	Dogg mot aviet	
Instance on Room 411A	Does not exist	
SPRINKLERS, STANDPIPE, FIRE SYSTEM	Inspected	
Dry Sprinkler Alarm Valve Assembly	Does not exist	
Wet Sprinkler Alarm Valve Assembly	Does not exist	
Fire Booster Pump Assembly	Does not exist	
Roof Tank	Does not exist	
Siamese Connection	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Sprinkler Head	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Sprinkler Piping	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Standpipe System	Does not exist	
Water Gong	Does not exist	
SWIMMING POOL	Does not exist	
VENTILATION	Inspected	
Is the building Mechanically ventilated?	Partial	
Exhaust Fan	Inspected	
Condition	3- Fair	
Approximate Total # of Fans	1-25	
Deficiency	No deficiencies recorded	
	Inspected	
Heating And Ventilating Unit	3- Fair	
Condition		
Deficiency	No deficiencies recorded	
Metal Ductwork	Inspected	
Condition	3- Fair	
Are there any uninsulated ductwork by design in Mechanical rooms?	No	
Are there chain operated dampers?	No	
Deficiency	No deficiencies recorded	
Supply Fan	Does not exist	

echanical Inspection		M615
Question	Response	
VENTILATION		
Unit Ventilator		
Condition	3- Fair	
Deficiency	No deficiencies recorded	