Mechanical I	Inspection	M883
Asset:	LEGACY HS FOR INTEGR. STUDIES - MANHATTAN, 34 WEST 14 STREET, MANHATTAN, NY, 10011	

Inspection Id Inspection T	**			Time 1		Last E	
864 MECHANIC	CAL			2023-	11-09 08:56A	M 2023-1	2-05 02:16PM
Isset Data							
Question			Answer				
Have any Systems/Major Bui	lding Components been upgraded?		Systems:	Gas Fired Don		leater; Electric	Pressure
			Vaara	Booster System 2022	n		
			Years:	Fixtures - Drir	dring Fountain	10	
			Systems: Years:	2018	iking rountain	IS	
			Systems:	MDF Room -	Dadica tad A/	C Equipment (	Dortable
			Systems.	A/C)	Dedica ied A	c Equipment (	1 Ortable
			Years:	2015			
Are there fuel tanks?			No				
Total # of water main service	entries to the asset		1				
MERs/Fan Rooms Locations			None				
Are there any spaces with Mi	issing or Defective CO Detectors?		Yes				
Location(s)	•		Water He	ater Room 509			
Are there any Painted/Obstru	cted Sprinkler Heads?		Yes				
Location(s)				by; 4th Floor - S			A" and
			"B" (painted, 6); Room 433 (Obstructed, 1)				
Are there any Emergency Sto	p Switches with Missing Hammers?		No compo	onents			
Priority Condition							
Exist Priority	Condition	Component	Location	Person(s)	Person(s)	Photo	
Last Year? Category	Description	Affected	Description	Notified	Title	Image	
No condition recorded							
Inspection							
Question			Response	2			
Mechanical							
AIR CONDITIONING			Inspected				
Chilled Water System			Does not				
	bution: Piping, Pumps and Auxiliario	es	Does not				
Cooling Coil in Ductwor	·k		Does not				
Cooling Tower			Does not				
DX Split System			Inspected Inspected				
Indoor Unit							
Condition				en Good and Fair	<u> </u>		
Deficiency				encies recorded			
Outdoor Unit			Inspected				
Condition				en Good and Fair	r		
Deficiency				encies recorded			
Dry Cooler			Does not				
Packaged / Rooftop Unit	t		Inspected				
Instance			Roof				
Instance Conditi			3- Fair				
Instance Quantit	ty		2				
Instance Quantit	ty Uom		EACH				
Manufacturer			Trane				
EquipmentId			1, 4				
Capacity/Size Q			15				
Capacity/Size U			Tons				
Source of Capac	-		Inspector	Estimate			
Installation Year			1994	_			
Source of Install			Documen	ted			
Source of Heatin			Gas				
Refrigerant Type	e		N/A				
CAS Partners Version 2.0 (P)		Page 1	1 of 9			Print	Date: 8/8/2024

united inspection	1/10/
uestion	Response
AIR CONDITIONING	
Packaged / Rooftop Unit	
Deficiency	No deficiencies recorded
Instance	Roof
Instance Condition	3- Fair
Instance Quantity	2
Instance Quantity Uom	EACH
Manufacturer	Trane
EquipmentId	2, 5
Capacity/Size Quantity	20
Capacity/Size UOM	Tons
Source of Capacity/Size	Inspector Estimate
Installation Year	1994
Source of Installation Year	Documented
Source of Heating	Gas
Refrigerant Type	N/A
Deficiency	No deficiencies recorded
Instance	Roof
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Trane
EquipmentId	3
Capacity/Size Quantity	25
Capacity/Size Quantity	Tons
Source of Capacity/Size	Inspector Estimate
Installation Year	1994
Source of Installation Year	Documented
Source of Heating	Gas
Refrigerant Type	N/A
Deficiency	OVER 20 TONS:DEFECTIVE COIL - EVAP
Deficiency Location/Instance	Roof
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Packaged Terminal A/C	Does not exist
Refrigerant Leak Detection System	Does not exist
Refrigerant Piping	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Return Fan	Does not exist
CENTRAL ACID WASTE NEUTRALIZING TANK	Does not exist
CLIMATE CONTROL SYSTEM	Inspected
BMS	Does not exist
	Does not exist  Does not exist
Pneumatic System Hybrid System	Does not exist  Does not exist
Electric System	Inspected
Instance	Throughout (VAV System)
Instance Condition	3- Fair
Instance Quantity	1 EACH
Instance Quantity Uom	EACH
Building Area Covered by Operational System	81-100%
Deficiency	DEFECTIVE TEMPERATURE CONTROL THERMOSTAT

## **Building Condition Assessment Survey 2023-2024**

2	
uestion	Response
CLIMATE CONTROL SYSTEM	
Electric System	
Deficiency Location/Instance	Cafeteria
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
COMPACTOR	Does not exist
CONVEYING	Inspected
Dumbwaiter	Does not exist
Elevator	Inspected
Condition	3- Fair
Are all the existing elevators operable?	Yes
Deficiency	No deficiencies recorded
Escalator	Does not exist
Non-auditorium Handicap Lift - Vertical	Does not exist
Non-auditorium Handicap Lift - Stair	Does not exist
Ash Hoist	Does not exist
Sidewalk Elevator	Does not exist
DOMESTIC WATER SYSTEM	Inspected
Domestic Cold Water System	Inspected
Gravity System	Does not exist
Pressure Booster System	Inspected
	Inspected
Electric Pressure Booster System	Basement - Water Meter N/A Room
Instance	1- Good
Instance Condition	
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Liquitrol
EquipmentId	N/A
Capacity/Size Quantity	2
Capacity/Size UOM	Total # Pumps
Capacity/Size 2 Quantity	15
Capacity/Size 2 UOM	Total Pumps HP
Source of Capacity/Size	Documented
Installation Year	2022
Source of Installation Year	Custodial Staff
Deficiency	DEFECTIVE PUMP
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Hydraulic/Pneumatic Booster System	Does not exist
Water Service	Inspected
	Basement - Water Meter Room
Instance	3- Fair
Instance Condition	
Instance Quantity	1
Instance Quantity Uom	EACH
Deficiency	No deficiencies recorded
Domestic Hot Water System	Inspected

Mechanical Inspection	M883
-----------------------	------

<u>*</u>	
uestion	Response
DOMESTIC WATER SYSTEM	
Domestic Hot Water System	
Domestic Water Heat Exchanger	Does not exist
Electric Domestic Water Heater	Does not exist
Gas Fired Domestic Water Heater	Inspected
Instance	Water Heater Room 509
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	A.O. Smith
EquipmentId	N/A
Capacity/Size Quantity	250
Capacity/Size UOM	MBH Input
Capacity/Size 2 Quantity	100
Capacity/Size 2 UOM	Gallons
Source of Capacity/Size	Documented
Installation Year	2022
Source of Installation Year	Custodial Staff
Deficiency	No deficiencies recorded
Oil Fired Domestic Water Heater	Does not exist
Heat Pump Domestic Water Heater	Does not exist
Domestic Water Distribution Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
DRAIN/WASTE/VENT AND STORM SYSTEM	Inspected
Interior Storm Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Sewage/Waste/Vent Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Sewage Ejector Pump	Does not exist
Sump Pump	Does not exist
DUAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)	Does not exist
FIXTURES	Inspected
	Inspected
Staff And Other	Does not exist
Janitor Sink	Inspected
Lavatory/Sink	
Condition	3- Fair
Deficiency	No deficiencies recorded
Toilet	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Urinal	Does not exist
Student	Inspected
Drinking Fountain	Inspected
Condition	1- Good
Deficiency	DEFECTIVE AUXILIARY (FAUCET, SHUT OFF VALVE,ETC.)
Deficiency Location/Instance	Corridor near Room 532
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2

## **Building Condition Assessment Survey 2023-2024**

NIO
Response
No violations recorded
Inspected
3- Fair
CRACKED/PHYSICAL DAMAGE
Girl's Toilet Room 413
1
EACH
REPLACE
PRIORITY 3
LEVEL 2
No violations recorded
Does not exist
Does not exist
Inspected
3- Fair
CRACKED/PHYSICAL DAMAGE
Boy's Toilet Room 412
1
EACH
REPLACE
PRIORITY 3
LEVEL 2
No violations recorded
DEFECTIVE FLUSHOMETER VALVE
Girl's Toilet Room 429
1
EACH
MAINTENANCE
PRIORITY 3
LEVEL 2
No violations recorded
Inspected
3- Fair
CLOGGED/LEAKING
Boy's Toilet Room 412
EACH
MAINTENANCE
PRIORITY 3
LEVEL 2
No violations recorded
Does not exist
Inspected
Inspected
3- Fair
No deficiencies recorded
Does not exist
Inspected

Mechanical Inspection	M883

		1,100
uestion	Response	
HEATING		
Hydronic Heating	Does not exist	
Radiator/Convector/Fin Tube	Does not exist	
Steam Heating	Does not exist	
Steam supplied by External Sources	Does not exist	
Unit Heater/Cabinet Heater	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
HEATING PLANT	Does not exist	
Enclosed IDF Room	Does not exist	
KITCHEN	Inspected	
Instance on 4th Floor	Inspected	
CO Detector	1	
Instance on 4th Floor	Not required	
Gas System	•	
Instance on 4th Floor	Does not exist	
Grease Trap		-
Instance on 4th Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Hood		
Instance on 4th Floor	Inspected	
Instance Condition	3- Fair	-
Deficiency	No deficiencies recorded	
Hood Exhaust Ductwork		
Instance on 4th Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Hood Exhaust Fan		
Instance on 4th Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Hood Fire Suppression System	10 4010101010101010101010101010101010101	
Instance on 4th Floor	Does not exist	
Hot Water Temperature Booster		
Instance on 4th Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Kitchen Sink	10 4010101010101010101010101010101010101	
Instance on 4th Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	Missing Air Gap	
Deficiency Location/Instance	Kitchen (1 of 3)	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 4	
Violations	SF102340	
Deficiency	MISSING INDIRECT WASTE	
Deficiency Location/Instance	Kitchen (1 of 3)	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	INSTALL	
Urgency of Action	PRIORITY 3	

Mechanical Inspection	M883

Question	Response	
KITCHEN		
Kitchen Sink		
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
MDF Room	Inspected	
Instance on Room 428	Inspected	
Dedicated A/C Equipment		
Instance on Room 428	Inspected	
Instance Condition	3- Fair	
Deficiency	DEFECTIVE	
Deficiency Location/Instance	Room 428 (1 of 2)	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
SCIENCE DEMO ROOM	Does not exist	
SCIENCE LAB	Inspected	
Instance on Rooms 404, 506, 518	Inspected	
Alternative Use	No	
Instance on Room 411	Inspected	
Alternative Use	Yes	
Instance on Room 516	Inspected	
Alternative Use	No	
Acid Waste Neutralizing Tank		
Instance on Rooms 404, 506, 518	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Room 411	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Room 516	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
CO Detector	1 to deficiences recorded	
Instance on Rooms 404, 506, 518	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Room 411	Not required	
Instance on Room 516	Inspected	
Instance On Room 516  Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
	No deficiencies recorded	
Emergency Shower Instance on Rooms 404, 506, 518	Does not exist	
Instance on Room 411	Does not exist	
Instance on Room 516	Does not exist	
Eye Wash	Does not exist	
Instance on Rooms 404, 506, 518	Does not exist	
Instance on Room 411	Does not exist	
Instance on Room 516		
Hood Exhaust Ductwork	Does not exist	
Instance on Rooms 404, 506, 518	Does not exist	
Instance on Rooms 404, 506, 518  Instance on Room 411	Does not exist  Does not exist	
HISTARICE OH KOOHI 411	Does not exist	

## **Building Condition Assessment Survey 2023-2024**

estion	Response
CIENCE LAB	
Hood Exhaust Ductwork	
Instance on Room 516	Does not exist
Hood Exhaust Fan	
Instance on Rooms 404, 506, 518	Does not exist
Instance on Room 411	Does not exist
Instance on Room 516	Does not exist
Fixed Laboratory Hood	
Instance on Rooms 404, 506, 518	Does not exist
Instance on Room 411	Does not exist
Instance on Room 516	Does not exist
Laboratory Sink	
Instance on Rooms 404, 506, 518	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 411	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 516	Inspected
Instance Condition	4- Between Fair and Poor
Deficiency	DEFECTIVE AUXILIARY (FAUCET, SHUT OFF
	VALVE,ETC.)
Deficiency Location/Instance	Room 516 (2 of 3)
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Make-up Air Unit	
Instance on Rooms 404, 506, 518	Does not exist
Instance on Room 411	Does not exist
Instance on Room 516	Does not exist
CIENCE PREP ROOM	Does not exist
PRINKLERS, STANDPIPE, FIRE SYSTEM	Inspected
Dry Sprinkler Alarm Valve Assembly	Does not exist
Wet Sprinkler Alarm Valve Assembly	Does not exist
Fire Booster Pump Assembly	Does not exist
Roof Tank	Does not exist
Siamese Connection	Does not exist
Sprinkler Head	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE/DETERIORATED
Deficiency Location/Instance	Main Lobby; 4th Floor - Stair "A", 5th Floor - Stairs "A" and "B"
Deficiency Locations instance	(painted, 6); Room 433 (Obstructed, 1)
Deficiency Quantity	7
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
Sprinkler Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded

## **Building Condition Assessment Survey 2023-2024**

uestion	Response
SPRINKLERS, STANDPIPE, FIRE SYSTEM	
Standpipe System	
Hose Valve Assembly	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Water Gong	Does not exist
SWIMMING POOL	Does not exist
VENTILATION	Inspected
Is the building Mechanically ventilated?	Yes
Exhaust Fan	Inspected
Condition	3- Fair
Approximate Total # of Fans	1-25
Deficiency	No deficiencies recorded
Heating And Ventilating Unit	Does not exist
Metal Ductwork	Inspected
Condition	3- Fair
Are there any uninsulated ductwork by design in Mechanical rooms?	No
Are there chain operated dampers?	No
Deficiency	DEFECTIVE REGISTER/DIFFUSER
Deficiency Location/Instance	Room 433
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	DEFECTIVE DUCTWORK
Deficiency Location/Instance	Roof (Exhaust Fan cover)
Deficiency Quantity	5
Quantity Uom	L.F.
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Supply Fan	Does not exist
Unit Ventilator	Does not exist