Mechanical Inspe	ection						Q364
Asset:	3K CENTE	CR @ 75-01 BR	OADWAY - Q	UEENS, 75-01	BROADWAY	, New York, 11373	
Inspection Id	Inspection	Type				Time In	Last Edited
ME: Q364	Mechanical	[2023-11-13 9:05 AM	2023-11-30 3:14 PM
Asset Data							
Question					Answer		
Are there fuel tar	nks?				No		
Total # of water	main service of	entries to the asset	t		0		
MERs/Fan Roon					None		
		sing or Defective			No		
		Switches with M			No		
		ted Sprinkler Hea			No No		
		ding Components	been upgraded?		No		
Priority Condition							
Priority Pr Condition Exist Ca Last Year?	riority ategory	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title Status	PhotoImage
No condition record	led						
nspection							
Question					Respon	nse	
Mechanical							
AIR CONDITION	AIR CONDITIONING Inspected						
Chilled Water	r System				Does no	ot Exist	
Condenser W	ater Distribu	tion: Piping, Pur	nps and Auxiliar	ries	Does no	ot Exist	
Cooling Coil i	in Ductwork				Does no	ot Exist	
Cooling Towe	er				Does no	ot Exist	
DX Split Syst					Inspect	ed	
Indoor Unit					Inspect		
Condition	-				1 - Goo		
Defici						iciencies recorded	
Outdoor Un	•				Inspect		
Condition					1 - Goo		
Defici						iciencies recorded	
Dry Cooler						ot Exist	
Packaged / Ro	oofton Unit				Inspect		
Instan					Roof		
	ce Condition				1 - Goo	nd	
-	ice Quantity				1		
	ice Quantity	Iom			EACH		
		OIII					
Source of Heating Refrigerant Type				Gas R-134 <i>A</i>	<u> </u>		
Instan	ce Manufactu	rer			GREEN	NHECK	
Equip					N/A		
Capac	city/Size Quan	tity			21		
Capac	city/Size UOM	1			Tons		
Sourc	e of Capacity/	Size			Inspect	or Estimate	
Install	lation Year				2020		
Sourc	e of Installatio	on			Docum	ented	
Defici	iency				No defi	ciencies recorded	
Packaged Ter	minal A/C				Does no	ot Exist	

iestion	Response	
AIR CONDITIONING	Response	
Refrigerant Piping	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Return Fan	Does not Exist	
CENTRAL ACID WASTE NEUTRALIZING TANK	Does not Exist	
CLIMATE CONTROL SYSTEM	Inspected	
BMS	Inspected	
Instance	Throughout	
Instance Condition	1 - Good	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Building Area Covered by Operational System	81-100%	
Installation Year	2020	
Source of Installation	Documented	
Deficiency	No deficiencies recorded	
Pneumatic System	Does not Exist	
Hybrid System	Does not Exist	
Electric System	Does not Exist	
COMPACTOR	Does not Exist	
CONVEYING	Does not Exist	
DOMESTIC WATER SYSTEM	Inspected	
Domestic Cold Water System	Does not Exist	
Domestic Hot Water System	Inspected	
Domestic Hot Water Remote Storage Tank	Does not Exist	
Domestic Water Heat Exchanger	Does not Exist	
Electric Domestic Water Heater	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Heat Pump Domestic Water Heater	Does not Exist	
Gas Fired Domestic Water Heater	Does not Exist	
Oil Fired Domestic Water Heater	Does not Exist	
Domestic Water Distribution Piping	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
DRAIN/WASTE/VENT AND STORM SYSTEM	Inspected	
Interior Storm Piping	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Sewage/Waste/Vent Piping	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Sewage Ejector Pump	Does not Exist	
Sump Pump	Does not Exist	
DUAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)	Does not Exist	
FIXTURES	Inspected	
Staff And Other	Inspected	
	Inspected	

chanical Inspection		Q364
Question	Response	
FIXTURES		
Staff And Other		
Janitor Sink	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Lavatory/Sink	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Toilet	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Urinal	Does not Exist	
Student	Inspected	
Drinking Fountain	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Lavatory/Sink	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Locker Room Shower	Does not Exist	
Sink And Fountain Combo Unit	Does not Exist	
Toilet	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Urinal	Does not Exist	
GAS FIRED FURNACE	Does not Exist	
GAS SERVICE	Does not Exist	
HEATING	Inspected	
Heating Coil In Ductwork	Does not Exist	
Hydronic Heating	Inspected	
Hydronic Hot Water Distribution: Piping, Pumps and Auxiliaries	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Backflow Preventer	Does not Exist	
Hot Water Heat Exchanger	Does not Exist	
Radiator/Convector/Fin Tube	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Steam Heating	Does not Exist	
Steam supplied by External Sources	Does not Exist	
Unit Heater/Cabinet Heater	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
HEATING PLANT	Inspected	
Replacement Quantity	256	
Replacement Uom	MBH Net	
Instance on 2nd Floor	Inspected	

,•	Th.	
estion	Response	
EATING PLANT		
Burner Type Heating Plant Oil Number	N/A	
Is there a water meter on the boiler make-up water piping?	N/A No	
Burner Exists?	No	
Boiler Auxiliaries	Inspected	
Instance on 2nd Floor	Inspected	
Boiler Auxiliary Piping		
Instance on 2nd Floor	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Boiler Emergency Stop Switch		
Instance on 2nd Floor	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Boiler Feedwater System		
Instance on 2nd Floor	Does not Exist	
Boiler Feedwater Treatment(Automatic)		
Instance on 2nd Floor	Does not Exist	
Boiler Flue Exhaust		
Instance on 2nd Floor	Does not Exist	
Boiler Make-up Water Backflow Preventer		
Instance on 2nd Floor	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Boiler Room Steam And Condensate Piping		
Instance on 2nd Floor	Does not Exist	
Boiler Safety Valve		
Instance on 2nd Floor	Does not Exist	
Boiler System	Inspected	
Instance on 2nd Floor	Inspected	
Coal-fired Boiler	•	
Instance on 2nd Floor	Does not Exist	
Hot Water Boiler		
Instance on 2nd Floor	Does not Exist	
Modular Boiler		
Instance on 2nd Floor	Inspected	
Instance	2nd Floor	
Instance Condition	1 - Good	
Instance Quantity	256	
Instance Quantity Instance Quantity Uom	MBH Net	
Instance Manufacturer	Lochinvar	
Equipment	N/A	
Capacity/Size Quantity	368	
Capacity/Size UOM	MBH Input	
Source of Capacity/Size	Documented	
Installation Year	2020	
Source of Installation	Documented	
Deficiency	No deficiencies recorded	

echanical Inspection		Q364
Question	Response	
HEATING PLANT	Inspected	
Boiler System	Inspected	
Steam Boiler		
Instance on 2nd Floor	Does not Exist	
Fuel System	Does not Exist	
Instance on 2nd Floor	Does not Exist	
Enclosed IDF Room	Does not Exist	
KITCHEN	Inspected	
Instance on 2nd Floor	Inspected	
CO Detector	Not Required	
Instance on 2nd Floor	Not Required	
Gas System	Does not Exist	
Instance on 2nd Floor	Does not Exist	
Grease Trap	Inspected	
Instance on 2nd Floor	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Hood	Does not Exist	
Instance on 2nd Floor	Does not Exist	
Hood Exhaust Ductwork	Does not Exist	
Instance on 2nd Floor	Does not Exist	
Hood Exhaust Fan	Does not Exist	
Instance on 2nd Floor	Does not Exist	
Hood Fire Suppression System	Does not Exist	
Instance on 2nd Floor	Does not Exist	
Hot Water Temperature Booster	Does not Exist	
Instance on 2nd Floor	Does not Exist	
Kitchen Sink	Inspected	
Instance on 2nd Floor	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
MDF Room	Inspected	
Instance on Room 218	Inspected	
Dedicated A/C Equipment	Inspected	
Instance on Room 218	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
SCIENCE DEMO ROOM	Does not Exist	
SCIENCE LAB	Does not Exist	
SCIENCE PREP ROOM	Does not Exist	
SPRINKLERS, STANDPIPE, FIRE SYSTEM	Does not Exist	
SWIMMING POOL	Does not Exist	
VENTILATION	Inspected	
Is the building mechanically ventilated?	Yes	
Exhaust Fan	Inspected	
Approximate Total # of Fans	1-25	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Heating And Ventilating Unit	Does not Exist	

Building Condition Assessment Survey 2023 - 2024

Mechanical Inspection Q364 Question Response VENTILATION Metal Ductwork Inspected Are there any uninsulated ductwork by design in Mechanical No No Rooms? Are there chain operated dampers? 1 - Good Condition Deficiency No deficiencies recorded **Supply Fan** Does not Exist **Unit Ventilator** Does not Exist