NYC Department of Education

Building Condition Assessment Survey 2023 - 2024

Mechanical Inspection

wieenamear msp	ection						Q421
Asset:	SPRINGFI	ELD GDNS A	F - QUEENS, 14	43-10 SPRING	FIELD BLVD	, New York, 11413	
Inspection Id	Inspection Type				Time In	Last Edited	
ME : Q421	Mechanica	1				2024-04-15 8:15 AM	2024-04-26 11:40 A
Asset Data							
Question					Answer		
Are there fuel tanks?					No		
Total # of water main service entries to the asset					0		
MERs/Fan Roon				None			
• •		ssing or Defective			No		
	p Switches with M	-		No			
Are there any Painted/Obstructed Sprinkler Heads?					No		
Have any Systems/Major Building Components been upgraded?					No		
Priority Condition	n						
Priority P Condition Exist C Last Year?	riority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title Status	PhotoImage
No condition record	led						
Inspection							
Question				Response			
Mechanical							
AIR CONDITIONING				Does not Exist			
CLIMATE CONTROL SYSTEM				Does not Exist			
COMPACTOR				Does not Exist			
CONVEYING				Does not Exist			
DOMESTIC WATER SYSTEM				Does not Exist			
DRAIN/WASTE/VENT AND STORM SYSTEM				Does not Exist			
DUAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)				Does not Exist			
FIXTURES				Does not Exist			
GAS FIRED FURNACE				Does not Exist			
GAS SERVICE				Does not Exist			
HEATING				Does not Exist			
HEATING PLANT				Does not Exist			
Enclosed IDF Room				Does not Exist			
MDF Room				Does not Exist			
SPRINKLERS, STANDPIPE, FIRE SYSTEM				Does not Exist			
VENTILATION					Does n	ot Exist	

VENTILATION

Does not Exist

Q421