Asset: PRE-K CENTER @ 108-18 ROOSEVELT AVENU	IE - OLIEENS, 108-18 ROOSEVELT	
AVENUE, New York, 11368	E - QUEENS, 100-10 ROOSE VELT	
Inspection Id Inspection Type	Time In	Last Edited
ME: Q422 Mechanical	2024-04-30 12:38 PM	И 2024-05-08 6:50 PM
set Data		
Question	Answer	
Are there fuel tanks?	No	
Total # of water main service entries to the asset	1	
MERs/Fan Rooms Locations	None	
Are there any spaces with Missing or Defective CO Detectors?	No	
Are there any Emergency Stop Switches with Missing Hammers?	No	
Are there any Painted/Obstructed Sprinkler Heads?	No	
Have any Systems/Major Building Components been upgraded?	No	
ority Condition		
riority Priority Condition Component Location Condition Exist Category Description Affected Description ast Year?	* /	PhotoImage
lo condition recorded		
spection		
Question	Response	
Mechanical		
AIR CONDITIONING	Inspected	
Chilled Water System	Does not Exist	
Condenser Water Distribution: Piping, Pumps and Auxiliaries	Does not Exist	
Cooling Coil in Ductwork	Does not Exist	
Cooling Tower	Does not Exist	
DX Split System	Does not Exist	
	Does not Exist	
Dry Cooler		
Packaged / Rooftop Unit	Inspected	
Instance Instance Condition	Schoolyard	
	1 - Good	
Instance Quantity	2 FACH	
Instance Quantity Uom Source of Heating	EACH Electric	
Refrigerant Type	R-410A	
Instance Manufacturer	Trane	
Equipment	AC-1, AC-2	
Capacity/Size Quantity	9	
Capacity/Size UOM	Tons	
Source of Capacity/Size	Inspector Estimate	
Installation Year	2018	
Source of Installation	Documented	
Deficiency	No deficiencies recorded	
Packaged Terminal A/C	Does not Exist	
Refrigerant Leak Detection System	Does not Exist	
Refrigerant Piping	Does not Exist	
Return Fan	Inspected	
Condition	1 - Good	
	No deficiencies recorded	

uestion	Response
CLIMATE CONTROL SYSTEM	Inspected
BMS	Does not Exist
Pneumatic System	Does not Exist
Hybrid System	Does not Exist
Electric System	Inspected
Instance	Throughout
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Building Area Covered by Operational System	81-100%
Deficiency	No deficiencies recorded
COMPACTOR	Does not Exist
CONVEYING	Does not Exist
DOMESTIC WATER SYSTEM	Inspected
Domestic Cold Water System	Inspected
Gravity System	Does not Exist
Pressure Booster System	Does not Exist
Water Service	Inspected
Instance	Cellar
Instance Condition	1 - Good
Instance Quantity	1
Instance Quantity Uom	EACH
Deficiency	WATER MAIN: MISSING BACKFLOW PREVENTION DEVI
Deficiency Location/Instance	Cellar
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Domestic Hot Water System	Inspected
	Does not Exist
Domestic Hot Water Remote Storage Tank	
Domestic Water Heat Exchanger	Does not Exist
Electric Domestic Water Heater	Inspected
Condition	2 - Between Good and Fair No deficiencies recorded
Deficiency Gas Fired Domestic Water Heater	No deficiencies recorded Does not Exist
Heat Pump Domestic Water Heater	Does not Exist
Oil Fired Domestic Water Heater	Does not Exist
Domestic Water Distribution Piping	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
DRAIN/WASTE/VENT AND STORM SYSTEM	Inspected
Interior Storm Piping	Inspected
Condition	1 - Good
Deficiency Sewage/Waste/Vent Piping	No deficiencies recorded

	_	
uestion	Response	
DRAIN/WASTE/VENT AND STORM SYSTEM	Inspected	
Sewage/Waste/Vent Piping	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Sewage Ejector Pump	Does not Exist	
Sump Pump	Does not Exist	
DUAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)	Does not Exist	
FIXTURES	Inspected	
Staff And Other	Inspected	
Janitor Sink	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Lavatory/Sink	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Toilet	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Urinal	Does not Exist	
Student	Inspected	
Drinking Fountain	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Lavatory/Sink	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Locker Room Shower	Does not Exist	
Sink And Fountain Combo Unit	Does not Exist	
Toilet	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Urinal	Does not Exist	
GAS FIRED FURNACE	Does not Exist	
GAS SERVICE	Does not Exist	
HEATING	Inspected	
Heating Coil In Ductwork	Does not Exist	
Hydronic Heating	Inspected	
Hydronic Hot Water Distribution: Piping, Pumps and Auxiliaries	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Backflow Preventer	Does not Exist	
Hot Water Heat Exchanger	Does not Exist	
Radiator/Convector/Fin Tube	Inspected	
Condition	1 - Good	<u> </u>
Deficiency	No deficiencies recorded	
Steam Heating	Does not Exist	
Steam supplied by External Sources	Does not Exist	
Unit Heater/Cabinet Heater	Inspected	

nestion	Response	
HEATING	Inspected	
Unit Heater/Cabinet Heater	1	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
HEATING PLANT	Inspected	
Replacement Quantity	91	
Replacement Uom	MBH Net	
Instance on 1st Floor	Inspected	
Burner Type	N/A	
Heating Plant Oil Number Is there a water meter on the boiler make-up water piping?	N/A No	
Burner Exists?	No	
Boiler Auxiliaries	Inspected	
Instance on 1st Floor	Inspected	
Boiler Auxiliary Piping		
Instance on 1st Floor	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Boiler Emergency Stop Switch		
Instance on 1st Floor	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Boiler Feedwater System		
Instance on 1st Floor	Does not Exist	
Boiler Feedwater Treatment(Automatic)		
Instance on 1st Floor	Does not Exist	
Boiler Flue Exhaust		
Instance on 1st Floor	Does not Exist	
Boiler Make-up Water Backflow Preventer		
Instance on 1st Floor	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Boiler Room Steam And Condensate Piping		
Instance on 1st Floor	Does not Exist	
Boiler Safety Valve		
Instance on 1st Floor	Does not Exist	
Boiler System	Inspected	
Instance on 1st Floor	Inspected	
Coal-fired Boiler		
Instance on 1st Floor	Does not Exist	
Hot Water Boiler		
Instance on 1st Floor	Does not Exist	
Modular Boiler		
Instance on 1st Floor	Inspected	
Instance	Boiler Room	
Instance Condition	1 - Good	
Instance Quantity	91	
Instance Quantity Uom	MBH Net	
Instance Manufacturer	Lochinvar	
Equipment	N/A	

-		Q ²
uestion	Response	
HEATING PLANT	Inspected	
Boiler System		
Modular Boiler		
Capacity/Size Quantity	105	
Capacity/Size UOM	MBH Gross	
Source of Capacity/Size	Documented	
Installation Year	2018	
Source of Installation	Documented	
Deficiency	No deficiencies recorded	
Steam Boiler		
Instance on 1st Floor	Does not Exist	
Fuel System	Does not Exist	
Instance on 1st Floor	Does not Exist	
Enclosed IDF Room	Does not Exist	
KITCHEN	Inspected	
Instance on 1st Floor	Inspected	
CO Detector	Not Required	
Instance on 1st Floor	Not Required	
Gas System	Does not Exist	
Instance on 1st Floor	Does not Exist	
Grease Trap	Inspected	
Instance on 1st Floor	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Hood	Does not Exist	
Instance on 1st Floor	Does not Exist	
Hood Exhaust Ductwork	Does not Exist	
Instance on 1st Floor	Does not Exist Does not Exist	
Hood Exhaust Fan	Does not Exist	
	Does not Exist Does not Exist	
Instance on 1st Floor		
Hood Fire Suppression System	Does not Exist	
Instance on 1st Floor	Does not Exist	
Hot Water Temperature Booster	Does not Exist	
Instance on 1st Floor	Does not Exist	
Kitchen Sink	Inspected	
Instance on 1st Floor	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
MDF Room	Inspected	
Instance on Room 112	Inspected	
Dedicated A/C Equipment	Inspected	
Instance on Room 112	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
SCIENCE DEMO ROOM	Does not Exist	
SCIENCE LAB	Does not Exist	
SCIENCE PREP ROOM	Does not Exist	
SPRINKLERS, STANDPIPE, FIRE SYSTEM	Inspected	
Dry Sprinkler Alarm Valve Assembly	Does not Exist	

Building Condition Assessment Survey 2023 - 2024

Mechanical Inspection Q422 Question Response SPRINKLERS, STANDPIPE, FIRE SYSTEM Wet Sprinkler Alarm Valve Assembly Does not Exist Fire Booster Pump Assembly Does not Exist **Roof Tank** Does not Exist Siamese Connection Does not Exist Sprinkler Head Inspected 2 - Between Good and Fair Condition No deficiencies recorded Deficiency **Sprinkler Piping** Inspected Condition 1 - Good No deficiencies recorded Deficiency Standpipe System Does not Exist **Water Gong** Does not Exist SWIMMING POOL Does not Exist VENTILATION Inspected Is the building mechanically ventilated? Yes **Exhaust Fan** Inspected 1-25 Approximate Total # of Fans Condition 1 - Good Deficiency No deficiencies recorded **Heating And Ventilating Unit** Does not Exist **Metal Ductwork** Inspected Are there any uninsulated ductwork by design in Mechanical No Rooms? Are there chain operated dampers? No Condition 1 - Good Deficiency No deficiencies recorded **Supply Fan** Does not Exist **Unit Ventilator** Does not Exist