Asset: JAMAICA AF - QUEENS, 167-01 GOTHIC DRIVE, New York, 11432				
Inspection Id Inspection Type	,	Time In	Last Edited	
ME: Q471 Mechanical		2023-11-20 10:19 AM	2023-12-07 2:57 PI	
lsset Data				
Question	Answer			
Are there fuel tanks?	No			
Total # of water main service entries to the asset	1			
MERs/Fan Rooms Locations	Mechanica	al Equipment Room		
Are there any spaces with Missing or Defective CO Detectors?	No			
Are there any Emergency Stop Switches with Missing Hammers?	No			
Are there any Painted/Obstructed Sprinkler Heads?	No			
Have any Systems/Major Building Components been upgraded?	Yes Systems:	Fixtures - Staff And Others - Uri	$\mathbf{rals}(2 \text{ of } 2)$	
	Years:	2021		
riority Condition				
PriorityPriorityConditionComponentLocationCondition ExistCategoryDescriptionAffectedDescriptionLast Year?	Person(s) Notified	Person(s) Title Status	PhotoImage	
No condition recorded				
nspection				
Question	Respon	se		
Mechanical				
AIR CONDITIONING	Does no	t Exist		
CLIMATE CONTROL SYSTEM	Does no	t Exist		
COMPACTOR	Does no	t Exist		
CONVEYING	Does no	t Exist		
DOMESTIC WATER SYSTEM	Inspecte	d		
Domestic Cold Water System	Inspecte	d		
Gravity System	Does no	t Exist		
Pressure Booster System	Inspecte	d		
Electric Pressure Booster System	Inspecte	d		
Instance	MER			
Instance Condition	4 - Betw	een Fair and Poor		
Instance Quantity	1			
Instance Quantity Uom	EACH			
Instance Manufacturer	Canariis			
Equipment	N/A			
Capacity/Size Quantity	2			
Capacity/Size UOM	Total # I	Pumps		
Capacity/Size2 Quantity	6			
Capacity/Size2 UOM	Total Pu	imps HP		
Source of Capacity/Size	Docume			
Installation Year	2001			
Source of Installation	Custodia	al Staff		
Deficiency		TIVE CONTROLS		
Deficiency Quantity	1			
Quantity Uom	EACH			
Potential Action	REPAIR	R		

NYC Department of Education

uestion	Response		
DOMESTIC WATER SYSTEM	Керопяс		
Domestic Cold Water System			
Pressure Booster System			
Electric Pressure Booster System			
Purpose of Action	LEVEL 2		
Deficiency Photo1	No photo recorded		
Violations	No violations recorded.		
Hydraulic/Pneumatic Booster System	Does not Exist		
Water Service	Inspected		
Instance	Mechanical Equipment Room		
Instance Condition	3 - Fair		
Instance Quantity	1		
Instance Quantity Uom	EACH		
Deficiency	No deficiencies recorded		
Domestic Hot Water System	Inspected		
Domestic Hot Water Remote Storage Tank	Does not Exist		
Domestic Water Heat Exchanger	Does not Exist		
Electric Domestic Water Heater	Does not Exist		
Heat Pump Domestic Water Heater	Does not Exist		
Gas Fired Domestic Water Heater	Inspected		
Instance	Mechanical Equipment Room		
Instance Condition	3 - Fair		
Instance Quantity	5 - ran 1		
Instance Quantity Uom	EACH		
Instance Manufacturer	PVI		
Equipment	N/A		
Capacity/Size Quantity	200		
Capacity/Size UOM			
	MBH Input 250		
Capacity/Size2 Quantity			
Capacity/Size2 UOM	Gallons		
Source of Capacity/Size Installation Year	Inspector Estimate		
	2001		
Source of Installation	Inspector Estimate		
Deficiency Oil Fired Domestic Water Heater	No deficiencies recorded Does not Exist		
Domestic Water Distribution Piping Condition	Inspected		
Deficiency	No deficiencies recorded	3 - Fair	
DENCICICULAR DENCICICA DENCICICA DENCICICA DE	Inspected		
	-		
Interior Storm Piping Condition	Inspected 3 Fair		
Deficiency	No deficiencies recorded	3 - Fair	
Sewage/Waste/Vent Piping	Inspected		
Condition	3 - Fair		
Deficiency	No deficiencies recorded		
Sewage Ejector Pump	Does not Exist		
Sump Pump	Does not Exist		
DUAL TEMPERATURE SYSTEM (CHILLED AND HOT	Does not Exist		

NYC Department of Education

Inspected	
3 - Fair	
No deficiencies recorded	
Inspected	
Inaccessible	
Does not Exist	
No deficiencies recorded	
Does not Exist	
Does not Exist	
Does not Exist	
Inspected Mechanical Equipment Room	
3 - Fair 1	
EACH	
-	

NYC Department of Education

hanical Inspection	Response	
	Response	
HEATING Radiator/Convector/Fin Tube	Does not Exist	
Steam Heating	Does not Exist	
Steam supplied by External Sources	Does not Exist	
Unit Heater/Cabinet Heater	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
HEATING PLANT	Does not Exist	
Enclosed IDF Room	Does not Exist	
MDF Room	Does not Exist	
SPRINKLERS, STANDPIPE, FIRE SYSTEM	Does not Exist	
VENTILATION	Inspected	
Is the building mechanically ventilated?	Yes	
Exhaust Fan	Inspected	
Approximate Total # of Fans	1-25	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Heating And Ventilating Unit	Does not Exist	
Metal Ductwork	Inspected	
Are there any uninsulated ductwork by design in Mechanical		
Rooms?	No	
Are there chain operated dampers?	No	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Supply Fan	Does not Exist	
Unit Ventilator	Does not Exist	