NYC Department of Education

Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

Asset:	JOHN ADA	AMS AF - QUE	ENS, 101-01 R	OCKAWAY E	BLVD, New Yo	rk, 11417		
Inspection Id	Inspection	Туре				Time In	Last Edited	
EE : Q481	Electrical					2024-01-31 12:48 PM	2024-04-18 12:42 PM	
sset Data								
Question					Answer			
Type of Service					Below Gr	ound		
Does Interactive Whiteboard (IWB) Exist?					No			
Water Penetration in Electrical Room?					No			
	·	ding Components	10		No			
	INTERCOMS	S IN FIRE RESC	UE AREAS		D			
Question Are there any Life Rescue Assistance Areas, Fire Rescue Areas,					Response No	<u>,</u>		
and/or Holding	Rooms in you							
riority Condition	n							
Priority P Condition Exist C Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title Status	PhotoImage	
No condition record	ded							
spection								
Question					Respor	nse		
Electrical								
ATHLETIC FIELD					Inspecto	ed		
Exterior Lig	hting				Does not Exist			
Local Sound	System			Inspected				
Installation Year				1990				
Source of Installation				Inspector Estimate				
Condition				5 - Poor				
Deficiency				AMPLIFIER NOT OPERATIONAL				
Deficiency Quantity				1				
Quantity Uom				EACH				
Potential Action				REPLACE SYSTEM				
Urgency of Action				PRIORITY 2				
Purpose of Action				LEVEL 2				
Deficiency Photo1				No photo recorded				
Violations					No violations recorded.			
Scoreboard					Inspecto	ed		
Instance					Facing	Football Field		
Instance Condition					5 - Poor	r		
Instan	nce Quantity				1			
Insta	Instance Quantity Uom				EACH			
Deficiency					NOT O	PERATIONAL		
Deficiency Quantity					1			
Quantity Uom					EACH			
Potential Action					REPLA	се		
Urgency of Action					PRIOR	ITY 3		
Purpose of Action					LEVEL	. 2		
Deficiency Photo1					No pho	to recorded		
Violations					No viol	ations recorded.		
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE					Does not Exist			
LOCKER ROOM					Does no	Does not Exist		

NYC Department of Education

Building Condition Assessment Survey 2023 - 2024

etrical Inspection		Q4
uestion	Response	
TOILET ROOM - STAFF	Does not Exist	
TOILET ROOM - STUDENT	Does not Exist	
AUXILIARY SIGNAL/BELL SYSTEM	Does not Exist	
EMERGENCY DC STANDBY BATTERY POWER	Does not Exist	
EMERGENCY GENERATOR SET	Does not Exist	
EMERGENCY LIGHT/EXIT LIGHT PANEL	Does not Exist	
EMERGENCY LIGHTING	Does not Exist	
EXIT LIGHT	Does not Exist	
EXIT/EMERGENCY LIGHT	Does not Exist	
FIRE ALARM SYSTEM	Does not Exist	
GROUNDING SYSTEM	Does not Exist	
LAN	Does not Exist	
LIGHTNING PROTECTION	Does not Exist	
MOTOR CONTROLLER	Does not Exist	
PANEL BOARD	Does not Exist	
PUBLIC ADDRESS SYSTEM	Does not Exist	
SECURITY	Does not Exist	
SERVICE SWITCH	Does not Exist	
SWITCHBOARD	Does not Exist	
TELEPHONE SYSTEM	Does not Exist	
TRANSFORMER	Does not Exist	