#### **Building Condition Assessment Survey 2023 - 2024**

#### **Electrical Inspection**

Inspection Id Inspection Type	Time In Last Edited
EE : Q727 Electrical	2024-04-09 11:35 AM 2024-04-23 3:33 PM
sset Data	
Question	Answer
Type of Service	Below Ground
Does Interactive Whiteboard (IWB) Exist?	Yes
Water Penetration in Electrical Room?	No
Have any Systems/Major Building Components been upgraded?	Yes
	Systems:Exit/Emergency Light, Telephone SystemYears:2016
	Systems: Service Switch, Switchboard, Grounding System
	Years: 2013
	Systems: Intrusion Alarm System (Remote Annunciator)
	Years: 2012
	Systems: Fire Alarm System
	Years: 2007
	Systems: All Other Electrical Systems and Components
	Years: 2002
DEDICATED INTERCOMS IN FIRE RESCUE AREAS	Demonse
Question Are there any Life Rescue Assistance Areas, Fire Rescue Areas,	Response No
and/or Holding Rooms in your building?	10
riority Condition	
Priority Priority Condition Component Location	n Person(s) Person(s) Title Status PhotoImage
Condition Exist Category         Description         Affected         Description           Last Year?         No condition recorded         Description         Description </td <td></td>	
Condition Exist Category Description Affected Descript Last Year?	
Condition Exist Category         Description         Affected         Description           Last Year?         No condition recorded         Inspection         Inspecification         Inspecification         Inspecification         Insp	
Condition Exist Category         Description         Affected         Description           Last Year?         No condition recorded	ion Notified
Condition Exist Category         Description         Affected         Description           Last Year?         No condition recorded         Inspection         Inspecification         Inspecification         Inspecification         Insp	ion Notified
Condition Exist Category       Description       Affected       Description         Last Year?       No condition recorded       Image: Cond	ion Notified Response Inspected Inspected
Condition Exist Category       Description       Affected       Description         Last Year?       No condition recorded       Image: Category       Description       Image: Category       Description       Image: Category       Image: Category       Description       Image: Category       Image: Category       Description       Image: Category       Im	ion Notified  Response  Inspected Inspected No
Condition Exist Category       Description       Affected       Description         Last Year?       No condition recorded       Image: Second Se	ion Notified  Response  Inspected Inspected No Inspected Inspected
Condition Exist Category       Description       Affected       Description         Last Year?       No condition recorded       Image: Category       Description       Image: Category       Description       Image: Category       Image: Category       Description       Image: Category       Image: Category       Description       Image: Category       Im	ion Notified  Response  Inspected Inspected No Inspected Does not Exist
Condition Exist Category       Description       Affected       Description         Last Year?       No condition recorded       Image: Section and the	ion Notified  Response  Inspected Inspected No Inspected Does not Exist Inspected Inspected
Condition Exist Category       Description       Affected       Description         No condition recorded       Image: Condition recorded       Image: Condition       Image: C	ion Notified  Response  Inspected Inspected No Inspected Does not Exist Inspected 3 - Fair
Condition Exist Category       Description       Affected       Description         No condition recorded       Image: Category in the second secon	ion Notified  Response  Inspected Inspected No Inspected Does not Exist Inspected 3 - Fair No deficiencies recorded
Condition Exist Category       Description       Affected       Description         No condition recorded       Image: Second	ion Notified  Response  Inspected Inspected No Inspected Does not Exist Inspected 3 - Fair No deficiencies recorded Does not Exist Does not Exist
Condition Exist Category       Description       Affected       Description         No condition recorded       Image: Second	ion Notified  Response  Inspected Inspected Inspected No Inspected Does not Exist Inspected 3 - Fair No deficiencies recorded Does not Exist Does not Exist Does not Exist Does not Exist
Condition Exist Category       Description       Affected       Description         No condition recorded       Image: Second	ion Notified  Response  Inspected Inspected No Inspected Does not Exist Inspected 3 - Fair No deficiencies recorded Does not Exist Does not Exist
Condition Exist Category       Description       Affected       Description         No condition recorded       Image: Second	ion Notified  Response  Inspected Inspected Inspected No Inspected Does not Exist Inspected 3 - Fair No deficiencies recorded Does not Exist Does not Exist Does not Exist Does not Exist
Condition Exist Category       Description       Affected       Description         No condition recorded       Image: Second	ion Notified  Response  Inspected Inspected No Inspected No Inspected Does not Exist Inspected 3 - Fair No deficiencies recorded Does not Exist
Condition Exist Category       Description       Affected       Description         No condition recorded       Image: Second	ion Notified           Response           Inspected           Inspected           No           Inspected           Does not Exist           Inspected           3 - Fair           No deficiencies recorded           Does not Exist
Condition Exist Category       Description       Affected       Description         No condition recorded       Image: Second	ion Notified           Response           Inspected           Inspected           No           Inspected           Does not Exist           Inspected           3 - Fair           No deficiencies recorded           Does not Exist           Inspected
Condition Exist Category       Description       Affected       Description         No condition recorded       Image: Section in the section is spection       Image: Section is spectral in the section is spectral is spectral in the section is spectral is spectral is spectral is spectral in the section in the section is spectral in the section is spectral in the section is spectral in the section in the section in the section is spectral in the section in the section in the section is spectral in the section is spectral in the section is spectral in the section in th	ion Notified  Response  Response  Inspected  Inspected  No  Inspected  Does not Exist  Inspected  3 - Fair  No deficiencies recorded  Does not Exist  Does not Exist  Does not Exist  Does not Exist  Inspected  Inspected
Condition Exist Category       Description       Affected       Description         Last Year?       No condition recorded       Image: Secretary Secretar	ion Notified  Response  Response  Inspected  Inspected  No  Inspected  Does not Exist  No deficiencies recorded  Response  Response
Condition Exist Category       Description       Affected       Description         Last Year?       No condition recorded       Image: Secretary of the secret	ion Notified  Response  Inspected  Inspected  Inspected  Inspected  Does not Exist  Inspected  3 - Fair  No deficiencies recorded  Does not Exist  Inspected  Inspected
Condition Exist Category       Description       Affected       Description         No condition recorded       Image: Second	ion Notified  Response  Inspected  Inspected  No  Inspected  Does not Exist  Inspected  Inspected In

(P)

uestion	Response	
TOILET ROOM - STAFF	κτομοποτ	
Lighting		
Lighting Fixture - Incandescent		
Lighting Fixture - LED	Does not Exist	
TOILET ROOM - STUDENT	Inspected	
	Inspected	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Does not Exist	
Surface Mounted	Inspected	
Condition	3 - Fair	
Deficiency Recessed Mounted	No deficiencies recorded	
	Does not Exist	
Lighting Fixture - Incandescent	Does not Exist	
Lighting Fixture - LED	Does not Exist	
EMERGENCY LIGHTING	Does not Exist	
EXIT LIGHT	Does not Exist	
EXIT/EMERGENCY LIGHT	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	FIXTURE LENS MISSING	
Deficiency Location/Instance	T-2	
Deficiency Quantity	2	
Quantity Uom	EACH	
Potential Action	INSTALL LENS	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 2	
Deficiency Photo1	No photo recorded	
Violations	No violations recorded.	
FIRE ALARM SYSTEM	Inspected	
Replacement Quantity	1,300	
Replacement Uom	S.F.	
Bell/Horn	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Strobe	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Manual Pull Station	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Fan Shutdown Control	Does not Exist	
Duct Smoke Detector	Does not Exist	
Area Smoke Detector	Does not Exist	
CO Detector	Does not Exist	
Fused Cutout Panel	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Fire Alarm Digital Communicator	Does not Exist	

uestion	Response	
FIRE ALARM SYSTEM		
Main Panel		
Bell At Panel	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Electronic)	Inspected	
Instance	T-2	
Instance Condition	2 - Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Instance Manufacturer	Faraday	
Equipment	Fire Alarm Control Panel	
Model	MPC - 6000	
Installation Year	2007	
Source of Installation	Documented	
Deficiency	No deficiencies recorded	
Remote Annunciator	Does not Exist	
GROUNDING SYSTEM	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
LAN	Inspected	
Local Distribution Frame (I/LDF)	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Main Equipment Rack (MDF)	Does not Exist	
PANEL BOARD	Inspected	
Molded Case Circuit Breaker Type	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
PUBLIC ADDRESS SYSTEM	Inspected	
Replacement Quantity	1,300	
Replacement Uom	S.F.	
Instance	Connected to Main Asset Q106	
Instance Condition	3 - Fair	
Instance Quantity	1	
	EACH	
Instance Quantity Uom		
Model Installation Year	N/A 2002	
Source of Installation	Documented	
Deficiency SECURITY	No deficiencies recorded	
	Inspected	
IPDVS/CCTV System	Does not Exist	
Intrusion Alarm System	Inspected	
Replacement Quantity	1,300	
Replacement Uom	S.F.	
Central Control Panel	Inspected	
Instance	T-2	
Instance Condition	3 - Fair	

uestion	Response	
SECURITY	response	
Intrusion Alarm System		
Central Control Panel		
Instance Quantity Uom	EACH	
Model	N/A	
Installation Year	2002	
Source of Installation	Documented	
Deficiency	No deficiencies recorded	
Infrared Sensor	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Panic Switch	Does not Exist	
Remote Annunciator	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Siren/Strobe	Does not Exist	
Lighting - Security	Inspected	
Replacement Uom	EACH	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
SERVICE SWITCH	Inspected	
Instance	Outdoor Electrical Enclosure	
Instance Condition	2 - Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Instance Manufacturer	Electrotech	
Equipment	N/A	
Capacity/Size Quantity	400	
Capacity/Size UOM	Amps	
Source of Capacity/Size	Nameplate	
Installation Year	2013	
Source of Installation	Custodial Staff	
Deficiency	No deficiencies recorded	
SWITCHBOARD	Inspected	
Number of Spares	1	
Fused Disconnect Switch Type	Does not Exist	
Molded Case Circuit Breaker Type	Inspected	
Instance	Outdoor Electrical Enclosure	
Instance Condition	2 - Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Instance Manufacturer	Electrotech	
Equipment	N/A	
Capacity/Size Quantity	400	
Capacity/Size UOM	Amps Total	
Capacity/Size2 Quantity	1	
Capacity/Size2 UOM	Section(S)	
Source of Capacity/Size	Service Switch Size	

etrical Inspection		Q727
uestion	Response	
SWITCHBOARD	Inspected	
Molded Case Circuit Breaker Type	Inspected	
Source of Installation	Custodial Staff	
Deficiency	No deficiencies recorded	
TELEPHONE SYSTEM	Inspected	
PBX/Intercom	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Standard	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	